

Messrs Grab Rentals Pte Ltd

TP AIG
Vic

Date : 21.12.2017

Estimate To Repair : Toyota Vios 1.5E CVT
Vehicle No : SLP7818K
Chassis No : MHFB29F3302012080

reg: Lkk. Adrian
22-12-2017 10:35hrs.

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	bootlid <i>Dented</i>	\$ 1,662.40	\$ 1,662.40 <i>762.50</i>
2	1 pc	bootlid lock <i>Dented</i>	\$ 190.40	\$ 190.40
3	1 pc	bootlid lock striker <i>new</i>	\$ 18.50	\$ 18.50
4	1 pc	bootlid weatherstrips <i>cut</i>	\$ 188.80	\$ 188.80
5	2 pc	bootlid hinge <i>new</i>	\$ 79.80	\$ 159.60
6	1 pc	bootlid inner trim <i>new</i>	\$ 234.30	\$ 234.30
7	4 pc	bootlid inner trim clips <i>new</i>	\$ 4.30	\$ 17.20
8	3 pc	bootlid lock cable clips	\$ 4.30	\$ 12.90
9	3 pc	bootlid wire harness clips <i>new</i>	\$ 4.30	\$ 12.90
10	1 pc	bootlid vios badge <i>new</i>	\$ 44.10	\$ 44.10
11	1 pc	bootlid centre emblem badge <i>new</i>	\$ 59.80	\$ 59.80
12	1 pc	bootlid E badge <i>new</i>	\$ 39.40	\$ 39.40
13	1 pc	bootlid outer garnish <i>new</i>	\$ 164.70	\$ 164.70
14	2 pc	rear licence plate lamp <i>new</i>	\$ 79.80	\$ 159.60
15	1 pc	rear end panel <i>dented</i>	\$ 694.70	\$ 694.70
16	1 pc	rear end panel inner trim <i>dented</i>	\$ 234.30	\$ 234.30
17	4 pc	rear end panel inner trim clips <i>new</i>	\$ 4.30	\$ 17.20
18	2 pc	rear luggage floor foam compartment <i>new</i>	\$ 75.00	\$ 150.00
19	2 pc	rear lamp <i>cracked</i>	\$ 375.80	\$ 751.60
20	1 pc	o/s rear lamp panel <i>new</i>	\$ 238.90	\$ 238.90
21	6 pc	rear lamp clips holder <i>new</i>	\$ 9.50	\$ 57.00
22	1 pc	o/s rear fender <i>Repis</i>	\$ 969.70	\$ 969.70 <i>4084.20</i>
23	1 pc	rear fender inner trim	\$ 395.10	\$ 395.10
24	4 pc	rear fender inner trim clips <i>new</i>	\$ 4.30	\$ 17.20 <i>3063.15</i>
25	1 pc	o/s rear fender air vent	\$ 45.10	\$ 45.10
26	1 pc	rear bumper <i>Deformed</i>	\$ 504.90	\$ 504.90
27	1 pc	rear bumper reinforcement <i>Best</i>	\$ 323.30	\$ 323.30
28	2 pc	rear bumper reflector <i>new</i>	\$ 130.50	\$ 261.00
29	2 pc	rear bumper side retainer <i>new</i>	\$ 115.10	\$ 230.20
30	10 pc	rear bumper clips <i>new</i>	\$ 4.30	\$ 43.00
31	2 pc	rear bumper splashshield cover <i>new</i>	\$ 89.80	\$ 179.60
				\$ 8,077.40
Less 25%				\$ 2,019.35
Balance c/f				\$ 6,058.05

Messrs Grab Rentals Pte Ltd

Date : 21.12.2017

Estimate To Repair : Toyota Vios 1.5E CVT
Vehicle No : SLP7818K
Chassis No : MHFB29F3302012080

Pages : 2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance b/f		\$ 6,058.05
		SPECIAL NETT ITEMS		
32	1 pc	rear licence plate Bent 280	\$ 80.00	\$ 80.00 60
33	1 set	rear bumper parking sensor damaged	\$ 500.00	\$ 500.00 20
				\$ 580.00
		LABOUR & MISC. CHARGES		
1		To check electrical lighting concerned.		\$ 60.00 30
2		To remove and refit rear windscreen glass.		\$ 180.00 X
3		To rust-proofing of the affected areas.		\$ 180.00 40
4		To reinstall of rear bumper parking sensor.		\$ 150.00 50
5		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.		\$ 120.00 60
6		To drop rear exhaust box and renew the same.		\$ 120.00 X
7		To transfer of bootlid fittings, attachments and perform water seepage test.		\$ 120.00 50
8		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	1630	\$ 1,300.00 80
9		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.		\$ 550.00 X
10		Putty and spray painting of the affected portion.		\$ 1,100.00 60
				\$ 3,640.00
		Grand Total		\$ 10,278.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ling.
22/12/17
H/S 06 Rays.

total: 4973.15
H/S: 3950

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216