

INSPECT
Meimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time

22/12/17 @ 1:26pm

Estimated Cost:

Bill to:

OL / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 84032

Insured:

at Workshop m/s

K. Kim Hin Auto

Tel:

64527018

of

160 Sin Ming Drive # 02-20 Sin Ming Autocity

Policy No:

DMPCSN 8021771702

Claim No:

SNM17D0721401

Sum Insured:

Excess:

—

Make of Veh:

(Client's Record)

D.O.A

17/12/2017

CA

REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:46am @ 28/12/17

Person Contacted:

Shuman

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJX 84032 - CC3/AIG 11017063/Ry.In D.O.A: 11/08/2011
28/12/17 @ 11:10am	revert to Chong Boon Sen via Meimen.
28/12/17 @ 5:13pm	Susan Teo informed C/A via Meimen.
29/12/17 @ 9:03am	Informed Simon & Mary Huet C/A & ex: \$ of by email.
04/01/18 @ 2:16pm	confirmed with Mary Huet final fig \$ 810.66, 7 days.
	Chad @ 986.99, 10%.
	No lump sum.

REF: CTI

ASSIGNMENT

From: Date: 26/12/17

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJX 84032

at Workshop m/s K-Kim Hin Auto

of 160 Sin Ming Drive #02-20

Insured

Policy No.

Claims No.

Sum Insured: Excess: —

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 846k

IDAC Accident Report: Consistent? Yes or No

GIA / PR. Seen: Consistent? Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJX 84032 Yr Reg: 07 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Maker: Mr A Bido cc 18PP

Colour: n. Car Bm A/C Insured / Std / NI / NA

Sp. Reading: 84310 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2452322J 572098

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 215/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 19/12/17

Rear:

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 26/12/17

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc bag & u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/12 File pass to Cocking

RECEIVED 05 OCT 2018

4/10/2018

Date/Time, File Pass to?

11/10/10 turner

Date/Time, File Return to?

3

☐ : Prel. Report☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photo:

Other:

TOTAL

Add Fee: ☐ : Site Insp: (\$☐ : Interview: (\$☐ : Tech. Insp: (\$☐ : Weekend: (\$

Report Format:

Lump Sum / I.B.I: (\$ 8610.66)

MER-00

220

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17024369/Kqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-12-2017



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJX 8403Z
Policy No.	DMPCSN3021771702	Coverage (\$)	0.00
Claim No.	SNM17D07214C01	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	26/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/12/2017	Inspection Date	22/12/2017
Survey held at	160 SIN MING DRIVE # 02-20,575722		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017 Sendback Est	22 Dec 2017 11:52 S\$9,455.48	22 Dec 2017 13:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	RICCIO ANNA MARIA, ID: S2643271E, Tel: +6596479480, Email: NOEMAIL		
Vehicle Reg. No.:	SJX8403Z	Date of Loss:	19/12/2017 21:00 - :59
Claim Type:	OD / SNM17D07214C01	Policy/Cover Note No.:	DMPCSN3021771702 (Comprehensive) Coverage: 16/07/2017 - 15/07/2018
		Excess:	S\$0.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/01/2018]		
Driver/Custodian:	RICCIO ANNA MARIA (65 / Female), NRIC: S2643271E, Tel: +6596479480		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 4 October 2018 2:16 PM
To: 'survey@kkimhin.com.sg'
Cc: SUR; simon@kkimhin.com.sg; sandrakhong@gmail.com; service@kkimhin.com.sg; admin1@kkimhin.com.sg
Subject: RE: VEHICLE SJX 8403Z (DOA: 19/12/2017)

Dear Meng Huat,

WITHOUT PREJUDICE

Confirm final fig \$8,610.66 before excess \$0/- & GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>
Sent: Monday, 17 September 2018 11:29 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; simon@kkimhin.com.sg; sandrakhong@gmail.com; service@kkimhin.com.sg; admin1@kkimhin.com.sg
Subject: RE: VEHICLE SJX 8403Z (DOA: 19/12/2017)

Hi Ms Shiau Chan,

Enclosed you attention.

P/P=\$8,610.66

Please confirm.

Thank you.

Regard

Meng Huat

K.kim Hin Auto

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, 2 August 2018 4:33 PM
To: survey@kkimhin.com.sg
Cc: SUR <sur@lkkauto.com>; simon@kkimhin.com.sg; sandrakhong@gmail.com; service@kkimhin.com.sg; admin1@kkimhin.com.sg
Subject: RE: VEHICLE SJX 8403Z (DOA: 19/12/2017)

Dear Meng Huat & Simon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 4 October 2018 2:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJX 8403Z (YOUR REF: SNM17D07214C01)

This mail is associated with :
SJX8403Z (SNM17D07214C01)
OD
Dec 19 2017 9:00PM
[RICCIO ANNA MARIA]
K Kim Hin Auto Pte Ltd

Dear Boon Sen,

We have received supplementary of \$142.17 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident, and is economical to repair.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 29 December, 2017 9:03 AM
To: Survey KKH
Cc: SUR
Subject: VEHICLE SJX 8403Z (DOA: 19/12/2017)

Dear Simon & Meng Huat,

As instructed by our client, please proceed to repair the insured vehicle **SJX 8403Z (excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Dec 2017 11:43	Cim Veh Model Changed	(201787) MERCEDES-BENZ B180 1.7 (A).	[R] Jane
2	22 Dec 2017 11:43	Cim Created	Reg No: SJX8403Z. Policy No: DMPCSN3021771702. Acct Date: 2017/12/19. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: K Kim Hin Auto Pte Ltd (HQ). Created from SAS:MKKH17167389	[R] Jane
3	22 Dec 2017 11:52	Cim Submitted	9455.48.	[R] Jane
4	22 Dec 2017 13:26	Cim Registration Modified	Excess: -> 0.00.	[I] Chong Boon Sen
5	22 Dec 2017 13:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
6	22 Dec 2017 13:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/04	[I] Chong Boon Sen
7	22 Dec 2017 13:26	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
8	22 Dec 2017 17:47	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	27 Dec 2017 17:52	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] CATHERINE CHONG KAI LING
10	28 Dec 2017 11:05	Adj Rpt Initiated		[A] SHIAU CHAN
11	28 Dec 2017 11:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/04	[A] SHIAU CHAN
12	28 Dec 2017 11:10	Adj Mandate Request	Cur,Req:8949.49:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	28 Dec 2017 17:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/04. Mandate Remarks: amount inclusive of check items	[I] Susan Teo
14	28 Dec 2017 17:13	Adj Mandate Set	Approved:8769.09:amount inclusive of check items	[I] Susan Teo

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1675918	22/12/2017 11:43	Motor	K Kim Hin Auto Pte Ltd (HQ)	K Kim Hin Auto Pte Ltd (HQ)	SJX8403Z		xx.xx
1679986	28/12/2017 11:05	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJX8403Z		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 28 Dec 2017

Preliminary Advice

Vehicle No	: SJX8403Z	Accident Date	: 19/12/2017
Make	: MERCEDES-BENZ B180	Policy No.	: DMPCSN3021771702
Assignment Date	: 22/12/2017	Excess	: S\$0.00
Date of Inspection	: 26/12/2017	Est. Duration of Repair	: 7.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear body & undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,455.48
Revised Amount	:S\$	7,160.99
Check Items (Estimated)	:S\$	1,787.50
Total	:S\$	8,948.49

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	27,586.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,414.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3271E
Vehicle Details	
Vehicle No.:	SJX8403Z
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	26694030753502
Chassis No.:	WDD2452322J572098
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$29,005.00
Original Registration Date:	16 Jul 2010
First Registration Date:	16 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$29,005.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jul 2020
PARF Rebate Amount:	\$17,403.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$10,183.00
Total Rebate Amount:	\$27,586.00

The information contained herein is correct as at 28 Dec 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3271E
Vehicle Details	
Vehicle No.:	SJX8403Z
Vehicle to be Exported:	No
Intended De-registration Date:	20 Dec 2017
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	26694030753502
Chassis No.:	WDD2452322J572098
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$29,005.00
Original Registration Date:	16 Jul 2010
First Registration Date:	16 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$29,005.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jul 2020
PARF Rebate Amount:	\$17,403.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jul 2020
COE Category:	B - Car (1601cc & above)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2017 17:23
Date Of Accident	19/12/2017 21:00
Exact Location Of Accident	JUNCTION BISHAN ROAD AND ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX8403Z
Insured/Policyholder	
Name Of Registered Owner	RICCIO ANNA MARIA
NRIC No	S2643271E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96479480
Alternative Phone No	OFFICE-96479480

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	B180-1.7 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3021771702
Cover Note Number	

Driver

Name of Driver	RICCIO ANNA MARIA
NRIC No	S2643271E
Date Of Birth	09/08/1952
Occupation	INDOOR
Date Of Driving Pass	12/05/1997
Driving Experience	20 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96479480
Fax Number	
Contact Number	OFFICE-96479480
Email Address	NOEMAIL

Address	15 CONWAY CIRCLE
Postcode	558260
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP6314D
Vehicle Make/Model/Colour	MITSUBISHI LANCER RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FANG MIN
NRIC/Passport Number	
Contact Number	93249391
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:

20/12/17

@

4:45pm

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS WAITING TO MAKE RIGHT TURN TO ANG MO KIO AVE 1.

TRAFFIC LIGHT TURNED GREEN AND FRONT VEHICLE MOVED. I WAS DISTRACTED AND I FOLLOWED, NOT REALISING THERE IS AN ONCOMING CAR AND WE COLLIDED.

FORTUNATELY NO ONE INJURED. I WAS ALONE IN MY CAR AND THERE ARE 2 PEOPLE IN THE OTHER CAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time:

Company Chop (if applicable)

20/12/17 @ 4:50pm
[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHC0206
Version: K.KIMHIN/1
Date Calculated: 22/12/2017 03:24

Full Report - V1
Registration: SJX8403Z
Printed: 22/12/2017 11:24

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	19/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA

Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3021771702	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 180
Model Sheet Number:	322 42
Registration:	SJX8403Z
Registration Month:	July
Registration Year:	2010
VIN Number:	WDD2452322J572098
Manufacture Year:	2010
Odometer:	Not Known
Colour:	
Engine Number:	26694030753502
Fuel Level:	%

Model Specs

FROM VIN J 533109	AIR CONDITIONING
SMOKER PACKAGE	LIGHT-/VIEW PACKAGE
RAIN SENSOR	FRT/RR ELECT WINDOWS
FOG LAMPS	AUDIO 20 CD CHANGER
LEATHER PAD ARTICO	SPORT PACKAGE
CHILD SEAT MOUNTING	ILLUM SUN VISORS
FRT SEAT LUGGAGE NET	DIPPING INT MIRROR
DR/SEAT STORAGE BOX	P/SEAT STORAGE BOX
FR SEAT COMFORT PACK	LUGGAGE COMP COVER
ST/WHEEL/LEV LEATHER	AUTOM-GEAR VARIABLE
ADJ STEERING COLUMN	CRUISE CONTROL
TYRES 215/45 ZR 17	SPARE WHEEL
WHEELS 7J X 17 ALLOY	MOD YEAR CHANGE 2010
PREPARE OFF VEHICLE	WATER BASED PAINT
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on	
	Inspection:	
Brakes Pedal Travel:	Date of Inspection:	22/12/2017
Place of Inspection:		
Pre-Accident Damage:		



Tyres Condition:

Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Not Authorised
1-B-1
Returning B4 plates



7 days

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHC0206****Version: K.KIMHIN/1****Date Calculated: 22/12/2017 03:24****Full Report - V1****Registration: SJX8403Z****Printed: 22/12/2017 11:24****Addresses****Repairer**

Name : K.KIM HIN AUTO PTE LTD

Address :

160 SIN MING DRIVE

#02-20

SIN MING AUTOCITY

Post Code : 575722

Email Address : service@kkimhin.com.sg

Cost Summary

Total Labour	\$2,415.00
Total Paint/Material	\$223.34
Total Parts	\$6,135.14
Total of Additional Costs	\$682.00
Excess:	TBA
Grand Total Exc GST:	\$9,455.48
7 % GST:	\$661.88
Grand Total Inc GST:	\$10,117.36

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$0.00/HR****Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
72-1590 01	RENEW L/R DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PART, RENEW IF NECESSARY	29.0	133.40
72-1750 01	ADDITION TO RENEW L/DOOR (2ND DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1752 01	ADDITION TO RENEW L/DOOR (2ND DOOR) (VEHICLE W/ELECTRIC WINDOW REGULATOR)	4.0	18.40
88-4425 01	FIT L/SIDE PANEL FOIL	3.0	13.80
60-2175 04	R + R ATTACHED PARTS OF THE REAR PANELLING FOR RENEWAL OF THE L/R WING INCLUDES: R + R ATTACHED PARTS IN THE REPAIR SECTION	46.0	211.60
63-1882 02	RENEW L/REAR WING CPL	122.0	561.20
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT REAR DOOR	2.0	9.20
97-2500 ZAX	L/R WING CAVITY PROTECTION	2.0	9.20
60-1628 02	R + R AND STORE L/R SEAT AND MATS	7.0	32.20
91-1087 01)	R + R LEFT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	9.20

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0206

Version: K.KIMHIN/1

Date Calculated: 22/12/2017 03:24

Full Report - V1

Registration: SJX8403Z

Printed: 22/12/2017 11:24

61-1128 01	R + R REAR UNDERBODY COVERING	4.0	18.40
40-2125 ZAX	BALANCE WHEEL ASS WORK	2.0	9.20
35-1306 01	R + R REAR AXLE (WHEELS REMOVED)	21.0	96.60
35-2001 01	RENEW REAR AXLE CARRIER (AXLE REMOVED)	17.0	78.20
40-2710 01	FIT L/R WHEEL	3.0	13.80
40-2702 ZAX	ADDITION TO R + R TYRE (TYRE CROSS-SECTION LESS THAN 55)	2.0	9.20
40-2181 ZAX	ADDITION TO BALANCE REAR WHEEL (FIT ADHESIVE WEIGHTS)	1.0	4.60
42-2851 01)	R + R L/REAR BRAKE PADS (WHEELS REMOVED)	3.0	13.80
42-2881 01)	REMOVE/REFIT LH REAR BRAKE DISC (WITH BARKE PADS REMOVED)	4.0	18.40
42-3302 01)	REMOVE/REFIT BRAKE SHOES LH PARKING BRAKE (WITH BRAKE PADS REMOVED)	3.0	13.80
35-5731 01)	R + R L/R AXLE SHAFT FLANGE ADD	3.0	13.80
35-6020 01	R + R REAR AXLE COUPLING BEARING	8.0	36.80
35-6000 01)	REMOVE/REFIT LH REAR WHEEL THRUST LINK (WITH WHEEL REMOVED)	3.0	13.80
42-1300 01	PARKING BRAKE ADJUSTMENT	3.0	13.80
0245	ADDITIONAL WORK PULLING FRONT PANELS	20.0*	92.00
2101	REPAIR L/SILL PANEL	20.0*	92.00
2205	REPAIR L/SILL PANEL COVER	20.0*	92.00
2583	REPAIR REAR BUMPER COVER	30.0*	138.00

LABOUR COST

Total Work Units

388.0

Corrosion Protection

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.6HRS

27.60

Sub Total

38.8HRS

\$1,784.80

Paint Labour

13.7HRS

\$630.20

Total Labour

52.5HRS

\$2,415.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- WATER BASED PAINT		
	- TWO COAT PEARL/MICA		
1781	L/R DOOR NEW PART PAINTING	16.0	
3481	L/R WING NEW PART PAINTING	19.0	
9551	L/R WHEEL NEW PART PAINTING	6.0	
1983	L/R DOOR MOULDING NEW PART PAINT K1R	3.0	
3617	L/R SIDE MOULDING NEW PART PAINT K1R	3.0	
2205	L/SILL PANEL COVER REPAIR PAINT PLASTIC	11.0	
2583	REAR BUMPER COVER REPAIR PAINT PLASTIC	15.0	
2101	L/SILL PANEL REPAIR PAINTING >50%	14.0	
1481	LEFT FRONT DOOR SURFACE PAINT	8.0	
4107	L/R INNER PILLAR SURFACE PAINT	5.0	
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0	

LABOUR COST - PAINT

TIME(PAINT)

104.0

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0206

Version: K.KIMHIN/1

Date Calculated: 22/12/2017 03:24

Full Report - V1

Registration: SJX8403Z

Printed: 22/12/2017 11:24

Preparation Main Work Plastic	8.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	137.0	
Total Paintwork Labour	13.7HRS	\$630.20
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$72.09
New Part Painting - Plastic K1R		\$3.93
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$34.62
Repair Painting		\$11.46
Repair Painting Plastic		\$59.94
Material-Const Main Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$223.34
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$223.34

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1781	1	L/R DOOR	169 730 2105	Delaware	0% 1,155.00*
1809	1	L/R DOOR SEAL	169 737 1330		0% 116.00*
1983	1	L/R DOOR MOULDING	169 690 3762 9696		0% 70.00*
2001	1	L/R DOOR INSULATION	169 682 0008		0% 30.00*
3481	1	L/R WING	169 630 4701		0% 1,870.00*
3533	1	L/R S/PANEL RR FOIL	169 639 1708		0% 15.00*
3617	1	L/R SIDE MOULDING	169 690 4162 9696		0% 50.00*
3803	1	L/R SIDE WINDOW	169 670 0912		0% 105.00*
3821	1	L/QTR GLASS BOND KIT	000 670 0100	over	0% 51.75U
3847	1	L/SIDE WINDOW STRIPE	169 673 0583		0% 20.00*
9081	1	REAR AXLE SUBFRAME	169 350 0100		0% 1,020.00*
9151	1	L/R BRAKE CARRIER (Horse)	169 420 0915	Az	0% 200.00*
9181	1	L/R WHEEL HUB	169 981 0027		0% 160.00*
9201	1	L/R SHOCK ABSORBER	169 326 0700		0% 130.00*
9379	1	L/R THRUST ARM	169 350 0129		0% 85.00*
9381	1	L/R COVER	169 352 0188		0% 20.00*
9551	1	L/R WHEEL	169 401 2602		0% 650.00*
f: OEM Parts			Sub Total		\$5,747.75
g: Original			Mark Up From Cost	(5 %)	\$287.39
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$6,135.14
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	SPECIALIST 0%	\$42.00
WHEEL ALIGNMENT	SPECIALIST	\$100.00
R/L GLASS SEALANT	SPECIALIST 0%	\$40.00
RL GLASS	SPECIALIST	\$20.00
DAMPINGSEAL		
R/L TYRE	SPECIALIST 0%	\$480.00
Total Extras		\$682.00

Final Calculation

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHC0206****Version: K.KIMHIN/1****Date Calculated: 22/12/2017 03:24****Full Report - V1****Registration: SJX8403Z****Printed: 22/12/2017 11:24**

Total Parts		\$6,135.14
Labour		
Total Panel/Mechanical	\$1,757.20	
Total Paintwork	\$630.20	
Corr Prot Internal 6 WU	\$27.60	
Total Labour		\$2,415.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$682.00	
Total of Additional Costs		\$682.00
Total Paint/Material Costs		\$223.34
Grand Total Excludes GST		\$9,455.48
GST @ 7 %		\$661.88
Grand Total Includes GST		\$10,117.36

Assessment Notes

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be requested and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3021771702	Date of Loss:	19/12/2017
Vehicle Reg. No.:	SJX8403Z	Driveable?	
Driver Age/Info:	65 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RICCIO ANNA MARIA	Contact No:	+6596479480
Driver:	RICCIO ANNA MARIA		
Make/Model:	MERCEDES-BENZ B180, 1.7 (A)	Vehicle Reg. Date:	16/07/2010
Vehicle Colour:	BROWN		
Engine No:	26694030753502	Chassis No:	WDD2452322J572098
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. PLEASE NOTE THAT PARTS HAVE NO STOCK AND WILL TAKE 4-5 WEEKS TO ORDER. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	6,817.14
Miscellaneous Items	0.00
Labour	2,638.34
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,455.48
+ GST 7.00% (S\$)	661.88
Nett Amount (S\$)	10,117.36

This claim is handled by: SHUMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2017)**Parts:** 144 MERCEDES-BENZ B180 1.7 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** K Kim Hin Auto Pte Ltd/SJX8403Z/22/12/2017 11:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*L/QTR GLASS BOND KIT	0.00	0.00	*51.75 F <i>NTM</i>
2	1	NA	*L/R BRAKE CARRIER	0.00	0.00	<i>BT</i> *200.00 F <i>✓</i>
3	1	NA	*L/R COVER	0.00	0.00	*20.00 F <i>X SV</i>
4	1	NA	*L/R DOOR	<i>imp/comp</i> 0.00	0.00	*1,155.00 F <i>✓</i>
5	1	NA	*L/R DOOR INSULATION	0.00	0.00	<i>REC</i> *30.00 F <i>✓</i>
6	1	NA	*L/R DOOR MOULDING	0.00	0.00	<i>REC</i> *70.00 F <i>✓</i>
7	1	NA	*L/R DOOR SEAL	0.00	0.00	<i>REC</i> *116.00 F <i>✓</i>
8	1	NA	*L/R S/PANEL RR FOIL	0.00	0.00	<i>REC</i> *15.00 F <i>✓</i>
9	1	NA	*L/R SHOCK ABSORBER	0.00	0.00	<i>BT</i> *130.00 F <i>✓</i>
10	1	NA	*L/R SIDE MOULDING	0.00	0.00	<i>REC</i> *50.00 F <i>✓</i>
11	1	NA	*L/R SIDE WINDOW	0.00	0.00	*105.00 F <i>RSAC</i>
12	1	NA	*L/R THRUST ARM	0.00	0.00	<i>BT</i> *85.00 F <i>✓</i>
13	1	NA	*L/R WHEEL	0.00	0.00	<i>BT</i> *650.00 F <i>✓</i>
14	1	NA	*L/R WHEEL HUB	0.00	0.00	<i>BT</i> *160.00 F <i>✓</i>
15	1	NA	*L/R WING	0.00	0.00	<i>BT</i> *1,870.00 F <i>✓</i>
16	1	NA	*L/SIDE WINDOW STRIPE	0.00	0.00	<i>REC</i> *20.00 F <i>✓</i>
17	1	NA	*REAR AXLE SUBFRAME	0.00	0.00	<i>BT</i> *1,020.00 F <i>✓</i>
18	1	NA	*SPECIALIST AUDATEX FEE	0	0.00	*42.00 FS <i>✓</i>
19	1	NA	*SPECIALIST R/L GLASS SEALANT	0	0.00	<i>30</i> *40.00 FS <i>ALL</i>
20	1	NA	*SPECIALIST R/L TYRE	0	0.00	*480.00 FS <i>RSAC</i>
21	1	NA	*SPECIALIST RL GLASS DAMPINGSEAL	0	0.00	<i>REC</i> *20.00 FS <i>✓</i>
22	1	NA	*SPECIALIST WHEEL ALIGNMENT	0	0.00	<i>60</i> *100.00 FS <i>✓</i>
23	1	NA	*SUNDRY PARTS	0	0.00	<i>REC</i> *100.00 FS <i>✓</i>

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,529.75
+ Margin on L,N Items 5.00% (S\$)	287.39
Total Parts (S\$)	6,817.14

K Kim Hin Auto Pte Ltd/SJX8403Z/22/12/2017 11:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	630.20 ✓
2	Total Paint Materials	New	223.34 ✓
3	Total Panel/Mechanical Labour	New	1513.40 1,784.80
Gross Labour Cost (S\$)			2,638.34

K Kim Hin Auto Pte Ltd/SJX8403Z/22/12/2017 11:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

CO. REG. NO: 199402370D

GST NO: M2-0123250-3


KIM HIN AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3021771702	Date of Loss:	19/12/2017
Vehicle Reg. No.:	SJX8403Z	Driveable?	
Driver Age/Info:	65 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RICCIO ANNA MARIA	Contact No:	+6596479480
Driver:	RICCIO ANNA MARIA		
Make/Model:	MERCEDES-BENZ B180, 1.7 (A)	Vehicle Reg. Date:	16/07/2010
Vehicle Colour:	BROWN		
Engine No:	26694030753502	Chassis No:	WDD2452322J572098
Odometer:	84310 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	SUPPLEMENTARY		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	142.17
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	142.17
+ GST 7.00% (S\$)	9.95
Nett Amount (S\$)	152.12
+ Previous Estimates (S\$)	10,117.36
Claim Total (S\$)	10,269.48

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2018)**Parts:** 144 MERCEDES-BENZ B180 1.7 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** K Kim Hin Auto Pte Ltd/SJX8403Z/28/09/2018 17:44**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/R OUT DOOR FRT FOIL	0.00	0.00	REC *22.00 F ✓
2	1		*L/R OUT DOOR RR FOIL	0.00	0.00	REC *24.00 F ✓
3	1		*L/R MOUNTING KIT	0.00	0.00	REC *14.40 F ✓
4	1		*L/WHEELHOUSE COVER	0.00	0.00	REC *75.00 F ✓
F=Franchise part.						
Sub Total (S\$)						135.40
+ Margin on L,N Items 5.00% (S\$)						6.77
Total Parts (S\$)						142.17

K Kim Hin Auto Pte Ltd/SJX8403Z/28/09/2018 17:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

K Kim Hin Auto Pte Ltd/SJX8403Z/28/09/2018 17:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHC0206
Version: K.KIMHIN/1
Date Calculated: 06/09/2018 08:22

Full Report - V1
Registration: SJX8403Z
Printed: 06/09/2018 15:23

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	19/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3021771702	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 180
Model Sheet Number:	322 42
Registration:	SJX8403Z
Registration Month:	July
Registration Year:	2010
VIN Number:	WDD2452322J572098
Manufacture Year:	2010
Odometer:	Not Known
Colour:	
Engine Number:	26694030753502
Fuel Level:	%



Model Specs

FROM VIN J 533109	AIR CONDITIONING
SMOKER PACKAGE	LIGHT-/VIEW PACKAGE
RAIN SENSOR	FRT/RR ELECT WINDOWS
FOG LAMPS	AUDIO 20 CD CHANGER
LEATHER PAD ARTICO	SPORT PACKAGE
CHILD SEAT MOUNTING	ILLUM SUN VISORS
FRT SEAT LUGGAGE NET	DIPPING INT MIRROR
DR/SEAT STORAGE BOX	P/SEAT STORAGE BOX
FR SEAT COMFORT PACK	LUGGAGE COMP COVER
ST/WHEEL/LEV LEATHER	AUTOM-GEAR VARIABLE
ADJ STEERING COLUMN	CRUISE CONTROL
TYRES 215/45 ZR 17	SPARE WHEEL
WHEELS 7J X 17 ALLOY	MOD YEAR CHANGE 2010
PREPARE OFF VEHICLE	WATER BASED PAINT
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
	Date of Inspection:
Brakes Pedal Travel:	22/12/2017
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHC0206****Version: K.KIMHIN/1****Date Calculated: 06/09/2018 08:22****Full Report - V1****Registration: SJX8403Z****Printed: 06/09/2018 15:23****Addresses****Repairer**

Name : K.KIM HIN AUTO PTE LTD

Address :

160 SIN MING DRIVE

#02-20

SIN MING AUTOCITY

Post Code : 575722

Email Address : service@kkimhin.com.sg

Cost Summary

Total Labour	\$2,143.60
Total Paint/Material	\$223.34
Total Parts	\$6,091.72
Total of Additional Costs	\$152.00
Excess:	TBA
Grand Total Exc GST:	\$8,610.66
7 % GST:	\$602.75
Grand Total Inc GST:	\$9,213.41

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$0.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
72-1590 01	RENEW L/R DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PART, RENEW IF NECESSARY	29.0	133.40
72-1750 01	ADDITION TO RENEW L/DOOR (2ND DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1752 01	ADDITION TO RENEW L/DOOR (2ND DOOR) (VEHICLE W/ELECTRIC WINDOW REGULATOR)	4.0	18.40
88-4425 01	FIT L/SIDE PANEL FOIL	3.0	13.80
60-2175 04	R + R ATTACHED PARTS OF THE REAR PANELLING FOR RENEWAL OF THE L/R WING INCLUDES: R + R ATTACHED PARTS IN THE REPAIR SECTION	46.0	211.60
63-1882 02	RENEW L/REAR WING CPL	122.0	561.20
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT REAR DOOR	2.0	9.20
97-2500 ZAX	L/R WING CAVITY PROTECTION	2.0	9.20
60-1628 02	R + R AND STORE L/R SEAT AND MATS	7.0	32.20
91-1087 01)	R + R LEFT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	9.20

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0206

Version: K.KIMHIN/1

Date Calculated: 06/09/2018 08:22

Full Report - V1

Registration: SJX8403Z

Printed: 06/09/2018 15:23

68-1110 02	R + R LEFT C-PILLAR TRIM	5.0	23.00
61-1128 01	R + R REAR UNDERBODY COVERING	4.0	18.40
40-2125 ZAX	BALANCE WHEEL ASS WORK	2.0	9.20
35-1306 01	R + R REAR AXLE (WHEELS REMOVED)	21.0	96.60
35-2001 01	RENEW REAR AXLE CARRIER (AXLE REMOVED)	17.0	78.20
40-2710 01	FIT L/R WHEEL	3.0	13.80
40-2702 ZAX	ADDITION TO R + R TYRE (TYRE CROSS-SECTION LESS THAN 55)	2.0	9.20
40-2181 ZAX	ADDITION TO BALANCE REAR WHEEL (FIT ADHESIVE WEIGHTS)	1.0	4.60
42-2851 01)	R + R L/REAR BRAKE PADS (WHEELS REMOVED)	3.0	13.80
42-2881 01)	REMOVE/REFIT LH REAR BRAKE DISC (WITH BARKE PADS REMOVED)	4.0	18.40
42-3302 01)	REMOVE/REFIT BRAKE SHOES LH PARKING BRAKE (WITH BRAKE PADS REMOVED)	3.0	13.80
35-5731 01)	R + R L/R AXLE SHAFT FLANGE ADD	3.0	13.80
35-6020 01	R + R REAR AXLE COUPLING BEARING	8.0	36.80
35-6000 01)	REMOVE/REFIT LH REAR WHEEL THRUST LINK (WITH WHEEL REMOVED)	3.0	13.80
42-1300 01	PARKING BRAKE ADJUSTMENT	3.0	13.80
2101	REPAIR L/SILL PANEL	8.0*	36.80
2205	REPAIR L/SILL PANEL COVER	8.0*	36.80
2583	REPAIR REAR BUMPER COVER	10.0*	46.00
LABOUR COST			
Total Work Units		329.0	
Corrosion Protection			
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.6HRS	27.60
Sub Total		32.9HRS	\$1,513.40
Paint Labour		13.7HRS	\$630.20
Total Labour		46.6HRS	\$2,143.60

PAINT WORK

Guide Number Description		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
		WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- WATER BASED PAINT		
	- TWO COAT PEARL/MICA		
1781	L/R DOOR NEW PART PAINTING	16.0	
3481	L/R WING NEW PART PAINTING	19.0	
9551	L/R WHEEL NEW PART PAINTING	6.0	
1983	L/R DOOR MOULDING NEW PART PAINT K1R	3.0	
3617	L/R SIDE MOULDING NEW PART PAINT K1R	3.0	
2205	L/SILL PANEL COVER REPAIR PAINT PLASTIC	11.0	
2583	REAR BUMPER COVER REPAIR PAINT PLASTIC	15.0	
2101	L/SILL PANEL REPAIR PAINTING >50%	14.0	
1481	LEFT FRONT DOOR SURFACE PAINT	8.0	
4107	L/R INNER PILLAR SURFACE PAINT	5.0	
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0	
LABOUR COST - PAINT			
TIME(PAINT)		104.0	

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0206

Version: K.KIMHIN/1

Date Calculated: 06/09/2018 08:22

Full Report - V1

Registration: SJX8403Z

Printed: 06/09/2018 15:23

Preparation Main Work Plastic	8.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	137.0	
Total Paintwork Labour	13.7HRS	\$630.20
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$72.09
New Part Painting - Plastic K1R		\$3.93
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$34.62
Repair Painting		\$11.46
Repair Painting Plastic		\$59.94
Material-Const Main Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$223.34
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$223.34

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
1781	1	L/R DOOR	169 730 2105		0%		1,155.00*
1809	1	L/R DOOR SEAL	169 737 1330		0%		116.00*
1947	1	L/R OUT DR FRT FOIL	169 698 1977		0%		22.00*
1951	1	L/R OUT DOOR RR FOIL	169 698 3177		0%		24.00*
1983	1	L/R DOOR MOULDING	169 690 3762 9696		0%		70.00*
2001	1	L/R DOOR INSULATION	169 682 0008		0%		30.00*
2087	1	L/R MOUNTING KIT	USE SINGLE PARTS		0%		14.40*
3481	1	L/R WING	169 630 4701		0%		1,870.00*
3533	1	L/R S/PANEL RR FOIL	169 639 1708		0%		15.00*
3617	1	L/R SIDE MOULDING	169 690 4162 9696		0%		50.00*
3677	1	L/WHEELHOUSE COVER	169 698 2330		0%		75.00*
3805	1	L/R SIDE WINDOW	169 670 0912		0%		0.00F
3821	1	L/QTR GLASS BOND KIT	000 670 0100		0%		0.00F
3847	1	L/SIDE WINDOW STRIPE	169 673 0583		0%		20.00*
9081	1	REAR AXLE SUBFRAME	169 350 0100		0%		1,020.00*
9151	1	L/R BRAKE CARRIER	169 420 0915		0%		200.00*
9181	1	L/R WHEEL HUB	169 981 0027		0%		160.00*
9201	1	L/R SHOCK ABSORBER	169 326 0700		0%		130.00*
9379	1	L/R THRUST ARM	169 350 0129		0%		85.00*
9551	1	L/R WHEEL	169 401 2602		0%		650.00*
f: OEM Parts			Saving				\$103.90
g: Original			Sub Total				\$5,706.40
h: Secondhand			Mark Up From Cost	(5 %)			\$285.32
p: Parallel			Sundry Parts	(Fixed)			\$100.00
x: Exchange			Total Parts				\$6,091.72

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	SPECIALIST	0%
WHEEL ALIGNMENT	SPECIALIST	\$42.00
R/L GLASS SEALANT	SPECIALIST	\$60.00
RL GLASS	SPECIALIST	\$30.00
		\$20.00

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHC0206****Version: K.KIMHIN/1****Date Calculated: 06/09/2018 08:22****Full Report - V1****Registration: SJX8403Z****Printed: 06/09/2018 15:23****DAMPINGSEAL****Total Extras****\$152.00****Final Calculation****Total Parts****Labour****\$6,091.72**

Total Panel/Mechanical

\$1,485.80

Total Paintwork

\$630.20

Corr Prot Internal 6 WU

\$27.60

Total Labour**\$2,143.60****Additional Costs**

Corr Prot Materials External

\$0.00

Cost of Specialist

\$152.00

Total of Additional Costs**\$152.00****Total Paint/Material Costs****\$223.34****Grand Total Excludes GST****\$8,610.66**

GST @ 7 %

Grand Total Includes GST**\$9,213.41****Assessment Notes**



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D155243

TAX INVOICE

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.SJX8403Z

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I155243
DATE : 02/01/2018
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 02/01/2018 17:09:10

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	169 401 2602MB	SPORT RIM	LC	1	PC	650.00	650.00
2	169 682 0008MB	DOOR INSULATION	LC	1	PC	30.00	30.00

RECEIVED BY

PICKED BY:

SUB-TOTAL : S\$ 680.00
ADD 7% GST : S\$ 47.60
TOTAL : S\$ 727.60

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



0158104

TAX INVOICE

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.SJX8403Z

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I158104
DATE : 19/01/2018
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 19/01/2018 17:47:46

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	169 420 0915MB	REAR KNUCKLE LH	DC	1	PC	200.00	200.00

RECEIVED BY

PICKED BY: 8839

SUB-TOTAL : S\$ 200.00
ADD 7% GST : S\$ 14.00
TOTAL : S\$ 214.00

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D155 014

REPRINT

TAX INVOICE

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.SJX8403Z

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I155014
DATE : 09/01/2018
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 02/01/2018 17:07:50

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	169 630 4701MB	RR FENDER LH	DC	1	PC	1,870.0	1,870.00
2	169 690 4162 9999	RR FENDER PROTECTOR LH 9999	DC	1	PCS	50.00	50.00
3	169 639 1708MB	STICKER	DC	1	PC	15.00	15.00
4	169 673 0583MB	SIDE WINDOW MOULDING	DC	1	PC	20.00	20.00
5	169 730 2105MB	RR DOOR LH	DC	1	PC	1,155.0	1,155.00
6	169 737 1330MB	RR DOOR RUBBER LH	SS2J01	1	PC	116.00	116.00
7	169 690 3762 9999	RR DOOR PROTECTOR LH 9999	DC	1	PC	70.00	70.00
8	169 350 0100MB	RR AXLE MEMBER	DC	1	PC	1,020.0	1,020.00
9	169 350 0129MB	RR THRUST ARM	DC	1	PC	85.00	85.00
10	169 981 0027MB	REAR WHEEL BEARING	SS3C10	1	PCS	160.00	160.00
11	169 326 0700MB	RR ABSORBER	SS1F13	1	PCS	130.00	130.00

RECEIVED BY

PICKED BY: 8839

SUB-TOTAL : S\$ 4,691.00
ADD 7% GST : S\$ 328.37
TOTAL : S\$ 5,019.37

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D156006

REPRINT

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO. SJX8403Z

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

TAX INVOICE

INV NO : 1156006
DATE : 08/01/2018
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 09/01/2018 12:32:29

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	169 698 1977MB	COVER	DC	1	PC	22.00	22.00
2	169 698 3177MB	COVER	DC	1	PC	24.00	24.00
3	169 698 2330MB	RR FENDER INNER SEAL LH	DC	1	PC	75.00	75.00

CM
6

[Handwritten signature]

case 1709110D
Quote 29465
19.12.17 CHINA

CA = 100223 = 17.1.18 = \$ 12.10 + 0.85 = \$ 12.95

RECEIVED BY _____ PICKED BY: MB

SUB-TOTAL : S\$ 121.00
ADD 7% GST : S\$ 8.47
TOTAL : S\$ 129.47

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D155 854

REPRINT

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK: VEH NO. SJX8403Z

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

PASA
A/C 1200

TAX INVOICE

INV NO : I155854
DATE : 05/01/2018
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 05/01/2018 17:18:04

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	003 990 3597MB	RIVET.DOOR	SS2A31	8	PC	1.80	14.40



cm

case 170911 03
BUK 29465
19.12.17 CHIN

RECEIVED BY

PICKED BY: 2956 ✓

SUB-TOTAL : S\$ 14.40
ADD 7% GST : S\$ 1.01
TOTAL : S\$ 15.41

Goods sold are not returnable except Repairs/Service at authorized workshop.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017 Sendback Est	22 Dec 2017 11:52 \$59,455.48	22 Dec 2017 13:26 Edit Adj Rpt	\$58,610.66 Edit Estimates	\$58,610.66 View Rpt		Pending for Survey Report Cancel Case
Supp #1	28 Sep 2018 17:42	28 Sep 2018 17:44 \$5142.17	28 Sep 2018 17:44			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: RICCIO ANNA MARIA , ID: S2643271E, Tel: +6596479480, Email: NOEMAIL									
Vehicle Reg. No.: SJX8403Z		Date of Loss: 19/12/2017 21:00 - :59 [89 Months and 3 Days From LTA Reg Date (Men Yr)]							
Claim Type: OD / SNM17D07214C01		Policy/Cover Note No.: DMPCSN3021771702 (Comprehensive) Coverage: 16/07/2017 - 15/07/2018							
		Excess: \$0.00							
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/01/2018]									
Driver/Custodian: RICCIO ANNA MARIA (65 / Female), NRIC: S2643271E, Tel: +6596479480									
Adj Asg. Remarks: SURVEY REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (28/12/2017): Alert - Adj Mandate Approved (\$58769.09) - SJX8403Z - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJX8403Z (SNM17D07214C01)

OD

Dec 19 2017 9:00PM

[RICCIO ANNA MARIA]

K Kim Hin Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports

1 per page ☒

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 17:51	Accident Statement	Load HTM	
2	22/12/17 11:52	Repairer Estimates	Load HTM	
3	28/09/18 17:44	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 11:08	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page ☒

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
2	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
3	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
4	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
5	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
6	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
7	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
8	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
9	20/12/17 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
10	20/12/17 17:47	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
11	20/12/17 17:47	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	
12	20/12/17 17:47	Accident Photo [Linked Accident Report Documents]	Load JPG ☒	

Documentation

1 per page ☒

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 17:46	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	22/12/17 11:48	Certificate of Insurance	Load PDF	
3	22/12/17 11:48	Log card (if available)	Load PDF	
4	22/12/17 11:48	TRANSFER FEE	Load PDF	
5	22/12/17 11:49	Insured's NRIC	Load PDF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/12/17 11:36	Revised Estimate	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 11:09	INSPECTION PHOTO	Load PDF	
2	28/12/17 11:09	WORKSHOP ESTIMATE	Load PDF	
3	28/12/17 11:09	REVISED AUDATEX	Load PDF	
4	04/10/18 13:48	SUPPLEMENTARY LIST	Load PDF	
5	04/10/18 13:48	REVISED AUDATEX	Load PDF	
6	04/10/18 17:45	RESURVEY PHOTO	Load PDF	
7	05/10/18 14:30	Parts Invoice	Load PDF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 17:51	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 17:46	Accident Photo		Load JPG	☒
2	20/12/17 17:46	Accident Photo		Load JPG	☒
3	20/12/17 17:46	Accident Photo		Load JPG	☒
4	20/12/17 17:46	Accident Photo		Load JPG	☒
5	20/12/17 17:46	Accident Photo		Load JPG	☒
6	20/12/17 17:46	Accident Photo		Load JPG	☒
7	20/12/17 17:46	Accident Photo		Load JPG	☒
8	20/12/17 17:46	Accident Photo		Load JPG	☒
9	20/12/17 17:46	Accident Photo		Load JPG	☒
10	20/12/17 17:47	Accident Photo		Load JPG	☒
11	20/12/17 17:47	Accident Photo		Load JPG	☒
12	20/12/17 17:47	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 17:46	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117024369/KQD3E2

Date: 05/10/2018

REFERENCE

Insured/Claimant: RICCIO ANNA MARIA Policy No: DMPCSN3021771702
Date of Loss: 19/12/2017 Nature of Claim: OD Claim No: SNM17D07214C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX8403Z**
Make & Model: MERCEDES-BENZ B180, 1.7 (A) Engine No: 26694030753502
Reg. Date: 16/07/2010 (Man. Year: 2010) Chassis No: WDD2452322J572098
Colour: Metallic Brown Odometer: 84310 km
Engine Capacity: 1699 cc
Market Value/New Car Price: S\$46,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,959.31	6,243.72	715.59	10.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,638.34	2,366.94	271.40	10.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,597.65	8,610.66	986.99	10.28
+ GST 7.00/7.00% (S\$)	671.83	602.75	69.08	10.28
Nett Amount (S\$)	10,269.48	9,213.41	1,056.07	10.28

INSPECTION

Date of Assignment: 22/12/2017 Present Location: K Kim Hin Auto Pte Ltd (HQ)
Date Inspected: 26/12/2017 Inspected At: K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2018)
Parts: 144	MERCEDES-BENZ B180 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX8403Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/QTR GLASS BOND KIT	Not Necessary	51.75 F	*- F
2	1	NA	*L/R BRAKE CARRIER	Bent	200.00 F	*200.00 F
3	1	NA	*L/R COVER	Serviceable	20.00 F	*- F
4	1	NA	*L/R DOOR	Dented / Warped	1,155.00 F	*1,155.00 F
5	1	NA	*L/R DOOR INSULATION	Necessary	30.00 F	*30.00 F
6	1	NA	*L/R DOOR MOULDING	Necessary	70.00 F	*70.00 F
7	1	NA	*L/R DOOR SEAL	Necessary	116.00 F	*116.00 F
8	1	NA	*L/R S/PANEL RR FOIL	Necessary	15.00 F	*15.00 F
9	1	NA	*L/R SHOCK ABSORBER	Bent	130.00 F	*130.00 F
10	1	NA	*L/R SIDE MOULDING	Necessary	50.00 F	*50.00 F
11	1	NA	*L/R SIDE WINDOW	Serviceable	105.00 F	*- F
12	1	NA	*L/R THRUST ARM	Bent	85.00 F	*85.00 F
13	1	NA	*L/R WHEEL	Dented	650.00 F	*650.00 F
14	1	NA	*L/R WHEEL HUB	Bent	160.00 F	*160.00 F
15	1	NA	*L/R WING	Bent	1,870.00 F	*1,870.00 F
16	1	NA	*L/SIDE WINDOW STRIPE	Necessary	20.00 F	*20.00 F
17	1	NA	*REAR AXLE SUBFRAME	Bent	1,020.00 F	*1,020.00 F
18	1	NA	*SPECIALIST AUDATEX FEE		42.00 FS	*42.00 FS
19	1	NA	*SPECIALIST R/L GLASS SEALANT	Necessary	40.00 FS	*30.00 FS
20	1	NA	*SPECIALIST R/L TYRE	Serviceable	480.00 FS	*- FS
21	1	NA	*SPECIALIST RL GLASS DAMPINGSEAL	Necessary	20.00 FS	*20.00 FS
22	1	NA	*SPECIALIST WHEEL ALIGNMENT		100.00 FS	*60.00 FS
23	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
Supplementary #1						
24	1		*L/R OUT DOOR FRT FOIL	Necessary	22.00 F	*22.00 F
25	1		*L/R OUT DOOR RR FOIL	Necessary	24.00 F	*24.00 F
26	1		*L/R MOUNTING KIT	Necessary	14.40 F	*14.40 F
27	1		*L/WHEELHOUSE COVER	Necessary	75.00 F	*75.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,665.15	5,958.40
+ Margin on L,N Items 5.00/5.00% (S\$)	294.16	285.32
Total Parts (S\$)	6,959.31	6,243.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	630.20	630.20
2	Total Paint Materials	New	223.34	223.34
3	Total Panel/Mechanical Labour	New	1,784.80	1,513.40
Gross Labour Cost (S\$)			2,638.34	2,366.94

Report was unsubmitted during this print-out.

< END OF ESTIMATES >