



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LOW YEE LING CHARLENE (LIU YULING) BLK 344 CHOA CHU KANG LOOP #07-47 680344 Contact No Mobile: 97618100	Cust No/Name /MS LOW YEE LING CHARLENE (LIU Y Reg No/Reg Date SKV4273G / 17/09/201 Date In/Mileage / 0 Chassis No KNAFX411MF5461319 Engine No G4FGFH781091 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	22/12/2017/ 15:33	TLC	442 / CocoLu	20263

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO REPAIR REAR BUMPER, REAR FENDER RH, REAR DOOR RH, FRT DOOR RH FRT FENDER RH, SIDE SILL RH,		800		1650.00
E PNT98000 TO SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH FRT DOOR RH, FRT FENDER RH, SIDE SILL RH, REAR DOOR HANDLE RH		2520		2940.00
M SUNDRY TO TRANSFER NEW RIM TO TYRE (FRT RH & REAR RH)				60.00
A 54900099 TO CHECK WIRING & ELECTRICAL SYSTEM				20.00
A 54900099 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				200.00
M SUNDRY TO SUPPLY FRT RIGHT RIM AND REAR RIGHT RIM				380.00
M SUNDRY Sundry				20.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00

5Days.
After paint photos.
Gino Qiang - 8288 0282
29/12/17

to Consultants hence notify
owner of the following:

- survey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: **Nett** 5 390.00

Confirm & accepted by

7% GST on 5390.00 377.30

Total Payable 5,767.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of repair the rubber seal or other repair requiring the removal of the windscreen.