

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 4042C

DATE 22/12/2017 14:30

MAKE :

MODEL : HYUNDAI i40

*LKK/Kalini PbyP*  
*Line* *AIG*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00
	Radiator Grille H Emblem ✗			\$ 290.80
	Radiator Grille Chrome Moulding ✗			\$ 395.50
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ✓			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Grille (RH) ✓			\$ 285.50
	Front Bumper Grille Airduct (RH) ?			\$ 155.00
	Front Bumper Bracket Top (LH/RH) ?			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp (RH) ✓			\$ 1,388.00
	<b>SUB TOTAL</b>			<b>\$ 5,746.90</b>
	<b>LESS 20%</b>			<b>\$ 1,149.38</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 4,597.52</b>
	Front Number Plate ✓			\$ 25.00 <b>Nett</b>
	Front No Plate Trim Cover ✓			\$ 30.00 <b>Nett</b>
				<b>\$ 55.00</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			<del>\$ 350.00</del>
	Spray Painting Charge			<del>\$ 400.00</del> <b>180</b>
	Wiring Charge			<del>\$ 50.00</del> <b>20</b>
	<b>TOTAL LABOUR</b>			<b>\$ 800.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 5,452.52</b>

*Kalini LKK*  
*22/12/17 1510 hrs*  
*2 Days*  
*PIP*  
*Before Paint photo*

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer \_\_\_\_\_  
Signature \_\_\_\_\_  
Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.