

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>	7		REMOVE AND REFIT REVERSE SENSOR INCLUDING CARRY OUT CHECKING AND TESTING.	30	0	0	Reviewing	
<input type="checkbox"/>	8		TRANSFER DOOR MECHANISM, WIRING AND ATTACHMENT ITEMS ONTO REPLACEMENT DOOR PANELS.	120	0	0	Reviewing	
<input type="checkbox"/>	9		REMOVE & REPLACE SPORT RIM.	30	0	0	Reviewing	
<input type="checkbox"/>	10		CONDUCT COMPUTERIZE WHEEL ALIGNMENT CHECK.	80	0	0	Reviewing	
<input type="checkbox"/>	11		CONDUCT OBD SCAN AND CHECK SYSTEM PERFORMANCE.	150	0	0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRR%	DISC OJUNT%	SALV AGE%	PART PRICE(NET)
	8	1			RH FRONT DOOR CYLINDER LOCK ASSY (DISC 10%)			Bent	305.33		0		305.33
	9	1			RH REAR DOOR (DISC 10%)			Bent	2112.98		0		2112.98
	10	1			RH REAR DOOR UPPER HINGE			Repair	0		0		0
	11	1			RH REAR DOOR LOWER HINGE			Repair	0		0		0
	12	1			RH REAR DOOR CHROME MOULDING (DISC 10%)			Necessary	106.6		0		106.6
	13	1			RH REAR DOOR WEATHERSTRIP (DISC 10%)			Necessary	281.52		0		281.52
	14	1			RH REAR DOOR WINDOW REGULATOR ASSY			Serviceable	0		0		0
	15	36			RIVET (FRONT & REAR DOOR) (DISC 10%)			Necessary	2.7		0		97.2
	16	1			RH REAR SPORT RIM (DISC 10%)			Cut	1170		0		1170
	17	1			RH REAR FENDER CHROME MOULDING (DISC 10%)			Necessary	106.61		0		106.61
	18	1			REAR BUMPER			Repair	0		0		0
	19	1			REAR BUMPER SIDE RETAINER RH (DISC 10%)			Necessary	31.05		0		31.05

Detailed Assessment

Inspection Date *

12/27/2017



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/40R18

Rear Tyre Size

245/40R18

FNOL INFORMATI... BLK 755 WOODLANDS AVENUE 4,
730755, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #


FNOL INFORMATI... S8849984J

CATEGORY Make

POLICY INFORMAT... TOYOTA

CATEGORY Date of Birth

FNOL INFORMATI... December 8, 1988



CATEGORY Model

POLICY INFORMAT... WISH 1.8

CATEGORY Age

FNOL INFORMATI... 29

CATEGORY Type

CATEGORY Occupation

FNOL INFORMATI... Unknown

CATEGORY Type of Paint

CATEGORY Education Qualification

FNOL INFORMATI... Other

CATEGORY Chassis No

POST SURVEY INF...

POLICY INFORMAT... ZNE100308859

CATEGORY Driving Experience

Direct settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents
Assessment Metrics Notes

Additional Instructions

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	4/19/18 8:54 AM	8200	8200	Open	Share	<input type="button" value="Clone"/>
TAY Ernest	12/26/17 3:41 PM	10291.53	10291.53	Open	Share	<input type="button" value="Clone"/>

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SGG7959T INSD GIA RPT.PDF	Reports & Statement	GIA Report	TEO Kitty	December 14, 2017

Direct settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents

Additional Instructions

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInspection Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 19, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	April 19, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 4, 2018