

# ST&T AUTOMOTIVE PTE LTD

48 Toh Guan Road East Enterprise Hub  
 #05-139, Singapore 608586  
 Tel: (65) 98779879 Fax: (65) 63565541

## Customer Vehicle detail

Car Number : SKN6083S Car Model : MB E200 Sedan  
 Chassis Number : WDD212034A974409 Registration Year : 30-Jun-2014  
 EngineNumber : 27492030151826  
 Insurance Company : Tokio Marine Insurance Singapore Ltd

## Third Party Vehicle detail

Car Number : SGG7959T Car Model :  
 Insurance Company : AXA Insurance (S) Pte Ltd

## Estimation of repair cost

<u>Item</u>	<u>Part Description</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Price</u>
				\$ <del>bt</del> 2,311.50
1	RH front door	1	\$ 2,311.50	\$ <del>bt</del> 2,311.50
2	RH front door chrome moulding	1	\$ 135.70	\$ <del>net</del> 135.70
3	RH front door weatherstrip	1	\$ 312.80	\$ <del>net</del> 312.80
4	RH front door window regulator assy	1	\$ 312.80	\$ ? 312.80
5	RH front door outer handle	1	\$ 744.05	\$ ? 744.05
6	RH front door inner lock	1	\$ 527.00	\$ <del>dis</del> 527.00
7	RH front door inner lock bracket	1	\$ 339.25	\$ ? 339.25
8	RH front door cylinder lock assy	1	\$ 28.75	\$ ? 28.75
9	RH rear door	1	\$ 339.25	\$ <del>bt</del> 339.25
10	RH rear door upper hinge	1	\$ 2,347.75	\$ <del>bt</del> 2,347.75
11	RH rear door lower hinge	1	\$ 133.52	\$ <del>Rp</del> 133.52
12	RH rear door chrome moulding	1	\$ 133.52	\$ <del>Rp</del> 133.52
13	RH rear door weatherstrip	1	\$ 118.45	\$ <del>net</del> 118.45
14	RH rear door window regulator assy	1	\$ 312.80	\$ <del>net</del> 312.80
15	Rivet (front & rear door)	36	\$ 759.00	\$ <del>x</del> 759.00
16	RH rear sport rim	1	\$ 3.00	\$ <del>net</del> 108.00
17	RH rear fender chrome moulding	1	\$ 1,300.00	\$ <del>cut</del> 1,300.00
18	Rear bumper	1	\$ 118.45	\$ <del>net</del> 118.45
19	Rear bumper side retainer RH	1	\$ 1,822.75	\$ <del>Rp</del> 1,822.75
20	RH rear bumper bracket	1	\$ 34.50	\$ <del>net</del> 34.50
21	Rear bumper chrome moulding LH & RH	2	\$ 20.70	\$ <del>x</del> 20.70
22	Clip, bumper	8	\$ 143.75	\$ <del>net</del> 287.50
			\$ 6.00	\$ <del>net</del> 48.00
			<b>Total</b>	<b>\$ 12,596.04</b>

# ST&T AUTOMOTIVE PTE LTD

48 Toh Guan Road East Enterprise Hub  
 #05-139, Singapore 608586  
 Tel: (65) 98779879 Fax: (65) 63565541

## Special Nett Item

1	Apply anti rust coating on repair area	1	\$ 60	100.00
2	Sealant kit for new panel	1	\$ 40	60.00
			<b>Total</b>	<b>\$ 160.00</b>

## Labour

1	Remove and dismantle damage parts on accident affected area, including all attachment items. Pull, strenghten and repair on RH center pillar and RH rear fender. Remove & reinstall rear bumper for repair. Adjust and align body gap to specification.		\$	1,000.00
2	Remove & reinstall rear seat and upholstery to facilitate repair.		\$	80.00
3	Supply paint material, carry out putty, masking and preparation before spray paint. Respray accident portion affected area on RH front and RH rear door (inner & outer), RH rear fender, rear bumper, RH front door handle, RH center pillar, RH side sill and RH front fender.		\$	1,200.00
4	Check all external lightings and wiring connections.		\$	30.00
5	Remove & refit reverse sensor including carry out checking and testing.		\$	30.00
6	Transfer door mechanism, wiring and attachment items onto replacement door panels.		\$	120.00
7	Remove & replace sport rim		\$	30.00
8	Conduct computerize wheel alignment check.		\$	✓ 80.00
9	Conduct OBD scan and check system performance		\$	150.00
			<b>Total</b>	<b>\$ 4,770.00</b>

**Grand Total \$ 17,526.04**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Taufik 97495749  
 - WP  
 27/12/17 @ 1140.  
 7 days.  
 Resurvey after paint  
 Sur @ lkkauto.com