

12/05/2001

ASS. REC. BY:

REF:

CS/MSI17024414/Ktbek

Special Instruction:

Survivor
menimen

Kenneth

ASSIGNMENT (Office)

From (Person): Elaine NGU

of

MSIG

Date/Time: 26/22016 @ 8.37am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 2651H

Insured:

GBB 3145L

at Workshop m/s LH Express Motor Trading (H0)

Tel:

9387 5767

of BIK 5038 Ang Mo Kio Industrial Park 2 #01-405 (569541)

Policy No: P28864978 MKC

Claim No:

542240

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/22017 @ 12.00

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 12:37pm @ 26/12/17

Person Contacted:

Mr. Kee

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 2651H - X
	GBB 3145L - X
	Lump Sum \$14600/- Cred: 35474.34 : 70%

ASS. REC. BY:

REF: *MS61**Kennerth*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *882k*

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: *08* days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *STF 265114*Yr Regn: *04, 16*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *NIS Syphy*c.c. *1598*Colour: *M. Red*

A/C: _____

Insured / Std / NI / NA

Sp. Reading: *40726*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MNTBBAB1780027134*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: *195/60R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. *7* mmR/Bal. *7* mmL/Bal. *7* mmL/Bal. *7* mmD.O.A. *20/12/17*D.O.I. *26/12/17*

Survey held at _____

Des. of Damages: *Frt* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*27/12**Re parts to Catherine, est not ready*

RECEIVED 14 JUN 2018

Date/Time, File Pass to?

14/6 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: *8*Resurvey No. of Trip: *1*Survey Fee: *350*

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

*360*Report Format: *TP*Lump Sum / I.B.I.: (\$ *14,600/-*)

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024414/Ktb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 3145L	Veh. Inspected	SJF 2651H
Policy No.	P28864978MKC	Coverage (\$)	0.00
Claim No.	542240	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	26/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/12/2017	Inspection Date	26/12/2017
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017		26 Dec 2017 08:37 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FABRICARE LAUNDRY PTE LTD, Co. Reg. No.: 199304634H		
Main Claimant:	HO CHEE KIAT, ID: S8024942Z		
Vehicle Reg. No.:	SJF2651H	Date of Loss:	20/12/2017 12:00 - :59
Claim Type:	TP / 542240	Policy/Cover Note No.:	P28864978MKC (Comprehensive) Coverage: 14/12/2017 - 13/12/2018
Vehicle Reg. No. (Insured):	GBB3145L	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	L H Express Motor Trading (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405, 569541 Ang Mo Kio - Tel: 64817221/64812027		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]		
Driver/Custodian (Insured):	SA'AT BIN MASTOP (/ Male), NRIC: S2036796B		
Adj Asg. Remarks:	Please assign Kenneth Kong		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Tan Jin Hao

From: Cheong Hoh Lee <mail@cheonghoh.sg>
Sent: Friday, 22 December, 2017 4:23 PM
To: Tan Jin Hao
Cc: Elaine Ngu
Subject: Re: PRI // Your Ref: LCH.my/AMK08-71011.17 ; Our Ref: GBB3145L

Dear Sir/ Madam,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong named in paragraph 3 serial no 2 of your said letter to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJF 2651 H is currently laying at our client's workshop, L.H. Express Motor Trading at Blk 5038 Ang Mo Kio Ave 3 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541. Kindly contact the person in charge Mr Yeo at 9008 9959 before your surveyor attending at the said workshop.

Kindly proceed to do the needful.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Dec 22, 2017, at 3:02 PM, Tan Jin Hao <jinhao_tan@sg.msig-asia.com> wrote:

WITHOUT PREJUDICE

Dear Sirs,

We are appointing the following surveyor for your claim: M/s Formteam Consultancy Pte Ltd.

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the surveyors listed below as the SJE, depending on their availability:

- | | |
|-----------------|------------------|
| 1. Adrian Ling | 6. Frankie Pang |
| 2. Kenneth Kong | 7. Ng You Han |
| 3. Marcus Chua | 8. Gary Soon |
| 4. Henry Ng | 9. Chow Bo Xiong |

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case any of our nominated SJE is not available.

N.B. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre-repair survey within the timeline stipulated under the NIMA Protocol.

Have A Great Week Ahead!

Tan Jin Hao

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2583 | Direct fax +65 6225 7402 | jinhao_tan@sg.msig-asia.com

<image001.png>

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G

| msig.com.sg <image002.png> <image003.png> <image004.png> <image005.png>

<image006.jpg>

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2017 19:46
Date Of Accident	20/12/2017 11:45
Exact Location Of Accident	JUNCTION OF SENOKO AVENUE & SENOKO WAY LANDPORT 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF2651H
Insured/Policyholder	
Name Of Registered Owner	HOE CHEE KIAT
NRIC No	S8024942Z
Email Address	HOECHEEKIAT2004@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-82006804
Alternative Phone No	OFFICE-82006804

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10734532
Cover Note Number	

Driver

Name of Driver	HOE CHEE KIAT
NRIC No	S8024942Z
Date Of Birth	19/10/1980
Occupation	INDOOR
Date Of Driving Pass	17/12/2002
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82006804
Fax Number	
Contact Number	OFFICE-82006804
Email Address	HOECHEEKIAT2004@YAHOO.COM.SG

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG SENOKO AVE TOWARDS SENOKO DR. WHEN I COME TO THE JUNCTION OF SENOKO WAY, VEHICLE B NEVER STOP AT THE STOP LINE FROM MY LEFT SIDE AND COME OUT TO THE JUNCTION. I COULDN'T STOP AT THE TIME AND HIT ONTO HIS VEHICLE RIGHT SIDE. MY VEHICLE FRONT PART ALL COLLIDED. WE EXCHANGE PARTICULAR AND TAKE PHOTO. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL UPLOAD TO FILEZILA ONCE INSURED SEND
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB3145L
Vehicle Make/Model/Colour	NISSAN/URVAN/SLIVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SA'AT BIN MASTOP
NRIC/Passport Number	S2036796B
Contact Number	91674049
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
Thomas Ng Chin Chun
Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG SENOKO AVE TOWARDS SENOKO DR. WHEN I COME TO THE JUNCTION OF SENOKO WAY. VEHICLE B NEVER STOP AT THE STOP LINE FROM MY LEFT SIDE AND COME OUT TO THE JUNCTION. I COULDN'T STOP AT THE TIME AND HIT ONTO HIS VEHICLE RIGHT SIDE. MY VEHICLE FRONT PART ALL COLLIDED. WE EXCHANGE PARTICULAR AND TAKE PHOTO. NO INJURIES INVOLVED.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
NG CHIN CHUN

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

20 December 2017 at 1:08 PM

Date/Time:

20 December 2017 at 1:08 PM

LH Express Motor Trading

Blk 5038#01-405, Ang Mo Kio Ind. Park 2 Singapore 569541.

Email: dylhmotortrading@gmail.com

Fax: 64816131 Tel: 64817221

Hoe Chee Kiat

Blk 689 Hougang Street 61 #04-226

Singapore 530689.

Vehicle No : SJF 2651 H
Chassis No : MNTBBAB17Z0027134
Make : Nissan Sylphy 1.6
Year : 2015

*Not Withheld
11 days @ 14,450/-
Resurvey After Paint*

*11 days
14 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

QTY	Description	Amount
-----	-------------	--------

Estimate Cost Of Repair

2	Head Lamp Panel LH/RH	\$265.65	NISA	\$531.30	LT
2	Head Lamp Bracket LH RH	\$33.00	NISA	\$66.00	LT
2	Front Side Retainer LH/RH	\$26.50	N/A	\$53.00	✓
1	Front Support Top Panel		Bu	\$237.30	✓
1	Front Reinforcement		Bu	\$561.90	✓
2	Head Lamp Lower Panel LH/RH	\$117.00	NISA	\$234.00	X
2	Air Guide LH/RH	\$235.20	CM	\$470.40	✓
1	Brace Panel		Bu	\$61.50	✓
				\$2,215.40	
				Less 30%	\$664.62
					\$1,550.78

Nett Items

1	Front Door Assy RH		R	\$960.30	X
1	Front Door Pillar RH		R	\$460.00	X
2	Head Lamp Assy LH/RH	o/s CRT	NISA	\$1,062.20	✓
1 set	Wires Harness		L.R	\$2,311.30	Good
1 set	Bumper Clip(Set)		Bu	\$40.00	✓
2	Front Upper Arm LH/RH		Bu	\$210.60	X
2	Front Knuckle Arm LH/RH		Bu	\$1,052.40	X
1	Stabilizer		Bu	\$294.10	X
1	Stabilizer Link		Bu	\$29.60	✓
1	Front Grille Emblem Logo		N/A	\$52.50	✓

LH Express Motor Trading

Blk 5038#01-405, Ang Mo Kio Ind. Park 2 Singapore 569541.

Email : dyllmotortrading@gmail.com

Fax: 64816131 Tel: 64817221

Hoe Chee Kiat

Blk 689 Hougang Street 61 #04-226

Singapore 530689.

Vehicle No : SJF 2651 H
Chassis No : MNTBBAB17Z0027134
Make : Nissan Sylphy 1.6
Year : 2015

*Not Withheld
L1Ry & 13, 900h
Resurvey After Point
11 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval **LKK Auto Consultants** Company

Acknowledged by Repairer
Signature:
Date:

QTY	Description	Amount
-----	-------------	--------

Estimate Cost Of Repair

2	Head Lamp Panel LH/RH	\$265.65	NISA	\$531.30	LT
2	Head Lamp Bracket LH/RH	\$33.00	NISA	\$66.00	LT
2	Front Side Retainer LH/RH	\$26.50	NIS	\$53.00	✓
1	Front Support Top Panel		Bu	\$237.30	✓
1	Front Reinforcement		Bu	\$561.90	✓
2	Head Lamp Lower Panel LH/RH	\$117.00	NIP	\$234.00	X
2	Air Guide LH/RH	\$235.20	CM	\$470.40	✓
1	Brace Panel		Bu	\$61.50	✓
				\$2,215.40	
		Less 30%		\$664.62	
				\$1,550.78	

Nett Items

1	Front Door Assy RH		R	\$960.30	X
1	Front Door Pillar RH		R	\$460.00	X
2	Head Lamp Assy LH/RH	o/s car	NISA	\$1,062.20	✓
1 set	Wires Harness		L.R. Cu	\$2,311.30	Good
1 set	Bumper Clip(Set)		Ru	\$40.00	✓
2	Front Upper Arm LH/RH	\$105.30	Sm	\$210.60	X
2	Front Knuckle Arm LH/RH	\$526.20	Sm	\$1,052.40	X
1	Stabilizer		Sm	\$294.10	X
1	Stabilizer Link		Sm	\$29.60	✓
1	Front Grille Emblem Logo		NIS	\$52.50	✓

1	Bonnet Insulator
1	Air Resonator
2	Bonnet Hinges LH/RH
1	Washer Tank
1	Spare water Tank
1	Bonnet Lock
1	Front Fender Signal Lamp RH
1	Front Chassis RH

\$44.20

Sm	\$86.30	X
CM	\$256.30	✓
RE	\$88.40	✓
ND	\$242.00	✓
ND	\$186.00	✓
By	\$35.20	✓
Sm	\$42.20	X
By R	\$481.00	✓
<hr/>		
\$9,744.90		
Less 10%	\$974.50	
\$8,770.40		

Special Nett Items

1	Front Bumper
2	Front Bumper Bracket LH/RH
1	Grille Bumper Center
2	Fog Lamp Garnish LH/RH
1	Number Plate Garnish
1	Bumper Lower Garnish
1	Tow Cover
1	Front Sponge
1	Under Cover Garnish
2	Front Shock Absorber LH/RH
1	Drive Shaft
2	Front Knuckle Bearing LH/RH
2	Front Lower Arm LH/RH
1	Air Con Condenser
1	Air Con Cooler Pipe
1	Air Con Suction Pipe
1	Air Con Discharge Hose
1	Radiator
2	Radiator Bracket LH/RH
1	Radiator Lower Hose
1	Radiator Upper Hose
1	Radiator Continous Hose
6pcs	Radiator Hose Clips
1	Fan Motor Assy
1	Front Grille
2	Front Grille Bracket LH/RH
2	Front Rad Side Air Guide LH/RH
1	Top Panel Garnish
1	Bonnet
1	Bonnet Cable
1	Oil Cooler Assy
1	Discharge Pipe(oil Cooler)

NLSR \$168.00

\$68.30

\$327.40

\$321.00

\$186.00

\$22.10

\$50.00

\$170.00

BT/CM	\$680.00	✓
OLSR	\$336.00	✓
Di/RA	\$250.00	✓
NLSR	\$136.60	✓
NLP	\$73.20	X
Return	\$135.60	✓
mit	\$21.30	✓
CM	\$125.30	X
Sm	\$144.20	X
OLSR	\$654.80	✓
R	\$910.70	X
Sm	\$642.00	X
OLSR	\$272.00	✓
Pr	\$752.00	✓
Rd	\$113.10	X
Sm	\$283.70	X
Sm	\$251.10	X
By	\$680.00	✓
R	\$44.20	X
Sm	\$60.80	X
Sm	\$32.10	✓
Sm	\$41.10	X
NLS	\$24.00	X
Sm	\$548.00	✓
mit	\$328.40	✓
mit	\$100.00	✓
Apoc	\$340.00	X
Di/CM	\$188.90	✓
By	\$480.00	✓
Sm	\$36.00	✓
Puc	\$585.00	✓
Sm	\$125.00	X

7101-36

LH Express Motor Trading

Blk 5038#01-405, Ang Mo Kio Ind. Park 2 Singapore 569541.

Email: dylhmotortrading@gmail.com

Fax: 64816131 Tel: 64817221

*Not with air
L1Lm @ 13,400k
Presury After Point*

Hoe Chee Kiat

Blk 689 Hougang Street 61 #04-226

Singapore 530689.

Vehicle No : SJF 2651 H
Chassis No : MNTBBAB17Z0027134
Make : Nissan Sylphy 1.6
Year : 2015

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

2	Head Lamp Panel LH/RH	<i>o/s R</i> \$265.65	<i>NISA</i> \$531.30 <i>LT</i>
2	Head Lamp Bracket LH/RH	\$33.00	<i>NISA</i> \$66.00 <i>LT</i>
2	Front Side Retainer LH/RH	\$26.50	<i>N/A</i> \$53.00 <i>✓</i>
1	Front Support Top Panel		<i>Bu</i> \$237.30 <i>✓</i>
1	Front Reinforcement		<i>Bu</i> \$561.90 <i>✓</i>
2	Head Lamp Lower Panel LH/RH	\$117.00	<i>N/A</i> \$234.00 <i>X</i>
2	Air Guide LH/RH	\$235.20	<i>CM</i> \$470.40 <i>✓</i>
1	Brace Panel		<i>Bu</i> \$61.50 <i>✓</i>
			\$2,215.40
		Less 30%	\$664.62
			\$1,550.78

Nett Items

1	Front Door Assy RH		<i>R</i> \$960.30 <i>X</i>
1	Front Door Pillar RH		<i>R</i> \$460.00 <i>X</i>
2	Head Lamp Assy LH/RH	<i>o/s R</i> \$531.10	<i>NISA</i> \$1,062.20 <i>✓</i>
1 set	Wires Harness		<i>L.R</i> <i>CM</i> \$2,311.30 <i>Good</i>
1 set	Bumper Clip(Set)		<i>Bu</i> \$40.00 <i>✓</i>
2	Front Upper Arm LH/RH	\$105.30	<i>Bu</i> \$210.60 <i>X</i>
2	Front Knuckle Arm LH/RH	\$526.20	<i>Bu</i> \$1,052.40 <i>X</i>
1	Stabilizer		<i>Bu</i> \$294.10 <i>X</i>
1	Stabilizer Link		<i>Bu</i> \$29.60 <i>✓</i>
1	Front Grille Emblem Logo		<i>N/A</i> \$52.50 <i>✓</i>

1	Bonnet Insulator
1	Air Resonator
2	Bonnet Hinges LH/RH
1	Washer Tank
1	Spare water Tank
1	Bonnet Lock
1	Front Fender Signal Lamp RH
1	Front Chassis RH

\$44.20

Sm	\$86.30	X
CM	\$256.30	✓
R	\$88.40	✓
nd	\$242.00	✓
nd	\$186.00	✓
Ry	\$35.20	✓
Sm	\$42.20	X
R	\$481.00	X
	\$9,744.90	
Less 10%	\$974.50	
	\$8,770.40	

Special Nett Items

1	Front Bumper	
2	Front Bumper Bracket LH/RH	NLSR
1	Grille Bumper Center	
2	Fog Lamp Garnish LH/RH	\$68.30
1	Number Plate Garnish	
1	Bumper Lower Garnish	
1	Tow Cover	
1	Front Sponge	
1	Under Cover Garnish	
2	Front Shock Absorber LH/RH	\$327.40
1	Drive Shaft	
2	Front Knuckle Bearing LH/RH	\$321.00
2	Front Lower Arm LH/RH	\$186.00
1	Air Con Condenser	
1	Air Con Cooler Pipe	
1	Air Con Suction Pipe	
1	Air Con Discharge Hose	
1	Radiator	
2	Radiator Bracket LH/RH	\$22.10
1	Radiator Lower Hose	
1	Radiator Upper Hose	
1	Radiator Continous Hose	
6pcs	Radiator Hose Clips	
1	Fan Motor Assy	
1	Front Grille	
2	Front Grille Bracket LH/RH	\$50.00
2	Front Rad Side Air Guide LH/RH	\$170.00
1	Top Panel Garnish	
1	Bonnet	
1	Bonnet Cable	
1	Oil Cooler Assy	
1	Discharge Pipe(oil Cooler)	

BTICM	\$680.00	✓
OLSR	\$336.00	✓
DiS/RW	\$250.00	✓
NLSR	\$136.60	✓
NLP	\$73.20	X
Return	\$135.60	✓
MIT	\$21.30	✓
NLP	\$125.30	X
Sm	\$144.20	X
OLSR	\$654.80	✓
R	\$910.70	X
Sm	\$642.00	X
OLSR	\$272.00	✓
Pu	\$752.00	✓
Sm	\$113.10	X
Sm	\$283.70	X
Sm	\$251.10	X
Ry	\$680.00	✓
R	\$44.20	X
Sm	\$60.80	X
Sm	\$32.10	✓
Sm	\$41.10	X
Nu	\$24.00	X
Sm	\$548.00	✓
MIT	\$328.40	✓
MIT	\$100.00	✓
Pyroster	\$340.00	X
DiS / CM	\$188.90	✓
Bu	\$480.00	✓
Sm	\$36.00	✓
Puc	\$585.00	✓
Sm	\$125.00	X

1	Suction Pipe(oil Cooler)	
1	Transmission Oil Cooler	
1	Fuse Box Assy	
1	Engine Control Unit	
1	Front Wheel House RH	
2	Front Fender LH/RH	\$360.00
2	Front Fender Inner Shield LH/RH	\$59.70
8	Front Fender Inner Shield Clips	\$15.00
1	Alternator	
1	Air Con Compressor	

Sm	\$125.00	X
Sm	\$560.00	X
mg cr	\$190.20	✓
R	\$2,815.00	✓
R	\$328.40	X
Br	\$720.00	✓
cr	\$119.40	✓
cr	\$120.00	✓
L-R R	\$1,987.00	6001n
Sm	\$1,191.00	X

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

\$1,800.00 1000

Supply Paint Material and necessary items. To respray replaced and other affected panels

\$1,500.00 1200

To remove/refit wire harness, all related connectors. Check for proper functions. To focus headlamp height.

\$150.00 100

To carry out antirust treatment on affected panels.

\$280.00 120

To provide towing service

\$100.00 50

To set vehicle on chassis alignment bench, inclusive of all necessary preparatory works.

\$350.00 250

To conduct wheel alignment(Before & After)

\$240.00 120

Remove / renew front under carriage/ suspension assembly with all attachments/componets.

\$250.00 180

To perform diagnostic check on engine misfire fault error by HHT. Programming engine control unit. Reset to factory specification.

nn \$580.00 X

To lift up engine air cleaner, engine inlet manifold assy & necessary attachment in connection to it in order to renew engine control unit. To check fuel injection wiring harness & installation.

nn \$800.00 X

To remove/renew air-con condenser with all necessary pipes and hoses. Vacuum and replendish cooling agent. Check proper function.

\$150.00 100

To remove/renew radiator assembly with connecting hoses. Replendish cooling agent and check proper function.

\$120.00 50

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.my/AMK08-71011.17
Your Ref: 542240

5 June 2018

WITHOUT PREJUDICE

MSIG Insurance (S) Pte Ltd-Motor Claims
16 Raffles Quay #24-01
Hong Leong Building
Singapore 048581
Attn: Chhia Nyuk Pui

BY FAX & EMAIL
Fax No: 62256371

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO SJF 2651 H AND GBB 3145 L ON 20 DECEMBER 2017
AT/ALONG JUNCTION OF SENOKO AVENUE & SENOKO WAY LANDPORT 7 -**

We refer to the above matter and to your offer of 4 June 2018.

Towards an amicable settlement, we have our client's instructions to counter propose 100% quantum (on 100% basis) as follows:

Repair Cost	\$ 14,600.00 (agreed by SJE)
Rental @ 21 days	\$ 2,520.00 (*)
LTA / GIA searches	\$ 36.49 (enclose LTA)
Costs & Incidentals	\$ 1,050.00 (if settled at this stage)
	\$ 7,475.99

*P/s : We have on 22 December 2017 notified you of the accident. The re- repair survey ("PRS") was carried out by your surveyor on 26 December 2017 (5 days) plus your surveyor recommended 14 days (please check with SJE) plus 2 weekends so we are claiming 21 days for rental. Please check with your appointed surveyor for the loss of use during PRS arrangement and number of days for loss of use.

Kindly let us hear from you **by close of business on 12 June 2018** whether we have a settlement herein.

For the avoidance of doubt, our 10 days' notice dated 31 May 2018 stands.

Yours faithfully


Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (SJF 2651 H)



































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2017		26 Dec 2017 08:37 Edit Adj Rpt	S\$14,600.00 Edit Estimates	S\$14,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	FABRICARE LAUNDRY PTE LTD , Co. Reg. No.: 199304634H								
Main Claimant:	HO CHEE KIAT , ID: S8024942Z								
Vehicle Reg. No.:	SJF2651H	Date of Loss:	20/12/2017 12:00 - :59 [20 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 542240	Policy/Cover Note No.:	P28864978MKC (Comprehensive) Coverage: 14/12/2017 - 13/12/2018						
Vehicle Reg. No. (Insured):	GBB3145L	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	L H Express Motor Trading (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405, 569541 Ang Mo Kio - Tel: 64817221/64812027								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/01/2018]								
Driver/Custodian (Insured):	SA'AT BIN MASTOP (/ Male), NRIC: S2036796B								
Adj Asg. Remarks:	Please assign Kenneth Kong								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJF2651H (542240)**
[GBB3145L]
TP
HO CHEE KIAT
Dec 20 2017 12:00PM
[FABRICARE LAUNDRY PTE LTD]
L H Express Motor Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	26/12/17 08:37	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: GBB3145L, Claimant: FABRICARE LAUNDRY PTE. LTD.</small>	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 11:02	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	14/06/18 09:21	LKK Auto Consultants Pte Ltd (HQ) General View	 Load JPG	<input checked="" type="checkbox"/>
2	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/06/18 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/06/18 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	14/06/18 09:28	Reinspection Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	14/06/18 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	14/06/18 09:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/17 08:41	PRI	Load PDF	
2	26/12/17 08:41	TP GIA REPORT	Load PDF	
3	26/12/17 08:41	Email from TP	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024414/KTBE2

Date: 14/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P28864978MKC

Claimant Vehicle No : SJF2651H

Insured Vehicle No : GBB3145L

Date of Loss: 20/12/2017

Nature of Claim: TP

Claim No: 542240

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJF2651H

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)

Engine No: HR16988260B

Reg. Date: 20/04/2016 (Man. Year: 2016)

Chassis No: MNTBBAB17Z0027134

Colour: Metallic Red

Odometer: 40726 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size: 195/60 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,203.24	14,702.30	11,500.94	43.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	3,620.00	2,700.00	42.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,523.24	18,322.30	14,200.94	43.66
Approved Total (Overridden) (S\$)		14,600.00		
Nett Amount (S\$)	32,523.24	14,600.00	17,923.24	55.11

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 26/12/2017 Inspected At:

L H Express Motor Trading (HQ)
BLK 5038 ANG MO KIO INDUSTRIAL
PARK 2 #01-405
Singapore 569541

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2018)
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF2651H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP PANEL LH / RH	O/S Repair / N/S Bent	531.30 FL	*265.65 FL
2	1		*HEAD LAMP BRACKET LH / RH	N/S Cracked	66.00 FL	*33.00 FL
3	2		*FRONT SIDE RETAINER LH / RH	Distorted	53.00 FL	*53.00 FL
4	1		*FRONT SUPPORT TOP PANEL	Buckled	237.30 FL	*237.30 FL
5	1		*FRONT REINFORCEMENT	Bent	561.90 FL	*561.90 FL
6	2		*HEAD LAMP LOWER PANEL LH / RH	No such part	234.00 FL	*- FL
7	2		*AIR GUIDE LH / RH	Cracked	470.40 FL	*470.40 FL
8	1		*BRACE PANEL	Bent	61.50 FL	*61.50 FL
9	1		*FRONT DOOR ASSY RH	Repair	960.30 FN	*- FN
10	1		*FRONT DOOR PILLAR RH	Repair	460.00 FN	*- FN
11	2		*HEAD LAMP ASSY LH / RH	O/S Cracked / N/S Broken	1,062.20 FN	*1,062.20 FN
12	1		*SET WIRES HARNESS (LOCAL REPAIR)	Cut	2,080.17 FS	*600.00 FS
13	1		*SET BUMPER CLIP	Necessary	40.00 FN	*40.00 FN
14	2		*FRONT UPPER ARM LH / RH	Serviceable	210.60 FN	*- FN
15	2		*FRONT KNUCKLE ARM LH / RH	Serviceable	1,052.40 FN	*- FN
16	1		*STABILIZER	Serviceable	294.10 FN	*- FN
17	1		*STABILIZER LINK	Serviceable	29.60 FN	*- FN
18	1		*FRONT GRILLE EMBLEM LOGO	Missing	52.50 FN	*52.50 FN
19	1		*BONNET INSULATOR	Serviceable	86.30 FN	*- FN
20	1		*AIR RESONATOR	Cracked	256.30 FN	*256.30 FN
21	2		*BONNET HINGES LH / RH	Repair	88.40 FN	*- FN
22	1		*WASHER TANK	Dented	242.00 FN	*242.00 FN
23	1		*SPARE WATER TANK	Dented	186.00 FN	*186.00 FN
24	1		*BONNET LOCK	Bent	35.20 FN	*35.20 FN
25	1		*FRONT FENDER SIGNAL LAMP RH	Serviceable	42.20 FN	*- FN
26	1		*FRONT CHASSIS RH	Bent	481.00 FN	*481.00 FN
27	1		*FRONT BUMPER	Bent / Cracked	680.00 FS	*680.00 FS
28	1		*FRONT BUMPER BRACKET RH / LH	N/S Bent / O/S Repair	336.00 FS	*168.00 FS
29	1		*GRILLE BUMPER CENTER	Distorted /Dented	250.00 FS	*250.00 FS
30	1		*FOG LAMP GARNISH LH / RH	N/S Dented	136.60 FS	*68.30 FS
31	1		*NUMBER PLATE GARNISH	No such part	73.20 FS	*- FS
32	1		*BUMPER LOWER GARNISH	Deformed	135.60 FS	*135.60 FS
33	1		*TOW COVER	Missing	21.30 FS	*21.30 FS
34	1		*FRONT SPONGE	No such part	125.30 FS	*- FS
35	1		*UNDER COVER GARNISH	Serviceable	144.20 FS	*- FS
36	1		*FRONT SHOCK ABSORBER LH / RH	O/S Bent	654.80 FS	*327.40 FS
37	1		*DRIVE SHAFT	Repair	910.70 FS	*- FS
38	2		*FRONT KNUCKLE BEARING LH / RH	Serviceable	642.00 FS	*- FS
39	1		*FRONT LOWER ARM LH / RH	O/S Distorted	272.00 FS	*186.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIR CON CONDENSER	Punctured	752.00 FS	*752.00 FS
41	1		*AIR CON COOLER PIPE	Dented	113.10 FS	*113.10 FS
42	1		*AIR CON SUCTION PIPE	Serviceable	283.70 FS	*- FS
43	1		*AIR CON DISCHARGE HOSE	Serviceable	251.10 FS	*- FS
44	1		*RADIATOR	Bent	680.00 FS	*680.00 FS
45	2		*RADIATOR BRACKET LH / RH	Repair	44.20 FS	*- FS
46	1		*RADIATOR LOWER HOSE	Serviceable	60.80 FS	*- FS
47	1		*RADIATOR UPPER HOSE	Cut	32.10 FS	*32.10 FS
48	1		*RADIATOR CONTINUOUS HOSE	Serviceable	41.10 FS	*- FS
49	6		*RADIATOR HOSE CLIPS	Not Necessary	24.00 FS	*- FS
50	1		*FAN MOTOR ASSY	Jammed	548.00 FS	*548.00 FS
51	1		*FRONT GRILLE	Missing	328.40 FS	*328.40 FS
52	2		*FRONT GRILLE BRACKET LH / RH	Missing	100.00 FS	*100.00 FS
53	2		*FRONT RAD SIDE AIR GUIDE LH / RH	Repeated	340.00 FS	*- FS
54	1		*TOP PANEL GARNISH	Distorted / Cracked	188.90 FS	*188.90 FS
55	1		*BONNET	Buckled	480.00 FS	*480.00 FS
56	1		*BONNET CABLE	Jammed	36.00 FS	*36.00 FS
57	1		*OIL COOLER ASSY	Punctured	585.00 FS	*585.00 FS
58	1		*DISCHARGE PIPE (OIL COOLER)	Serviceable	125.00 FS	*- FS
59	1		*SUCTION PIPE (OIL COOLANT)	Serviceable	125.00 FS	*- FS
60	1		*TRANSMISSION OIL COOLER	Dented	560.00 FS	*560.00 FS
61	1		*FUSE BOX ASSY	MTG Cracked	190.20 FS	*190.20 FS
62	1		*ENGINE CONTROL UNIT	Bent	2,815.00 FS	*2,815.00 FS
63	1		*FRONT WHEEL HOUSE RH	Repair	328.40 FS	*- FS
64	2		*FRONT FENDER LH / RH	Buckled	720.00 FS	*720.00 FS
65	2		*FRONT FENDER INNER SHIELD LH / RH	Cracked	119.40 FS	*119.40 FS
66	8		*FRONT FENDER INNER SHIELD CLIPS	Necessary	120.00 FS	*120.00 FS
67	1		*ALTERNATOR (LOCAL REPAIR)	Dented	1,987.00 FS	*600.00 FS
68	1		*AIR CON COMPRESSOR	Serviceable	1,191.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	27,425.77	15,442.65
- List Item Discount on L Items 30.00/30.00% (\$\$)	664.62	504.83
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	557.91	235.52

Total Parts (\$\$)	26,203.24	14,702.30
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS	New	1,800.00	1,200.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,500.00	1,200.00
3	TO REMOVE / REFIT WIRE HARNESS, ALL RELATED CONNECTORS. CHECK FOR PROPER FUNCTION. TO FOCUS HEADLAMP HEIGHT	New	150.00	100.00
4	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS	New	280.00	120.00
5	TO PROVIDE TOWING SERVICE	New	100.00	50.00
6	TO SET VEHICLE ON CHASSIS ALIGNMENT BENCH, INCLUSIVE OF ALL NECESSARY PREPARATORY WORKS	New	350.00	250.00
7	TO CONDUCT WHEEL ALIGNMENT (BEFORE & AFTER)	New	240.00	120.00
8	REMOVE / RENEW FRONT UNDER CARRIAGE / SUSPENSION ASSEMBLY WITH ALL ATTACHMENTS / COMPONENTS	New	250.00	180.00
9	TO PERFORM DIAGNOSTIC CHECK ON ENGINE MISFIRE FAULT ERROR BY HHT. PROGRAMMING ENGINE CONTROL UNIT. RESET TO FACTORY SPECIFICATION	New	580.00	250.00
10	TO LIFT UP ENGINE AIR CLEANER, ENGINE INLET MANIFOLD ASSY & NECESSARY ATTACHMENT IN CONNECTION TO IT IN ORDER TO RENEW ENGINE CONTROL UNIT. TO CHECK FUEL INJECTION WIRING HARNESS & INSTALLATION	New	800.00	0.00
11	TO REMOVE / RENEW AIR-CON CONDENSER WITH ALL NECESSARY PIPES AND HOSES. VACUUM AND REPLENDISH COOLING AGENT. CHECK PROPER FUNCTION	New	150.00	100.00
12	TO REMOVE / RENEW RADIATOR ASSEMBLY WITH CONNECTING HOSES. REPLENDISH COOLING AGENT AND CHECK PROPER FUNCTION	New	120.00	50.00
Gross Labour Cost (\$\$)			6,320.00	3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >