

INS. CASE OWNER:

CC6 / LCR170

LKK:

IDAC:

S

Marens

DOI:

ASSIGNMENT

26/12/17

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

( YES / NO )

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO )

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLN 89536



INSRS:

WSP:

Tel:

Liability:

RMKS:

Regans



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

10-1-18 NO GIA IN MERIMEN YET  
17-1-18 EMAILED AIG FOR OI GIA

RECEIVED 07 MAY 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

x

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

x

Loss of Rental (LOR):

S\$

x

(

days)

Loss of Use (LOU):

S\$

x

(\$

x

days)

Loss of Income (LOI):

S\$

x

(\$

x

days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

x

Medical:

S\$

x

Disbursement:

S\$

x

(e.g. Tow/ Independent)

Legal Cost:

S\$

x

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

x

Name 1:

Payee 2: (S/N: if N.A.)

S\$

x

Name 2:

Payee 3: (S/N: if N.A.)

S\$

x

Name 3:

COPY SENT 26/1/18

Surveyor Marcus

REF:

A167

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLN89536at Workshop m/s pagesu

of \_\_\_\_\_

Insured: SLJ8937A

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

G/A / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

72006

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLN89536 Yr Regn: 5 17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota Vios cc: 1496Colour: 3. blue A/C: Insured / Std / NI / NASp. Reading: 5-1368 T.Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: MHFB29F3302011270

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

mm

L/Bal.

mm

D.O.A.

24/1/17

D.O.I.

26/1/17

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

26/1/17 Cont. invd 2/s \$2600 with willan.

R ( \$3,777.93 / 599. )

Date/Time. File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transporter

1 - 2 - 3 - 4 - 5

Photo

Notes

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                               |                            |            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                        |                                                                                               | Ref : CC6/LCR17024427/Uea3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDINGS SINGAPORE 079120                                                                               |                                                                                               | Date : 27-12-2017          |            |  |
|                                                                                                                                           |                                                                                               | Code : LCR                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                               |                            |            |                                                                                     |
| Insured Veh.                                                                                                                              | SLJ 8937A                                                                                     | Veh. Inspected             | SLN 8953G  |                                                                                     |
| Policy No.                                                                                                                                |                                                                                               | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                                 |                                                                                               | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                               |                                                                                               | Assign Date                | 27/12/2017 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                               |                            |            |                                                                                     |
| Make & Model                                                                                                                              |                                                                                               | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                                        | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                               | Colour                     |            |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                             | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                    |                                                                                               | Modification               |            |                                                                                     |
| General                                                                                                                                   |                                                                                               |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                               |                            |            |                                                                                     |
|                                                                                                                                           | Size                                                                                          | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                               |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                               |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                               |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                               |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                               |                            |            |                                                                                     |
|                                                                                                                                           |                                                                                               |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                               |                            |            |                                                                                     |
| Accident Date                                                                                                                             | 24/12/2017                                                                                    | Inspection Date            | 26/12/2017 |                                                                                     |
| Survey held at                                                                                                                            | PEGASUS ENGINEERING & TRADING PTE LTD<br>174 WESTWOOD CRESCENT, WESTVILLE<br>SINGAPORE 648541 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                               |                            |            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                               |                            |            |                                                                                     |

Messrs Grab Rentals Pte Ltd

Estimate To Repair Toyota Vios 1.5E CVT  
Vehicle No : SLN8953G  
Chassis No : MHFB29F3302011270

*Not Authorized  
to be  
2600/2  
3 day.  
26/12/17  
who photo after repair*

Third Party Insurer : AIG  
Insured's Veh No : SLJ8937A  
Date of accident : 24.12.2017

Date : 26.12.2017

Pages : 1 of 2

| S/No              | Quantity | Description                    | Unit price               | Amount      |
|-------------------|----------|--------------------------------|--------------------------|-------------|
| <b>LIST ITEMS</b> |          |                                |                          |             |
| 1                 | 1 pc     | bootlid <i>762.47</i>          | <i>20/2600</i> \$ 836.80 | \$ 836.80   |
| 2                 | 1 pc     | bootlid E badge                | <i>2600</i> \$ 34.40     | \$ 34.40    |
| 3                 | 1 pc     | bootlid centre emblem badge    | <i>2600</i> \$ 59.80     | \$ 59.80    |
| 4                 | 1 pc     | bootlid vios badge             | <i>2600</i> \$ 44.10     | \$ 44.10    |
| 5                 | 1 pc     | bootlid lock                   | <i>2600</i> \$ 90.40     | \$ 90.40    |
| 6                 | 1 pc     | bootlid lock striker           | <i>2600</i> \$ 18.50     | \$ 18.50    |
| 7                 | 1 pc     | bootlid weatherstrips          | <i>2600</i> \$ 156.80    | \$ 156.80   |
| 8                 | 1 pc     | bootlid outer garnish          | <i>2600</i> \$ 105.00    | \$ 105.00   |
| 9                 | 4 ps     | bootlid outer garnish clip     | <i>2600</i> \$ 4.50      | \$ 18.00    |
| 10                | 2 ps     | rear licence plate lamp        | <i>2600</i> \$ 48.50     | \$ 97.00    |
| 11                | 1 pc     | rear end panel                 | <i>2600</i> \$ 694.70    | \$ 694.70   |
| 12                | 1 pc     | rear end panel inner trim      | <i>2600</i> \$ 224.30    | \$ 224.30   |
| 13                | 4 ps     | rear end panel inner trim clip | <i>2600</i> \$ 4.30      | \$ 17.20    |
| 14                | 1 pc     | rear bumper                    | <i>2600</i> \$ 504.90    | \$ 504.90   |
| 15                | 2 ps     | rear bumper reflector          | <i>2600</i> \$ 130.50    | \$ 261.00   |
| 16                | 2 ps     | rear bumper side retainer      | <i>2600</i> \$ 116.30    | \$ 232.60   |
| 17                | 10 ps    | rear bumper clip               | <i>2600</i> \$ 4.30      | \$ 43.00    |
| 18                | 1 pc     | rear bumper reinforcement      | <i>2600</i> \$ 323.30    | \$ 323.30   |
| 19                | 2 pc     | rear lamp                      | <i>2600</i> \$ 375.80    | \$ 751.60   |
| 20                | 4 ps     | rear lamp clip holder          | <i>2600</i> \$ 4.30      | \$ 17.20    |
|                   |          |                                |                          | \$ 4,530.60 |
| Less 25%          |          |                                |                          | \$ 1,132.65 |
|                   |          |                                |                          | \$ 3,397.95 |
| Balance c/f       |          |                                |                          | \$ 3,397.95 |

Please conduct the survey at

**Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216**

Messrs Grab Rentals Pte Ltd

Date : 26.12.2017

Estimate To Repair : Toyota Vios 1.5E CVT  
Vehicle No : SLN8953G  
Chassis No : MHFB29F3302011270

Pages : 2 of 2

| S/No | Quantity | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | Unit price | Amount      |
|------|----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------|
|      |          | Balance b/f                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |            | \$ 3,397.95 |
|      |          | <b>SPECIAL NETT ITEMS</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |            |             |
| 21   | 1 pc     | rear licence plate 40                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | \$ 80.00   | \$ 80.00    |
| 22   | 1 set    | rear bumper parking sensor 200                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | \$ 500.00  | \$ 500.00   |
|      |          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |            | \$ 580.00   |
|      |          | <b>LABOUR &amp; MISC. CHARGES</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |            |             |
| 1    |          | To check electrical lighting concerned.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 30         | \$ 60.00    |
| 2    |          | To rust-proofing of the affected areas.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 60         | \$ 160.00   |
| 3    |          | To reinstall of rear bumper parking sensor.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 120        | \$ 120.00   |
| 4    |          | To remove and refit interior fittings, trimmings, garnish and other, to enable repair.                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 60         | \$ 150.00   |
| 5    |          | To transfer of bootlid fittings, attachments and perform water seepage test.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 60         | \$ 120.00   |
| 6    |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.                                                                                                                                                                                                                                                                                                                                                                                                                                      | 480        | \$ 950.00   |
| 7    |          | Putty and spray painting of the affected portion.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 700        | \$ 900.00   |
|      |          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |            | \$ 2,400.00 |
|      |          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |            | 321.22      |
|      |          | <b>Grand Total</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |            | \$ 6,377.95 |
|      |          | <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To survey before any work commencing</li> <li>• To display damaged part(s) for survey</li> <li>• Parts prices are subject to LKK estimation</li> <li>• Third party survey is on a "without prejudice" basis</li> <li>• No illegal modifications or alterations</li> <li>• Supplementary items must be surveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer<br/>Signature:<br/>Date:</p> |            |             |

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

## Joy Irene (LKKAuto)

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Thursday, 3 May 2018 4:42 PM  
**To:** 'Tee, Chee-Wah'  
**Cc:** Admin A  
**Subject:** RE: TP / 0078904623SG ( ACCIDENT INVOLVING SLJ 8937A (LCRF) & SLN 8953G ON 24/12/2017(12:30hrs) ALONG PENANG LANE)

Dear Tee,

Noted.

We will proceed to inform TP repairer and will submit our report in Merimen.

Thank you.

Best Regards,

Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Tee, Chee-Wah [mailto:[Chee-Wah.Tee@aig.com](mailto:Chee-Wah.Tee@aig.com)]  
**Sent:** Friday, 27 April 2018 10:51 AM  
**To:** Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: TP / 0078904623SG ( ACCIDENT INVOLVING SLJ 8937A (LCRF) & SLN 8953G ON 24/12/2017(12:30hrs) ALONG PENANG LANE)

Dear Joy,

OI GIA uploaded for your reference.

We have repudiated all claims based on unauthorized driver.

Thank you.

Regards,

Tee Chee Wah  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120  
Tel +64191089 | Fax +68357416  
[Chee-Wah.Tee@aig.com](mailto:Chee-Wah.Tee@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

## Joy Irene (LKKAuto)

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Thursday, 3 May 2018 5:04 PM  
**To:** Asher Sng (LKKAuto); Pegasus Engineering  
**Cc:** Admin A; CS A Team  
**Subject:** RE: LOD - THIRD PARTY CLAIM - SLN8953G YOUR REF : SLJ8937A ON 24.12.2017  
**Attachments:** POLICE REPORT.pdf

WITHOUT PREJUDICE

Dear Sharon,

We refer to the subject of this e-mail.

We would like to inform you that our principal M/s AIG Asia Pacific Insurance Pte Ltd has repudiated all claims related to this accident due to breach of their policy terms and conditions. The driver involved was unauthorized.

In view of this, we regret to inform you that we are unable to look into your claim.

We will be proceeding to close this matter on our end.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                      |                                                |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 27 Dec 2017<br><a href="#">Edit Reg</a> |               | 26 Dec 2017 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$2,600.00</b><br><a href="#">Edit Estimates</a> | <b>S\$2,600.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

|                             |                                                                                                                        |                        |                                                                            |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------------------------|
| Insured:                    | LCRF PTE LTD, Co. Reg. No.: 201624597K                                                                                 |                        |                                                                            |
| Main Claimant:              | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G                                                                         |                        |                                                                            |
| Vehicle Reg. No.:           | SLN8953G                                                                                                               | Date of Loss:          | 24/12/2017 00:00 - :59<br>[7 Months and 2 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 0078904623SG                                                                                                      | Policy/Cover Note No.: | 0999994979                                                                 |
| Vehicle Reg. No. (Insured): | SLJ8937A                                                                                                               | Policy No. (Claimant): | MTGRAB20171499                                                             |
|                             |                                                                                                                        | Excess:                |                                                                            |
| Repairer:                   | Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846                           |                        |                                                                            |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com |                        |                                                                            |
| Claimant's Insurer:         | Great American Insurance Company (HQ) - Tel: 6804 6047                                                                 |                        |                                                                            |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/01/2018]         |                        |                                                                            |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (28/12/2017): NO OI GIA REPORT
- AIG\_SG (28/12/2017): NO TP GIA REPORT

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

\*SLN8953G (0078904623SG)  
[SLJ8937A]  
TP  
GRAB RENTALS PTE LTD  
Dec 24 2017 12:00AM  
[LCRF PTE LTD]  
Pegasus Engineering & Trading Pte Ltd

|                  |                 |                                   |               |  |                    |  |              |  |              |  |                                                                                       |                                     |                                     |  |
|------------------|-----------------|-----------------------------------|---------------|--|--------------------|--|--------------|--|--------------|--|---------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--|
| Upload Documents |                 |                                   | Upload Photos |  | Compose New Letter |  | Upload Video |  | Upload Audio |  | View                                                                                  |                                     | View in Browser                     |  |
| Photos/Images    |                 |                                   |               |  |                    |  |              |  |              |  | 3 per page                                                                            |                                     | <input checked="" type="checkbox"/> |  |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  |                    |  |              |  |              |  | Thumbnail                                                                             | Print                               |                                     |  |
| 1                | 27/12/17 21:05  | Chassis Number                    |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 2                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 3                | 27/12/17 21:05  | Odometer Reading                  |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 4                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 5                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 6                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 7                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 8                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |    | <input checked="" type="checkbox"/> |                                     |  |
| 9                | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |   | <input checked="" type="checkbox"/> |                                     |  |
| 10               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 11               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 12               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 13               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 14               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 15               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 16               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 17               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 18               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 19               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 20               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 21               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 22               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 23               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 24               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 25               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 26               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 27               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 28               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 29               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 30               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 31               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 32               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 33               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 34               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 35               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 36               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |
| 37               | 27/12/17 21:05  | General View                      |               |  |                    |  |              |  |              |  |  | <input checked="" type="checkbox"/> |                                     |  |

| Photos/Images |                 |                                           | 3 per page                                                                                   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                    | Print                               |
| 38            | 27/12/17 21:05  | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 39            | 27/12/17 21:05  | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 40            | 27/12/17 21:05  | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 41            | 27/12/17 21:05  | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation |                 |                                           | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                    | Print                               |
| 1             | 08/01/18 09:25  | TP ESTIMATE - MARKED                      |  Load PDF |                                     |
| 2             | 08/01/18 09:25  | TP GIA REPORT                             |  Load PDF |                                     |
| 3             | 08/01/18 11:53  | LETTER TO INSURED TO REPORT               |  Load PDF |                                     |
| 4             | 08/01/18 19:03  | EMAIL FROM LCR TO HIRER                   |  Load PDF |                                     |
| 5             | 03/05/18 17:05  | TO REPUDIATE FROM AIG                     |  Load PDF |                                     |
| 6             | 03/05/18 17:05  | EMAIL TO REPAIRER OF REPUDIATION          |  Load PDF |                                     |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                    | Print                               |
| 1             | 01/02/18 08:58  | Singapore Accident Statement              |  Load PDF |                                     |
| 2             | 27/04/18 10:45  | Singapore Accident Statement<br>OI GIA    |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                       |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR17024427/UJA3Q2

Date: 09/05/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994979  
 Claimant Vehicle No: SLN8953G Insured Vehicle No: SLJ8937A  
 Date of Loss: 24/12/2017 Nature of Claim: TP Claim No: 0078904623SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLN8953G  
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NRX155343  
 Reg. Date: 22/05/2017 (Man. Year: 2017) Chassis No: MHFB29F3302011270  
 Colour: Silver Odometer: 51368 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 3,977.95        | 1,811.23        | 2,166.72        | 54.47        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 2,460.00        | 1,440.00        | 1,020.00        | 41.46        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>6,437.95</b> | <b>3,251.23</b> | <b>3,186.72</b> | <b>49.50</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>2,600.00</b> |                 |              |
| <b>(S\$)</b>                             | <b>6,437.95</b> | <b>2,600.00</b> | <b>3,837.95</b> | <b>59.61</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>450.66</b>   | <b>182.00</b>   | <b>268.66</b>   | <b>59.61</b> |
| <b>Nett Amount (S\$)</b>                 | <b>6,888.61</b> | <b>2,782.00</b> | <b>4,106.61</b> | <b>59.61</b> |
| <b>Global Sum Settlement (S\$)</b>       |                 | <b>0.00</b>     |                 |              |

## INSPECTION

Date of Assignment: 26/12/2017  
 Date Inspected: 26/12/2017 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)  
 51 DEFU LANE 10  
 Singapore 539216  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition         | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|-------------------|------------|------------|
| 1   | 1   |          | *BOOTLID                        | Dented / Buckled  | 836.80 FL  | *762.47 FL |
| 2   | 1   |          | *BOOTLID E BADGE                | Necessary         | 34.40 FL   | *34.40 FL  |
| 3   | 1   |          | *BOOTLID CENTRE EMBLEM BADGE    | Necessary         | 59.80 FL   | *59.80 FL  |
| 4   | 1   |          | *BOOTLID VIOS BADGE             | Necessary         | 44.10 FL   | *44.10 FL  |
| 5   | 1   |          | *BOOTLID LOCK                   | Twisted           | 90.40 FL   | *90.40 FL  |
| 6   | 1   |          | *BOOTLID LOCK STRIKER           | Not Necessary     | 18.50 FL   | *- FL      |
| 7   | 1   |          | *BOOTLID WEATHERSTRIP           | Not Necessary     | 156.80 FL  | *- FL      |
| 8   | 1   |          | *BOOTLID OUTER GARNISH          | Not Necessary     | 105.00 FL  | *- FL      |
| 9   | 4   |          | *BOOTLID OUTER GARNISH CLIP     | Not Necessary     | 18.00 FL   | *- FL      |
| 10  | 2   |          | *REAR LICENCE PLATE LAMP        | Not Necessary     | 97.00 FL   | *- FL      |
| 11  | 1   |          | *REAR END PANEL                 | Repair            | 694.70 FL  | *- FL      |
| 12  | 1   |          | *REAR END PANEL INNER TRIM      | Not Necessary     | 224.30 FL  | *- FL      |
| 13  | 4   |          | *REAR END PANEL INNER TRIM CLIP | Not Necessary     | 17.20 FL   | *- FL      |
| 14  | 1   |          | *REAR BUMPER                    | Dented / Deformed | 504.90 FL  | *504.90 FL |
| 15  | 2   |          | *REAR BUMPER REFLECTOR          | Not Necessary     | 261.00 FL  | *- FL      |
| 16  | 2   |          | *REAR BUMPER SIDE RETAINER      | Bent              | 232.60 FL  | *232.60 FL |
| 17  | 10  |          | *REAR BUMPER CLIP               | Necessary         | 43.00 FL   | *43.00 FL  |
| 18  | 1   |          | *REAR BUMPER REINFORCEMENT      | Bent              | 323.30 FL  | *323.30 FL |
| 19  | 2   |          | *REAR LAMP                      | Not Necessary     | 751.60 FL  | *- FL      |
| 20  | 4   |          | *REAR LAMP CLIP HOLDER          | Not Necessary     | 17.20 FL   | *- FL      |
| 21  | 1   |          | *REAR LICENCE PLATE             | Bent              | 80.00 FS   | *40.00 FS  |
| 22  | 1   |          | *SET REAR BUMPER PARKING SENSOR | Shorted           | 500.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |                 |                 |
|-----------------------------------------------------|-----------------|-----------------|
| Sub Total (\$\$)                                    | 5,110.60        | 2,334.97        |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,132.65        | 523.74          |
| <b>Total Parts (\$\$)</b>                           | <b>3,977.95</b> | <b>1,811.23</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                                                                            | Lab.Type | Repairer's      | Amount          |
|--------------------------|------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                                                                                                        |          |                 |                 |
| 1                        | TO CHECK ELECTRICAL LIGHTING CONCERNED                                                                                 | New      | 60.00           | 30.00           |
| 2                        | TO RUST-PROOFING OF THE AFFECTED AREAS                                                                                 | New      | 160.00          | 60.00           |
| 3                        | TO REINSTALL OF REAR BUMPER PARKING SENSOR                                                                             | New      | 120.00          | 50.00           |
| 4                        | TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR                                  | New      | 150.00          | 60.00           |
| 5                        | TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST                                            | New      | 120.00          | 60.00           |
| 6                        | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New      | 950.00          | 480.00          |
| 7                        | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                       | New      | 900.00          | 700.00          |
| Gross Labour Cost (\$\$) |                                                                                                                        |          | <b>2,460.00</b> | <b>1,440.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >