

Messrs Grab Rentals Pte Ltd

Estimate To Repair Toyota Vios 1.5E CVT
Vehicle No : SLN8953G
Chassis No : MHFB29F3302011270

*Not Authorized
to be
1/5 @ 2600/2
3 days.
26/12/17
where the other repair*

Third Party Insurer : AIG
Insured's Veh No : SLN8937A
Date of accident : 24.12.2017

Date : 26.12.2017

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	bootlid 762.47	\$ 836.80	\$ 836.80
2	1 pc	bootlid E badge	\$ 34.40	\$ 34.40
3	1 pc	bootlid centre emblem badge	\$ 59.80	\$ 59.80
4	1 pc	bootlid vios badge	\$ 44.10	\$ 44.10
5	1 pc	bootlid lock	\$ 90.40	\$ 90.40
6	1 pc	bootlid lock striker	\$ 18.50	\$ 18.50
7	1 pc	bootlid weatherstirp	\$ 156.80	\$ 156.80
8	1 pc	bootlid outer garnish	\$ 105.00	\$ 105.00
9	4 ps	bootlid outer garnish clip	\$ 4.50	\$ 18.00
10	2 ps	rear licence plate lamp	\$ 48.50	\$ 97.00
11	1 pc	rear end panel	\$ 694.70	\$ 694.70
12	1 pc	rear end panel inner trim	\$ 224.30	\$ 224.30
13	4 ps	rear end panel inner trim clip	\$ 4.30	\$ 17.20
14	1 pc	rear bumper	\$ 504.90	\$ 504.90
15	2 ps	rear bumper reflector	\$ 130.50	\$ 261.00
16	2 ps	rear bumper side retainer	\$ 116.30	\$ 232.60
17	10 ps	rear bumper clip	\$ 4.30	\$ 43.00
18	1 pc	rear bumper reinforcement	\$ 323.30	\$ 323.30
19	2 pc	rear lamp	\$ 375.80	\$ 751.60
20	4 ps	rear lamp clip holder	\$ 4.30	\$ 17.20
				\$ 4,530.60
Less 25%				\$ 1,132.65
				\$ 3,397.95
Balance c/f				\$ 3,397.95

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Messrs Grab Rentals Pte Ltd

Date : 26.12.2017

Estimate To Repair Toyota Vios 1.5E CVT
Vehicle No : SLN8953G
Chassis No : MHFB29F3302011270

Pages : 2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance b/f		\$ 3,397.95
		<u>SPECIAL NETT ITEMS</u>		
21	1 pc	rear licence plate <i>40</i>	\$ 80.00	\$ 80.00 <i>40</i>
22	1 set	rear bumper parking sensor <i>200</i>	\$ 500.00	\$ 500.00 <i>200</i>
				\$ 580.00
		<u>LABOUR & MISC. CHARGES</u>		
1		To check electrical lighting concerned.	<i>30</i>	\$ 60.00
2		To rust-proofing of the affected areas.	<i>60</i>	\$ 160.00
3		To reinstall of rear bumper parking sensor.	<i>50</i>	\$ 120.00
4		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	<i>60</i>	\$ 150.00
5		To transfer of bootlid fittings, attachments and perform water seepage test.	<i>60</i>	\$ 120.00
6		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	<i>480</i>	\$ 950.00
7		Putty and spray painting of the affected portion.	<i>700</i>	\$ 900.00
				\$ 2,400.00
			<i>3241.22</i>	
		Grand Total		\$ 6,377.95
LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216