

Date : 26/12/2017

TO: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be in receipt and
• Motor Claims Department

Attn : Motor Claims Department
Fax : 6415 3727
Acknowledged by Repairer
Signature:

Our Customer : Ng Kok Leong
Vehicle No : SFS1622C
Model : Hyundai Elantra 1.6AT
Manufacture Year : 2015 (20/02/2016)
Date of Accident : 24/12/2017
Total Estimate Repair Days : 7
Total Pages : 2

Re: Repair Estimate For Third Party Claim against SLR1217Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>deep cut/de</i>	1	\$531.80	\$531.80	✓
2	Rear bumper clip <i>rec</i>	10	\$4.00	\$40.00	✓
3	Rear bumper side retainer LH <i>ref</i>	1	\$38.00	\$38.00	✓
4	Rear bumper reflector LH <i>11</i>	1	\$79.00	\$79.00	X
5	Rear bumper pad <i>11</i>	1	\$261.00	\$261.00	X
6	Tail lamp LH	1	\$450.00	\$450.00	X
7	Rear fender LH <i>re</i>	1	repair	repair	X
8	Rear fender weatherstrip LH <i>11</i>	1	\$75.00	\$75.00	X
9	Rear fender weatherstrip clip <i>11</i>	10	\$4.00	\$40.00	X
10	Rear mudflap LH <i>gand</i>	1	\$74.00	\$74.00	✓
11	Rear absorber LH	1	\$240.00	\$240.00	✓
12	Rear wheel hub bearing LH	1	\$375.00	\$375.00	✓
13	Rear axle <i>11</i>	1	\$1,189.00	\$1,189.00	X
	Total			\$3,392.80	<i>1298.80</i>
	Less 20%			\$678.56	
	Sub Total 1			\$2,714.24	<i>1039.04</i>
A.	Spare Parts (S/Nett)				
1	Rear tyre LH <i>cut LP200</i>	1	\$550.00	\$550.00	<i>802 1605-N</i>
2	Sports rim LH <i>cut</i>	1	\$650.00	\$650.00	<i>450 S-N</i>
	Sub-Total 2			\$1,200.00	
	Total for Parts			\$3,914.24	<i>6105-N</i>
B.	Labour				
1	To check wiring.			\$60.00	<i>20</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$500.00	<i>300</i>
3	Spray painting all affected parts & areas.			\$600.00	<i>400</i>
4	To remove and refit rear undercarriage and suspension LH.			\$250.00	<i>150</i>
5	To check and realign wheels with computerized wheel alignment.			\$120.00	<i>60</i>
6	To spray anti-rust undercoat.			\$90.00	<i>11 X</i>
	Total Labour			\$1,620.00	<i>930</i>
	Total Repair Cost			\$5,534.24	

not Arden
1/5 @ 2050
27/1/17

P- 1298.80
20%
1039.04
S.N 610
1540 - 930
2579.04