

Surveyor:

Ank

DOI:

ASSIGNMENT

26/12/17

Date / Time:

26/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

CB 6580G

Name of Insured:

MS Bus Service

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

22/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Tan Guk Kwe

Driver Tel No.:

8 3318443

(V/L: YES / NO)

Claim No.:

SNM17 D07286 (C02/0

Policy No.:

DMBISN1 691201600

Make / Model:

Golden Dragon

Place of Accident:

Lentor Ave

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 1712 L



INSRS:

WSP:

Tel:

Liability:

RMKS:

CDUE/loyang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

DATE / PIC

31/12/18

SHC 1712 L. X; CB 6580 G - X

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7 0301 2018

After call ltr to OI:

2 (email) 2/1

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

27.12.2017

Sent By:

Confirm with:

Confirm by:

FINALIZATION

Date/Time:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

12/01/2018

Confirm with

Catherine

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost: (with ST)

S\$

1,081.30

Loss of Rental (LOR):

S\$

562.50

(

4.5 days)

x 125.00

Loss of Use (LOU):

S\$

-

(\$

x days)

Loss of Income (LOI):

S\$

225.00

(\$

50.00 x

4.5 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

1,876.29

Global Sum S\$:

1,870.00

FINAL PAYMENT

Date/Time:

12/01/2018

Confirm with:

Catherine

Email

Call

Payee 1:

S\$

1,870.00

Payee 2: (Strike if N.A.)

S\$

-

Payee 3: (Strike if N.A.)

S\$

-

Name 1:

Comfort & Delgro Engineering Pte. Ltd.

Name 2:

Name 3:

RECEIVED 15 JAN 2018

COPY SENT 16/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee:

\$400.00

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____


Excess _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SHC1712L

Vin Reg:

26c 217

Type: M/Car / M/Cycle / Bus / Van / Lorry / T/C / Prima Mover /

Truck / Trailer or

Make:

Hyundai I40

168

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp Reading:

1121

T/Radio

Insured / Std / NI / NA

Eng No:

C No:

1CMLHLP4/4A H4100 0085

Gen. Cond: Good / P / Poor / Burnt

Steering: Inord P / Jammed / Leaked / Burnt or

Brake: Inord P / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Har/hark

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

22/12/17

D.O.I:

26/2/17

Survey held at:

CDHE (Luzon)

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/12/17 Calul P/P \$1010.56 / 2 Pgs.

CTE
PIP

(Red: \$2,751.60 / 73%)

Surveyor recommended days (2 days) +
 1 Public holiday + 2 weekends = 5 days.

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Date/Time File Return to?

2

Add Fee:

☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Weekend \$

Site Insp \$

Interview \$

Tech. Insp \$

Weekend \$

Report Format:

Lump Sum / I.B.I. / S

Blank box for additional notes or signatures.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17024431/K1ka3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 27-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 6580G	Veh. Inspected	SHC 1712L	
Policy No.	DMB1SN1691201600	Coverage (\$)	0.00	
Claim No.	SNM17D07286/C02/0	Excess (\$)	0.00	
Assign From		Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2017	Inspection Date	26/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI17024431/K1ka3

Date: 27.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 1712L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/12/2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	3,762.16
Revised Estimate Amount	: S\$	1,010.56
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Tuesday, 2 January, 2018 2:22 PM
To: Mei Kwan (LKKAUTO); Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAUTO); Admin A; Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving CB6580G (OI : SNM17D07286/C02/0) AND SHC1712L (TP : LKK REF - CC3/CTI17024431/K1ka3) on 22/12/2017
Attachments: MCHM17170885-CB6580G.pdf
Importance: High
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan &/or Zaini.

Further to our earlier email, we attached our insured's accident report for your immediate attention.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive
Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6174

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

jowyn.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jowyn Tay

Sent: Thursday, 28 December, 2017 3:35 PM

To: 'Mei Kwan (LKKAUTO)' <Meikwan@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

"Wishes you a Happy New Year 2018"

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200206384E

Our Reference : To Be Advised

Date : 28-Dec-17

Via Ordinary & Registered Mail

MS NLS Bus Service
Blk 231 Compassvale Walk
#04-450
SINGAPORE 540231

Dear Sirs,

**ACCIDENT INVOLVING CB6580G & SHC1712L ON 22 DEC 2017 ALONG LENTOR AVENUE /
MANDAI ROAD**

We refer to the abovementioned accident.


Please be advised that the third party vehicle SHC1712L is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd** to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us **IMMEDIATELY** through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advise that we and / or LKK Auto Consultants Pte Ltd will not be handling the third party claim and your **NO CLAIM DISCOUNT** will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,


Jowyn Tay
Motor Division
Claims Department
Fax : 62247478 / 62247175
Email : claimsdept@sg.cntaiping.com

cc. LKK Auto Consultants Pte Ltd
Attn : Zaini
Ref : CC3/CTI17024431/K1ka3
Contact no: 68412132
via email address : zaini@lkkauto.com.sg

Agent : AN0580A Odds & Even
via Facsimile :

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305100668

CUSTOMER

VMS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L (R) 65508755 (O)
(P)

REGN NO: SHC1712L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 23.12.2017 09:05
YR OF MANU. 20.12.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU100045	COMPLETION DATE/TIME:

SCOUT CARD NO.

JOB DESCRIPTION

Accident Date: 22.12.2017
NATURE: 3P 22.12.2017

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

to: SHC1712L CHIANG @

Vehicle No.: SHC1712L

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1712L

MAKE :

MODEL : HYUNDAI i40

DATE 26/12/2017 10:33

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (RH) <i>x repair</i>			\$ 2,020.10	
	Rear Fender Inner Lining (RH) <i>x</i>			\$ 164.40	
	Rear Windscreen Moulding <i>x</i>			\$ 60.00	
	Rear Wheel Hup-Cap (RH) <i>✓</i>			\$ 150.70	
	<i>Rear Door (RH) x repair</i>				
	SUB TOTAL			\$ 2,395.20	
	LESS 20%			\$ 479.04	
	DISCOUNTED TOTAL			\$ 1,916.16	
	Rear Windscreen Sealant <i>x</i>			\$ 46.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>✓</i>			\$ 80.00	Nett
				\$ 126.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00 ⁴⁰⁰	
	Spray Painting Charge			\$ 400.00 ³⁶⁰	
	Tuff Kote			\$ 50.00 ^x	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 ⁵⁰	
	Remove/Refix Rear Windscreen Glass			\$ 120.00 ^x	
	TOTAL LABOUR			\$ 1,720.00	
	ESTIMATE TOTAL			\$ 3,762.16	
<i>Ka Lian (LKK)</i> <i>26/12/17 14:00</i> <i>2 Dye</i> <i>PIP</i> <i>After Repair photo</i>					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplemental items must be resurveyed and is subject to final approval from insurance company Acknowledged by Repairer: Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1712L

MAKE :

MODEL : HYUNDAI i40

DATE 26/12/2017 10:33

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>x repair</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>x see</i>			\$ 164.40
	Rear Windscreen Moulding <i>x "</i>			\$ 60.00
	Rear Wheel Hup-Cap (RH) <i>hatched</i>			\$ 150.70
	<i>Rear door (RH) x repair</i>			
	SUB TOTAL			\$ 2,395.20
	LESS 20%			\$ 479.04
	DISCOUNTED TOTAL			\$ 1,916.16
	Rear Windscreen Sealant <i>x "</i>			\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>see</i>			\$ 80.00
				\$ 126.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>400</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Tuff Kote			\$ 50.00 <i>x "</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>x "</i>
	TOTAL LABOUR			\$ 1,720.00
	ESTIMATE TOTAL			\$ 3,762.16

Kg 1/2 1 (1/4)

26/12/17 14:10

2 Dye

P/P

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305100668
REGN NO : SHC1712L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 20.12.2017
DATE/TIME IN : 23.12.2017 09:05
ACCIDENT DATE : 22.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	150.70	20.00	120.56
0002 28-01-0103-2013-A	I40V3 APP LOGO REAR DOOR	1	80.00	2.00-	80.00

SUB-TOTAL : 200.56

JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	360.00
0002 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	50.00

SUB-TOTAL : 810.00

TOTAL : 1,010.56

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Our Job Ref No : 305100668
Date : 28/12/17

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHC1712L

Fax :

22/12/2017

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: CHINA CB6580G
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$200.56
 - (b) Labour Charges \$810.00
 - Total for Part-By-Part Repair Cost** \$1,010.56
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Kalvin
Date : 29/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Zaini (LKK Auto)

From: Catherine Koh Mui Gek <catherinekoh@cdge.com.sg>
Sent: Friday, 12 January 2018 5:11 PM
To: Zaini (LKK Auto)
Subject: Re: SHC 1712L CB 6580G CC3/CTI17024431/K1ka3 22/12/2017
Zaini Ol's sketch plan attached

Dear Zaini

Strictly without prejudice, we accept your offer at \$1870.00. Kindly forward DV soonest.

Thank you.

Best Regards
Catherine Koh
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148733 | Fax : 62141843

From: "Zaini (LKK Auto)" <Zaini@lkkauto.com>
To: 'William Tan Thoo Seng' <williamtan@cdge.com.sg>; 'Catherine Koh Mui Gek' <catherinekoh@cdge.com.sg>
Cc: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>
Date: 12/01/2018 04:57 PM
Subject: SHC 1712L CB 6580G CC3/CTI17024431/K1ka3 22/12/2017 Zaini Ol's sketch plan attached

WITHOUT PREJUDICE

Your Ref: T 1217/ SHC1712L / WT(st)
Our Ref: CC3/CTI17024431/K1ka3

Dear Sirs,

ACCIDENT INVOLVING CB 6580G & SHC 1712L ON 22/12/2017

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **S\$ 1,870.00 (all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,
Zaini Kusaini | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108
Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 12 January 2018 12:10 PM
To: 'William Tan Thoo Seng' <williamtan@cdge.com.sg>; 'Catherine Koh Mui Gek' <catherinekoh@cdge.com.sg>




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17024431/K1ka3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 17-01-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	CB 6580G	Veh. Inspected	SHC 1712L
Policy No.	DMB1SN1691201600	Coverage (\$)	0.00
Claim No.	SNM17D07286/C02/0	Excess (\$)	0.00
Assign From		Assign Date	26/12/2017
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU100045	Colour	BLUE
Odometer	1121	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/12/2017	Inspection Date	26/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1712L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	2,020.10	-
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	164.40	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
1	REAR WHEEL HUP-CAP (RH)	GRAZED	150.70	150.70
1	REAR DOOR (RH)(NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-479.04	-30.14
			1,916.16	120.56
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
			126.00	80.00
LABOUR				
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR FENDER (RH) AND REAR DOOR (RH).		1,000.00	400.00
	SPRAY PAINTING CHARGE.		400.00	360.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
			1,720.00	810.00
GRAND TOTAL			3,762.16	1,010.56
RECOMMENDED COST OF REPAIRS				1,010.56

Report Ref No. CC3/CTI17024431/K1ka3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.