



Messrs Grab Rentals Pte Ltd

Estimate To Repair

Vehicle No :

Chassis No :

Mazda 3 4-Door Sedan 1.5L

SLK4316M

RU31228893

not Affected
make
27/12/17
2017 photo attached
4/5 2000

Third Party Insurer :

Direct Asia

Insured's Veh No :

SJY5006B

Date of accident :

22.12.2017

Date : 23.12.2017

Pages :

1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	rear bumper	\$ 1,075.00	\$ 1,075.00
2	1 pc	rear bumper reinforcement	\$ 538.00	\$ 538.00
3	2 ps	rear bumper reflector @\$51.00	\$ 102.00	\$ 204.00
4	2 ps	rear bumper side retainer @\$37.00	\$ 74.00	\$ 148.00
5	2 ps	rear bumper side guide @\$55.10	\$ 110.20	\$ 220.40
6	4 ps	rear bumper side guide rivets @\$9.10	\$ 36.40	\$ 145.60
7	10 ps	rear bumper clip @\$5.00	\$ 50.00	\$ 500.00
8	2 ps	rear bumper screw spacer @\$10.00	\$ 20.00	\$ 40.00
9	2 ps	rear bumper space screw @\$15.00	\$ 30.00	\$ 60.00
10	1 pc	rear end panel	\$ 506.00	\$ 506.00
11	1 pc	rear end panel inner trim	\$ 86.00	\$ 86.00
12	4 ps	rear end panel inner trim clips @\$5.00	\$ 20.00	\$ 80.00
13	1 pc	bootlid Skyactiv badge	\$ 64.00	\$ 64.00
14	1 pc	bootlid centre logo badge	\$ 75.00	\$ 75.00
15	1 pc	bootlid Mazda 3 badge	\$ 54.00	\$ 54.00
16	2 ps	rear lamps	\$ 519.00	\$ 1,038.00
17	6 ps	rear lamp clips holders	\$ 10.00	\$ 60.00
Less 20%				\$ 4,894.00
				\$ 978.80
				\$ 3,915.20
SPECIAL NETT ITEMS				
18	1 set	rear bumper parking sensor	\$ 450.00	\$ 450.00
Balance C/F				\$ 4,365.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Messrs Grab Rentals Pte Ltd

Date : 23.12.2017

Estimate To Repair Mazda 3 4-Door Sedan 1.5L
Vehicle No : SLK4316M
Chassis No : RU31228893

Pages : 2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 4,365.20
		<u>LABOUR & MISC. CHARGES</u>		
1		To reinstall of rear bumper parking sensor.	50	\$ 120.00
2		To rust-proofing of the affected areas.	11 X	\$ 100.00
3		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	60	\$ 120.00
4		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	300	\$ 700.00
5		Putty and spray painting of the affected portion.	480	\$ 750.00
				\$ 1,790.00
		Grand Total	2530	\$ 6,155.20