



Admin LH - Direct \$82.
新福德車廠私人有限公司 P

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

CHARTERED MOTOR PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 23/12/2017

Estimated repair cost for vehicle no: SKU9333P MAZDA 3 4DR 1.5 A '15

not attached
check
4/5 @ 3200/2
26/12/17
3 day.
take photo after repair

S/N	QTY	ITEMS	U7PRICE	AMOUNT	
1	1	Front L/H Head Lamp	one	\$2,245.00	✓
2	1	Front L/H Head Lamp Lower Bracket	11	\$25.10	X
3	1	Front Bumper	one	\$1,031.70	✓
4	10	Front Bumper Clip	\$6.50	\$65.00	✓
5	1	Front L/H Bumper Side Retainer	one	\$28.70	✓
6	1	Front L/H Bumper Fog Lamp	11	\$351.40	X
7	1	Front L/H Bumper Fog Lamp Cover Assy	one	\$152.50	✓
8	1	Front L/H Bumper Fog Lamp Top Signal Lamp	one	\$157.30	✓
9	1	Front Bumper Wiper Nozzle Cover	one	\$85.10	✓
10	1	Front Bumper Wiper Nozzle Motor & Bracket Assy	11	\$242.40	X
11	1	Front Grille	11	\$581.60	X
12	2	Front Grille Chrome Moulding	one	\$176.70	✓
13	1	Front L/H Fender	one	\$333.90	X

20%

Subtotal:- \$5,476.40

P- 3942
3153.6

Labour charges

To check wiring

30 \$60.00

Tuff kote

11X \$60.00

Panel beating

300 \$600.00

Spray painting

520 \$600.00

Subtotal:- \$1,320.00

Total:- \$6,796.40

4003.6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: