

INS. CASE OWNER:

CC 6 / III 1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$ 2600 (4 days) Reduction: 77 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No. : Nil

If NO or B 28, Ass. Lia :

Repair Cost:

\$ 2,600.00

Loss of Rental (LOR):

\$ (days)

Loss of Use (LOU):

\$ 300.00 (\$ 60 x 5 days)

Loss of Income (LOI):

\$ (\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$ 745

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$ 2,907.45

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$ 2,907.45

Name 1:

New Hack Teck Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

RECEIVED 13 FEB 2018

COPY SENT 12/2/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III17024437/Uyb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 27-12-2017



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 8040D	Veh. Inspected	SGG 3288Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/12/2017	Inspection Date	26/12/2017
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAN YOON LIAN

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 24/12/2017

Estimated repair cost for vehicle no: SGG3288Y HONDA MOBILIO SV 1.5 A '16

Not Affected
Make
we recall
26/12/17
Tel: 6747 9241
4/5 \$ 2600
4 day

26/12/2017

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Front Bonnet		\$699.90	X
2	2	Front Bonnet Hinge	\$59.10	\$118.20	X
3	1	Front Bonnet Lock		\$106.20	X
4	2	Front Head Lamp	\$1,088.70	\$2,177.40	X
5	2	Front Head Lamp Lower Bracket	\$38.40	\$76.80	X
6	1	Front Grille		\$242.60	/
7	1	Front Grille Chrome		\$251.20	/
8	1	Front Grille Emblem Logo		\$57.10	/
9	1	Front Bumper		\$559.80	/
10	10	Front Bumper Clip	\$6.50	\$65.00	/
11	2	Front Bumper Side Retainer	\$25.00	\$50.00	1pc
12	1	Front Bumper Number Plate		\$50.00	/
13	1	Front Bumper Centre Garnish		\$165.60	/
14	1	Front Bumper Lower Cover		\$144.90	X
15	2	Front Bumper Fog Lamp	\$327.20	\$654.40	1pc
16	2	Front Bumper Fog Lamp Cover & Chrome Assy	\$145.00	\$290.00	1pc
17	1	Front Bumper Reinforcement		\$210.50	X
18	1	Front Support Panel		\$663.10	X
19	1	Front Support Panel Top Cover		\$187.00	X
20	8	Front Support Panel Top Cover Clip	\$6.50	\$52.00	X
21	1	Front Air-Con Condenser		\$668.10	X
22	1	Front Radiator		\$1,200.50	X

20%

Subtotal:- \$8,690.30

P- 2795

Labour charges

To remove & refit air-con condenser, radiator, fan motor
& top up gas

11 \$380.00 X

To check wiring

20 \$60.00

Tuff kote

11 \$150.00 X

Panel beating

400 \$1,000.00

Spray painting

600 \$1,000.00

Subtotal:- \$2,590.00

Total:- \$11,280.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary "works" must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1866G

Vehicle Details

Vehicle No.:	SGG3288Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	MOBILIO SV 1.5 CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15Z12871820
Chassis No.:	MRHDD4870GP000148
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,047.00
Original Registration Date:	06 May 2016
First Registration Date:	06 May 2016
Transfer Count:	0
Actual ARF Paid:	\$19,047.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 May 2026
PARF Rebate Amount:	\$14,285.00

Intended COE Rebate Details



COE Expiry Date:	05 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$36,807.00
Total Rebate Amount:	\$51,092.00

The information contained herein is correct as at 26 Dec 2017

OK

Print Received Message

This mail is associated with :

***SGG3288Y (MCA170414)**
[SJP8040D]
TP
TAN YOON LIAN
Dec 24 2017 12:00AM
[COMFORTDELGRO RENT-A-CAR PTE LTD]
New Hock Teck Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/02/2018 14:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2907.45) - SGG3288Y - Claim Handler: Lalitha Krishnan

Approved:2907.45.

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1801-0005 / SGG3288Y
Yr Ref : SJP8040D
Date : 18th January 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

India International Insurance Pte Ltd

64 Cecil Street
#04-05 IOB Building
Singapore 049711

Dear Sirs,

RE: ACCIDENT INVOLVING SGG3288Y & SJP8040D AT BLK 243 TAMPINES ST 21 CARPARK ON 24.12.2017, 16:25HR

We are instructed by **TAN YOON LIAN** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SGG3288Y** was damaged by vehicle **SJP8040D** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 2,600.00
2) Loss of Use for 07 days (4 + 1 Weekend + 2 public holidays)	\$ 420.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 3,027.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$3,027.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,



NEW HOCK TECK MOTOR PTE LTD

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)


In consideration for your agreement to repair my motor vehicle registration no. SAG32804 and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 26 day of 12 2017.

Signature	:	
Name	:	<u>Tan Yoon Lian</u>
ID No.	:	<u>S1411866G</u>
Address	:	_____
Witness Signature	:	
Witness Name	:	<u>Chew Yee Yin</u>
Witness ID	:	<u>S8826618H</u>
Witness Address	:	<u>1 Kaki Bukit Avenue 6 #01-43</u> <u>Singapore 417883</u>

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

WITHOUT PREJUDICE to
any insurance policyholder's right to
claim against their insurer
(Note: This document is not a receipt for
funds to the Discharge Voucher)

India Ref: MC177414
Claimant Ref: SG937884

We/ New Hock Teck Motor Pte Ltd (the workshop) hereby confirm that we/ have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 2,600.00 (repair cost), S\$ 300.00 (loss of use), S\$ 7.45 (search fee), vehicle no SG63288Y that was damaged pursuant to the accident which occurred on 24/12/17 (date) at Bkk 241 Tampines St 21 (location) involving vehicle no STP 80400 insured vehicle. This is pursuant to the inspection conducted on 26/12/17 (date) at "the workshop".

We/ confirm that we/ are/ am authorized by the owner Tan Yoon Lian ("the third party claimant") of vehicle no SG63288Y to make the claim as set out in the above paragraph and we/ have full authority to settle the matter on his/ her behalf in a manner that we/ deem fit. We/ enclose herein the letter of authority given by "the third party claimant".

We/ further confirm that we/ will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SG63288Y (vehicle no) as a result of the accident.

We/ confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/ authorize you to pay the total amount of S\$ 3,907.45 to New Hock Teck Motor Pte Ltd.

Dated this 12 day of 02 2018

CLAIMANT:

Signature

Name

NRIC

Address

Nationality

Occupation

新 福 德 車 廠
NEW HOCK TECK MOTOR PTE LTD
1 Kallit Bukit Ave 6, Bk C #01-43
Autobay@Kallit Bukit Singapore 417883
Tel: 6747 9241 Fax: 6741 7276
Email: admin@nhtmotor.com
UEN: 201718370K

WITNESS:

Signature

Name

NRIC

Address

Nationality

Occupation

Uks 

Signed by appointed Surveyor

LKK AUTO-CONSULTANTS PL
51 Ubi Ave 1, #01-25
Paya Ubi Industrial Park
Singapore 408933
Tel: 6256 3561



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

India International Insurance Pte Ltd
64 Cecil Street #04/ #05
IOB Building
Singapore 049711

Client: TAN YOON LIAN

Invoice No : NPL1801-0005

Date : 18-Jan-18

Date of Accident : 24-Dec-17

Vehicle No. : SGG3288Y

Model Type : Honda Mobilio

Descriptions		Amount
Lump Sum Repair Cost		2,600.00
Total		2,600.00

SIN DOLLARS: TWO THOUSAND AND SIX HUNDRED ONLY





Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 26 Dec 2017 / 11:19:31

Receipt Date/Time : 26 Dec 2017 / 11:19:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171226-000672

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJP8040D				
As at 24 Dec 2017/16:25:00				
Insurance Co: INDIA INTL INS PTE LTD				
1	Insurance Enquiry - SJP8040D			
	Enquiry Fee	7.00	0.49	7.49
	20171226111847520014			
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20171226111853975	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Dec 2017 Edit Reg		26 Dec 2017 00:00 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORTDELGRO RENT-A-CAR PTE LTD, Co. Reg. No.: 198105775H		
Main Claimant:	TAN YOON LIAN, ID: S1411866G		
Vehicle Reg. No.:	SGG3288Y	Date of Loss:	24/12/2017 00:00 - :59
Claim Type:	TP / MCA170414	Policy/Cover Note No.:	M480822/02
Vehicle Reg. No. (Insured):	SJP8040D	Policy No. (Claimant):	M0006165
	Excess:		
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]		
Claimant's Insurer:	Etiga Insurance Pte Ltd (HQ) - Tel: 63360477		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/01/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (09/02/2018): Alert - Adj Mandate Approved (S\$2907.45) - SGG3288Y - Claim Handler: Lalitha Kri...
- III_SG (01/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SGG3288Y - Claim Handler: Lalitha Krishn...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGG3288Y (MCA170414)**
[SJP8040D]
TP
TAN YOON LIAN
Dec 24 2017 12:00AM
[COMFORTDELGRO RENT-A-CAR PTE LTD]
New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	29/01/18 15:10	Odometer Reading							 Load JPG	☒	
2	29/01/18 15:10	General View							 Load JPG	☒	
3	29/01/18 15:10	Chassis Number							 Load JPG	☒	
4	29/01/18 15:10	General View							 Load JPG	☒	
5	29/01/18 15:10	General View							 Load JPG	☒	
6	29/01/18 15:10	General View							 Load JPG	☒	
7	29/01/18 15:10	General View							 Load JPG	☒	
8	29/01/18 15:10	General View							 Load JPG	☒	
9	29/01/18 15:10	General View							 Load JPG	☒	
10	29/01/18 15:10	General View							 Load JPG	☒	
11	29/01/18 15:10	General View							 Load JPG	☒	
12	29/01/18 15:10	General View							 Load JPG	☒	
13	29/01/18 15:10	General View							 Load JPG	☒	
14	29/01/18 15:10	General View							 Load JPG	☒	
15	29/01/18 15:10	General View							 Load JPG	☒	
16	29/01/18 15:10	General View							 Load JPG	☒	
17	29/01/18 15:10	General View							 Load JPG	☒	
18	29/01/18 15:10	General View							 Load JPG	☒	
19	29/01/18 15:11	General View							 Load JPG	☒	
20	29/01/18 15:11	General View							 Load JPG	☒	
21	29/01/18 15:11	General View							 Load JPG	☒	
22	29/01/18 15:11	General View							 Load JPG	☒	
23	29/01/18 15:11	General View							 Load JPG	☒	
24	29/01/18 15:11	General View							 Load JPG	☒	
25	29/01/18 15:11	General View							 Load JPG	☒	
26	29/01/18 15:11	General View							 Load JPG	☒	
27	29/01/18 15:11	General View							 Load JPG	☒	
28	29/01/18 15:11	General View							 Load JPG	☒	
29	29/01/18 15:11	General View							 Load JPG	☒	
30	29/01/18 15:11	General View							 Load JPG	☒	
31	29/01/18 15:11	General View							 Load JPG	☒	
32	29/01/18 15:11	General View							 Load JPG	☒	
33	29/01/18 15:11	General View							 Load JPG	☒	
34	29/01/18 15:11	General View							 Load JPG	☒	
35	29/01/18 15:11	General View							 Load JPG	☒	

36	29/01/18 15:11	General View	1	Load JPG	✓
37	29/01/18 15:11	General View	1	Load JPG	✓
38	29/01/18 15:11	General View	1	Load JPG	✓
39	29/01/18 15:11	General View	1	Load JPG	✓
40	29/01/18 15:11	General View	1	Load JPG	✓
41	29/01/18 15:11	General View	1	Load JPG	✓
42	29/01/18 15:11	General View	1	Load JPG	✓
43	29/01/18 15:11	General View	1	Load JPG	✓
44	29/01/18 15:11	General View	1	Load JPG	✓
45	29/01/18 15:11	General View	1	Load JPG	✓
46	29/01/18 15:11	General View	1	Load JPG	✓
47	29/01/18 15:11	General View	1	Load JPG	✓
48	29/01/18 15:11	General View	1	Load JPG	✓
49	29/01/18 15:11	General View	1	Load JPG	✓
50	29/01/18 15:11	General View	1	Load JPG	✓
51	29/01/18 15:11	General View	1	Load JPG	✓
52	29/01/18 15:11	General View	1	Load JPG	✓
53	29/01/18 15:11	General View	1	Load JPG	✓
54	29/01/18 15:11	General View	1	Load JPG	✓
55	29/01/18 15:11	General View	1	Load JPG	✓
56	29/01/18 15:11	General View	1	Load JPG	✓
57	29/01/18 15:11	General View	1	Load JPG	✓
58	29/01/18 15:11	General View	1	Load JPG	✓
Documentation				1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 16:46	TP GIA REPORT	1	Load PDF	
2	08/02/18 17:40	WORKSHOP INVOICE	1	Load PDF	
3	08/02/18 17:40	LTA SEARCH	1	Load PDF	
4	08/02/18 17:40	LOD	1	Load PDF	
5	13/02/18 17:02	DISCHARGE VOUCHER	1	Load PDF	
6	13/02/18 17:02	AUTHORISATION TO ACT FORM	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	04/01/18 09:12	Singapore Accident Statement-IV	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III17024437/UYB3Q2

Date: 13/02/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M480822/02

Claimant Vehicle No: SGG3288Y

Insured Vehicle No: SJP8040D

Date of Loss: 24/12/2017

Nature of Claim: TP

Claim No: MCA170414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG3288Y

Make & Model: HONDA MOBILIO, 1.5 RS Basic (A)

Engine No: L15Z12871820

Reg. Date: 06/05/2016 (Man. Year: 2016)

Chassis No: MRHDD4870GP000148

Colour: Black

Odometer: 21843 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,690.30	2,236.00	6,454.30	74.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,020.00	1,570.00	60.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,280.30	3,256.00	8,024.30	71.14
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	11,280.30	2,600.00	8,680.30	76.95
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,907.45		

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 26/12/2017 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2018)
Parts:	M1-MPV	HONDA MOBILIO 1.5 RS Basic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG3288Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	699.90 F	*- FL
2	2		*FRONT BONNET HINGE	Not Necessary	118.20 F	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	106.20 F	*- FL
4	1		*FRONT HEAD LAMP	N/S Cracked	2,177.40 F	*1,088.70 FL
5	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	76.80 F	*- FL
6	1		*FRONT GRILLE	Cracked	242.60 F	*242.60 FL
7	1		*FRONT GRILLE CHROME	Scratched	251.20 F	*251.20 FL
8	1		*FRONT GRILLE EMBLEM LOGO	Necessary	57.10 F	*57.10 FL
9	1		*FRONT BUMPER	Dented / Deformed	559.80 F	*495.80 FL
10	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*39.00 FL
11	1		*FRONT BUMPER SIDE RETAINER	N/S Bent	50.00 F	*25.00 FL
12	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
13	1		*FRONT BUMPER CENTRE GARNISH	Twisted	165.60 F	*165.60 FL
14	1		*FRONT BUMPER LOWER COVER	Not Necessary	144.90 F	*- FL
15	1		*FRONT BUMPER FOG LAMP	N/S Cracked	654.40 F	*235.00 FL
16	1		*FRONT BUMPER FOG LAMP COVER & CHROME ASSY	N/S Scratched	290.00 F	*145.00 FL
17	1		*FRONT BUMPER REINFORCEMENT	Repair	210.50 F	*- FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	663.10 F	*- FL
19	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	187.00 F	*- FL
20	8		*FRONT SUPPORT PANEL TOP COVER CLIP	Not Necessary	52.00 F	*- FL
21	1		*FRONT AIR-CON CONDENSER	Not Necessary	668.10 F	*- FL
22	1		*FRONT RADIATOR	Not Necessary	1,200.50 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,690.30	2,795.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	559.00
Total Parts (S\$)	8,690.30	2,236.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS	New	380.00	0.00
2	TO CHECK WIRING	New	60.00	20.00
3	TUFF KOTE	New	150.00	0.00
4	PANEL BEATING	New	1,000.00	400.00
5	SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,590.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >