

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts En Auton	TODILE			
DIR	ECT ASIA INSURA	NCE (SINGAPORE) PL	Ref : CC6/DAI17024	439/Ups3			
88 SOUTH BRIDGE ROAD SINGAPORE 058716			Date: 27-12-2017 Code: DAI				
1.		Policy Particular	s :- THIRD PARTY CLA	M			
	Insured Veh.	SKZ 3584U	Veh. Inspected	SGX 6885P			
	Policy No.		Coverage (\$)	0.00			
	Claim No.		Excess (\$)	0.00			
	Assign From	7	Assign Date	27/12/2017			
2.		Vehicle Par	ticulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	(4)	Steering				
	Brakes		Modification				
	General						
3.		Cond	itions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre		, i	mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre		3	mm			
4.		Descrip	tion of Damages				
5.		Gene	ral Information				
J.	Accident Date	23/12/2017	Inspection Date	26/12/2017			
_	Survey held at	FASTECH AUTO PTE LTD	inspection sate				
	July Hold at	1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883					
5a.			Remarks				

FASTECH AUTO PTE LTD

AND FASTECH AUTO PTE LTD

AND FASTECH AUTO PTE LTD

VEHICLE NO: SGX6885P QTY **PARTICULAR** LIST ITEMS: 1PCS REAR WINDSCREEN MOULDING nec \$68.10 1PCS TAILGATE Book 5700 \$663.33 -1PCS TAILGATE 'S' LOGO nu \$30.00 1PCS TAILGATE 'SWIFT' EMBLEM NUC \$31.30 -1PCS tui TAILGATE INNER LOCK \$179.45 1PCS 11 TAILGATE LOCK STRIKER \$60.00 × 1PCS TAILGATE WEATHERSTRIP \$201.47 -Tw/ 2PCS 27 TAILGATE & DAMPERS \$570.00 × 1PCS TAILGATE OUTER HONDLE hondle \$100.30 1PCS TAILGATE INNER TRIM BOARD \$165.20 × TAILGATE INNER TRIM BOARD CLIPS 1SET \$40.00 ner 1PCS REAR BUMPER \$597.80 NS 2PCS REAR BUMPER REFLECTORS @40.50 \$81.00 X 2PCS REAR BUMPER SIDE RETAINERS@34.70 Aud \$69.40 1SET REAR BUMPER CLIPS \$40.00 REAR BUMPER LICENCE PLATE LAMP 310 1SET \$60.00 1PCS REAR END PANEL 50440D \$389.10 1PCS REAR END PANEL TOP GARNISH \$103.68 1PCS REAR END PANEL AIR VENT \$38.32 crumbed/340 1PCS REAR FLOOR PANEL \$655.00 1PCS REAR FLOOR PANEL TOP BOARD 70-1 \$189.49 2PCS Cre TAILLAMPS @285.00 \$570.00 2PCS TAILLAMP HOUSING PANELS @145.30 \$290.60 2PCS REAR FENDERS@ 525.00 \$1,050.00 2PCS REAR FENDER INNER TRIMS @145.30 \$290.40 1PCS REAR EXHAUST Burt \$329.90 1PCS REAR EXHAUST HEAT SHIELD Buy \$148.50 -1PCS REAR CHASSIS MEMBER O/S \$501.00 🔀 TOTAL: \$7,513.34 SPECIAL NETT ITEMS: shot \$280.00 2005.1 1SET REAR BUMPER REVERSE SENSOR nec 1PCS REAR END PANEL SEALANT \$50.00 But 1PCS \$20.00 15-5.2 REAR LICENSE PLATE ne 1PCS REAR WINDSCREEN SEALANT \$50.00 HOS.N 1PCS REAR FLOOR PANEL INSULATOR nu \$450.00 / 205.2

LABOUR CHARGES:

TO CHECK WIRING

\$50.00 30

7-4505.4

TO DISMENTLE & REPLACING REVERSE SENSOR \$80.00 TO DISMENTLE & REFIX REAR WINDSCREEN \$150.00 /20 TO TRANSFER TAILGATE MECHANISM \$100.00 60 TO SPRAY RUST PROOFING \$150.00 90 TO DISMENTLE & REFIX SEAT CUSHION UPHOLSTERY \$150.00 80 TO DISMENTLE & REFIX REAR EXHAUST \$100.00 60 TO CONDUCT CHASSIS ALIGNMENT M₁ \$380.00 X TO DISMENTLE & REFIX PETROL TANK \$100.00 60 LABOUR FOR PANEL BEATING, CUT, WEILD, STRAIGHTEN & REPLACING PARTS \$2,000.00 / 400 TO PUTTY & SPRAY PAINTING \$1,800.00 /080 TOTAL: \$13,423.34

7284.36

LEF Auto Consultants hence notify the 5-care: of the following:

- . To resulter suray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation.
- . There arry survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours: Monday to Friday, 09:00 – 17:00 UEN: 566550020G / GST Reg. No.: M400017735

23/12/17

uploaded

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

					ADDI	ENDUM					
(A)	PARTICULARS OF	PERSO	ONMAKI	NGTH	EAMENDN	MENTS:					
	Original Report No	o :	MMA	1171	FP283	Ve	hicle Re	gistration	No: _	SKZ	3584 U
	Name(as shownin NRI	IC):	lee	Di	we;	NR	IC/FIN/	Passport	No :	59108	216 H
	(*Vehicle Driver/	Vehic	le Owner)(*)PI	ease delete	e as approp	riate				
	Address	:								Singapor	re()
	Contact (Tel)	:				Mc	bile No	o.:9	6827	090	
	Email Address	:									
	Date of Accident	;	23 12	117		Tin	ne of Ac	cident:		11:45	
	Place of Accident	;	Slip	Rol	Paya	Lebar	Rd	twels	PIG	CTuas)	
	Insurance Compar		- 51		7)						
	# Amend	g ame	ndments Revert	: - 	rom)	Reporti	ng	+ .	owh	Davna g	
		4/4		,	,		-				

NRIC/FINNo .:

Date: 23 112117

From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 7 February 2018 9:18 AM 'Charandeep Singh'; Motor Claims; Claim

To: Cc:

Subject:

RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA)

AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Attachments:

LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey

Photos.pdf; Insurance Search Fee.pdf; Rental Receipt.pdf; LOA.pdf

Without Prejudice

Hi Charan,

We refer to the above matter.

We seek your approval to offer Third Party repairer, Fastech Auto Pte Ltd at \$7,308.00(all-in). The breakdown is as follows: -

1. Cost of Repair (w/GST)

\$ 6,206.00

2. Loss of Rental (11days x \$100.00)**

\$1,100.00

3. LTA/ GIA Search Fee

2.00 TOTAL \$ 7,308.00

Enclosed herewith the supporting document for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charandeep Singh [mailto:charandeep.singh@directasia.com]

Sent: Monday, 15 January 2018 3:21 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Motor Claims <motorclaims@directasia.com>; Claim <claim@directasia.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Aaron Wang <aaron.wang@directasia.com>; Derrick Quok <derrick@directasia.com>; Kenneth Lim <kenneth@directasia.com> Subject: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP: LKK

REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Sir/Madam,

^{**}Recommended 07 repair days + 2Sunday + 2PH = 11days

From:

Charandeep Singh < charandeep.singh@directasia.com>

Sent:

Monday, 9 April 2018 4:13 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A

Subject:

RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI:

DAI - TBA) AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Attachments:

RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI :

DAI - TBA) AND SGX6885P (TP : LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao Tong,

Please reply to my email dated 5th March 2018.

As mentioned in my email there does not appear to be major damages to third party vehicle that warrants a high repair cost.

No direct settlement for this case.

Please advise if parts were dismantled in front of the surveyor during survey?

(Y(1).

Regards

Charan Singh / Claims Specialist

Direct: +65 6603 3617

olanse on hallor, rearly

DirectAsia Insurance

Customer Service: +65 6665 5555 Retail: 88 South Bridge Road, S(058716)

www.directasia.com

000000

CONTREM TALITY NOTICE

status at the area, super print, at sper, on the

CONFIDENTIALITY NOTICE: This email (and any attachment) is intended only for the attention of the addressee and may contain legally printinged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender by return email. Thank you. An e-mail reply to this address may be subject to interception or monitoring for operational reasons or for lawful business practices. Direct Asia Insurance (Singapore) Pte ttd (Company Res; 2008/256116)

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, 9 April, 2018 8:44 AM

To: Charandeep Singh

Cc: Admin A

Subject: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI : DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan,

We refer to our email dated 07/02/2018, 05/03/2018 &17/03/2018.

Kindly let us have your approval/instruction please.

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 2 June 2018 12:16 PM

To: Charandeep Singh (charandeep.singh@directasia.com)

Cc: Admin A

Subject: RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI:

DAI - TBA) AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Attachments: RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI:

DAI - TBA) AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017; LOA.PDF; Rental Receipt.pdf; Insurance Search Fee.pdf; LKK Resurvey Photos.pdf;

LKK Survey Photos.pdf; LKKAdjustment1.pdf; LKKInspection.pdf

Hi Charan,

We have reviewed the matter.

According to surveyor, the rear portion of third party vehicle was badly damage due to direct impact from the rear. The initial estimate from third party amounting to \$13,423.34. After check on each and every part surveyor managed to adjust repair cost at Lump Sum \$5,800.00 representing a reduction of 58% on repair cost. Kindly refer to our survey photos for your perusal. The dismantling was not done in front of the surveyor during the first survey.

Kindly let us have your mandate/instruction on this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charandeep Singh [mailto:charandeep.singh@directasia.com]

Sent: Monday, 9 April 2018 4:13 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao Tong,

Please reply to my email dated 5th March 2018.

As mentioned in my email there does not appear to be major damages to third party vehicle that warrants a high repair cost.

No direct settlement for this case.

Please advise if parts were dismantled in front of the surveyor during survey?

From: Charandeep Singh < charandeep.singh@directasia.com>

Sent: Tuesday, 5 June 2018 2:33 PM

To: Hsiao Tong (LKKAuto)

Cc: Admin A

Subject: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI : DAI - TBA)

AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao Tong,

As mentioned to you earlier there does not appear to be major damages to third party vehicle that warrants a high repair cost.

At most our offer to the third party is as follows:

1. Cost of Repair (w/GST) \$ 5,350.00 2. Loss of Rental (9 days x \$100.00)** \$ 900.00 3. LTA/ GIA Search Fee \$ 2.00

Please settle up to the stated amount.

Regards

Charan Singh / Claims Specialist

Direct: +65 6603 3617

DirectAsia Insurance

Customer Service: +65 6665 5555 Retail: 88 South Bridge Road, 5(058716)

www.directasia.com



CONFIDENTIALITY NOTICE

CONFIDENTIALITY NOTICE: This emult (and any attachment) is intended only for the attention of the addressee and may contain legally provileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete. The criginal, destroy all copies and inform the sender by return email. Thank you, An e-mail reply to this address may be subject to interception or monitoring for operational reasons or for leading a practices. Direct Asia Insurance (Singapore) Pte Ltd (Company Res. 2008;261.16)

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, 2 June, 2018 12:16 PM

To: Charandeep Singh

Cc: Admin A

Subject: RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI : DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan,

We have reviewed the matter.

From: Hsiao Tong (LKKAuto)

Sent: Friday, 8 June 2018 8:48 AM

To: Jason Fastech Auto (jason@fastechauto.com.sg)

Subject: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING

SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017]

Your Ref: SGX 6885P Without Prejudice

Our Ref: CC6/DAI17024439/Ups3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$6,250.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Fastech Auto <jason@fastechauto.com.sg>

Sent: Saturday, 9 June 2018 9:55 AM

To: Hsiao Tong (LKKAuto)

Subject: RE: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT

INVOLVING SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017]

Without Prejudice

Dear Hsiao Tong,

We are unable to accept your offer, therefore we are counter proposing global sum 7000.00 all in.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405

Tel: 67465405 Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Friday, June 8, 2018 8:48 AM

To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>

Subject: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA)

& SGX 6885P ON 23/12/2017]

Your Ref: SGX 6885P Without Prejudice

Our Ref: CC6/DAI17024439/Ups3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$6,250.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

From:

Hsiao Tong (LKKAuto)

Sent:

Monday, 11 June 2018 12:46 PM

To:

'Charandeep Singh'

Cc:

Admin A

Subject:

RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA)

AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Without Prejudice

Hi Charan,

Further to your below email.

Please be informed that third party rejected our offer and proposed global sum \$7,000.00(all-in).

For your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charandeep Singh [mailto:charandeep.singh@directasia.com]

Sent: Tuesday, 5 June 2018 2:33 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP: LKK

REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao Tong,

As mentioned to you earlier there does not appear to be major damages to third party vehicle that warrants a high repair cost.

At most our offer to the third party is as follows:

1. Cost of Repair (w/GST)

\$ 5,350.00

2. Loss of Rental (9 days x \$100.00)**

\$ 900.00

3. LTA/ GIA Search Fee

\$ 2.00

TOTAL \$ 6,252.00

Please settle up to the stated amount.

From:

Charandeep Singh <charandeep.singh@directasia.com>

Sent:

Saturday, 28 July 2018 12:43 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A

Subject:

RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao,

Please offer up to \$\$6,500.00 all in.

We will not negotiate for settlement any higher.

Regards

Charan Singh / Claims Specialist Direct: +65 6603 3617

DirectAsia Insurance

Customer Service: +65 6665 5555 20 Anson Road, #08-01 Singapore 079912

www.directasia.com



CONFIDENTIALITY NOTICE

CONFIDENTIALITY NOTICE: This email (and any attachment) is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender by return email. Thank you. An e-mail reply to this address may be subject to interception or monitoring for operational reasons or for lawful business practices. Direct Asia Insurance (Singapore) Pte Ltd (Company Reg. 200822611G)

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, 28 July, 2018 11:02 AM

To: Charandeep Singh

Cc: Admin A

Subject: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

2nd Reminder

Hi Charan,

Further to our below email.

Kindly let us have your further mandate/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 7 July 2018 12:03 PM

To: 'Charandeep Singh' <charandeep.singh@directasia.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP:

LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan.

We refer to our below email.

Kindly let us have your further mandate/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 11 June 2018 12:46 PM

To: 'Charandeep Singh' < charandeep.singh@directasia.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP:

LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Without Prejudice

Hi Charan,

Further to your below email.

Please be informed that third party rejected our offer and proposed global sum \$7,000.00(all-in).

For your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charandeep Singh [mailto:charandeep.singh@directasia.com]

Sent: Tuesday, 5 June 2018 2:33 PM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP: LKK

REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao Tong,

As mentioned to you earlier there does not appear to be major damages to third party vehicle that warrants a high repair cost.

At most our offer to the third party is as follows:

1. Cost of Repair (w/GST) \$ 5,350.00 2. Loss of Rental (9 days x \$100.00)** \$ 900.00 3. LTA/ GIA Search Fee \$ 2.00

Please settle up to the stated amount.

Regards

Charan Singh / Claims Specialist Direct: +65 6603 3617

DirectAsia Insurance

Customer Service: +65 6665 5555 Retail: 88 South Bridge Road, S(058716)

www.directasia.com



CONFIDENTIALITY NOTICE

CONFIDENTIALITY NOTICE: This email (and any attachment) is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised uso, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender by return email. Thank you, An e-mail reply to this address may be subject to interception or monitoring for operational reasons or for lawful business practices. Direct Asia Insurance (Singapore) Pte Ltd (Company Reg. 200822611G)

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, 2 June, 2018 12:16 PM

To: Charandeep Singh

Cc: Admin A

Subject: RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan.

We have reviewed the matter.

According to surveyor, the rear portion of third party vehicle was badly damage due to direct impact from the rear. The initial estimate from third party amounting to \$13,423.34. After check on each and every parts, surveyor managed to adjust repair cost at Lump Sum \$5,800.00 representing a reduction of 58% on repair cost. Kindly refer to our survey photos for your perusal. The dismantling was not done in front of the surveyor during the first survey.

Kindly let us have your mandate/instruction on this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charandeep Singh [mailto:charandeep.singh@directasia.com]

Sent: Monday, 9 April 2018 4:13 PM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Hsiao Tong,

Please reply to my email dated 5th March 2018.

As mentioned in my email there does not appear to be major damages to third party vehicle that warrants a high repair cost.

No direct settlement for this case.

Please advise if parts were dismantled in front of the surveyor during survey?

Regards

Charan Singh / Claims Specialist Direct: +65 6603 3617

DirectAsia Insurance

Customer Service: +65 6665 5555 Retail: 88 South Bridge Road, S(058716)

www.directasia.com



CONFIDENTIALITY MOTICE

CONFIDENTIALITY NOTICE: This email (and any attachment) is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender by return email. Thank you. An e-mail reply to this address may be subject to interception or monitoring for operational reasons or for lawful business practices. Direct Asia Insurance (Singapore) Pte Etd (Company Reg. 2008;23(11G))

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, 9 April, 2018 8:44 AM

To: Charandeep Singh

Cc: Admin A

Subject: [EXT] RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND

SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan,

We refer to our email dated 07/02/2018, 05/03/2018 &17/03/2018.

Kindly let us have your approval/instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 17 March 2018 8:21 AM

To: Charandeep Singh (charandeep.singh@directasia.com) < charandeep.singh@directasia.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP:

LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan,

We refer to our email dated 07/02/2018 & 05/03/2018.

Kindly let us have your approval/instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 5 March 2018 9:50 AM

To: Charandeep Singh (charandeep.singh@directasia.com; Claim

(claim@directasia.com) <claim@directasia.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP:

LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Hi Charan,

We refer to our email dated 07/02/2018.

Kindly let us have your approval/instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 7 February 2018 9:18 AM

To: 'Charandeep Singh' < charandeep.singh@directasia.com; Motor Claims < motorclaims@directasia.com; Claim

<claim@directasia.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP:

LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Without Prejudice

Hi Charan,

We refer to the above matter.

We seek your approval to offer Third Party repairer, Fastech Auto Pte Ltd at \$7,308.00(all-in). The breakdown is as follows: -

1. Cost of Repair (w/GST)

Loss of Rental (11days x \$100.00)**

3. LTA/ GIA Search Fee

\$ 6.206.00

\$ 1,100.00

2.00

\$ TOTAL \$ 7,308.00

**Recommended 07 repair days + 2Sunday + 2PH = 11days

Enclosed herewith the supporting document for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charandeep Singh [mailto:charandeep.singh@directasia.com]

Sent: Monday, 15 January 2018 3:21 PM

To: Shirley Hiew (LKK Auto) < Shirley Hiew@lkkauto.com >; Motor Claims < motorclaims@directasia.com >; Claim <claim@directasia.com>

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com; Admin A < admin-a@lkkauto.com; Aaron Wang <aaron.wang@directasia.com>; Derrick Quok <derrick@directasia.com>; Kenneth Lim <kenneth@directasia.com> Subject: Our ref 74369 _Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP: LKK REF - CC6/DAI17024439/Ups3) on 23/12/2017

Dear Sir/Madam,

OI rear ended third party vehicle . At fault case.

Regards

Charan Singh / Claims Specialist Direct: +65 6603 3617

DirectAsia Insurance

Customer Service: +65 6665 5555 Retall: 88 South Bridge Road, S(058716)

www.directasia.com



CONFIDENTIALITY NOTICE

CONFIDENTIALITY NOTICE: This email (and any attachment) is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender by return email. Thank you. An e-mail reply to this address may be subject to interception or monitoring for operational reasons or for lawful business practices, Direct Asia Insurance (Singapore) Pte Ltd (Company Reg. 200822611G)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Monday, 15 January, 2018 2:39 PM

To: Motor Claims; Claim

Cc: Hsiao Tong (LKKAuto); Admin A; Aaron Wang; Derrick Quok; Kenneth Lim; Charandeep Singh

Subject: [EXT] RE: Direct Settlement - Accident Involving SKZ3584U (OI: DAI-TBA) AND SGX6885P (TP: LKK REF

- CC6/DAI17024439/Ups3) on 23/12/2017

Dear Sir/Madam,

We refer to the above matter.

Please kindly advice liability soonest.

Meanwhile, kindly provide us the claim reference for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>ShirleyHiew@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Friday, 29 December 2017 10:45 AM

To: motorclaims@directasia.com; claim@directasia.com

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >; Admin A < admin-a@lkkauto.com >; 'Aaron Wang'

<aaron.wang@directasia.com>; 'Derrick Quok' <derrick@directasia.com>; 'Kenneth Lim' <kenneth@directasia.com>; 'Charandeep Singh' <charandeep.singh@directasia.com>

Subject: Direct Settlement - Accident Involving SKZ3584U (OI: DAI - TBA) AND SGX6885P (TP: LKK REF -

CC6/DAI17024439/Ups3) on 23/12/2017

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SGX 6885P at Fastech Auto Pte Ltd - Kaki Bukit.

Enclosed for your perusal is:

TP's GIA report

· Photographs of TP vehicle in its damaged condition

Please kindly advice liability soonest.

Meanwhile, kindly provide us the claim reference for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler , you may contact the undersigned.

"Wishes you a Merry Christmas & Happy New Year 2018"

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>ShirleyHiew@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

IMPORTANT NOTICE: This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

Jason Tang

Tisiao Tong (Ektota)	
From: Sent: To: Subject:	Hsiao Tong (LKKAuto) Tuesday, 31 July 2018 9:19 AM 'jason@fastechauto.com.sg' RE: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017]
Without Prejudice	
Hi Jason,	
We refer to your below	email.
We have our principal	instruction to improve our offer at a global sum of \$6,500.00(all-in).
Kindly confirm accepto	ance.
"Kindly note that this negotia the matter amicably without from this negotiation of term	tion between parties on this matter is purely on a without prejudice basis with the sole intention of resolvin parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred s/settlement.
	being discovered or subsequently produced by either party that will materially affect/influence on the issue arty is not bound, thereafter, by the negotiation terms/settlement."
Best Regards, Hsiao Tong, Chew 0	Case Handler
LKK Auto Consultan	
	ail: <u>chewht@lkkauto.com</u> fax: 6741-4108 rial Park, Ubi Avenue 1, #02-25 S(408933)
Dik 31, raya Obi Indust	Hall alk, Obl Avenue 1, #02-25 5(400933)
From: Jason Fastech Aut Sent: Saturday, 9 June 20	o <jason@fastechauto.com.sg> 018 9:55 AM</jason@fastechauto.com.sg>
) <chewht@lkkauto.com> 5X 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT 3/12/2017]</chewht@lkkauto.com>
Without Prejudice	
Dear Hsiao Tong,	
We are unable to accept	your offer, therefore we are counter proposing global sum 7000.00 all in.
Thank you.	
Best Regards	

From:

Jason Fastech Auto <jason@fastechauto.com.sg>

Sent:

Wednesday, 1 August 2018 12:52 PM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$6,500.00(all-in).

Thank you.

Best Regards

Jason Tang Fastech Auto Pte Ltd 1 Kaki Bukit Ave 6 #01-46/48/50 AutoBay Singapore 417883

Tel: 67465405 Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Tuesday, July 31, 2018 9:19 AM To: jason@fastechauto.com.sg

Subject: RE: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT

ASIA) & SGX 6885P ON 23/12/2017]

Without Prejudice

Hi Jason,

We refer to your below email.

We have our principal instruction to improve our offer at a global sum of \$6,500.00(all-in).

Kindly confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Fastech Auto < jason@fastechauto.com.sg>

Sent: Saturday, 9 June 2018 9:55 AM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >

Subject: RE: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT

ASIA) & SGX 6885P ON 23/12/2017]

Without Prejudice

Dear Hsiao Tong,

We are unable to accept your offer, therefore we are counter proposing global sum 7000.00 all in.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Friday, June 8, 2018 8:48 AM

To: Jason Fastech Auto (jason@fastechauto.com.sg) < jason@fastechauto.com.sg>

Subject: Your Ref: SGX 6885P *Our Ref: CC6/DAI17024439/Ups3s2 [ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA)

& SGX 6885P ON 23/12/2017]

Your Ref: SGX 6885P

Without Prejudice

Our Ref: CC6/DAI17024439/Ups3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKZ 3584U(DIRECT ASIA) & SGX 6885P ON 23/12/2017

We refer to the above matter.

We have our principal instruction to offer at a global sum of §6,250.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		ationale Des Experts En Autom				
DIRECT ASIA INSUR	ANCE (SINGAPORE) PL	Ref : CC6/DAI170244	439/Upb3s2			
88 SOUTH BRIDGE F SINGAPORE 058716	ROAD	Date: 06-08-2018 Code: DAI				
	Policy Particula	ars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 3584U	Veh. Inspected	SGX 6885P			
Policy No.	MT/00354732	Coverage (\$)	0.00			
Claim No.	74369	Excess (\$)	0.00			
Assign From		Assign Date	26/12/2017			
2.	Vehicle Pa	articulars & Condition				
Make & Model	SUZUKI SWIFT (A)	c.c	1328			
Engine No.	HIDDEN	Year of Reg.	2007			
Chassis No.	ZC11S181838	Colour	GREY			
Odometer	116269	Steering	IN ORDER			
Brakes	IN ORDER	Modification	SPORTS RIM			
General	GOOD					
3.	Con	ditions of Tyres				
	Size	Make	Balance			
R/H Front Tyre	185/60R15	NEXEN	6 mm			
L/H Front Tyre	185/60R15	NEXEN	6 mm			
R/H Rear Tyre	185/60R15	NEXEN	6 mm			
L/H Rear Tyre	185/60R15	NEXEN	6 mm			
4.	Descri	iption of Damages				
THE VEHICLE S	USTAINED DAMAGES AT THE	REAR PORTION.				
DAMAGES SEE	DETAILS.					
5.	12/15/15/16/16/16/16/16/16/16/16/16/16/16/16/16/	eral Information				
Accident Date	23/12/2017	Inspection Date	26/12/2017			
Survey held a	FASTECH AUTO PTE LTD	•				
	1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883					
5a.		Remarks				
A)THE INSPECT B)IN ACCORDA	TION WAS CONDUCTED ON A" NCE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.			
5b.	Estim	ate Days of Repair				
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	7 Working Da	ys			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 6885P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	68.10	68.10
1	TAILGATE	BADLY DENTED	663.33	663.33
1	TAILGATE 'S' LOGO	NECESSARY	30.00	30.00
1	TAILGATE 'SWIFT' EMBLEM	NECESSARY	31.30	31.30
1	TAILGATE INNER LOCK	TWISTED	179.45	179.45
1	TAILGATE LOCK STRIKER	NOT NECESSARY	60.00	
1	TAILGATE WEATHERSTRIP	TWISTED	201.47	201.47
2	TAILGATE DAMPERS	NOT NECESSARY	570.00	
1	TAILGATE OUTER HANDLE	TWISTED	100.30	100.30
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	165.20	
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	40.00	40.00
1	REAR BUMPER	DISTORTED	597.80	597.80
2	REAR BUMPER REFLECTORS @ \$40.50	NO SUCH PARTS	81.00	
2	REAR BUMPER SIDE RETAINERS @ \$34.70	BENT	69.40	69.40
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
1	SET REAR BUMPER LICENCE PLATE LAMP	BROKEN	60.00	60.00
1	REAR END PANEL	BADLY DENTED	389.10	389.10
1	REAR END PANEL TOP GARNISH	TWISTED	103.68	103.68
1	REAR END PANEL AIR VENT	CRACKED	38.32	38.32
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	655.00	655.00
3	REAR FLOOR PANEL TOP BOARD	TORN	189.49	189.49
2	TAILLAMPS @ \$285.00	CRACKED	570.00	570.00
2	TAILLAMP HOUSING PANELS @ \$145.30	TO REPAIR SEE LABOUR	290.60	1
2	REAR FENDERS @ \$525.00	TO REPAIR SEE LABOUR	1,050.00	3
2	REAR FENDER INNER TRIMS @ \$145.30	NOT NECESSARY	290.40	
	REAR EXHAUST	BENT	329.90	329.90
	REAR EXHAUST HEAT SHIELD	BENT	148.50	148.50
1	REAR CHASSIS MEMBER O/S	TO REPAIR SEE LABOUR	501.00	

Report Ref No. CC6/DAI17024439/Upb3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 15% DISCOUNT		-	-675.77
			7,513.34	3,829.37
	SPECIAL NETT ITEMS			
- 1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
	REAR LICENCE PLATE (SN)	BENT	20.00	15.00
	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	450.00	120.00
			850.00	425.00
	LABOUR			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		150.00	90.00
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	
	TO DISMANTLE & REFIX PETROL TANK.		100.00	60.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS, REAR FENDERS AND REAR CHASSIS MEMBER O/S.		2,000.00	1,400.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,080.00
			5,060.00	3,030.00
	GRAND TOTAL		13,423.34	7,284.37

RECOMMENDED COST OF LUMP SUM REPAIRS	5,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC6/DAI17024439/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.