

Not Authored
L1 Page 8

Vehicle No.:	SHD 9759U - CANDY
Chassis No.:	VF1ABL15AUC276883
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	21.12.2017
Third Party Insurer :	AIG

PART			LIST	
1	1	BUMPER COVER REAR	\$	CM 1,108.46 —
2	1	BUMPER LOWER REAR	\$	PS 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	SL 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	SL 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	SL 44.99 X
6	1	BUMPER REFLECTOR RH	\$	CM 43.61 —
7	1	BUMEPR BRACKET SIDE LH REAR	\$	SL 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	SL 44.99 X
9	1	BUMPER REFLECTOR LH	\$	SL 43.61 X
10	1	BUMPER BEAM REAR	\$	777.52 7
11	1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	225.95 7
13	1	BOOT REAR	\$	R 2,872.68
14	1	BOOT FINISHER	\$	SL 470.06
15	1	BOOT WHEATERSTRIP	\$	SL 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	SL 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	SL 493.35
18	1	BOOT BADGE 'RENAULT'	\$	SL 225.36
19	1	BOOT BADGE	\$	SL 225.36
20	1	BOOT SWITCH	\$	SL 168.13
21	1	BOOT LOCK	\$	R 202.67
22	1	BOOT LOCK CATCH	\$	R 74.40
23	2	LICENCE PLATE LAMP	\$	SL 50.52
24	2	BOOT RUBBER PLUG	\$	SL 221.81
25	1	FENDER PANEL INNER TRIM REAR RH	\$	SL 671.45
26	1	FENDER PANEL REAR RH	\$	R 3,299.13
27	1	WHEELARCH REAR RH	\$	SL 543.47
28	1	TAILLAMP RH	\$	SL 552.55
29	1	TAILLAMP PANEL RH	\$	R 986.70
30	1	TAILLAMP LH	\$	SL 552.55
31	1	TAILLAMP PANEL LH	\$	R 986.70
32	1	OUTER PANEL REAR (End Panel)	\$	R 1,471.77
33	1	OUTER PANEL REAR (End Panel)TRIM	\$	SL 404.56
34	1	EXHAUST REAR	\$	R 7,489.05

35	1	EXHAUST CAP REAR	\$	230.49
----	---	------------------	----	--------

TOTAL	\$	26,678.51
10%	\$	2,667.85
	\$	24,010.66

Specical Nett

1	1SET	PARKING AID	\$	<i>Shon</i> 700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i> 20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>nn</i> 20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00	—
10	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	<i>nn</i> 24.20	
12	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i> 30.00	
13	1	BOOT STICKER "6555-3333"	\$	<i>nn</i> 30.00	
14	1	BOOT INNER TRIM CLIP	\$	<i>nn</i> 45.00	
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00	
16	1	FENDER INNER TRIM CLIP RH	\$	<i>nn</i> 28.00	
17	1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
18	2	REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
19	1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i> 385.00	
22	1	SPARE TYRE	\$	<i>Sn</i> 330.00	

TOTAL	\$	2,157.02
TOTAL PARTS	\$	26,167.68

Putty And Spray Painting Of The Affected Portion.	\$	<i>2200</i> 3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>2000</i> 2,800.00
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

TOTAL	\$	7,710.00
Over All Total	\$	33,877.68

(PARTS BY PARTS)
Repair Days

10 Days
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: