



# 吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: [KIVILEPC@GMAIL.COM](mailto:KIVILEPC@GMAIL.COM) WEBSITE: [KIVILEPC.COM](http://KIVILEPC.COM)

ROC NO.: 53114844X GST REG NO.: M90370110N

VEHICLE NO: JJS1672 MODEL: YAMAHA LC135

HANDLE BAR	/ BT	110	/
BAR HOLDER	X NN	75	X
HANDLE GRIP	X	38	X
HANDLE BALANCE	- Cut	35	/
MIRROR	- Cut	55	/
TOP FAIRING	- SCR	135	/
FRONT FAIRING	- CPA	135	/
CENTER FAIRING	- CPA	135	/
SIDE FAIRING LH	- CPA	195	/
SIDE FAIRING RH	/ Cut	195	/
FRONT MUDGUARD	- Cut	85	/
FORK LOWER CLAMP	X NN	160	X
FORK SET	Repair - BT	440	120 (local repair) (SN)
FRONT RIM	X NN	250	X
RADIATOR	- Cut BT	280	/
RADIATOR HOLDER	- BT	100	/
AIR INTAKE	/ mis	145	/
FRONT FOOTREST	X	45	X
RUBBER FOOTREST	X	38	X
REAR FOOTREST LH	X	45	X
REAR FOOTREST HOLDER LH	X NN	75	X
GEAR LEVER	X	65	X
CHAIN COVER	X	38	X
REAR BOX	/ Cut	135	/
EXHAUST PROTECTOR S	- BT	75	/
EXHAUST PROTECTOR B	- BT	95	/
IU UNIT	/ Scr	165	/
TRANSPORT		50	40
BODY ALIGHTMENT		280	X NN
LABOUR		350	150
		4024	

3 Days.

lumpsum repair

After repair photos.

Eric Qiap - 82860282

27/12/17

2e75  
10%: 1867.5

SN: 12e  
labour: 190

2177.5

20%: 1700

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: