

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 7678Z

DATE 26/12/2017 10:10

MAKE :

DOA: 23.12.2017

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>X repair</i>			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip X			\$ 22.00	
	Rear Bumper Sponge X			\$ 137.40	
	Rear Bumper Under Cover X			\$ 185.80	
	Rear Bumper Protector (LH/RH) X		\$ 38.00	\$ 76.00	
	SUB TOTAL			\$ 1,482.90	
	LESS 20%			\$ 296.58	
	DISCOUNTED TOTAL			\$ 1,186.32	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 350.00 ¹⁰⁰	
	Spray Painting Charge			\$ 200.00 ¹⁸⁰	
	Wiring Charge			\$ 50.00 X	
	Remove/Refix Reverse Sensor			\$ 120.00 X	
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 2,092.02	
	<i>Kaluar 16/1/14</i>				
	<i>26/12/14 1100hr</i>				
	<i>2 Pys</i>				
	<i>PIP</i>				
	<i>After Repair</i>				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Larry Ng