

Hsiao Tong (LKKAuto)

From: Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>
Sent: Friday, 16 March 2018 4:50 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: <Seek Instruction> Your ref: 7846650801SG *Our Ref: CC3/LCR17024451/K1pb3 [ACCIDENT INVOLVING SLL 7110P(OI - LCRF) & SHA 1917Z(TP) ON 22/12/2017]

Have reviewed. Please proceed to settle at best.

Regards,

Ng Hai Chuan AIG

Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994| Fax +68357416

Hai-Chuan.Ng@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Saturday, March 10, 2018 3:52 PM
To: Ng, Hai-Chuan
Subject: <Seek Instruction> Your ref: 7846650801SG *Our Ref: CC3/LCR17024451/K1pb3 [ACCIDENT INVOLVING SLL 7110P(OI - LCRF) & SHA 1917Z(TP) ON 22/12/2017]

Your ref: **7846650801SG**
Our Ref: CC3/LCR17024451/K1pb3

Dear Mr Ng,

ACCIDENT INVOLVING SLL 7110P(OI - LCRF) & SHA 1917Z(TP) ON 22/12/2017

We refer to the above matter.

Third party reported that he was turning left from Tampines St 12 to Tampines Ave 10. He was at the outer right lane and travelling straight after turning. Suddenly OID side-swipe on his left.

OID reported that he made a left turn on the inner left lane. Suddenly third party collided onto his car.

Attached here with a copy of third party's video footage for your easy reference. From the video footage, third party turned into outer right lane and suddenly there was a jerk. The damages to third party vehicle

was on the left front portion(fender - dented). We are of the opinion that it is likely that OID was making a wider turn, encroached into third party's lane and resulted the collision.
Therefore, we would like to propose to settle the matter at best.

For your comments/instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.