

22/03/2002

ASS. REC. BY:

REF: CS/AIG/17024453/ Srd3e2

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

9:41am @ 27/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 8287S

Insured:

at Workshop m/s

Tong Luek Auto

Tel:

6250 0088

of 160 Sin Ming Drive # 07-01/06

Policy No:

Claim No:

0909664957SG

Sum Insured:

Excess:

TBA \$1200

Make of Veh:

(Client's Record)

D.O.A.

14/12/17

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:30am @ 27/12/17

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction

✓ Estimate

GBD 8287S - X

Sent preli through menmen; pending mandate

Mandate revoked; recent IA and seek mandate

4/1/18

Mandate approve; Inform Kpanner to proceed to repair; LH rear door has been disallow by insurance

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ 74K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBD 8287 S. Yr Regn: 26/5/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Citan 109 C.C. 1461

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 16463 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF 41560524/47732

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: N/A S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front R/Bal. 6 mm

Rear R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/12/2017 D.O.I. 27/12/2017

Survey held at Tong Luch.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

13/2/18 Sebastian confirmed final by \$7784.20 with repaire. (Red 6411.80, 45%)

operation@office4auto.com.sg

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

2) _____

Add Fee: ☐ Site Insp (\$ _____) \$ S + RS. \$ SI

Transportation:

☐ Interview (\$ _____) Photos☐ Tech. Invs (\$ _____) Others☐ Weekend (\$ _____)

Report Format : OD

Lump Sum / (B): (\$ 7784.20)

TOTAL

210

Survey Department Check List (Case Handler)

Reference No.: CG 11617024453 Grd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Nivitha): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Sebastian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Sebastian 10/5/18
Case Handler Date

- FW: Estimated repair cost for repairing of vehicle GBD8287S (Own Damaged Claim)

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Wednesday, 27 December, 2017 9:41:02 AM
Attachments:  GBD8287S-Estimate.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

-----Original Message-----

From: Operation / Candy Ong [mailto:operation@tlauto.com.sg]
Sent: Tuesday, December 26, 2017 2:39 PM
To: Chin, Lee-Ying
Cc: tlauto@singnet.com.sg
Subject: Estimated repair cost for repairing of vehicle GBD8287S (Own Damaged Claim)

Dear Lee Ying,

Please find attached documents for your information and necessary action.

The vehicle is now garage at our workshop

Kindly arrange your surveyor to inspect the vehicle at an earlier date

Best Regards,
Candy Ong
Tong Luck Auto Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17024453/Srd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 27-12-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	GBD 8287S
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From CHIN LEE YING	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/12/2017	Inspection Date
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 28 Dec 2017

Preliminary Advice

Vehicle No	: GBD8287S	Accident Date	: 14/12/2017
Make	: MERCEDES-BENZ CITAN 109 CDI VAN	Policy No.	:
Assignment Date	: 28/12/2017	Excess	: S\$1,200.00
Date of Inspection	: 27/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,196.00
Revised Amount	:S\$	6,698.50
Check Items (Estimated)	:S\$	4,974.20
Total	:S\$	11,672.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	39,253.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,747.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

***GBD8287S (0909664957SG)**

OD

Dec 14 2017 8:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/01/2018 12:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - GBD8287S - Claim Handler: Loo, Tong Shing

Maintained: Labour 36 R & R radiator and condenser to take out. (support panel not affected) LH rear door to repair. (top portion severe dent not consistent) kindly take out above items and revert mandate.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 03 Jan 2018

Preliminary Advice

Vehicle No	: GBD8287S	Accident Date	: 14/12/2017
Make	: MERCEDES-BENZ CITAN 109 CDI VAN	Policy No.	:
Assignment Date	: 28/12/2017	Excess	: S\$1,200.00
Date of Inspection	: 27/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,196.00
Revised Amount	:S\$	6,598.50
Check Items (Estimated)	:S\$	5,074.20
Total	:S\$	11,672.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	39,253.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,747.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, January 04, 2018 3:57 PM
To: 'operation@tlauto.com.sg'
Cc: SUR; Sebastian Yeang (LKK Auto)
Subject: GBD 8287S

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBD 8287S (excess \$1,200/-)**. Please note that the item **20. Rear Door LH** has been disallow from insurance.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***GBD8287S (0909664957SG)**

OD

Dec 14 2017 8:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/01/2018 15:16 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6598.50) - GBD8287S - Claim Handler: Loo, Tong Shing

Approved:6598.50:LH rear door disallow - To repair. Re-inspection to be done for damage check and supplementary items / labour.

Print Received Message

This mail is associated with :

***GBD8287S (0909664957SG)**

OD

Dec 14 2017 8:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/12/2017 14:38 PM.
To LKK_HQ
Subject GBD8287S / OD / 14/12/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$1200.00

Thank you
Loo, Tong Shing

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3778Z

Vehicle Details

Vehicle No.: GBD8287S

Vehicle to be Exported: No

Intended De-registration Date: 28 Dec 2017

Vehicle Make: MERCEDES BENZ

Vehicle Model: CITAN 109 CDI VAN EXTRA-LONG - 2 SEATERS

Primary Colour: White

Manufacturing Year: 2014

Engine No.: K9KB608D354462

Chassis No.: WDF4156052U147732

Maximum Power Output: -

Open Market Value: \$23,615.00

Original Registration Date: 26 May 2015

First Registration Date: 26 May 2015

Transfer Count: 0

Actual ARF Paid: \$1,181.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 May 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$53,001.00

COE Rebate Amount: \$39,253.00

Total Rebate Amount: \$39,253.00

The information contained herein is correct as at 28 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/12/2017 12:37
Date Of Accident	14/12/2017 09:00
Exact Location Of Accident	KPE PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD8287S
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68498357

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CITAN 109 CDI VAN EXTRA-LONG - 2 SEATERS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	NUR MUHAMMAD BIN ABDUL RAZAK
NRIC No	S8208037F
Date Of Birth	09/03/1982
Occupation	OUTDOOR
Date Of Driving Pass	04/03/2005
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93631839
Fax Number	
Contact Number	
EEmail Address	NURMD@THEPESTMAN.COM.SG

Vehicle Make/Model/Colour

NISSAN/ SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR/GREY

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ADRIAN LIM

NRIC/Passport Number

S7821659Z

Contact Number

81136008

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

ACCIDENT STATEMENT (2000 characters)

Was driving along the said location, on the centre lane of three lane road. Vehicle ahead of suddenly brake. I unable to stopped in time despite applying my brake. My front portion collided onto the rear of vehicle c, in a spilt second vehicle b on my rear collided onto my vehicle. Three vehicle was involve, there was no injuries.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Reporting only

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M Z 400

COMPREHENSIVE COMMERCIAL MOTOR

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1200.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

CERTIFICATE NO. 999995180/100776831-00000

SUM INSURED S\$1.00

INSURING WITH COE/PARF Yes

GBD8287S

1) VEHICLE REGISTRATION NO.

Daimler Fleet Management Singapore Pte Ltd

2) NAME OF INSURED

**3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT**

01 Jan 2017

4) DATE OF EXPIRY OF INSURANCE

31 Dec 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Insured's order or with their permission.

Please refer to policy terms and conditions.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use for the carriage of passengers or goods in connection with the Insured's business. Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.

The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired. 4) Use for any purpose in connection with the Motor Trade.

SOLE AGENT'S WORKSHOP: For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop.

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118)
2. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
3. Ethoz - 30 Bukit Batok Cres (Tel: 66547777)
4. DPS Body & Paint (Subsidiary of C&C) - 209 Pandan Gardens (Tel: 65684501)
5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)
6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Not Included

*** NAMED DRIVER** NA

HIRE PURCHASE COMPANY NA

**Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 09 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

030023-000
JARDINE LLOYD THOMPSON PTE LTD
138 MARKET STREET
#07-01 CAPITAGREEN
SINGAPORE 048946

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPIUS

5894370

88208037F

01-06-2008

SECRET



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 14/12/2017

ESTIMATE

NO : QUOT201712-0068(00)

DATE : 21/12/2017

POLICY NO : 999995580

VEH REG NO : GBD8287S

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI VAN EXTRA-LONG - 2
SEATERS

CHASSIS NO : WDF4156052U147732

ENGINE NO : K9KB608D354462

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD8287S

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Support panel ?	1	438.00	438.00
2 Front grille assy ✓ ?	1	528.00	528.00
3 Front grille base ✓ Deform	1	122.00	122.00
4 Front grille chrome (set) ✓ Cut	1	248.00	248.00
5 Front grille centre emblem ✓ NEC	1	58.00	58.00
6 Front grille centre logo ✓ NEC	1	65.00	65.00
7 Front grille support ?	1	120.00	120.00
8 Headlamp assy - RH / LH LH CRK ✓ RM ?	2	255.00	510.00
9 Front bumper ✓ Deform	1	1,060.00	1,060.00
10 Front bumper inner frame ?	1	285.00	285.00
11 Front bumper reinforcement ?	1	429.00	429.00
12 Front bumper bracket - RH / LH ?	2	45.00	90.00
13 Front bumper lower grille ✓ Deform	1	71.00	71.00
14 Front bumper towing cover ✓ Deform	1	18.00	18.00
15 Front bumper fog lamp - RH / LH ?	2	285.00	570.00
16 Front bumper fog lamp cover - RH / LH ✓ Deform	2	130.00	260.00
17 Front bumper clips ✓ NEC	15	5.50	82.50
18 Front engine under cover ?	1	375.00	375.00
19 Radiator guide ?	1	238.00	238.00
NG-20 Rear door - LH ✓ DT	1	755.00	755.00
X 21 Rear door weatherstrip ✓ NEC	1	205.00	205.00
22 Rear door 'CITAN' emblem - LH ✓ NEC	1	47.00	47.00
23 Rear end panel (inner) ?	1	282.00	282.00
24 Rear end panel (outer) ?	1	494.00	494.00
25 Rear end panel top garnish CRK X	1	280.00	280.00
26 Rear bumper R	1	723.00	723.00
27 Rear bumper towing cover ✓ MS	1	38.00	38.00
28 Rear bumper clips ✓ NEC	15	5.50	82.50
29 Rear bumper pad (set) ✓ CRK	1	380.00	380.00
30 Rear bumper reinforcement ?	1	368.00	368.00
31 Rear bumper reverse sensor cable (with sensor) - set ✓ ANG	1	438.00	438.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 14/12/2017

ESTIMATE

NO : QUOT201712-0068(00)

DATE : 21/12/2017

POLICY NO : 999995580

VEH REG NO : GBD8287S

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI VAN EXTRA-LONG - 2
SEATERS

CHASSIS NO : WDF4156052U147732

ENGINE NO : K9KB608D354462

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD8287S

Description	Quantity	Unit Price	Amount
		S\$	S\$
			9,660.00
		Add 10%	966.00
			10,626.00
SPECIAL NET			
32 Front number plate ✓ SCR	1	40.00	40.00
33 Air-con gas ?	1	55.00	55.00
34 Rear door '4pax' sticker - LH ✓ NEC	1	20.00	20.00
35 Rear door '70km/h' sticker - LH ✓ NEC	1	25.00	25.00
			140.00
LABOUR			
36 To remove and refit radiator assy and air con condenser, to facilitate the repairs	1	150.00	150.00
37 To remove and refit rear bumper sensor	1	100.00	100.00
38 To check and rectify wiring system & focus on lighting	1	80.00	80.00
39 To panel beat and straighten front fender, front chassis frame, LH rear door hinges, RH rear chassis frame, to cut out rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,600.00	1,600.00
40 To spray same on affected areas	1	1,500.00	1,500.00
			3,430.00
		TOTAL	S\$ 14,196.00
		ADD GST @ 7%	993.72
		GRAND TOTAL	S\$ 15,189.72

64193000

SINGAPORE DOLLAR FIFTEEN THOUSAND ONE HUNDRED EIGHTY-NINE AND CENTS SEVENTY-TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian 27/12/2017

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

90036121

sebastianyong@lkkauto.com FOR TONG LUCK AUTO PTE LTD

- Revert

- Excess : TBA

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 14/12/2017

ESTIMATE

NO : QUOT201712-0068(00)

DATE : 21/12/2017

POLICY NO : 999995580

VEH REG NO : GBD8287S

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI VAN EXTRA-LONG - 2
SEATERS

CHASSIS NO : WDF4156052U147732

ENGINE NO : K9KB608D354462

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD8287S

Description	Quantity	Unit Price	Amount	
		S\$	S\$	
PARTS				
1 Support panel ?	1	438.00	438.00	X H
2 Front grille assy. ?	1	528.00	528.00	X N/A
3 Front grille base ✓ Deform	1	122.00	122.00	/
4 Front grille chrome (set) ✓ Cut	1	248.00	248.00	/
5 Front grille centre emblem ✓ NEC	1	58.00	58.00	/
6 Front grille centre logo ✓ NEC	1	65.00	65.00	/
7 Front grille support Repld.	1	120.00	120.00	/
8 Headlamp assy - RH / LH LH CRK ✓ RH ?	2	255.00	510.00	/
9 Front bumper ✓ Deform	1	1,060.00	1,060.00	/
10 Front bumper inner frame Repld	1	285.00	285.00	/
11 Front bumper reinforcement Repld	1	429.00	429.00	/
12 Front bumper bracket RH / LH ?	2	45.00	90.00	X NN
13 Front bumper lower grille ✓ Deform	1	71.00	71.00	/
14 Front bumper towing cover ✓ Deform	1	18.00	18.00	/
15 Front bumper fog lamp - RH / LH Repld.	2	285.00	570.00	285 /
16 Front bumper fog lamp cover - RH / LH ✓ Deform	2	130.00	260.00	/
17 Front bumper clips ✓ NEC	15	5.50	82.50	/
18 Front engine under cover ?	1	375.00	375.00	X NN
19 Radiator guide ?	1	238.00	238.00	R
20 Rear door - LH ✓ DT	1	755.00	755.00	R
21 Rear door weatherstrip ✓ NEC	1	205.00	205.00	/
22 Rear door 'CITAN' emblem - LH ✓ NEC	1	47.00	47.00	/
23 Rear end panel (inner) ?	1	282.00	282.00	X NN
24 Rear end panel (outer) ?	1	494.00	494.00	R
25 Rear end panel top garnish CRK X	1	280.00	280.00	NN
26 Rear bumper R	1	723.00	723.00	R
27 Rear bumper towing cover ✓ MS	1	38.00	38.00	/
28 Rear bumper clips ✓ NEC	15	5.50	82.50	/
29 Rear bumper pad (set) ✓ CRK	1	380.00	380.00	/
30 Rear bumper reinforcement Repld.	1	368.00	368.00	/
31 Rear bumper reverse sensor cable (with sensor) - set ✓ ANG	1	438.00	438.00	/



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 14/12/2017

ESTIMATE

NO : QUOT201712-0068(00)

DATE : 21/12/2017

POLICY NO : 999995580

VEH REG NO : GBD8287S

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI VAN EXTRA-LONG - 2
SEATERS

CHASSIS NO : WDF4156052U147732

ENGINE NO : K9KB608D354462

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD8287S

Description	Quantity	Unit Price	Amount
		S\$	S\$
	10% 5,172.00 /		9,660.00
	10% 517.20 /	Add 10%	966.00
	<u>\$ 5,689.20 /</u>		10,626.00
SPECIAL NET			
32 Front number plate ✓ SCR	1	40.00	40.00
33 Air-con gas ?	1	55.00	55.00
34 Rear door '4pax' sticker - LH ✓ NEC	1	20.00	20.00
35 Rear door '70km/h' sticker - LH ✓ NEC	1	25.00	25.00
			<u>140.00</u> 85 /
LABOUR			
36 To remove and refit radiator assy and air con condenser, to facilitate the repairs	1	150.00	150.00
37 To remove and refit rear bumper sensor	1	100.00	100.00
38 To check and rectify wiring system & focus on lighting	1	80.00	80.00
39 To panel beat and straighten front fender, front chassis frame, LH rear door hinges, RH rear chassis frame, to cut out rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,600.00	1,600.00
40 To spray same on affected areas	1	1,500.00	1,500.00
			<u>3,430.00</u> 2010 /
	<u>\$ 7,178.20</u>		
	XS 1,200.00	TOTAL	S\$ 14,196.00
	7% 6,584.20	ADD GST @ 7%	993.72
	<u>460.89</u>	GRAND TOTAL	<u>S\$ 15,189.72</u>
	<u>7,045.09</u>		

SINGAPORE DOLLAR FIFTEEN THOUSAND ONE HUNDRED EIGHTY-NINE AND CENTS SEVENTY-TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian 27/12/2017

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

90036121

sebastianyong@lkkauto.com FOR TONG LUCK AUTO PTE LTD

- Revert

- Excess : T&A

AUTHORISED SIGNATURE



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8092840

DATE	03/01/2018	PAGE	1
TERM	30 Days Net	SALES TAX	Ong Hai Choon
CUSTOMER REF	GBD828/S	OUR REF	15653

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER : TONGLUJC1

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

Telephone No : 62500088

575722

DELIVER TO:

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722



PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MHA906	817 00 16	B-6G	1 PC	58.00	58.00
2 MHA415	817 00 32	B-0/F	1 PC	122.00	122.00
3 MHA415	880 05 00	B-5J	1 PC	248.00	248.00
4 MHA415	612 43 00	B-3A	1 PC	429.00	429.00
5 MHA415	885 01 25	B-4J	1 PC	285.00	285.00
6 MHA639	741 05 80	B-D-03E	1 PC	205.00	205.00
7 MHA415	885 01 22	B-3E	1 PC	38.00	38.00
8 MHA124	990 04 92	B-12C	15 PCS	5.50	82.50
9 MHA201	758 00 58	1A-01F	1 PC	47.00	47.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT JOB'S PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK

C.V. JOINT
MADE IN JAPAN

Stackis



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8092632

DATE	02/01/2018	PAGE	1
TERM	30 Days Net	SALES TAX	Orig Hai Choon
CUSTOMER REF	GBD8287S	CUR REF	16271

DELIVER TO:

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722



GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: TONGLUCCI
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 62500088

PART NO	PARTICULARS	QTY	QUANTITY	UNIT PRICE	AMOUNT
100005 512 46 00	100005 512 46 00	1	1	368.00	368.00
100005 510 73 35	100005 510 73 35	1	1	438.00	438.00
100005 510 00 25	100005 510 00 25	1	1	71.00	71.00
100005 820 03 56	100005 820 03 56	1	1	285.00	285.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor



C.V. JOINT
MADE IN JAPAN

Stockists



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kelang, #01-01 Min Ghee Building

Singapore 338564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8092147

DATE	27/12/2017	PAGE	1
TERMS	30 Days Net	CALLS/STAMP	Ong Hai Choo
CUSTOMER REF	GBD828/S	OUR REF	1/3/1

DELIVER TO:

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722



GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: TONGLUO

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07 01
SIN MING AUTOCITY
SINGAPORE 575722

575722

Telephone No : 62500088

ROUTE

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
15-026 03 01	160, SIN MING DRIVE #07-01	GB-SC	1 PC	255.00	255.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor



G.V. JOINT
MADE IN JAPAN


Stockists



MITSUBISHI
MOTORS



BMW



Mercedes-Benz



MOTOWA



KIA



GMB



FUCHS



KANAE



bisaSAFE



HYUNDAI



TOYOTA



HONDA



Vauxhall



SUBARU



MAZDA



NISSAN



SUZUKI



ISUZU



MITSUBISHI FUSO



FOTON

DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339594.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8092399

DATE	28/12/2017	PAGE	1
TERM	30 Days Net	SALUTATION	Ong Hai Choor
CUSTOMER REF	GBD8287S	COURTESY	50636

3ST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: TONGLUCCI

TONG LUCK AUTO PTE LTD

160, SIN MING DRIVE #07-01

SIN MING AUTOCITY

SINGAPORE 575722

575722

Telephone No : 62500088

ROUTE

SM3

DELIVER TO:

TONG LUCK AUTO PTE LTD

160, SIN MING DRIVE #07-01

SIN MING AUTOCITY

SINGAPORE 575722



PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
115 826 00 01	Head Bay	GBB-5C	1 PC	255.00	255.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT JOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

IGN & COMPANY'S STAMP


Exclusive Distributor



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



MIN GHEE AUTO PTE. LTD.

**Head Office : 8, Jalan Lembah Kallang, #01-01 Mln Ghee Building
Singapore 339564.**

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

: info@minahae.com

Website : <http://www.minghee.com>

TAX INVOICE

INV NO : 8092880

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

CO REG NO. 198905613E

ACCOUNT NUMBER : TONGJICI

51. सिद्धांत

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

575722

Telephone No : 62500088



PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
885 08 14	885 08 14	1 PC	1	18.00	18.00
885 04 92	885 04 92	15 PCS	15	5.50	82.50
885 02 16	885 02 16	1 PC	1	120.00	120.00
817 00 32	817 00 32	1 PC	1	65.00	65.00
885 02 25	885 02 25	2 PCS	2	130.00	260.00

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

885 08 14

885 04 92

885 02 16

817 00 32

885 02 25

SIGN & COMPANY'S STAMP

DATE _____

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017		28 Dec 2017 12:02 Edit Adj Rpt	\$7,784.20 Edit Estimates	\$7,784.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z, Tel: +6593631839		
Vehicle Reg. No.:	GBD8287S	Date of Loss:	14/12/2017 08:00 - :59
Claim Type:	OD / 0909664957SG	Policy/Cover Note No.:	(Comprehensive)
		Excess:	\$1,200.00
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 09/01/2018]		
Driver/Custodian:	NUR MUHAMMAD BIN ABDUL RAZAK (35 / Male), NRIC: S8208037F, Tel: +6593631839		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (04/01/2018): Alert - Adj Mandate Approved (\$6598.50) - GBD8287S - Claim Handler: Loo, Tong S...
- AIG_SG (02/01/2018): Alert - Adj Mandate Maintained - GBD8287S - Claim Handler: Loo, Tong Shing
- AIG_SG (28/12/2017): GBD8287S / OD / 14/12/2017 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD8287S (0909664957SG)

OD

Dec 14 2017 8:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 16:20	Adjuster Immediate Advice	 Load HTM	☐
2	03/01/18 14:20	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 17:56	General View	 Load JPG	☒
2	28/12/17 17:56	General View	 Load JPG	☒
3	28/12/17 17:56	General View	 Load JPG	☒
4	28/12/17 17:56	General View	 Load JPG	☒
5	28/12/17 17:56	General View	 Load JPG	☒
6	28/12/17 17:56	General View	 Load JPG	☒
7	28/12/17 17:56	General View	 Load JPG	☒
8	28/12/17 17:56	General View	 Load JPG	☒
9	28/12/17 17:56	General View	 Load JPG	☒
10	28/12/17 17:56	General View	 Load JPG	☒
11	28/12/17 17:56	General View	 Load JPG	☒
12	28/12/17 17:56	General View	 Load JPG	☒
13	28/12/17 17:56	General View	 Load JPG	☒
14	28/12/17 17:56	General View	 Load JPG	☒
15	28/12/17 17:56	General View	 Load JPG	☒
16	28/12/17 17:56	General View	 Load JPG	☒
17	28/12/17 17:56	General View	 Load JPG	☒
18	28/12/17 17:56	General View	 Load JPG	☒
19	28/12/17 17:56	General View	 Load JPG	☒
20	28/12/17 17:56	General View	 Load JPG	☒
21	28/12/17 17:56	General View	 Load JPG	☒
22	28/12/17 17:56	General View	 Load JPG	☒
23	28/12/17 17:56	General View	 Load JPG	☒
24	28/12/17 17:56	General View	 Load JPG	☒
25	28/12/17 17:56	General View	 Load JPG	☒
26	28/12/17 17:56	General View	 Load JPG	☒
27	28/12/17 17:56	General View	 Load JPG	☒
28	28/12/17 17:56	General View	 Load JPG	☒
29	28/12/17 17:56	General View	 Load JPG	☒
30	28/12/17 17:56	General View	 Load JPG	☒
31	28/12/17 17:56	General View	 Load JPG	☒

32	28/12/17 17:56	General View	1	Load JPG	☒
33	28/12/17 17:56	General View	1	Load JPG	☒
34	28/12/17 17:56	General View	1	Load JPG	☒
35	28/12/17 17:56	General View	1	Load JPG	☒
36	28/12/17 17:56	General View	1	Load JPG	☒
37	28/12/17 17:56	General View	1	Load JPG	☒
38	28/12/17 17:56	General View	1	Load JPG	☒
39	28/12/17 17:56	General View	1	Load JPG	☒
40	28/12/17 17:56	General View	1	Load JPG	☒
41	28/12/17 17:56	General View	1	Load JPG	☒
42	28/12/17 17:56	General View	1	Load JPG	☒
43	28/12/17 17:56	General View	1	Load JPG	☒
44	28/12/17 17:56	General View	1	Load JPG	☒
45	28/12/17 17:56	General View	1	Load JPG	☒
46	28/12/17 17:56	General View	1	Load JPG	☒
47	28/12/17 17:56	General View	1	Load JPG	☒
48	28/12/17 17:56	General View	1	Load JPG	☒
49	28/12/17 17:56	General View	1	Load JPG	☒
50	28/12/17 17:56	General View	1	Load JPG	☒
51	28/12/17 17:56	General View	1	Load JPG	☒
52	28/12/17 17:56	General View	1	Load JPG	☒
53	28/12/17 17:56	General View	1	Load JPG	☒
54	28/12/17 17:56	General View	1	Load JPG	☒
55	28/12/17 17:56	General View	1	Load JPG	☒
56	28/12/17 17:56	General View	1	Load JPG	☒
57	28/12/17 17:56	General View	1	Load JPG	☒
58	28/12/17 17:56	General View	1	Load JPG	☒
59	28/12/17 17:56	General View	1	Load JPG	☒
60	28/12/17 17:56	General View	1	Load JPG	☒
61	28/12/17 17:56	General View	1	Load JPG	☒
62	28/12/17 17:56	General View	1	Load JPG	☒
63	28/12/17 17:56	General View	1	Load JPG	☒
64	28/12/17 17:56	General View	1	Load JPG	☒
65	28/12/17 17:56	General View	1	Load JPG	☒
66	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
67	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
68	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
69	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
70	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
71	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
72	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
73	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
74	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
75	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
76	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
77	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
78	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
79	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒

80	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
81	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
82	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
83	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
84	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
85	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
86	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
87	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
88	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
89	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
90	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
91	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
92	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
93	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
94	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
95	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
96	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒
97	14/02/18 15:49	Reinspection Photo	1	Load JPG	☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 18:00	Certificate of Insurance	1 Load PDF	
2	28/12/17 18:00	WORKSHOP EST	1 Load PDF	
3	28/12/17 18:00	Insured Persons NRIC & DL	1 Load PDF	
4	03/01/18 14:31	AMENDED MARKED ESTIMATE	1 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page ▼	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	14/12/17 13:02	Accident Statement	1 Load HTM	
2	21/12/17 11:41	Addendum Sheet	1 Load TIF	
3	21/12/17 11:42	Accident Statement Addm. #1	1 Load HTM	

Photos/Images			3 per page ▼	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	14/12/17 12:57	Accident Photo	1 Load JPG	☒
2	14/12/17 12:57	Accident Photo	1 Load JPG	☒
3	14/12/17 12:58	Accident Photo	1 Load JPG	☒
4	14/12/17 12:58	Accident Photo	1 Load JPG	☒
5	14/12/17 12:58	Accident Photo	1 Load JPG	☒
6	14/12/17 12:58	Accident Photo	1 Load JPG	☒
7	14/12/17 12:58	Accident Photo	1 Load JPG	☒
8	14/12/17 12:58	Accident Photo	1 Load JPG	☒
9	14/12/17 12:58	Accident Photo	1 Load JPG	☒
10	14/12/17 12:58	Accident Photo	1 Load JPG	☒
11	14/12/17 12:58	Identification Card	1 Load JPG	☒
12	14/12/17 12:58	Identification Card	1 Load JPG	☒

Documentation			1 per page ▼	☒
---------------	--	--	--------------	-------------------------------------

					☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	14/12/17 12:57	Sketch Plan		Load JPG	☒
2	14/12/17 12:57	Common Statement		Load TIF	
3	21/12/17 11:41	Individual Statement		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG17024453/SRD3E2

Date: 14/02/2018

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No:

Date of Loss: 14/12/2017

Nature of Claim: OD Claim No: 0909664957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD8287S**
Make & Model: MERCEDES-BENZ CITAN 109 CDI VAN, 1.5 EXTRA LONG 2 SEATERS (A) Engine No: K9KB608D354462
Reg. Date: 26/05/2015 (Man. Year: 2014) Chassis No: WDF4156052U147732
Colour: White Odometer: 104631 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$74,000.00
Price:
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,766.00	5,774.20	4,991.80	46.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,010.00	1,420.00	41.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,196.00	7,784.20	6,411.80	45.17
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	12,996.00	6,584.20	6,411.80	49.34
+ GST 7.00/7.00% (S\$)	909.72	460.89	448.83	49.34
Nett Amount (S\$)	13,905.72	7,045.09	6,860.63	49.34

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 27/12/2017 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUPPORT PANEL (WCP)	Not Necessary	438.00 F	*- F
2	1	*FRONT GRILLE ASSY (WCP)	Not Necessary	528.00 F	*- F
3	1	*FRONT GRILLE BASE (WCP)	Deformed	122.00 F	*122.00 F
4	1	*SET FRONT GRILLE CHROME (WCP)	Cut	248.00 F	*248.00 F
5	1	*FRONT GRILLE CENTRE EMBLEM (WCP)	Necessary	58.00 F	*58.00 F
6	1	*FRONT GRILLE CENTRE LOGO (WCP)	Necessary	65.00 F	*65.00 F
7	1	*FRONT GRILLE SUPPORT (WCP)	Damaged	120.00 F	*120.00 F
8	2	*HEADLAMP ASSY - RH / LH (WCP)	Cracked	510.00 F	*510.00 F
9	1	*FRONT BUMPER (WCP)	Deformed	1,060.00 F	*1,060.00 F
10	1	*FRONT BUMPER INNER FRAME (WCP)	Cracked	285.00 F	*285.00 F
11	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	429.00 F	*429.00 F
12	2	*FRONT BUMPER BRACKET RH/LH (WCP)	Not Necessary	90.00 F	*- F
13	1	*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	71.00 F	*71.00 F
14	1	*FRONT BUMPER TOWING COVER (WCP)	Deformed	18.00 F	*18.00 F
15	1	*FRONT BUMPER FOG LAMP RH / LH (WCP)	O/S Cracked	570.00 F	*285.00 F
16	2	*FRONT BUMPER FOG LAMP COVER - RH/LH (WCP)	Deformed	260.00 F	*260.00 F
17	15	*FRONT BUMPER CLIPS (WCP)	Necessary	82.50 F	*82.50 F
18	1	*FRONT ENGINE UNDER COVER (WCP)	Not Necessary	375.00 F	*- F
19	1	*RADIATOR GUIDE (WCP)	Repair	238.00 F	*- F
20	1	*REAR DOOR - LH (WCP)	Repair	755.00 F	*- F
21	1	*REAR DOOR WEATHERSTRIP (WCP)	Necessary	205.00 F	*205.00 F
22	1	*REAR DOOR CITAN EMBLEM - LH (WCP)	Necessary	47.00 F	*47.00 F
23	1	*REAR END PANEL (INNER) (WCP)	Not Necessary	282.00 F	*- F
24	1	*REAR END PANEL (OUTER) (WCP)	Not Necessary	494.00 F	*- F
25	1	*REAR END PANEL TOP GARNISH (WCP)	Not Necessary	280.00 F	*- F
26	1	*REAR BUMPER (WCP)	Repair	723.00 F	*- F
27	1	*REAR BUMPER TOWING CLIPS (WCP)	Missing	38.00 F	*38.00 F
28	15	*REAR BUMPER CLIPS (WCP)	Necessary	82.50 F	*82.50 F
29	1	*SET REAR BUMPER PAD (WCP)	Cracked	380.00 F	*380.00 F
30	1	*REAR BUMPER REINFORCEMENT (WCP)	Bent	368.00 F	*368.00 F
31	1	*SET REAR BUMPER REVERSE SENSOR CABLE (WITH SENSOR) (WCP)	Damaged	438.00 F	*438.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
32	1	*FRONT NUMBER PLATE	Scratched	40.00 FS	*40.00 FS
33	1	*AIR-CON GAS	Not Necessary	55.00 FS	*- FS
34	1	*REAR DOOR 4 PAX STICKER - LH	Necessary	20.00 FS	*20.00 FS
35	1	*REAR DOOR 70KM/H STICKER - LH	Necessary	25.00 FS	*25.00 FS
F=Franchise part. S=SpcNett.					
Sub Total (S\$)				9,800.00	5,257.00
+ Margin on L,N Items 10.00/10.00% (S\$)				966.00	517.20
Total Parts (S\$)				10,766.00	5,774.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT RADIATOR ASSY AND AIR CON CONDENSER, TO FACILITATE THE REPAIRS	New	150.00	100.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	80.00
3	TO CHECK AND RECTIFY WIRING SYSTEM & FOCUS ON LIGHTING	New	80.00	30.00
4	TO PANEL BEAT AND STRAIGHTEN FRONT FENDER, FRONT CHASSIS FRAME, LH REAR DOOR HINGES, RH REAR CHASSIS FRAME, TO CUT OUT REAR END PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,600.00	800.00
5	TO SPRAY SAME ON AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			3,430.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >