

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05691

Vehicle Insured : SDU6766B
Accident Date : 21-Dec-2017

Date : 22-Dec-2017

Our Ref : 217196 (AIG) / CHAN

PAGE : 1

ROS LI MOHAMED YUSOF
80 EDGEDALE PLAINS
#06-03
Singapore 828735

1st Accident

ESTIMATED COST OF REPAIR FOR BMW 320I SKB7907Y

=====

| | | | |
|-------|----------------------------|-------------|----------------------|
| 1 pc | Rear bumper fascia | | <i>Bu</i> 1,182.00 ✓ |
| 1 pc | Rear bumper tow cover | | <i>sn</i> 19.30 X |
| 2 pcs | Rear bumper parking sensor | @ S\$231.10 | <i>Bu</i> 462.20 X |
| 2 pcs | Parking sensor o ring | @ S\$ 4.95 | 9.90 7 |
| 4 pcs | Parking sensor holder | @ S\$ 62.50 | 250.00 7 |
| 1 pc | Rear bumper reinforcement | | 413.90 7 |
| 1 pc | Rear bumper inner parts | | 50.85 7 |

2,388.15

Less 10% : 238.82

2,149.33

To putty and spray replaced parts

350.00 *2500*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *2200*

To remove & rewire parking sensor
wire

40.00 ✓

Total : S\$ 2,939.33

=====

Singapore Dollars Two Thousand Nine Hundred and
Thirty Nine and Cents Thirty Three Only

Not Applicable

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: