

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$5

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI/GIA REPORT: YES / NO ; TP/GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to Of:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 1350

(4 days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

024/01/18

Confirm with:

Email

Call

Insured Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 1350.00

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

2400 x 60 x 4 days

Loss of Income (LOI):

\$5

(\$ x days)

LCR only

LOU only

LOR + LOU

LOR + LOI

GLA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5 1,997.45

Global Sum \$5:

FINAL PAYMENT

Date/Time:

024/01/18

Confirm with:

Email

Call

Name 1:

\$5

1,997.45

Name 1:

Wei Lee Notes Works

Name 2 (Strike if N.A.):

\$5

Name 2:

Name 3 (Strike if N.A.):

\$5

Name 3:

RECEIVED 28 JAN 2018

COPY SENT
26/1/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17024462/yb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-12-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJD 590Z	Veh. Inspected	SKC 5829Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/12/2017	Inspection Date		
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9, SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

the Repairer of the following:

• To resurvey before/after spray painting
• To display (damaged parts) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

TEL: 456 9830 • FAX: 455 3986
Business Regn No: 269436/00J

22, Dec 2017

Signature:

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 S 079120

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle No: SJD590Z

Accident involving vehicle No: SKC5829Y/SJD590Z

DOA: 19/12/2017 At Multi storey carpark, Parkway Parade

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SKC5829Y

To supply

Description	Qty	Amount
Rear bumper / TN	1	482.00 /
Rear bumper enforcement/sponge / CAA	1	123.50 /
Rear bumper retainer, Rh / KL	1	69.80 /
Rear bumper clip / KL	1	38.00 /
Rear bumper foglamp, Rh X NN	1	37.20 X
End panel X repair	1	580.60 X
End panel top garnish / CAA	1	202.70 /
Taillamp, Rh / CAA	1	918.00 342
Lid X repair	1	618.50 X
Lid reflector, Rh / CAA	1	171.60 /
	Parts	3,241.90
	Parts less 25%	810.47
		2,431.43

Reverse sensor / DM

220.00

To remove damaged parts and attachments.

Repair/reshape dented areas.

Straighten chassis where necessary.

Renew/align all parts into position.

To spray paint.

850.00

750.00

400

500

4 days.

ump sum repair

After repair photos.

Guo Qiang - 82880282

28/12/17.

1429.6
25%: 1072.2

2192.2

20%: 1750

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455-3986 6458 0128
Business Regn No : 269438/00J

22, Dec 2017

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 S 079120

Attn : Motor claim dept-3rd party claim

Claiming against your Insured vehicle No: SJD590Z

Accident involving vehicle No: SKC5829Y/SJD590Z

DOA: 19/12/2017 At Multi storey carpark, Parkway Parade

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SKC5829Y

To supply

Description	Qty	Amount
Rear bumper / TN	1	482.00 ✓
Rear bumper enforcement/sponge / CAA	1	123.50 ✓
Rear bumper retainer, Rh / KCL	1	69.80 ✓
Rear bumper clip / KCL	1	38.00 ✓
Rear bumper foglamp, Rh X SW	1	37.20 X
End panel X Repair	1	580.60 X
End panel top garnish 3 / CAA	1	202.70 ✓
Taillamp, Rh 1 / CAA	1	918.00 ✓
Lid X repair	1	618.50 X
Lid reflector, Rh 3 / CAA	1	171.60 ✓
	Parts	3,241.90
	Parts less 25%	810.47
		2,431.43

Reverse sensor / DM

220.00

To remove damaged parts and attachments.

Repair/reshape dented areas.

Straighten chassis where necessary.

Renew/align all parts into position.

To spray paint.

850.00 400
750.00 500

2605-60
501-40
1504-20
1120
2624-20
524-26
2099-36
4/sum
2012-100

4/sum
2012-100

28/12 Thursday
12:30 PM - 2:30 PM

Guo Qiang
02/1/18

4 days
Lump sum repair
After repair photos.
Guo Qiang - 82880282
28/12/17.

GuoQiang@lkkauto.com

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SKC5829Y
Vehicle to be Exported:	No
Intended De-registration Date:	29 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	3ZZ4785564
Chassis No.:	MR053ZEE106114758
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	31 Aug 2008
First Registration Date:	31 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2018
PARF Rebate Amount:	\$8,388.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2018
COE Category:	A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$12,501.00
COE Rebate Amount:	\$836.00
Total Rebate Amount:	\$9,224.00

The information contained herein is correct as at 29 Dec 2017

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986 6458 0128
Business Regn No : 269436/00J

Jas

Guo Qiang.

02/1/18

22, Dec 2017

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 S 079120

Attn : Motor claim dept-3rd party claim

Claiming against your insured vehicle No: SJD590Z

Accident involving vehicle No: SKC5829Y/SJD590Z

DOA: 19/12/2017 At Multi storey carpark, Parkway Parade

4 days.

umpsum repair

After repair photos.

Guo Qiang - 82880282

28/12/17.

GuoQiang@lkkauto.com

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SKC5829Y

To supply

Description	Qty	Amount
Rear bumper / TN	1	482.00
Rear bumper enforcement/sponge / CAA	1	123.50
Rear bumper retainer, Rh / KL	1	69.80
Rear bumper clip / KL		38.00
Rear bumper foglamp, Rh / R	1	37.20
End panel / Repair	1	580.60
End panel top garnish / CAA	1	202.70
Taillamp, Rh / CAA	1	918.00
Lid / Repair	1	618.50
Lid reflector, Rh / CAA	1	171.60
	Parts	3,241.90
	Parts less 25%	810.47
		2,431.43

Reverse sensor / On

220.00

To remove damaged parts and attachments.

Repair/reshape dented areas.

Straighten chassis where necessary.

Renew/align all parts into position.

To spray paint.

850.00

750.00

400

500.

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 3985~~ 6458 0128

Business Regn No : 269436/00J

24, Jan 2018

AIG Asia Insurance Pte Ltd

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SJD590Z

Accident involving vehicle no: SKC5829Y/SJD590Z

ON 19/12/2017 AT Multi storey carpark, Parkway Parade

Dear officer incharge

We are the workshop for the owner of vehicle no: SKC5829Y

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle.

The claim for vehicle No: SKC5829Y as follow:-

Cost of repair to SKC5829Y	\$ 1,750.00	finalised with your surveyor
Loss of use	\$ 240.00	\$60x4d
LTA search fee	\$ 7.45	

\$ 1,997.35

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG17024462/Gyb3

05 JANUARY 2018

D'ARANJO JOSEPH IRVING LINDSAY
49 YARROW GARDENS
SINGAPORE 455042

Dear Sir/Madam,

**ACCIDENT INVOLVING SKC 5829Y & SJD 590Z ALONG/AT PARKWAY
SHOPPING CENTRE EXITING CARPARK ON 19/12/2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jas Khine
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: jaskhine@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I, KH Leasing Pte Ltd ("the third party claimant") of
261A Upp Thomson Road (address), owner of
8KC 5829Y (vehicle no.) hereby authorize Wei Lee Motor Works
the (workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. 8KC 5829Y that was damaged pursuant to the accident
which occurred 19/12/17 (date) at Multi storey carpark, Parkway Parade (location)
involving vehicle no/s. 8FD 590Z This ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 02 (day) of Jan (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, WEI LEE MOTOR WORKS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,750.00 (Repair Cost), S\$240.00 (Loss of ~~Rental~~/Use) S\$7.45 (Disbursement), for vehicle no. SKC 5829Y that was damaged pursuant to the accident which occurred on 19/12/2017 (date) along PARKWAY SHOPPING CENTRE EXITING CARPARK (location) involving vehicle no/s SJD 590Z.

This is pursuant to the inspection conducted on 28/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KH LEASING PTE LTD ("the third party claimant") of vehicle no. SKC 5829Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKC 5829Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.



This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 24 (day) of Jan (month) 2018 (year)

Signed by appointed surveyor

Signed by "the workshop" (with chop)

  24/1/18

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128

Business Regn No: 269438/00J

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
S079120

INVOICE NO:12521
DATE:24,Jan 2018

PARTICULARS	AMOUNT (\$)
Vehicle No: SKC5829Y	
Cost of repair for vehicle No: SKC5829Y	1,750.00
Lump sum repaired as recommended by your appointed surveyor-LKK Auto Consultants.	<u>1,750.00</u>

Payments to be made by crossed cheque in favour of WEI LEE MOTOR WORKS



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 20 Dec 2017 / 18:01:34

Receipt Date/Time : 20 Dec 2017 / 18:01:34

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171220-001968

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJD590Z				
As at 19 Dec 2017/12:50:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SJD590Z			
	Enquiry Fee	7.00	0.49	7.49
	20171220180036830118			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	20171220180047621	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017 Edit Reg		27 Dec 2017 00:00 Edit Adj Rpt	S\$1,750.00 Edit Estimates	S\$1,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	D'ARANJO JOSEPH IRVING LINDSAY, ID: S1366048D		
Main Claimant:	KH LEASING PTE LTD, Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SKC5829Y	Date of Loss:	19/12/2017 12:00 - :59
Claim Type:	TP / 6208705203SG	Policy/Cover Note No.:	2100067282 (Comprehensive)
Vehicle Reg. No. (Insured):	SJD590Z	Policy No. (Claimant):	5090891147
	Excess:		
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/01/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)































There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKC5829Y (6208705203SG)**
[SJD590Z]
TP
KH LEASING PTE LTD
Dec 19 2017 12:00PM
[D'ARANJO JOSEPH IRVING LINDSAY]
Wei Lee Motor Works

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼	
Letters/Correspondences						1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit			
Assessment Reports						1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	28/12/17 12:03	Accident Statement <small>From: SC - Reg. No: SJD590Z, Claimant: DARANJO JOSEPH IRVING LINDSAY</small>		Load HTM			
Photos/Images						3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
2	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
3	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
4	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
5	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
6	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
7	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
8	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
9	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
10	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
11	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
12	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
13	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
14	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
15	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
16	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
17	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
18	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
19	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
20	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
21	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
22	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
23	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
24	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
25	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
26	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
27	25/01/18 14:58	General View		Load JPG	<input checked="" type="checkbox"/>		
28	25/01/18 14:58	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		

29	25/01/18 14:58	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
30	25/01/18 14:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	25/01/18 14:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/12/17 16:14	EMAIL FROM AIG DD 27122017	1	Load PDF	
2	27/12/17 16:14	TP EST & GIA REPORT	1	Load PDF	
3	29/12/17 15:07	TP ESTIMATE- MARKED	1	Load PDF	
4	01/02/18 08:47	WORKSHOP INVOICE	1	Load PDF	
5	01/02/18 08:47	AUTHORISATION TO ACT FORM	1	Load PDF	
6	01/02/18 08:47	Release Voucher	1	Load PDF	
7	01/02/18 08:47	LTA SEARCH	1	Load PDF	
8	01/02/18 08:47	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJD590Z (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SKC5829Y (TP veh)		1.6 (A)
Date of Accident:	19/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,251.42
Final Repair Cost	:	\$	1,750.00
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,997.45

4.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Wei Lee Motor Works	:	\$ 1,997.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

01 Feb
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17024462/GYB3Q2

Date: 01/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100067282
 Claimant Vehicle No: SKC5829Y Insured Vehicle No: SJD590Z
 Date of Loss: 19/12/2017 Nature of Claim: TP Claim No: 6208705203SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC5829Y
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4785564
 Reg. Date: 31/08/2008 (Man. Year: 2008) Chassis No: MR053ZEE106114758
 Colour: Black Odometer: 191578 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,651.42	1,292.20	1,359.22	51.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	900.00	700.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,251.42	2,192.20	2,059.22	48.44
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	4,251.42	1,750.00	2,501.42	58.84
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,997.45		

INSPECTION

Date of Assignment: 27/12/2017
 Date Inspected: 28/12/2017 Inspected At: Wei Lee Motor Works (HQ)
 BLOCK 9 SIN MING INDUSTRIAL
 ESTATE #01-32
 Singapore 575644
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	482.00 FL	*482.00 FL
2	1		*REAR BUMPER ENFORCEMENT /SPONGE	Cracked	123.50 FL	*123.50 FL
3	1		*REAR BUMPER RETAINER ,RH	Necessary	69.80 FL	*69.80 FL
4	1		*REAR BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
5	1		*REAR BUMPER FOGLAMP ,RH	Serviceable	37.20 FL	*- FL
6	1		*END PANEL	Repair	580.60 FL	*- FL
7	1		*END PANEL TOP GARNISH	Cracked	202.70 FL	*202.70 FL
8	1		*TAILLAMP, RH	Cracked	918.00 FL	*342.00 FL
9	1		*LID	Repair	618.50 FL	*- FL
10	1		*LID REFLECTOR ,RH	Cracked	171.60 FL	*171.60 FL
11	1		*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,461.90	1,649.60
- List Item Discount on L Items 25.00/25.00% (S\$)	810.48	357.40
Total Parts (S\$)	2,651.42	1,292.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS ,REPAIR/RESHAPE DENTED AREAS ,STRAIGHTEN CHASSIS WHERE NECESSARY ,RENEW/ALIGN ALL PARTS INTO POSITION	New	850.00	400.00
2	RENEW /ALIGN ALL PARTS INTO POSITION	New	750.00	500.00
Gross Labour Cost (S\$)			1,600.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >