

12/03/2002

ASS. REC. BY:

REF: CS/EGI17024463/Nrd307 Special Instruction:

Surveyor

Sebastian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

4:12pm @ 27/12/17

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGH 6754T

Insured:

YM 7813K

at Workshop m/s

Lai Huet (Meng Kee)

Tel:

6453 8110

of

160 Jin Ming Drive #04-01

Policy No:

Claim No:

DSMFPI703060

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:21am @ 27/12/17

Person Contacted:

Jenny

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGH 6754T-X

YM 7813K-CC4/AIG09010276/Kn1vn

D.O.A: 06/05/2009

24/1/18

Sent preli through email.

15/4/18

Confirm with Jenny L/S \$5850.00 @ 12 days (Red: \$1755.40, 23%)

REF:

31604

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGH 67547 Yr Regn: 17/6/2006Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Uvis C.C. 1497Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 107675 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR055174204192577 (Door JM, No Chassis Number Photo)Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175 / 65 R14R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 22/12/2017 D.O.I. 27/12/2017Survey held at Lai Huat Meng KeeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

RECEIVED 15 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final ReportDays Of Repair: 12Resurvey No. of Trip: 1Survey Fee: 250

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

2)

Report Format :

Lump Sum / L.B.T. (\$) TP 5850Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

250

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 26 December, 2017 4:12 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YM7813K / TP : SGH6754T/LKK / DOA : 22/12/2017 (DSMFP1703060)
Attachments: YM7813K - SAS.pdf; SGH6754T - SAS.pdf; SGH6754T - ESTIMATE.pdf; SGH6754T - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LAI HUAT (MENG KEE) MOTOR PTE LTD**,

ADDRESS : BLK 160 SIN MING DRIVE
#04-01 SIN MING AUTOCITY
SINGAPORE 575722

PERSON TO CONTACT : JENNY @ 6453 8110

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.


Attached are estimate, insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?

TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO

TravelProtect

your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Plc. Ltd.



BUY NOW




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17024463/Srd3		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 27-12-2017		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 7813K	Veh. Inspected	SGH 6754T	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMFP1703060	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2017	Inspection Date	27/12/2017	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2017 11:55
Date Of Accident	22/12/2017 16:05
Exact Location Of Accident	MARGARET DR (NEAR LAMP POST 49)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH6754T
Insured/Policyholder	
Name Of Registered Owner	SEBASTIAN STELLA
NRIC No	S1693160H
Email Address	STEL_SEB@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96227969
Alternative Phone No	OTHERS-96227969

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	0100648675-11000
Cover Note Number	

Driver

Name of Driver	SEBASTIAN STELLA
NRIC No	S1693160H
Date Of Birth	11/06/1965
Occupation	INDOOR
Date Of Driving Pass	27/04/1994
Driving Experience	23 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96227969
Fax Number	
Contact Number	OTHERS-96227969
EEmail Address	STEL_SEB@YAHOO.COM.SG

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 23/12/17
12.10 pm.

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: S6927273H

REPUBLIC OF SINGAPORE DRIVING LICENCE

1693160H

SEBASTIAN STELLA

Birth Date: 11 Jun 1965
Issue Date: 10 May 2003

000469556D



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1693160H

Name
SEBASTIAN STELLA

செபஸ்தியன் ஸ்டெல்லா

Race
INDIAN

Date of Birth
11-06-1965

Sex
F

Country of Birth
SINGAPORE




S1693160H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	PASS DATE
Class 3		27 Apr 1994

NP 428A

Licence No: S1693160H



1285821

33664

NRIC No. S1693160H



Blood Group
A-

Date of issue
16-09-1993

APT BLK 90 DAWSON ROAD #17-14
SINGAPORE 142090

NRIC No: S1693160H

Date: 04/04/2016

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3160H

Vehicle Details

Vehicle No.: SGH6754T

Vehicle to be Exported: Yes

Intended De-registration Date: 23 Dec 2017

Vehicle Make: TOYOTA

Vehicle Model: VIOS 1.5E A

Primary Colour: Silver

Manufacturing Year: 2006

Engine No.: 1NZX443330

Chassis No.: MR053HY4204192517

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,707.00

Original Registration Date: 19 Jun 2006

First Registration Date: 19 Jun 2006

Transfer Count: 0

Actual ARF Paid: \$13,978.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$23,227.00

COE Rebate Amount: \$16,203.00

Total Rebate Amount: \$16,203.00

Message

Thank you



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 23 Dec 2017, 11:53:32.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	YM7813K	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	23 Dec 2017 / 11:54:06

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Reg No : 196700086Z
Reg No : MR-8500000-9

TAX INVOICE

Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
Bodyshop Retail Cash Sales Pandan TCBC Toyota	c0110038/PBPREG	Ms Sebastian Stella
Bodyshop Retail Cash Sales	Document No	90 Dawson Road
Pandan TCBC Toyota	38021209	#17-14
	Document Date	Singapore 142090
	23/12/2017	Mobile: 96227969

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
2006	EEPSKT FL	NCP42R	19/06/2006	SGH6754T	107486	28910	66/CASH/SGH6754T
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
053HY4204192517	1NZX443330	00	Shashitharan	--/--/----	0.00	--/--/----	0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
B	BP-LAB TOWING FEES *				80.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.					

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	80.00
		Labour 0.00	GST 7.00%
		Materials 80.00	Less
		Lubrication/Fluid 0.00	0.00
		Others 0.00	
		0.00	Amount Due
			85.60

PLEASE TEAR ALONG PERFORATED LINE

3545077

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3160H
Vehicle Details	
Vehicle No.:	SGH6754T
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX443330
Chassis No.:	MR053HY4204192517
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,707.00
Original Registration Date:	19 Jun 2006
First Registration Date:	19 Jun 2006
Transfer Count:	0
Actual ARF Paid:	\$13,978.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	18 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$16,141.00
Total Rebate Amount:	\$16,141.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Dec 2017

OK

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 1 of 3
Your ref. TP-YM 7813K ERGO
Job No. 69102
Our ref. 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on ... 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front fender LH ✓ DT	170.60	25.00	127.95
1.00	Pc	Front fender inner shield LH ✓ Deform	23.50	25.00	17.63
10.00	Pcs	Front fender inner shield clips LH ✓ NEC	3.00	25.00	22.50
1.00	Pc	Front fender signal lamp LH ✓ CRK	25.50	25.00	19.13
1.00	Pc	Front fender top side cover LH ✓ cut	25.90	25.00	19.43
1.00	Pc	Front door LH ✓ PUN	1,208.00	25.00	906.00
1.00	Pc	Front door protector LH ✓ BT	58.90	25.00	44.18
1.00	Pc	Front door outer moulding LH ✓ NEC	29.90	25.00	22.43
1.00	Pc	Front door outer lock handle LH ✓ MS	61.95	25.00	46.46
1.00	Pc	Front door outer key lock cover LH ✓ MS	24.35	25.00	18.26
1.00	Pc	Front door lock LH ✓ DMG	415.40	25.00	311.55
1.00	Pc	Front door window weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Front door key lock LH ✓ DMG	93.50	25.00	70.13
1.00	Pc	Front door outer handle holder LH ✓ MS	148.30	25.00	111.23
1.00	Pc	Front door window glass LH ✓ CRK	102.20	25.00	76.65
1.00	Pc	Front door window regulator LH 3 X NN	110.90	25.00	83.18
1.00	Pc	Front door window channel LH ✓ BT	88.20	25.00	66.15
1.00	Pc	Front door top hinge LH ✓ BT	87.30	25.00	65.48

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 2 of 3
Your ref. TP-YM 7813K ERGO
Job No. 69102
Our ref 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on ... 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00	Pc	Front door lower hinge LH ✓ BT	83.10	25.00	62.33
1.00	Pc	Front door wing mirror LH assy ✓ MS	175.90	25.00	131.93
1.00	Pc	Front door weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Rear door LH ✓ Deform.	1,295.14	25.00	971.36
1.00	Pc	Rear door protector LH ✓ NEC	49.80	25.00	37.35
1.00	Pc	Rear door top hinge LH ✓ BT	87.20	25.00	65.40
1.00	Pc	Rear door lower hinge LH ✓ BT	83.10	25.00	62.33
Nett item:					
1.00	Pc	Front fender signal lamp chrome ring LH ✓ cut	25.00	10.00	22.50
1.00	Pc	Front sport rim LH (14") ✓ cut	200.00	10.00	180.00
Special nett item:					
1.00	Pc	Front tyre LH (Michelin-175 65 R14) 80% ✓ Pun ✓	130.00	10%	130.00
Labour & Misc: 5 x NN					
1.00		Towing charge ✓	80.00		80.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 3 of 3
Your ref. TP-YM 7813K ERGO
Job No. 69102
Our ref 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model .. Toyota Vios
Accident on ... 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To check wheel alignment	60.00	✓	60.00
1.00		To remove and refix front and rear passenger seat, carpet, etc	150.00 120.		150.00
1.00		To knock dents front door pillar LH, front door inner pillar LH, centre pillar LH, centre inner pillar LH, rocker panel LH and renew of parts	1,100.00 1000		1,100.00
1.00		To spray paint	1,100.00 1100		1,100.00

12 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian
27/12/2017.

- Lump Sum Repair.
- Photo After Paint.
- Question Mark Item Photo.

90036121
sebastianyeang@lkkauto.com.

Sub-Total
GST 7.00%

Total

4467.54
- 25%
3350.66
+ 202.5
+ 2464.0
6017.16
- 20%
4813.73

7605.40
6,256.40
437.95
6,694.35

∴ L/s \$4800 @ 12 days

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

626-32

7605.40

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

SUPPLEMENTARY

EST. No EST0018136
Sebastian Stella

Page 1 of 1
Your ref. : TP-YM 7813K ERGO
Job No : 69102
Our ref : 17.12.32
Payment :
Date : 10/1/2018

Attn

Vehicle No SGH 6754T
Vehicle Model . Toyota Vios
Accident on . 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts.					
SUPPLEMENTARY ITEM.					
2.00	Pcs	Front shock absorber	444.80 222.40	25.00	333.60
2.00	Pcs	Rear shock absorber	350.6 175.30	25.00	262.95
2.00	Pcs	Front shock absorber support	124.40 62.20	25.00	93.30
2.00	Pcs	Suspension arm	452.2 226.10	25.00	339.15
1.00		Labour to remove and renew suspension, etc	320.00		320.00

Sub-Total 1,349.00
GST 7.00% 94.43
Total S\$ 1,443.43

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC Deluxe oven heater for re-spraying all motor vehicles."

Janice Lee (LKKAuto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Wednesday, November 07, 2018 4:11 PM
To: SUR
Subject: FW: Finalisation - SGH 6754T / Toyota Vios
Attachments: SGH 6754T.pdf; IMG_3200.jpg; IMG_3201.jpg; IMG_3202.jpg; IMG_3203.jpg; IMG_3568.jpg; IMG_3569.jpg; IMG_3570.jpg; IMG_6110.jpg; IMG_6111.jpg; IMG_6112.jpg; PHOTO-2018-02-08-09-05-27.jpg; PHOTO-2018-02-08-09-05-28 (1).jpg; PHOTO-2018-02-08-09-05-28 (2).jpg; PHOTO-2018-02-08-09-05-28.jpg; PHOTO-2018-02-08-09-05-29 (3).jpg; PHOTO-2018-02-08-09-05-29.jpg

Importance: High

Dear Sir

For your confirmation, please.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Wednesday, 29 August, 2018 3:10 PM
To: sebastianyeang@lkkauto.com
Cc: sur@lkkauto.com
Subject: Finalisation - SGH 6754T / Toyota Vios

Dear Sir

- Parts: \$4,665.40 (include supplementary)
- SN: \$ 104.00
- L&P: \$2,680.00 (include supplementary)

Sub-total: \$7,449.40

LS -20%: (\$1,489.88) = \$5,959.52

Lump Sum: \$5950.00 / 15 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 1 of 3
Your ref. TP-YM 7813K ERGO
Job No. 69102
Our ref. 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on .. 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Front fender LH ✓ BT	170.60	25.00	127.95
1.00	Pc	Front fender inner shield LH ✓ De Form	23.50	25.00	17.63
10.00	Pcs	Front fender inner shield clips LH ✓ NEC	3.00	25.00	22.50
1.00	Pc	Front fender signal lamp LH ✓ CRK	25.50	25.00	19.13
1.00	Pc	Front fender top side cover LH ✓ cut	25.90	25.00	19.43
1.00	Pc	Front door LH ✓ PUN	1,208.00	25.00	906.00
1.00	Pc	Front door protector LH ✓ BT	58.90	25.00	44.18
1.00	Pc	Front door outer moulding LH ✓ NEC	29.90	25.00	22.43
1.00	Pc	Front door outer lock handle LH ✓ ms	61.95	25.00	46.46
1.00	Pc	Front door outer key lock cover LH ✓ ms	24.35	25.00	18.26
1.00	Pc	Front door lock LH ✓ DMG	415.40	25.00	311.55
1.00	Pc	Front door window weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Front door key lock LH ✓ DMG	93.50	25.00	70.13
1.00	Pc	Front door outer handle holder LH ✓ ms	148.30	25.00	111.23
1.00	Pc	Front door window glass LH ✓ CRK	102.20	25.00	76.65
1.00	Pc	Front door window regulator LH ? PHOTO	110.90	25.00	83.18
1.00	Pc	Front door window channel LH ✓ BT	88.20	25.00	66.15
1.00	Pc	Front door top hinge LH ✓ BT	87.30	25.00	65.48

2065.77

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 2 of 3
Your ref. TP-YM 7813K ERGO
Job No 69102
Our ref 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model . Toyota Vios
Accident on : 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Front door lower hinge LH ✓ BT	83.10	25.00	62.33
1.00	Pc	Front door wing mirror LH assy ✓ MS	175.90	25.00	131.93
1.00	Pc	Front door weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Rear door LH ✓ Deform	1,295.14	25.00	971.36
1.00	Pc	Rear door protector LH ✓ NEC	49.80	25.00	37.35
1.00	Pc	Rear door top hinge LH ✓ BT	87.20	25.00	65.40
1.00	Pc	Rear door lower hinge LH ✓ BT	83.10	25.00	62.33
Nett item:					
1.00	Pc	Front fender signal lamp chrome ring LH ✓ cut	25.00	10.00	22.50
1.00	Pc	Front sport rim LH (14") ✓ cut	200.00	10.00	180.00
					1570.63
Special nett item:					
1.00	Pc	Front tyre LH (Michelin-175 65 R14) 80% ✓ (PUN)	130.00	104 (SN) 130.00	
Labour & Misc.					
1.00		Towing charge ✓	80.00		80.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 3 of 3
Your ref. TP-YM 7813K ERGO
Job No. 69102
Our ref. 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on . . 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00		To check wheel alignment	60.00	✓	60.00
1.00		To remove and refix front and rear passenger seat, carpet, etc	150.00	120	150.00 120
1.00		To knock dents front door pillar LH, front door inner pillar LH, centre pillar LH, centre inner pillar LH, rocker panel LH and renew of parts	1,100.00	1000	1,100.00 100
1.00		To spray paint	1,100.00	1000 1154	1,100.00 1,100.00

12 days

Sebastian
27/12/2017
- Lump Sum Repair.
- Photo After Paint.
- Question Mark Itam Photo.
90036121

sebastianyeap@kkauto.com

2360

Sub-Total	6,256.40
GST 7.00%	437.95
Total	S\$ 6,694.35

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Date

30.12.17 13:50

Vehicle ident no.

Odometer reading: km/miles

SGH 6754 T

109675

		Before	Target Data		Actual
Rear axle	Camber	left	-1°03'	-0°56' +/-0°25'	-1°03'
		right	-0°48'		-0°48'
		cross	-0°15'	0°00' +/-0°30'	-0°16'
	Toe	left	0°04'	0°10' +/-0°08'	0°04'
		right	0°20'		0°20'
		total	0°24'	0°19' +/-0°15'	0°24'
	Geometrical driving axis		-0°08'	0°00'	-0°08'
Front axle	Camber	left	-1°18'	-0°35' +/-0°45'	-1°18'
		right	-0°51'		-0°51'
		cross	-0°27'	0°00' +/-0°30'	-0°27'
	Caster	left	2°14'	1°38' +/-0°45'	2°14'
		right	1°14'		1°14'
		cross	1°01'	0°00' +/-0°30'	1°01'
	SAI	left	10°31'	10°05' +/-0°45'	10°32'
		right	10°30'		10°31'
		cross	0°01'	0°00' +/-0°30'	0°01'
	Track differential angle	left			
		right			
	Toe	left	-0°15'	0°00' +/-0°06'	-0°03'
		right	-0°24'		-0°03'
		total	-0°40'	0°00' +/-0°12'	0°06'
	Setback			0°00'	
Max steering lock	left steer	left		-35°47' +/-2°00'	
		right		31°33' +/-2°00'	
	right steer	left		31°33' +/-2°00'	
		right		-35°47' +/-2°00'	

Janice Lee (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Thursday, November 15, 2018 3:18 PM
To: Janice Lee (LKKAUTO)
Subject: RE: Finalization - SGH 6754T / Toyota Vios

Dear Janice

Amount confirm with thanks.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Tuesday, 13 November, 2018 4:09 PM
To: Jenny Lim
Subject: RE: Finalization - SGH 6754T / Toyota Vios

Dear Jenny,

Kindly confirm \$5,850.00 @ 12 Days

Parts : \$4,467.55 = \$3,350.66(25%)
Nett item : \$225.00 = \$202.50(10%)
Labour : \$2,464.00
Supp Part : \$1,372.00 = \$1,029.00(25%)
Labour : \$260.00
Total : \$7,306.16 = \$5,850.00(L/S)

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Wednesday, November 07, 2018 4:11 PM
To: SUR <sur@lkkauto.com>

Subject: FW: Finalisation - SGH 6754T / Toyota Vios

Importance: High

Dear Sir

For your confirmation, please.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]

Sent: Wednesday, 29 August, 2018 3:10 PM

To: sebastianyeang@lkkauto.com

Cc: sur@lkkauto.com

Subject: Finalisation - SGH 6754T / Toyota Vios

Dear Sir

- Parts: \$4,665.40 (include supplementary)
- SN: \$ 104.00
- L&P: \$2,680.00 (include supplementary)

Sub-total: \$7,449.40

LS -20%: (\$1,489.88) = \$5,959.52

Lump Sum: \$5950.00 / 15 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17024463/Nrd3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 03-12-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 7813K	Veh. Inspected	SGH 6754T	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMFP1703060	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204192517	Colour	SILVER	
Odometer	109675	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R14	MICHELIN	8 mm	
L/H Front Tyre	175/65 R14	MICHELIN	8 mm	
R/H Rear Tyre	175/65 R14	MICHELIN	8 mm	
L/H Rear Tyre	175/65 R14	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2017	Inspection Date	27/12/2017	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 6754T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH	DENTED	170.60	170.60
1	FRONT FENDER INNER SHIELD LH	DEFORMED	23.50	23.50
10	FRONT FENDER INNER SHIELD CLIPS LH @\$3.00	NECESSARY	30.00	30.00
1	FRONT FENDER SIGNAL LAMP LH	CRACKED	25.50	25.50
1	FRONT FENDER TOP SIDE COVER LH	CUT	25.90	25.90
1	FRONT DOOR LH	PUNCTURE	1,208.00	1,208.00
1	FRONT DOOR PROTECTOR LH	BENT	58.90	58.90
1	FRONT DOOR OUTER MOULDING LH	NECESSARY	29.90	29.90
1	FRONT DOOR OUTER LOCK HANDLE LH	MISSING	61.95	61.95
1	FRONT DOOR OUTER KEY LOCK COVER LH	MISSING	24.35	24.35
1	FRONT DOOR LOCK LH	DAMAGED	415.40	415.40
1	FRONT DOOR WINDOW WEATHERSTRIP LH	NECESSARY	49.90	49.90
1	FRONT DOOR KEY LOCK LH	DAMAGED	93.50	93.50
1	FRONT DOOR OUTER HANDLE HOLDER LH	MISSING	148.30	148.30
1	FRONT DOOR WINDOW GLASS LH	CRACKED	102.20	102.20
1	FRONT DOOR WINDOW REGULATOR LH	NOT NECESSARY	110.90	-
1	FRONT DOOR WINDOW CHANNEL LH	BENT	88.20	88.20
1	FRONT DOOR TOP HINGE LH	BENT	87.30	87.30
1	FRONT DOOR LOWER HINGE LH	BENT	83.10	83.10
1	FRONT DOOR WING MIRROR LH ASSY	MISSING	175.90	175.90
1	FRONT DOOR WEATHERSTRIP LH	NECESSARY	49.90	49.90
1	REAR DOOR LH	DEFORMED	1,295.14	1,295.14
1	REAR DOOR PROTECTOR LH	NECESSARY	49.80	49.80
1	REAR DOOR TOP HINGE LH	BENT	87.20	87.20
1	REAR DOOR LOWER HINGE LH	BENT	83.10	83.10
2	FRONT SHOCK ABSORBER @\$222.40 (ADDITIONAL)	BENT	444.80	444.80
2	REAR SHOCK ABSORBER @\$175.30 (ADDITIONAL)	BENT	350.60	350.60
2	FRONT SHOCK ABSORBER SUPPORT @\$62.20 (ADDITIONAL)	BENT	124.40	124.40
2	SUSPENSION ARM @\$226.10 (ADDITIONAL)	DISTORTED	452.20	452.20

Report Ref No. CS/EG17024463/Nrd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,487.61	-1,459.89
			4,462.83	4,379.65
	<u>NETT ITEMS</u>			
1	FRONT FENDER SIGNAL LAMP CHROME RING LH (N)	CUT	25.00	25.00
1	FRONT SPORT RIM LH (14") (N)	CUT	200.00	200.00
	LESS 10% DISCOUNT		-22.50	-22.50
			202.50	202.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE LH (MICHELIN - 175 65 R14) (SN) (80%)	PUNCTURE	130.00	104.00
			130.00	104.00
	<u>LABOUR</u>			
	TOWING CHARGE.		80.00	80.00
	TO CHECK WHEEL ALIGNMENT.		60.00	60.00
	TO REMOVE AND REFIX FRONT AND REAR PASSENGER SEAT, CARPET, ETC.		150.00	120.00
	TO KNOCK DENTS FRONT DOOR PILLAR LH, FRONT DOOR INNER PILLAR LH, CENTRE PILLAR LH, CENTRE INNER PILLAR LH, ROCKER PANEL LH AND RENEW OF PARTS.		1,100.00	1,000.00
	TO SPRAY PAINT.		1,100.00	1,100.00
	LABOUR TO REMOVE AND RENEW SUSPENSION, ETC. (ADDITIONAL)		320.00	260.00
			2,810.00	2,620.00
GRAND TOTAL			7,605.33	7,306.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,850.00

Report Ref No. CS/EGI17024463/Nrd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.