

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

HO YEW WAH

c/o 46 Lentor Plain

Singapore 786548

Not Authorised
61 Days @ 350d
Per day After Paint
6 days

Date: 27/12/2017

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA VIOS / EZ3883C		
1 pc	rear boot lid <i>584.20</i>	<i>Per</i> 695.60 ✓
1 pc	rear boot lock <i>102.00</i>	<i>Per</i> 178.40 ✓
1 pc	rear boot lock catch	<i>R</i> 52.10 x
1 pc	rear boot weatherstrip <i>186.50</i>	<i>Per/Pr</i> 263.10 <i>50% in</i>
1 pc	rear boot outer moulding	<i>Pr</i> 243.20 x
2 pcs	rear boot hinges @ 142.20	<i>R</i> 284.40 x
1 pc	rear boot key cylinder	<i>Pr</i> 256.00 x
2 pcs	rear boot number plate lamp @ 178.10	<i>Pr</i> 356.20 x
1 pc	rear boot emblem "E"	<i>Pr</i> 44.20 ✓
1 pc	rear boot emblem "VIOS"	<i>Pr</i> 46.20 ✓
1 pc	rear boot emblem logo	<i>Pr</i> 48.30 ✓
1 pc	rear bumper <i>481.80</i>	<i>Pr</i> 527.60 ✓
2 pcs	rear bumper side retainer @ 46.30	<i>Pr/Pr</i> 92.60 ✓
2 pcs	rear bumper bracket @ 78.40	<i>Pr/Pr</i> 156.80 ✓
1 pc	rear bumper dust cover	<i>Pr</i> 164.30 x
16 pcs	rear bumper clip @ 2.60	<i>Pr</i> 41.60 ✓
2 pcs	rear bumper reflector <i>215.00</i>	<i>Pr/Pr</i> 430.00 ✓
2 pcs	rear tail lamp assy <i>409.10</i>	<i>Pr/Pr</i> 1,039.20 ✓
2 pcs	rear tail lamp housing panel @ 312.50	<i>R</i> 625.00 x
1 pc	rear end panel	<i>Pr</i> 526.25 ✓
1 pc	rear end panel top garnish <i>213</i>	<i>Pr/Pr</i> 247.30 ✓
1 pc	rear spare tyre panel	<i>R</i> 764.60 x
1 pc	rear spare tyre top board <i>155.00</i>	<i>Pr</i> 315.20 ✓
1 pc	rear exhaust silencer	<i>R</i> 956.70 x
sub-total		8,354.85
less 25%		2,088.71
sub-total		6,266.14

	Balance brought forward.		6,266.14	
1 pc	rear number plate	s.nett	<i>Rm</i> 35.00	<i>X</i>
1 set	reverse sensor	s.nett	<i>CR</i> 220.00	
			<i>200.00</i>	
	sub-total		6,521.14	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		<i>700</i> 1,200.00	
	To check wiring system.		<i>200</i> 60.00	
	To install reserve sensor.		<i>500</i> 80.00	
	To spray painting on affected areas.		<i>800</i> 1,000.00	
	To apply rust proofing on affected areas.		<i>600</i> 150.00	
	To apply waterproof sealant on affected areas.		<i>600</i> 150.00	
	To remove carpet, trimming and seats to enable repair.		<i>600</i> 120.00	
	To bench pull chassis alignment and relign.		<i>200</i> 400.00	<i>X</i>
	Total		9,681.14	

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

HO YEW WAH
c/o 46 Lenton Plain
Singapore 786548

Date: 16/01/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : TOYOTA VIOS / EZ3883C / SUPPLEMENTARY	
2 pcs	rear boot side foam box <i>new</i> @ 171.4	342.80 <i>LP</i>
	Sub-total	342.80
	Less 25%	85.70
	Total	257.10