

ASS. REC. BY:

REF: CS/SMO17024467/4td3n7

Special Instructions

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Gracie Teo

of SMB

Date/Time: 27/12/17 @ 9.05am

Estimated Cost:

Bill to:

$$OD(\overline{TP})WS+TPRES/ODRES/EVA/INV/MV/CS$$

To Inspect Vehicle No:

SL 9410 K

Insured:

GBC 852T

at Workshop m/s

Pegasus

Tek:

6858 18 46

of

51 Defu Leine 40

Policy No:

Claim No:

CMTD1704668/NSW

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:04pm @ 27/12/17

Person Contacted:

Shevron

Vehicle IN OUT[illegible]

Suzuki (Mercury)

REF:

SMO

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

DAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. _____

SLL 94101C

Yr Regn. _____

3 17

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Vios

C.C. _____

1496

Colour: _____

Silver

A/C: Insured / Std / NI / NA

Sp. Reading _____

56762

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MH1FB29F3202007596

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Normal / Jammed / Leaked / Burnt orBrake: ☒ Normal / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

195/50 R16

☒ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

7 mm

R/Bal. _____

7 mm

L/Bal. _____

7 mm

L/Bal. _____

7 mm

D.O.A. _____

26/1/17

D.O.I. _____

27/1/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 52827

28/1/17 confirmed L/S @ 4500 with Sam. (Red: 7772, 63%)

RECEIVED 03 JAN 2018

Date/Time, File Pass to?

1) 31 Typist

Date/Time, File Return to?

2) _____



: Preli. Report



: Final Report

Days Of Repair: _____

5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Insp (\$ _____)



Weekend (\$ _____)

) S-RS (\$ _____)

) Photos: _____

) Others: _____

TOTAL

350

Report Format: _____

TP

Lump sum / I.B.I. (\$ _____)

4500/-

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 27 December, 2017 9:05 AM
To: Pegasus Engineering; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Ngo, Sau Wei Shawn; Henry, Irene James
Subject: CMTD1704668/NSW - Accident invlg GBC852T & SLL9410K on 26.12.2017
Attachments: 26122017171453.pdf; SLL9410K 26.12.2017.pdf

Your Reference: SLL9410K

Our Claim Reference: CMTD1704668/NSW

Hi Alvin,

We acknowledged receipt of your claim documents.

Please be informed that Shawn Ngo is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK,

Please make arrangement to conduct the survey for SLL9410K.

Aside to Shawn,

Please advise on the liability request from Pegasus Engineering & Trading Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Tuesday, December 26, 2017 5:14 PM

To: Claims - Motor Survey

Subject: CMTD1704668/NSW Third party survey - SLL9410K; Your insured - GBC852T DOA: 26.12.2017

Our ref: SLL9410K

Your ref: GBC852T

Without Prejudice

Dear Sir/Mdm,

We refer to the above matter.

Enclose the following documents for your attention:-

- a. Copy of our client's SAS report
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Please assist to arrange for survey soonest, the vehicle is grounded in our workshop.

We await for your favourable reply.

Thanks & Regards,

Alvin Low
Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17024467/Utd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 27-12-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 852T	Veh. Inspected	SLL 9410T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704668/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/12/2017	Inspection Date	27/12/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 11:13
Date Of Accident	26/12/2017 09:30
Exact Location Of Accident	ORCHARD BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL9410K
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98235866

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS 1.5E CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20170568

Driver

Name of Driver	TAN KEE CHIAN
NRIC No	S8070082B
Date Of Birth	18/04/1980
Occupation	OUTDOOR
Date Of Driving Pass	18/04/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91625448
Fax Number	
Contact Number	
EEmail Address	QZ.DOITNOW@GMAIL.COM

Address	BLOCK 346 KANG CHING ROAD #08-111
Postcode	610346
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 26.12.2017 at about 0930 hours, I was driving my vehicle (A: SLL9410K) along 2nd lane of Orchard Boulevard towards Paterson road. Upon reaching the junction, I was slowed down and stationary due to the traffic light was turned red. Out of sudden, I felt an impact from the rear and realized that vehicle (B: GBC852T) hit onto my vehicle's rear portion. Vehicle A (SLL9410K): No passenger onboard Vehicle B (GBC852T): No passenger onboard

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC852T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	LU JIAN WEN
NRIC/Passport Number	S8809118C
Contact Number	93716688
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN KEE CHIAN
Approximate Age	37
Injuries Sustain	
Injured person in which vehicle?	SLL9410K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLOCK 346 KANG CHING ROAD #08-111
Postcode	610346

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: Yang Jing
NRIC/FIN No.: 9390802

SKETCH PLAN

A hand-drawn map on graph paper showing a street layout. A vertical line on the left is labeled "Orchard Boulevard". A horizontal line at the top is labeled "Orchard Turn". Two small rectangular buildings are drawn near the intersection, labeled "A" and "B". Above the map, the following text is written:

A: SL29410 K
B: GBC 852T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Yang Hong

NRIC/FIN No.: 9290752C

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.: SLL9410K
 Vehicle Type: Z10 - Private Hire (Chauffeur) Motor Car Vehicle Scheme: Normal
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: - Vehicle Attachment 3: -
 Vehicle Make: TOYOTA Vehicle Model: VIOS 1.5E CVT
 Chassis No.: MHFB29F3202007596 Engine No.: 2NRX131157
 Motor No.: - Trailer Chassis No.: -
 Propellant: Petrol Passenger Capacity: 4
 Engine Capacity: 1496 cc Power Rating: -
 Maximum Power Output: 79.0 kW (105 bhp)
 Unladen Weight: 1065 kg Maximum Laden Weight: 1500 kg
 Primary Colour: Silver Secondary Colour: -
 First Registration Date: 16 Mar 2017 Original Registration Date: 16 Mar 2017
 Manufacturing Year: 2017 Open Market Value: \$12,946.00
 PARF Eligibility: Yes Minimum PARF Benefit: \$3,973.00
 No. of Transfers: 0 Additional Registration Fee Rate: First \$12,946.00 (100%)
 Actual ARF Paid: \$7,946.00

Owner Particulars

Owner Name: GRAB RENTALS PTE LTD
 Owner ID Type: Company
 Owner ID: 201617200G
 Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
 Registered Block/House No.: 6
 Registered Street Name: SHENTON WAY
 Registered Unit No.: # 38 - 01
 Registered Building Name: OUE DOWNTOWN
 Registered Postal Code: 068809
 COE No. / Expiry Date: 2017020101002819R / 15 Mar 2027
 COE Bid Category: A - Car (up to 1600cc & 97kW (130bhp))
 QP Paid: \$50,889.00

Transaction Details

Business Transaction Ref. No.: 20170316091556212673
 Business Transaction Date: 16 Mar 2017
 Business Transaction Time: 09:15:58

Message

The above vehicle has been successfully registered.

Please note that \$49,316.00 will be deducted from your GIRO account.

16/03/2017

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLL9410K
Vehicle to be Exported:	No
Intended De-registration Date:	27 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX131157
Chassis No.:	MHFB29F3202007596
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,946.00
Original Registration Date:	16 Mar 2017
First Registration Date:	16 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$7,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2027
PARF Rebate Amount:	\$5,959.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):	10
QP Paid:*	\$50,889.00
COE Rebate Amount:	\$46,868.00
Total Rebate Amount:	\$52,827.00

The information contained herein is correct as at 27 Dec 2017

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : ALVIN LOW WAI LUN

Tel :

Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :

Tel :

Fax :

Quotation No : QO17/12-1198	Quotation Date : 26/12/2017	Terms : 30 DAYS
Vehicle No : SLL9410K	Chassis No : MHFB29F3202007596	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: SOMPO ,TP VEHICLE NUMBER: GBC852T , DATE OF ACCIDENT: 26.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>m/suc 762-47</i>	1	1,662.4000	1,662.40
2	BOOTLID VIOS BADGE <i>acc</i>	1	44.1000	44.10
3	BOOTLID CENTRE EMBLEM BADGE <i>acc</i>	1	59.8000	59.80
4	BOOTLID E BADGE <i>acc</i>	1	39.4000	39.40
5	BOOTLID OUTER GARNISH <i>best/cne</i>	1	164.7000	164.70
6	BOOTLID OUTER GARNISH CLIPS <i>11</i>	8	3.8000	30.40
7	BOOTLID LOCK <i>twi</i>	1	190.4000	190.40
8	BOOTLID LOCK STRIKER <i>11</i>	1	18.5000	18.50
9	BOOTLID WEATHERSTRIP <i>twi</i>	1	188.8000	188.80
10	BOOTLID HINDGE <i>1</i>	2	79.8000	159.60
11	BOOTLID LOCK CABLE CLIP <i>11</i>	3	4.3000	12.90
12	BOOTLID WIRE HARNESS CLIP <i>11</i>	3	4.3000	12.90
13	BOOTLID INNER TRIM COVER <i>11</i>	1	398.1000	398.10
14	BOOTLID INNER TRIM COVER CLIPS <i>11</i>	6	4.3000	25.80
15	REAR END PANEL <i>S. 1500</i>	1	456.4000	456.40
16	REAR END PANEL INNER TRIM <i>twi</i>	1	234.3000	234.30
17	REAR BUMPER <i>DD</i>	1	504.9000	504.90
18	REAR BUMPER REINFORCEMENT <i>DD</i>	1	323.5000	323.50
19	REAR BUMPER SIDE RETAINER <i>Bel</i>	2	115.1000	230.20
20	REAR BUMPER CLIPS <i>acc</i>	10	4.3000	43.00
21	REAR BUMPER SIDE HOLDER <i>Bel</i>	2	22.3000	44.60
22	REAR BUMPER REFLECTOR <i>C12</i>	2	130.5000	261.00
23	REAR LAMP <i>C12</i>	2	375.8000	751.60

C/F 0.00

Page 1 of 3

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/12-1198	Quotation Date : 26/12/2017	Terms : 30 DAYS
Vehicle No : SLL9410K	Chassis No : MHFB29F3202007596	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: SOMPO ,TP VEHICLE NUMBER: GBC852T , DATE OF ACCIDENT: 26.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR LAMP CLIP HOLDER 11	4	9.5000	38.00 X
25	REAR LICENSE PLATE LAMP 11	2	79.8000	159.60 X
26	REAR FENDER R	2	969.7000	1,939.40 X
27	REAR LUGGAGE FLOOR PANEL ~	1	678.7000	678.70 X
28	REAR LUGGAGE FLOOR SIDE FOAM COMPARTMENT 111	2	75.0000	150.00 X
29	SPARE TYRE FASTENER CLAMP 11	1	29.8000	29.80 X
30	REAR EXHAUST BOX ~	1	638.8000	638.80 X
31	REAR EXHAUST BOX HEAT SHROUD 11	1	46.6000	46.60 X
32	REAR EXHAUST BOX MOUNT 11	2	78.9000	157.80 X
33	LESS 25% (ITEMS 1-32)	1	-2,424.0000	-2,424.00
34	REAR BUMPER PARKING SENSOR 1 set 2 stated	2	500.0000	2005.1,000.00
35	REAR LICENSE PLATE	1	80.0000	80.00 X
36	REAR LUGGAGE FLOOR PANEL INSULATOR 11	1	280.0000	280.00 X
37	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 50
38	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	180.0000	180.00 80
39	DROP REAR EXHAUST BOX AND RENEW THE SAME.	1	150.0000	150.00 X
40	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00 20
41	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	150.00 80
42	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	1	120.0000	120.00 60
43	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,860.0000	1,860.00 100

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO17/12-1198

Quotation Date : 26/12/2017

Terms : 30 DAYS

Vehicle No : SLL9410K

Chassis No : MHFB29F3202007596

Third Party Insurer :

Model : VIOS

Date of Accident :

Remarks : TP INSURER: SOMPO ,TP VEHICLE NUMBER: GBC852T , DATE OF ACCIDENT: 26.12.2017

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
44	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	1,000.0000	900 1,000.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5654.37

Sub Total	12,272.00
GST(7.00%)	859.04
Total (SGD)	13,131.04

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17024467/Utd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 09-01-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 852T	Veh. Inspected	SLL 9410K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704668/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3202007596	Colour	SILVER
Odometer	56762	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm
L/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm
R/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm
L/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/12/2017	Inspection Date	27/12/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9410K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED / BUCKLED	1,662.40	762.47
1	BOOTLID VIOS BADGE	NECESSARY	44.10	44.10
1	BOOTLID CENTRE EMBLEM BADGE	NECESSARY	59.80	59.80
1	BOOTLID E BADGE	NECESSARY	39.40	39.40
1	BOOTLID OUTER GARNISH	BENT / CRACKED	164.70	164.70
8	BOOTLID OUTER GARNISH CLIPS @\$3.80	NOT NECESSARY	30.40	-
1	BOOTLID LOCK	TWISTED	190.40	190.40
1	BOOTLID LOCK STRIKER	NOT NECESSARY	18.50	-
1	BOOTLID WEATHERSTRIP	TWISTED	188.80	188.80
2	BOOTLID HINDGE @\$79.80	TO REPAIR SEE LABOUR	159.60	-
3	BOOTLID LOCK CABLE CLIP @\$4.30	NOT NECESSARY	12.90	-
3	BOOTLID WIRE HARNESS CLIP @\$4.30	NOT NECESSARY	12.90	-
1	BOOTLID INNER TRIM COVER	NOT NECESSARY	398.10	-
6	BOOTLID INNER TRIM COVER CLIPS @\$4.30	NOT NECESSARY	25.80	-
1	REAR END PANEL	BADLY DENTED	456.40	456.40
1	REAR END PANEL INNER TRIM	TWISTED	234.30	234.30
1	REAR BUMPER	DENTED	504.90	504.90
1	REAR BUMPER REINFORCEMENT	DENTED	323.50	323.50
2	REAR BUMPER SIDE RETAINER @\$115.10	BENT	230.20	230.20
10	REAR BUMPER CLIPS @\$4.30	NECESSARY	43.00	43.00
2	REAR BUMPER SIDE HOLDER @\$22.30	BENT	44.60	44.60
2	REAR BUMPER REFLECTOR @\$130.50	CRACKED	261.00	261.00
2	REAR LAMP @\$375.80	CRACKED	751.60	751.60
4	REAR LAMP CLIP HOLDER @\$9.50	NOT NECESSARY	38.00	-
2	REAR LICENSE PLATE LAMP @\$79.80	NOT NECESSARY	159.60	-
2	REAR FENDER @\$969.70	TO REPAIR SEE LABOUR	1,939.40	-
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	678.70	-
2	REAR LUGGAGE FLOOR SIDE FOAM COMPARTMENT @\$75.00	NOT NECESSARY	150.00	-
1	SPARE TYRE FASTENER CLAMP	NOT NECESSARY	29.80	-
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	638.80	-

Report Ref No. CS/SMO17024467/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST BOX HEAT SHROUD	NOT NECESSARY	46.60	-
2	REAR EXHAUST BOX MOUNT @\$78.90	NOT NECESSARY	157.80	-
	LESS 25% DISCOUNT		-2,424.00	-1,074.79
			7,272.00	3,224.38
	SPECIAL NETT ITEMS			
2	SET REAR BUMPER PARKING SENSOR @\$500.00 (SN)	SHORTED	1,000.00	200.00
1	REAR LICENSE PLATE (SN)	DENTED	80.00	40.00
1	REAR LUGGAGE FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	280.00	-
			1,360.00	240.00
	LABOUR			
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		180.00	80.00
	DROP REAR EXHAUST BOX AND RENEW THE SAME.	NOT NECESSARY	150.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		150.00	80.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		120.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION. REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOTLID HINGE, REAR FENDER, REAR LUGGAGE FLOOR PANEL AND REAR EXHAUST BOX.		1,860.00	1,000.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,000.00	900.00
			3,640.00	2,190.00
	GRAND TOTAL		12,272.00	5,654.38
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00

Report Ref No. CS/SMO17024467/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.