

22/03/2001

ASS. REC. BY:

REF:

CS3/SM0170224474 / Wbs²

Special Instructions:

range & days

Surveyor:

ASSIGNMENT (Office)

From (person):

Grace Teo

of

SMO

Date/Time:

11:58am @ 26/12/17

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 39K

Insured:

SKV 86/6A

at Workshop m/s

Triple-T Automobile

Tel:

6385 1171

of

BKS Defu Lane 10 # 01-574, 539186

Policy No:

Claim No:

CMTD1704654 / THE

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp)

H.O.D. Endorsement:

Date/Time:

12:32pm @ 26/12/17

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKN 39K - x
	SKV 86/6A - CS / TSI 5020397 / Avbn2
	Dismantle Part : 29.12.2017
	After repair: 02/01/2018

DCA: 27/11/15

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 26 December, 2017 11:58 AM
To: Irene; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: candy@iaconsulting.com.sg; 'analysis impact'; Choo, Thelma; Henry, Irene James
Subject: CMTD1704654/THE - Accident invlg SKV8616A & SKN39K on 22.12.2017
Attachments: doc03889620171226093714.pdf

Your Reference: SKN39K

Our Reference: CMTD1704654/THE

Without Prejudice

Date: 26th December 2017

Attention:
M/S TRIPLE-T AUTOMOBILE

Accident invlg SKV8616A & SKN39K on 22.12.2017

Dear Irene,

We refer to your email reply dated 26/12/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Irene [mailto:motor@iaconsulting.com.sg]

Sent: Tuesday, December 26, 2017 11:44 AM

To: Teo, Grace

Cc: candy@iaconsulting.com.sg; 'analysis impact'; Choo, Thelma; Henry, Irene James

Subject: RE: CMTD1704654/THE - Accident invlg SKV8616A & SKN39K on 22.12.2017

Dear Grace,

We refer to the above matter.

We regret to inform you that our client will not appoint any of the surveyors from your list provided in your email below.

However, we are pleased to provide below a list of ten surveyors for your consideration.

Gilbert Leow	Impact Analysis Consultant
Andy Ho	Impact Analysis Consultant
Shandy Loh	Impact Analysis Consultant
Michael Yap	Mccooy Pte Ltd
Joshua Ong	Delta-V Consultant
James Ong	Delta-V Consultant
Nick Ng	Delta-V Consultant
Loo Yee Khang	Cozon Engineers
Alex Teo	Cozon Engineers
Denise Yap	Pal's Appraiser Pte Ltd

Kindly let us know if you agree or disagree to appointing any of the above surveyors within the timeline stipulated under the NIMA protocol.

Thank you.

Regards

Irene Tan

Triple-T Automobile

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Tuesday, 26 December 2017 11:36 AM
To: Irene
Cc: candy@iaconsulting.com.sg; analysis impact; Choo, Thelma; Henry, Irene James
Subject: CMTD1704654/THE - Accident invlg SKV8616A & SKN39K on 22.12.2017

Your Reference: SKN39K
Our Reference: CMTD1704654/THE

Date: 26th December 2017

Without Prejudice

Attention:
M/S TRIPLE-T AUTOMOBILE

Accident invlg SKV8616A & SKN39K on 22.12.2017

Dear Irene,

We refer to your Notice of Accident dated 26/12/2017.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Irene [<mailto:motor@iaconsulting.com.sg>]

Sent: Tuesday, December 26, 2017 9:38 AM

To: Claims - Motor Survey

Cc: candy@iaconsulting.com.sg; analysis impact

Subject: ACCIDENT INVOLVING SKN39K AND SKV8616A ALONG BUKIT TIMAH AFTER SIXTH AVE ON 22.12.2017

Dear Sir,

attached herewith the Notification Of Accident for your reference.

Kindly let us have a list of your ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA Protocol.

Best Regards,

Irene Tan

Triple-T Automobile

Tel: 6385 1171



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO17024474/Wbs2		
50 RAFFLES PLACE #05-01/06		Date: 03-04-2018		
SINGAPORE LAND TOWERSINGAPORE 048623				
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKV 8616A	Veh. Inspected	SKN 39K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1704654/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAFP32060CS46933	Colour	BLACK	
Odometer	129924 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/25ZR21	MICHELIN	4 mm	
L/H Front Tyre	295/25ZR21	MICHELIN	4 mm	
R/H Rear Tyre	295/25ZR21	MICHELIN	3 mm	
L/H Rear Tyre	295/25ZR21	MICHELIN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	22/12/2017	Inspect Date / Time	27/12/2017 (11:14 AM)	
Survey held at	TOP 93 51, UBI AVE 1 #01-07			
Repairer	TRIPLE-T AUTOMOBILE			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO17024474/Wbs2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.