

INS. CASE OWNER:

CC 7 /AIG1702

LKK-  
IDAC

Surveyor:

DOI:

Date / Time :

Registered in Merimex:

Pre-assign / CCU / FTE

Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :\$8

Is driver the owner?

( YES / NO )

Nature of Accident :

If **NO**, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

**Insured Liability :**

Final ? Yes / No

INSRS:  
WSP:  
Tel :  
Liability  
RMKS:

INRS:  
WSP:  
Tel :  
Liability  
RMKS:

INSRS:  
WSP;  
Tel:  
Liability  
Risks:

INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/Time		STAGE		DATE / PIC	
28/11/18		Non-Reporting ltr (1st):			
VIC		Non-Reporting ltr (2nd):			
		Non-Reporting ltr (Final):			
		Notification ltr (if non-pickup):			
		Call Of:		02/01/19 - VIC	
		After call ltr to OI:			
		<b>Documentation Check List: Handler    Typist</b>			
		Notification ltr (if non-pickup)		<input type="checkbox"/>	<input type="checkbox"/>
		After call ltr to OI:		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Authorisation To Act:		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Release Voucher:		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Final Repair Bill:		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Car Rental Invoice:		<input type="checkbox"/>	<input type="checkbox"/>
		Towing Invoice		<input type="checkbox"/>	<input type="checkbox"/>
		LTA / GIA:		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Medical Bill:		<input type="checkbox"/>	<input type="checkbox"/>
		PIR:		<input type="checkbox"/>	<input type="checkbox"/>
		Mandate/Reject Instruction:		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		LOD		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Payment Breakdown Form:		<input type="checkbox"/>	<input type="checkbox"/>
		Post-Repair Photos:		<input type="checkbox"/>	<input type="checkbox"/>
		Others:		<input type="checkbox"/>	<input type="checkbox"/>
IMINARY ADVICE		Date/Time:		Sent By:	
		IN ORDER TO CLOSE.			
FINALIZATION		Date/Time:		Confirm with:	
Repair Cost: 916		SS 9,120.80 (7 days) Reduction: 21 %		Confirm by:	
FINAL SETTLEMENT		Date/Time: 21/05/18		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability: % 100 (Agreed / Assessed)		BOLA S/N No.: 136		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Repair Cost: (w/acc)		SS 9,866.26		If NO or B 28, Ass. Lia:	
Cost of Rental (LOR):		SS - ( days)		COI EXTING ROUNDABOUT	
Cost of Use (LOU):		SS 540.00 x 9 days		COPY SENT 15/5/18	
Loss of Income (LOI):		SS - (\$ x days)		1) Claim status: Normal/Reject/Private Settle	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>		LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		2) Report Format:	
LTA Search		SS 2.00		3) Survey fee: \$360.00	
Medical:		SS -			
Disbursement:		(e.g. Tow/ Independent)			
Towing Cost		SS -			
Global Sum		SS 10,408.26		Global Sum SS: -	
FINAL PAYMENT		Date/Time:		Confirm with:	
Payment 1:		SS 9,866.26		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payment 2: (Strike if N.A.)		SS 540.00		Name 1: PERFORMANCE MOTORS LTD	
Payment 3: (Strike if N.A.)		SS -		Name 2: TAN KIA HOCK GARY	
		Name 3: -			

RECEIVED 22 MAY 2018

 Springer



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17024475/hb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-12-2017		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLC 7443B	Veh. Inspected	SLR 7838S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	25/12/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190666 (AfterSales)  
Fax. 63449773

316, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190526 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

27 DEC 2017

Estimate No. : b1 45301  
Date Estimated : 27/12/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

## - ESTIMATE REPAIR FOR -

Gary Tan Kia Hock  
20 Newton Road  
#11-02

Singapore 307953

## - ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR7838S	5J97769	28/08/2017	X1 sDrive18i	0

## DESCRIPTION

To replace rear right door, attachments and repair rocker panel and repair front right door. *u.s*

*3825* *✓* *2612* *2,902.00*  
VALUE 4,250.00

Painting front right door, rear right door and rocker panel.

*2611* *2612* *2,902.00*

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

*451* *✓* 531.00

To conduct checks on the electrical wiring system on the left/right side member for proper function.

*150* *✓* 177.00

To carry out body cavity preservation.  
(Per panel).

*100* *✓* 118.00

To supply and install rear right window glass solar film.

*NNX* 425.00

Sundries. *New*

*8* *✓* *80* 150.00

Total Labour 1: **8,553.00**

## DESCRIPTION

RR RH DOOR *✓* *Pure* *X* *Y* *NN*  
RH LOWER REAR DOOR HINGE *X* *NN*  
RH UPPER REAR DOOR HINGE *X* *NN*  
FRT RH MOULDING ROCKER PANEL *✓* *cut*  
REAR RH MOULDING ROCKER PANEL *✓* *cut*  
LETTERING S DRIVE 18i *✓* *MC*  
SYSTEM LATCH REAR RH (ZS) *X*  
RR RH SIDE DOOR WINDOW FIXED *X* *NN*  
Crashpad Tür *X*  
SOUND INSULA *X*  
FRT DOOR EGDE PROTECTION *X*  
REAR RH WHEEL ARCH TRIM *✓* *scr.*

QTY	PRIC	VALUE
1	1,140.10	1,140.10
1	55.75	55.75
1	55.75	55.75
1	72.80	72.80
1	58.80	58.80
1	91.55	91.55
1	339.85	339.85
1	142.55	142.55
1	33.85	33.85
1	72.75	72.75
1	169.30	169.30
1	144.00	144.00

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401533W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

380, Rampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63449771

318, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 45301  
Date Estimated : 27/12/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR7838S	5J97769	28/08/2017	X1 sDrive18i	0

## DESCRIPTION

RH TRIM UNDERRIDE PROTECTION (X LIN) - Cut  
LH SIDE SKIRT TRIM (LINES) - Cut

QTY	PRIC	VALUE
1	212.75	212.75
1	245.55	245.55

Total Parts : 2,835.35

Claims CO / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date/Taxi 08/1/18 Excess \$0

Surveyor's Name Gue Giang Sign \_\_\_\_\_

Surveyor's Tel 82880782 Authorized Yes/No \_\_\_\_\_

Authorized Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No \_\_\_\_\_

Surveyor's E-mail Gue Giang@1K4Auto.com

No. of Working Days Recommend 7

before paint photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,553.00
Parts	:	2,835.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	797.18
Grand Total	:	12,185.53

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

11,971.5

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020061-X



## SUPPLEMENTARY

Estimate No. : b1 45301  
Date Estimated : 27/12/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Gary Tan Kia Hock  
20 Newton Road  
#11-02

Singapore 307953

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLR7838S	5J97769	28/08/2017	X1 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT • <i>/ 5 nbl</i>	2.05	5.00		10.25
# EXPANDING RIVET •	1.35	20.00		27.00
# RH SIDE SKIRT TRIM (LINES) • - <i>Repair</i>	245.55	1.00		245.55

Total Labour :	
Total Parts :	282.80
Total Labour & Parts :	282.80



## FINAL REPORT

Estimate No. : b1 45301  
Date Estimated : 27/12/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Gary Tan Kia Hock  
20 Newton Road  
#11-02

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 307953

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLR7838S	5J97769	28/08/2017	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear RH door and attachments, front/rear RH rocker panel moulding, rear RH wheel arch trim, RH side skirt trim include making good front RH door, RH rocker panel and knocking out dents caused by the accident	3825.00		3,825.00
To spray paint front RH door, rear RH door and RH rocker panel	2612.00		2,612.00
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00
To conduct checks on the electrical wiring system on the EH side member for proper function	150.00		150.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.05	5.00		10.25
RR RH DOOR	1,140.10	1.00		1,140.10
FRT RH MOULDING ROCKER PANEL	72.80	1.00		72.80
REAR RH MOULDING ROCKER PANEL	58.80	1.00		58.80
LETTERING S DRIVE 18i	91.55	1.00		91.55
# EXPANDING RIVET *	1.35	20.00		27.00
REAR RH WHEEL ARCH TRIM	144.00	1.00		144.00
RH TRIM UNDERRIDE PROTECTION (X LIN	212.75	1.00		212.75
# RH SIDE SKIRT TRIM (LINES) *	245.55	1.00		245.55

### # SUPPLEMENTARY ITEMS

Total Labour :	7,218.00
Total Parts :	2,002.80
Total Labour & Parts :	9,220.80
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,220.80
GST @7%:	645.46
Grand Total :	9,866.26



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR 7838S	Model:	
Date of Accident:	25.12.2017		

Global Sum Settlement	[ ] Yes	[ ] No	
Repair Estimate	\$	12185.53	
Final Repair Cost	\$	9866.26	
Loss of Use	\$	540.00	9 days at \$60 per day
Rental (if any)	\$		days
LTA / GIA Search Fee	\$	2.00	
Others:	\$		
	\$		
Final Settlement Sum	\$	10408.26	

Is Third Party Workshop GIA Registered? [ ] YES [ ] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No
	BOLA Scenario No: _____
	BOLA Liability: _____ (%)      Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	\$ 9866.26
2)	Performance Motors Ltd	\$ 2.00
3)	Gary Tan Kia Hock.	\$ 540.00

Signed by appointed surveyor \_\_\_\_\_

Date \_\_\_\_\_

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report/ Bill (if any))



## Print Received Message

This mail is associated with :

**\*SLR7838S (3307604313SG)**  
**[SLC7443B]**  
TP  
GARY TAN KIA HOCK  
Dec 25 2017 2:00PM  
[FONG KWOK KWONG]  
Performance Motors Limited

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 08/05/2018 10:03 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10408.26) - SLR7838S - Claim Handler: Kesaval, Jaclyn-M

Approved:10408.26.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 JANUARY 2018

**FONG KWOK KWONG  
130 HILLVIEW AVENUE  
#07-01  
SINGAPORE 669596**

Dear Sir/Madam,

**OUR REF : CC3/AIG17024475/hb3  
YOUR REF : SLC 7443B  
ACCIDENT INVOLVING SLC 7443B AND SLR 7838S ALONG NEWTON CIRCUS  
ROUNDAABOUT ON 25.12.2017**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLR 7838S against your motor insurance policy.

Based on the accident report and accident scenario and all available information at hand, it was reported that your vehicle had collided to the Third-Party vehicle SLR 7838S while exiting the roundabout. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**

I, Gang Tan Kia Hock (the third party claimant) of 20 Newton Road #11-02 (307953) (address), owner of SLA7838 (vehicle no.) hereby authorize Performance Motors Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLA7838 that was damaged pursuant to the accident which occurred on 28-12-2017 (date) along NEWTON CIRCUS ROUNDABOUT (location) involving vehicle no/s SLC7443B ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 08 (day) of 01 (month) 2018 (year)

X

Signed by "the third party claimant"  
(with chop if applicable)

  
Inthira P. Thirumany  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 150057  
Signed by "the workshop" (with chop)

**RELEASE VOUCHER**  
**(AIG Express Third Party Claim)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$9866.26 (Repair Cost), S\$540.00 Loss of ~~rental~~ use), S\$ 2.00 (Disbursement), for vehicle no. SLR7838S that was damaged pursuant to the accident which occurred on 28.12.17 (date) along NEWTON CROSS (location) involving vehicle no/s SLC 7443B. This is pursuant to the inspection conducted on 8.1.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Garry Tan Kia Hock ("the third party claimant") of vehicle no. SLR7838S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLR7838S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 (day) of 05 (month) 2018 (year)

 XEQ

Signed by appointed surveyor

  
  
Incorporated in Singapore  
Performance Motors Limited  
303 Alexandra Road  
Singapore 119957  
Signed by "the workshop" (with chop)

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020061-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63390888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/536 (Motorrad)  
Fax. 64786601 (AfterSales)  
64796624 (Motorrad)

(Vic)

## SERVICE TAX INVOICE

Repair Order No. : <b>B1 1235364</b>	Page No. : <b>1 of 2</b>
Date IN : <b>09/01/2018</b>	Invoice Number : <b>1945467 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>20/03/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

## - CUSTOMER INFORMATION -

Mr Gary Tan Kia Hock  
20 Newton Road  
#11-02

Singapore 307953

## - INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO. <b>SLR7838S</b>	CHASSIS NO. <b>5J97769</b>	REGN. DATE <b>28/08/2017</b>	MODEL <b>X1 SDRIVE18I</b>	MILEAGE <b>2531</b>
------------------------------	-------------------------------	---------------------------------	------------------------------	------------------------

## - - - - LABOUR 1 - - - -

To replace rear right door and attachments, rear right wheel arch trim and right side skirting trim etc including to make good the front right door, right rocker panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	3,825.00
To respray front right door, rear right door and right rocker panel.	2,612.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.	451.00
To conduct checks on all doors and bootlid central locking system for proper function.	150.00
To carry out body cavity preservation.	100.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 25.12.2017. 3RD PARTY CAR : SLC7443B.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR GUO QIANG FROM LKK AUTO CONSULTANTS PTE LTD ON 8.1.2018. AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON 3.1.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$60X9. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **7,218.00**

## - - - - PARTS - - - -

	Qty	Retail Price	NETT
LETTERING S DRIVE 18I	1	91.55	91.55
REAR RH MOULDING ROCKER PANEL	1	58.80	58.80
REAR RH WHEEL ARCH TRIM	1	144.00	144.00
RR RH DOOR	1	1,140.10	1,140.10
FRT RH MOULDING ROCKER PANEL	1	72.80	72.80
RH TRIM UNDERRIDE PROTECTION (X LIN	1	212.75	212.75
EXPANDING NUT	5	2.05	10.25

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438185  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190328 (AfterSales)  
63190333/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1235364</b>	Page No. : <b>2 of 2</b>
Date IN : <b>09/01/2018</b>	Invoice Number : <b>1945467 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>20/03/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

RH SIDE SKIRT TRIM (LINES)	1	245.55	245.55
EXPANDING RIVET	20	1.35	27.00
	<b>Total Parts :</b>		<b>2,002.80</b>
 - - - - LABOUR 2 - - - -			<b>NETT</b>
			<b>0.00</b>
<b>Total Labour 2:</b>			<b>0.00</b>

Labour Charges :	<b>7,138.00</b>	Total Labour & Parts Charges :	<b>S\$ 9,220.80</b>
Parts Charges :	<b>2,002.80</b>	Less Insurance Excess :	<b>S\$ 0.00</b>
Lubricant/Misc :	<b>80.00</b>	Invoice Total Amount Exclude GST :	<b>S\$ 9,220.80</b>
		GST @ 7% :	<b>S\$ 645.46</b>
		Invoice Total Amount Include GST :	<b>S\$ 9,866.26</b>

Computer generated invoice. No signature is required.	Amount Payable Include GST :	<b>S\$ 9,866.26</b>
---	------------------------------	---------------------

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.







RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-17-194400

Date of Request: 26/12/2017

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 26/12/2017  
Enquiry By: THEMIS ALLIANCE  
TP Vehicle No: SLC7443B  
Accident Date: 25/12/2017

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLC7443B	AIG Asia Pacific Insurance Pte. Ltd.	25/05/2017-24/05/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-17-194400

Date of Request: 26/12/2017

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 26/12/2017  
Enquiry By THEMIS ALLIANCE  
TP Vehicle No. SLC7443B  
Accident Date 25/12/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2017 <a href="#">Edit Reg</a>		08 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$59,220.80</b> <a href="#">Edit Estimates</a>	<b>\$59,220.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>FONG KWOK KWONG</b> , ID: S0132874C								
Main Claimant:	<b>GARY TAN KIA HOCK</b> , ID: S7441217C								
Vehicle Reg. No.:	<b>SLR7838S</b>	Date of Loss:	25/12/2017 14:00 - :59 [3 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3307604313SG</b>		Policy/Cover Note No.:	2100467152 (Comprehensive) Coverage: 25/05/2017 - 24/05/2018					
Vehicle Reg. No. (Insured):	<b>SLC7443B</b>	Policy No. (Claimant):	VPA/P1983659						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 08/01/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (08/05/2018): Alert - Adj Mandate Approved (\$10408.26) - SLR7838S - Claim Handler: Kesaval, J...									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLR7838S (3307604313SG)**  
**[SLC74438]**  
**TP**  
**GARY TAN KIA HOCK**  
**Dec 25 2017 2:00PM**  
**[FONG KWOK KWONG]**  
**Performance Motors Limited**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>		
<b>Video</b>															1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	08/05/18 10:02	Video - Accident (Front)											Load MP4				
2	08/05/18 10:02	Video - Accident (Back)											Load MP4				
<b>Letters/Correspondences</b>															1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit				
<b>Assessment Reports</b>															1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	28/12/17 11:52	Accident Statement <small>From: OD - Reg. No: SLC74438, Claimant: FONG KWOK KWONG</small>											Load HTM				
<b>Photos/Images</b>															3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
2	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
3	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
4	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
5	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
6	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
7	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
8	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
9	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
10	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
11	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
12	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
13	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
14	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
15	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
16	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
17	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
18	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
19	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
20	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
21	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
22	12/03/18 09:58	General View											Load JPG	<input checked="" type="checkbox"/>			
23	12/03/18 09:59	General View											Load JPG	<input checked="" type="checkbox"/>			
24	12/03/18 09:59	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>			
25	12/03/18 09:59	Chassis Number											Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/17 16:37	TP GIA REPORT	Load PDF	
2	27/12/17 16:37	TP ESTIMATE	Load TIF	
3	03/01/18 10:05	TP SCENE PHOTOS	Load PDF	
4	03/01/18 10:36	LETTER TO OI	Load PDF	
5	10/01/18 18:27	TP ESTIMATE- MARKED	Load PDF	
6	23/04/18 08:55	GIA SEARCH	Load PDF	
7	23/05/18 11:47	WORKSHOP INVOICE	Load PDF	
8	23/05/18 11:47	AUTHORISATION TO ACT FORM	Load PDF	
9	23/05/18 11:47	Release Voucher	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLC7443B (Insd veh)	Model:	BMW X1 1.5 SDRIVE 18i (A)
	SLR7838S (TP veh)		
Date of Accident:	25/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	12,488.13
Final Repair Cost	:	\$	9,866.26
Loss of Use	:	\$	540.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,408.26

9.00 days at \$60.00 per day  
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/~~No~~—BOLA Scenario No: \_\_\_\_\_  
 13b \_\_\_\_\_  
 BOLA Liability: \_\_\_\_\_100\_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 9,866.26
2)	Tan Kia Hock Gary	:	\$ 540.00
3)		:	\$

JOANNE LEE KHANG MIN

23 May  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17024475/GHB3Q2

Date: 23/05/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100467152  
**Claimant Vehicle No :** SLR7838S **Insured Vehicle No :** SLC7443B  
 Date of Loss: 25/12/2017 Nature of Claim: TP Claim No: 3307604313SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLR7838S**  
 Make & Model: BMW X1, 1.5 SDRIVE 18i (A) Engine No: F464H523B38A15A  
 Reg. Date: 28/08/2017 (Man. Year: 2017) Chassis No: WBAHS120405J97769  
 Colour: Brown Odometer: 2531 km  
 Engine Capacity: 1499 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18  
 Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm  
 Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,268.15	2,082.80	1,185.35	36.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,403.00	7,138.00	1,265.00	15.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,671.15</b>	<b>9,220.80</b>	<b>2,450.35</b>	<b>20.99</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>816.98</b>	<b>645.46</b>	<b>171.52</b>	<b>20.99</b>
<b>Nett Amount (S\$)</b>	<b>12,488.13</b>	<b>9,866.26</b>	<b>2,621.87</b>	<b>20.99</b>
<b>+ Loss of Use (9.0 x S\$60.00/day) (S\$)</b>		<b>540.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>10,408.26</b>		

## INSPECTION

Date of Assignment: 08/01/2018  
 Date Inspected: 08/01/2018 Inspected At: Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 7.0 days



---

**Adjuster:** XING GUO QIANG**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*RR RH DOOR	Buckled	1,140.10 FS	*1,140.10 FS
3	1		*RH LOWER REAR DOOR HINGE	Not Necessary	55.75 FS	*- FS
4	1		*RH UPPER REAR DOOR HINGE	Not Necessary	55.75 FS	*- FS
5	1		*FRT RH MOULDING ROCKER PANEL	Cut	72.80 FS	*72.80 FS
6	1		*REAR RH MOULDING ROCKER PANEL	Cut	58.80 FS	*58.80 FS
7	1		*LETTERING S DRIVE 18I	Necessary	91.55 FS	*91.55 FS
8	1		*SYSTEM LATCH REAR RH (ZS)	Not Necessary	339.85 FS	*- FS
9	1		*RR RH SIDE DOOR WINDOW FIXED	Not Necessary	142.55 FS	*- FS
10	1		*CRASHPAD TUR F464H523B38A15A	Not Necessary	33.85 FS	*- FS
11	1		*SOUND INSULA	Not Necessary	72.75 FS	*- FS
12	1		*FRT DOOR EDGE PROTECTION	Not Necessary	169.30 FS	*- FS
13	1		*REAR RH WHEEL ARCH TRIM	Scratched	144.00 FS	*144.00 FS
14	1		*RR TRIM UNDERRIDE PROTECTION (XLIN)	Cut	212.75 FS	*212.75 FS
15	1		*LH SIDE SKIRT TRIM (LINES)	Cut	245.55 FS	*245.55 FS
16	5		*EXPANDING NUT	Necessary	10.25 FS	*10.25 FS
17	20		*EXPANDING RIVET	Necessary	27.00 FS	*27.00 FS
18	1		*RH SIDE SKIRT TRIM (LINES)	Repeated	245.55 FS	*- FS
Total Parts (S\$)					3,268.15	2,082.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR RIGHT DOOR ,ATTACHMENTS AND REPAIR ROCKER PANEL AND REPAIR FRONT RIGHT DOOR	New	4,250.00	3,825.00
2	PAINTING FRONT RIGHT DOOR ,REAR DOOR AND ROCKER PANEL	New	2,902.00	2,612.00
3	TO TRANSFER LOCK MECHANISM FRONT OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
4	TO CONDUCT CHECKS ON THE ELECTRICAL WIRING SYSTEM ON THE LEFT /RIGHT SIDE MEMBER FOR PROPER FUNCTION	New	177.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
6	TO SUPPLY AND INSTALL REAR RIGHT WINDOW GLASS SOLAR FILM	New	425.00	0.00
Gross Labour Cost (S\$)			8,403.00	7,138.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >