

S Three Automotive Recovery Pte Ltd (Co.Reg.No:201325741R)
 Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C
 Singapore 575643
 Tel: 62841542 / 62841575 Fax: 64875315 Email: sthreeautomotive@gmail.com

TP INSURER: **AIG Asia Pacific Insurance Pte. Ltd. (Express)**
HITACHI CAPITAL ASIA PACIFIC PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/12/2017
Vehicle Reg. No.:	SLK3163T	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	VICTOR GAN SIAU THONG		
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	12/01/2017
Vehicle Colour:	SILVER	Chassis No:	RU31211300
Engine No:	LEB5911310		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	S THREE AUTOMOTIVE RECOVERY PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	26,274.56
Labour	10.00
Paintwork Labour	4,430.00
Towing	0.00
	0.00
Gross Total (S\$)	30,714.56
+ GST 7.00% (S\$)	2,150.02
Nett Amount (S\$)	32,864.58

This claim is handled by: **MICHELLE LIM**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2017)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK3163T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / <i>Le</i>	20.00	0.00	*963.50 FL
2	1		*REAR BUMPER SIDE RH <i>X cut NN</i>	20.00	0.00	*390.00 FL
3	1		*REAR BUMPER SIDE LH <i>X NN</i>	20.00	0.00	*390.00 FL
4	1		*REAR BUMPER RETAINER RH <i>X re</i>	20.00	0.00	*32.00 FL
5	1		*REAR BUMPER RETAINER LH <i>X NN</i>	20.00	0.00	*32.00 FL
6	1		*REAR BUMPER BRACKET RH <i>X NN</i>	20.00	0.00	*60.00 FL
7	1		*REAR BUMPER BRACKET LH <i>X NN</i>	20.00	0.00	*60.00 FL
8	1		*REAR BUMPER REFLECTOR RH <i>X</i>	20.00	0.00	*151.10 FL
9	1		*REAR BUMPER REFLECTOR LH <i>CRA</i>	20.00	0.00	*151.10 FL
10	1		*REAR BUMPER LOWER COVER <i>re</i>	20.00	0.00	*395.00 FL
11	1		*REAR BUMPER INNER SHIELD LH <i>re</i>	20.00	0.00	*150.00 FL
12	1		*REAR FENDER PROTECTOR RH <i>re</i>	20.00	0.00	*185.00 FL
13	1		*REAR FENDER PROTECTOR LH <i>re</i>	20.00	0.00	*185.00 FL
14	1		*TAILLAMP RH <i>CRA</i>	20.00	0.00	*652.00 FL
15	1		*TAILLAMP LH <i>CRA</i>	20.00	0.00	*652.00 FL
16	1		*TAILLAMP INNER LOWER SIDE PANEL <i>NN</i>	20.00	0.00	*428.00 FL
17	1		*TAILLAMP INNER PANEL LH <i>NN</i>	20.00	0.00	*535.00 FL
18	1		*REAR END PANEL <i>NN</i>	20.00	0.00	*680.00 FL
19	1		*REAR END INNER GARNISH <i>re</i>	20.00	0.00	*192.30 FL
20	1		*REAR FENDER INNER TRIM RH <i>NN</i>	20.00	0.00	*340.00 FL
21	1		*REAR FENDER INNER TRIM LH <i>CRA</i>	20.00	0.00	*340.00 FL
22	1		*REAR TOOLS BOX <i>re</i>	20.00	0.00	*495.00 FL
23	1		*REAR TOOLS BOARD COVER <i>re</i>	20.00	0.00	*398.00 FL
24	1		*REAR FENDER TRIM GARNISH RH <i>NN</i>	20.00	0.00	*420.00 FL
25	1		*REAR FENDER TRIM GARNISH LH <i>NN</i>	20.00	0.00	*420.00 FL
26	1		*TAILGATE <i>NN</i>	20.00	0.00	*1,380.00 FL
27	1		*TAILGATE LOCK <i>re</i>	20.00	0.00	*126.00 FL
28	1		*TAILGATE INNER TRIMBOARD <i>CRA</i>	20.00	0.00	*425.00 FL
29	1		*TAILGATE OUTER HANDLE <i>re</i>	20.00	0.00	*320.00 FL
30	1		*TAILGATE OUTER HANDLE LOGO <i>re</i>	20.00	0.00	*45.00 FL
31	1		*TAILGATE NO PLATE LAMP LH <i>CRA</i>	20.00	0.00	*76.00 FL
32	1		*TAILGATE LAMP RH <i>CRA</i>	20.00	0.00	*450.00 FL
33	1		*TAILGATE LAMP LH <i>CRA</i>	20.00	0.00	*450.00 FL
34	1		*TAILGATE HINGE RH <i>BT</i>	20.00	0.00	*80.00 FL
35	1		*TAILGATE HINGE LH <i>BT</i>	20.00	0.00	*80.00 FL
36	1		*TAILGATE INNER TRIM COVER <i>NN</i>	20.00	0.00	*166.00 FL
37	1		*TAILGATE LOCK CATCH <i>NN</i>	20.00	0.00	*58.00 FL
38	1		*TAILGATE STOPPER LH <i>NN</i>	20.00	0.00	*60.00 FL
39	1		*TAILGATE RUBBER BEARING <i>NN</i>	20.00	0.00	*185.00 FL
40	1		*TAILGATE EMBLEM VEZEL <i>NN</i>	20.00	0.00	*56.20 FL
41	1		*TAILGATE LOCK AUTO SWITCH HANDLE <i>NN</i>	20.00	0.00	*175.00 FL
42	1		*TAILGATE LOCK AUTO CONTROL UNIT <i>NN</i>	20.00	0.00	*380.00 FL
43	1		*TAILGATE INNER HANDLE <i>NN</i>	20.00	0.00	*78.00 FL
44	1		*HYBRID AIR RESOLATOR BOX <i>NN</i>	20.00	0.00	*780.00 FL
45	1		*HYBRID AIR DUCT <i>NN</i>	20.00	0.00	*390.00 FL
46	1		*HYBRID TOP PANEL COVER <i>NN</i>	20.00	0.00	*330.00 FL
47	1		*TAILGATE WINDSCREEN MOULDING <i>NN</i>	20.00	0.00	*138.00 FL
48	1		*REAR SPARE TYRE PANEL <i>NN</i>	20.00	0.00	*1,130.00 FL
49	1		*REAR SPARE TYRE BOARD <i>NN</i>	20.00	0.00	*380.00 FL
50	1		*KEYLESS SENSOR <i>NN</i>	20.00	0.00	*280.00 FL
51	1		*KEYLESS SENSOR RELAY <i>NN</i>	20.00	0.00	*128.00 FL
52	1		*HYBRID BATTERY CONTROL UNIT SYSTEM <i>NN</i>	20.00	0.00	*12,600.00 FL
53	1		*TAILGATE TRIM CLIPS <i>NN</i>	0	0.00	*80.00 FS
54	1		*TAILGATE REVERSE CAMERA <i>NN</i>	0	0.00	*680.00 FS
55	1		*TAILGATE NO PLATE <i>NN</i>	0	0.00	*50.00 FS
56	1		*TAILGATE TOP COVER & CENTER GARNISH CLIPS <i>NN</i>	0	0.00	*150.00 FS
57	1		*REAR BUMPER CLIPS <i>NN</i>	0	0.00	*80.00 FS

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
58	1		*REAR REVERSE SENSOR / DM	0	0.00	200 *280.00 FS
59	1		*REAR BUMPER LOWER COVER CLIPS - MC	0	0.00	20 *80.00 FS
60	1		*REAR BUMPER INNER SHIELD CLIPS RH	0	0.00	*120.00 FS
61	1		*REAR BUMPER INNER SHIELD CLIPS LH	0	0.00	*120.00 FS
62	1		*REAR END PANEL SEALANT	0	0.00	20 *100.00 FS
63	1		*REAR END PANEL PRIMER AND CLEANER X	0	0.00	*100.00 FS
64	1		*TAILLAMP INNER CLIPS RH X	0	0.00	*60.00 FS
65	1		*TAILLAMP INNER CLIPS LH X	0	0.00	*60.00 FS
66	1		*TAILLAMP INNER HOLDER RH X	0	0.00	*60.00 FS
67	1		*TAILLAMP INNER HOLDER LH X	0	0.00	*60.00 FS
68	1		*REAR SPARE TYRE PANEL SEALANT X	0	0.00	*80.00 FS
69	1		*REAR SPARE TYRE PANEL INSULATOR X	0	0.00	*280.00 FS
70	1		*REAR END INNER PANEL MEMBER X	20.00	0.00	*350.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	32,233.20
- List Item Discount on L Items (\$\$)	5,958.64
Total Parts (\$\$)	26,274.56

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Rear LH Fender - BUC

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA	New ¹⁰⁰⁰ 600	1,600.00
2	SPRAY PAINTING ON ACCIDENT AREA	New ¹⁰⁰⁰ 600	1,400.00
3	R&R TAILGATE COMPARTMENT	New 60	200.00
4	R&R CARPET AND INNER TRIM TO ASSIST REPAIR	New 60	200.00
5	R&R REAR SEAT AND FRONT SEAT TO ASSIST REPAIR	New 60	280.00
6	R&R REAR BUMPER REVERSE SENSOR	New 40	120.00
7	R&R REVERSE CAMERA & CALIBRATION SYSTEM	New 40	120.00
8	R&R CAMERA AND INSTALLING WIRING SYSTEM	New NN X	120.00
9	R&R WINDSCREEN GLASS	New 120	150.00
10	CHECK & REPAIR WIRING SYSTEM	New 30	120.00
11	RESPRAY TUFF KOTE ON ACCIDENT AREA	New 60	120.00
Gross Labour Cost (S\$)			4,430.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

7 Days. (8).
Gua Qian - 82880282
After repair photos.
lumpsum repair.
26/12/17.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: