

12/03/2002

ASS. REC. BY:

REF:

CS/MSH17024478 / Kthbnz Special Instruction:

Supervisor:

Kenneth
Merriman

ASSIGNMENT (Office)

From (Person):

Catherine Thia of MSIG

Date/Time: 26/2/2017 @ 14.15

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 4450J

Insured:

SKR 6436L

at Workshop m/s

Cheng Hoe Motor Pte Ltd (Yishun)

Tel:

of

BLK 1019 # 01-374/382 Yishun Industrial Park A (768761)

Policy No:

A80426279QMX

Claim No:

540967

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

2.47pm @ 26/2/17

Person Contacted:

June

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLF 4450J - X

SKR 6436L - X

3/5 L1Rm @ 3100l Confirmed & Paid (Red: 1728.88 : 35%)

ASS. REC. BY:

REF:

MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 4450J Yr Regn: 06, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda 3 c.c. 1498Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 62586 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TN 6BN 42A 8.4 03 11810Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12 File pass to Customer

RECEIVED 04 MAY 2018

Date/Time, File Pass to?



Prel. Report

1) 415 TYPIST

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 3100)20010310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17024478/Ktb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 27-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 6436L	Veh. Inspected	SLF 4450J	
Policy No.	A80426279QMX	Coverage (\$)	0.00	
Claim No.	540967	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/12/2017	Inspection Date	27/12/2017	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2017		26 Dec 2017 14:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BONG HUI LING, ID: S7763305G, Tel: +6598183845, Email: cecil@aia.com.sg		
Main Claimant:	AZIANA BINTE AB AZIZ, ID: S8606698Z		
Vehicle Reg. No.:	SLF4450J	Date of Loss:	13/12/2017 19:00 - :59
Claim Type:	TP / 540967	Policy/Cover Note No.:	A80426279QMX (Comprehensive) Coverage: 21/02/2017 - 24/03/2018
Vehicle Reg. No. (Insured):	SKR6436L	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]		
Driver/Custodian (Insured):	BONG HUI LING (40 / Female), NRIC: S7763305G, Tel: +6598183845		
Adj Asg. Remarks:	CLIENT REQUEST KENNETH KONG .PLS CONTACT JUNE FOR THE SURVEY		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	6698Z
Vehicle Details	
Vehicle No.	SLF4450J
Vehicle to be Exported	Yes
Intended De-registration Date	14 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour	Grey
Manufacturing Year	2015
Engine No.	P520287463
Chassis No.	JM6BM42A8G0311610
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,138.00
Original Registration Date	15 Jun 2015
First Registration Date	15 Jun 2015
Transfer Count	1
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 Jun 2025
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	14 Jun 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$66,000.00
COE Rebate Amount	\$49,500.00
Total Rebate Amount	\$53,250.00

The information contained herein is correct as at 14 Dec 2017

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLF4450J

TP/MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES1791445

Date: 26 Dec 2017

Policy No: 5084119161

Veh Reg No: SLF4450J

Make/Model: MAZDA MAZDA 3
4DOOR SEDAN

Chassis No: JM6BM42A8G0311610

Engine No: P520287463

Reg. Date: 15/06/2015

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 13/12/2017

TP Veh Reg No: SKR6436L

Not Authorized
1. B1
Running Beyond
6 days

Estimate Repair Cost to Vehicle No :SLF4450J

PAGE:1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 FRONT LH DOOR	<i>Del/wrap</i> 1,143.00	1 PC	1,143.00	✓
2 FRONT LH DOOR FRAME STICKER	64.00	1 PC	64.00	✓
3 FRONT LH SIDE MIRROR	683.00	1 PCS	683.00	✗
4 FRONT LH DOOR INNER RUBBER	106.50	1 PC	106.50	✗
5 REAR LH DOOR	<i>Del/wrap</i> 999.60	1 PC	999.60	✓
6 REAR LH DOOR FRAME STICKER	75.00	1 PC	75.00	✓
7 REAR LH DOOR INNER RUBBER	115.00	1 PCS	115.00	✗
			3,186.10	
		Less 20%	637.22	2,548.88
Special Net				
8 SUN VISOR	120.00	1 PCS	120.00	✓
			120.00	120.00
Labour				
9 REMOE AND REFIX FRONT AND REAR LH DOORS, TRANSFER DOOR, ATTACHMENT. TO KNOCK AND REPAIR REAR LH FENDER, FRONT LH FENDER, REAR BUMPER AND REALIGN THE SAME	700.00	1 LA	700.00	<i>600</i>
10 REMOVE AND REFIX FRONT AND REAR LH DOORS GLASS AND CHECK CENTRE LOCKING AND POWER MIRROR	120.00	1 LA	120.00	✓
11 TO REMOVE AND REFIX REAR LH SPORT RIM, REPAIR, BALANCING AND RESPRAY PAINTING	80.00	1 LA	80.00	<i>60.00</i>
12 PUTTY AND RESPRAY ON FRONT LH FENDER, FRONT AND REAR LH DOOR, REAR LH FENDER, REAR BUMPER, DOOR HANDLE AND ALL AFFECTED AREA.	1,200.00	1 LA	1,200.00	<i>1100</i>
13 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,160.00	2,160.00
		Total		SS 4,828.88
		Add GST @ 7%		338.02
		Total Amount Payable		SS 5,166.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024478/KTBN2

Date: 07/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80426279QMX
Claimant Vehicle No :	SLF4450J	Insured Vehicle No :	SKR6436L
Date of Loss:	13/12/2017	Nature of Claim:	TP
		Claim No:	540967

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF4450J	Engine No:	P520287463
Make & Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Chassis No:	JM6BM42A8G0311610
Reg. Date:	15/06/2015 (Man. Year: 2015)	Odometer:	62586 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50ZR17	Rear Tyre Size:	215/50ZR17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,668.88	1,945.28	723.60	27.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,940.00	220.00	10.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,828.88	3,885.28	943.60	19.54
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	4,828.88	3,100.00	1,728.88	35.80
+ GST 7.00/7.00% (S\$)	338.02	217.00	121.02	35.80
Nett Amount (S\$)	5,166.90	3,317.00	1,849.90	35.80

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 26/12/2017 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts: 143	MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4450J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Dented/Warped	1,143.00 FL	*1,143.00 FL
2	1		*FRONT LH DOOR FRAME STICKER	Necessary	64.00 FL	*64.00 FL
3	1		*FRONT LH SIDE MIRROR	Serviceable	683.00 FL	*- FL
4	1		*FRONT LH DOOR INNER RUBBER	Serviceable	106.50 FL	*- FL
5	1		*REAR LH DOOR	Dented/Warped	999.60 FL	*999.60 FL
6	1		*REAR LH DOOR FRAME STICKER	Necessary	75.00 FL	*75.00 FL
7	1		*REAR LH DOOR INNER RUBBER	Serviceable	115.00 FL	*- FL
8	1		*SUN VISOR	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,306.10	2,401.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	637.22	456.32
Total Parts (\$\$)	2,668.88	1,945.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX FRONT AND REAR LH DOORS,TRANSFER DOOR,ATTACHMENT.TO KNOCK AND REPAIR REAR LH FENDER.FRONT LH FENDER.REAR BUMPER AND REALIGN THE SAME	New	700.00	600.00
2	REMOVE AND REFIX FRONT AND REAR LH DOOR GLASS AND CHECK CENTRE LOCKING AND POWER MIRROR	New	120.00	120.00
3	TO REMOVE AND REFIX REAR LH SPORT RIM,REPAIR.BALANCING AND RESPRAY PAINTING	New	80.00	60.00
4	PUTTY AND RESPRAY ON FRONT LH FENDER,FRONT AND REAR LH DOOR,REAR LH FENDER,REAR BUMPER,DOOR HANDLE AND ALL AFFECTED AREA	New	1,200.00	1,100.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			2,160.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >