

LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg
Company Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : TP17/061

Date : 23/12/2017
Vehicle Num. : SJU 7990S
Make/Model : HONDA CIVIC-2009
Chassis/Eng# : JHMF16309S203308/R18A14016809
Accident Date : 22/12/2017
Claim No. :
Reference : LYB/SJU7990S/AXA/tp/sy
Policy No. :

Not Authorized
1/12/18 819,950k
Resurvey After Paint

S/N Quantity Particular Unit Price Amount S\$

LIST ITEMS :		
1.	1	FRONT BONNET
2.	2	FRONT BONNET HINGES
3.	1	FRONT BONNET LOCK (UPPER)
4.	1	FRONT SUPPORT PANEL
5.	1	FRONT BRACE PANEL
6.	2	FRONT HEADLAMP
7.	2	FRONT HEADLAMP LOWER BRACKET
8.	1	FRONT BUMPER
9.	2	FRONT BUMPER RETAINER
10.	1	FRONT BUMPER REINFORCEMENT
11.	1	FRONT NO. PLATE GARNISH
12.	1	FRONT EMBLEM 'H'
13.	2	FRONT BUMPER FOG LAMP
14.	2	FRONT BUMPER FOG LAMP COVER
15.	1	FRONT BUMPER GRILLE CENTRE
16.	1	FRONT BONNET INSULATOR
17.	1	FRONT ENGINE UNDER COVER (CENTRE)
18.	1	FRONT BONNET LEVER
19.	1	FRONT GRILLE (BLACK)
20.	1	FRONT GRILLE (CHROME)
21.	2	FRONT FENDER
22.	1	FRONT RADIATOR
23.	1	FRONT RADIATOR FAN ASSY
24.	1	FRONT AIR-CON CONDENSER

<i>Bu</i>		485.90	✓
38.90	<i>R</i>	77.80	X
	<i>Di</i>	85.10	✓
	<i>Bu</i>	498.10	✓
	<i>R</i>	498.10	X
<i>mj</i>		1,806.80	✓
903.40	<i>Di</i>	58.80	✓
29.40	<i>Bu</i>	628.00	✓
	<i>Di</i>	26.20	✓
13.10	<i>R</i>	218.80	✓
	<i>Di</i>	40.50	✓
	<i>R</i>	24.70	✓
<i>Sm</i>		607.60	X
303.80	<i>Sm</i>	192.20	X
96.10	<i>Sm</i>	194.50	X
	<i>Sm</i>	75.40	X
	<i>Sm</i>	62.40	X
	<i>R</i>	38.50	X
	<i>Di</i>	224.60	✓
	<i>Di</i>	165.20	✓
<i>o/s Bu</i>		1,075.00	✓
537.50	<i>Di</i>	1,507.20	✓
<i>my Bu</i>	<i>Sm</i>	464.40	X
	<i>Bu</i>	729.80	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...

7077.20

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg
Company Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : TP17/061

Date : 23/12/2017
Vehicle Num. : SJU 7990S
Make/Model : HONDA CIVIC-2009
Chassis/Eng# : JHMF16309S203308/R18A14016809
Accident Date : 22/12/2017
Claim No. :
Reference : LYB/SJU7990S/AXA/tp/sy
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	FRONT AIR-CON FAN ASSY		452.40 X
26.	1	FRONT RADIATOR CAP		25.00 X
27.	2	FRONT RADIATOR MOUNTING	15.60	31.20 X
28.	1	COOLANT		40.10 X
29.	1	FRONT RADIATOR COWLING		105.40 X
30.	1	FRONT AIR-CON PIPE (IN)		97.40 X
31.	1	FRONT AIR-CON PIPE (OUT)		201.80 X
32.	1	FRONT AIR-CON HOSE		24.20 X
33.	1	REAR EMBLEM 'H'		23.40 X
34.	1	REAR EMBLEM 'CIVIC'		28.80 X
35.	2	REAR BOOT LID HINGES	48.60	97.20 X
36.	2	REAR REFLECTORS	202.40	404.80 X
37.	2	REAR TAILLAMPS	308.40	616.80 X
38.	1	REAR BOOT LID UPPER LOCK		189.50 X
39.	1	REAR TAILEND PANEL		303.80 X
40.	1	REAR TAILEND PANEL TEROSTAT SEALANT		54.20 X
41.	1	REAR SPARE TYRE HOUSING PANEL		948.50 X
42.	1	REAR BOOT LID WEATHERSTRIP		95.00 X
43.	1	REAR BUMPER		658.10 X
44.	2	REAR BUMPER SIDE RETAINER	16.40	32.80 X
45.	1	REAR SILENCER		535.40 X
46.	1	REAR SILENCER OUTER CHROME PIPE		93.40 X
47.	1	REAR BOOT LID		610.40 X
48.	1	REAR SPARE TYRE HOUSING PANEL TEROSTAT SEALANT		54.20 X
49.	1	REAR TAILEND PANEL INNER TRIM		56.50 X

List TotalS\$:
20.00% Discount S\$:


15,565.90
3,113.18
12,452.72

CONTINUE / ...

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg
Company Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : TP17/061

Date : 23/12/2017
Vehicle Num. : SJU 7990S
Make/Model : HONDA CIVIC-2009
Chassis/Eng# : JHMF016309S203308/R 18A14016809
Accident Date : 22/12/2017
Claim No. :
Reference : LYB/SJU7990S/AXAtp/sy
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1	FRONT NO PLATE (EMBOSS)		25.00 ✓
2.	1	FRONT NO. PLATE HOLDER		25.00 ✓
3.	10	FRONT BUMPER CLIPS	3.70	37.00 ✓
4.	7	FRONT BONNET INSULATOR CLIPS	3.70	25.90 ✓
5.	12	FRONT ENGINE UNDER COVER CLIPS	3.70	44.40 ✓
6.	1	REAR NO PLATE (EMBOSS)		25.00 ✓
7.	1	REAR NO PLATE HOLDER		25.00 ✓
8.	2	REAR BUMPER CLIPS	3.70	7.40 ✓
9.	1 SET	REAR REVERSE SENSOR		250.00 ✓
10.	1	TOWING FEE		50.00 ✓
11.	10	REAR TAILEND PANEL INNER TRIM CLIP	3.90	39.00 ✓
Special Nett Total S\$:				553.70
LABOUR :				
TO CHECK FOCUS HEADLAMP				100.00 ✓
TO CHECK FRONT WIRING FUNTION				80.00 ✓
TO VACUM & TOP UP AIR-CON GAS				120.00 ✓
LABOUR TO REPLACE FRT AIR CON CONDENSER PARTS				180.00 ✓
TO HEAT,CUT/WELDFRONT PANEL INCLUDING TO HEAT,KNOCK OUT				
LABOUR CHARGES AS RECOMMENDED FOR REPLACED DAMAGED PART				1,000.00 ✓
TO APPLY RUSTPROOFING ON REPAIRED/REPLACED PANELS FRONT				150.00 ✓

CONTINUE / ...

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.

Page 4 / 4



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est, Singapore 575645
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg
Company Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : TP17/061

Date : 23/12/2017
Vehicle Num. : SJU 7990S
Make/Model : HONDA CIVIC-2009
Chassis/Eng# : JHMFD16309S203308/R18A14016809
Accident Date : 22/12/2017
Claim No. :
Reference : LYB/SJU7990S/AXA/tp/sy
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO PUTTY,PRIMER TO SPRAY ON FRONT BONNET(INNER/OUTER)

BUMPER,SUPPORT PANEL,BRACE PANEL,HEADLAMP PANEL,

FRONT RHS/LHS FENDER USING 2K PAINTS.

TO CHECK REAR WIRING FUNCTION

TO REMOVE & REPLACE REAR EXHAUST

TO REPLACE REVERSE SENSOR

TO HEAT CUT/WELD REAR PANEL INCLUDING TO HEAT,KNOCK OUT

TO STRAIGHTEN ON AFFECTED AREA & LABOUR TO REPLACE PART

MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB

TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID

TO APPLY RUSTPROOFING ON REPAIRED/REPLACED PANELS REAR

TO PUTTY,PRIMER TO SPRAY ON REAR BOOT LID(INNER/OUTER)

BUMPER,SPARE TYRE PANEL,TAILEND PANEL & TOUCH UP PAINT

JOB ON AFFECTED AREA USING 2K PAINTS.

Labour Total S\$:

1200
1,800.00
80.00
150.00
120.00
1,500.00
350.00
80.00
150.00
200
250
500
900

1,800.00
7,660.00

E. & O.E.

Total S\$: 20,666.42

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.