

12/05/2017

REF: CS/MSG17024487/Gthb2 Special Instructions

SS REC BY:

Signature
Mummen

GQ

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MS16

Date/Time: 22/22/17

Estimated Cost:

Bill to:

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7510 H

Insured:

FBF 9996 L

at Workshop m/s

SK Automobile Pte Ltd

Tel:

of 8 Kaki Bukit Ave 4 #08-46 Premier@ Kaki Bukit S (415875)

Policy No:

MSP/VMT/17-358698

Claim No:

MSC/V/17-001973

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/22/17 @ 07.06

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9.48am @ 26/12/17

Person Contacted:

Mr. Khoo

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 7510H - X

FBF 9996L - X

Lump Sum \$88001- (Red: 18216.13, 67%)

ASSIGNMENT

From: _____ Date: 26/12/17

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 7510H

at Workshop m/s SK Automobile

of 8 koki Bk Ave 4 # 08-46 Premier

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) Mr. Khoo @ 81210478

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN 7510H Yr Regn: 16 May 2017

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Hybrid C.C. 1797

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 51416 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 8 VW 5/8019786

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 ZR16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 87 mm

L/Bal. 87 mm

D.O.A.

Rear

R/Bal. 87 mm

L/Bal. 87 mm

D.O.I. 26-12-17

Survey held at w/s 12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/7/2018

Date/Time. File Pass to?

18 Typst ☐ : Preli. Report

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) TP
8800/-

Days Of Repair: 8Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$) _____

☐ : Interview (\$) _____

☐ : Tech. Insp (\$) _____

☐ : Weekend (\$) _____

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17024487/Gtb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 27-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBF 9996L	Veh. Inspected	SLN 7510H	
Policy No.	MSD/VMT/17-358698	Coverage (\$)	0.00	
Claim No.	MSC/V/17-001973	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	22/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/12/2017	Inspection Date	27/12/2017	
Survey held at	8 KAKI BUKIT AVE 4 #08-46			
Repairer	SK AUTOMOBILE PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2017		22 Dec 2017 13:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIEW ONG KEM, ID: S1320321J		
Main Claimant:	TSG LIMO SERVICES, Co. Reg. No.: 53326564M		
Vehicle Reg. No.:	SLN7510H	Date of Loss:	18/12/2017 07:00 - :59
Claim Type:	TP / MSC/V/17-001973	Policy/Cover Note No.:	MSD/VMT/17-358698 (TP, Fire & Theft) Coverage: 13/02/2017 - 12/02/2018
Vehicle Reg. No. (Insured):	FBF9996L	Policy No. (Claimant):	
		Excess:	
Repairer:	Sk Automobile Pte Ltd () 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 8121 0478		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Margaret Loh

From: Woon Choo Kwok
Sent: Thursday, 21 December, 2017 4:13 PM
To: Catherine Thia; Margaret Loh
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: Arrange surveyor for SLN7510H Your Ref:FBL9996L
Attachments: SLN7510H GIA.PDF; SLN7510H ARRANGE.pdf

Dear CT & ML,

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Thursday, December 21, 2017 3:31 PM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: Arrange surveyor for SLN7510H Your Ref:FBL9996L

From: SK Admin [<mailto:admin@skauto.com.sg>]
Sent: 21 December 2017 14:40
To: Claims <claims@sg.msig-asia.com>
Cc: JING XIONG KHOO <xiongskauto@gmail.com>
Subject: Arrange surveyor for SLN7510H Your Ref:FBL9996L

Dear Sir / Mdm,

We the repairers of motor vehicle no. SLN7510H
Kindly arrange surveyor to conduct a pre-repair inspection.

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

--
Regards,

Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Denise Tay (LKKAUTO)

From: SK Admin <admin@skauto.com.sg>
Sent: Saturday, 4 August 2018 1:07 PM
To: Denise Tay (LKKAUTO)
Cc: Veron Chen (LKKAUTO); JING XIONG KHOO; simon koh
Subject: Re: FINALIZATION OF 2 VEHICLE

Dear Denise,

Refer to your email below, we confirmed accept your COR.

We'll submit final bill & relevant doc to insurance.

Thanks for your kind attention

--

Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155

On Tue, Jul 31, 2018 at 11:43 AM, SK Admin <admin@skauto.com.sg> wrote:

Dear Denise,

Sorry to keep you waiting. we'll revert to you asap as we are still check the price

--

Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155

On Tue, Jul 31, 2018 at 11:19 AM, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear SK admin,

Any update on the finalization?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 25 July 2018 2:43 PM
To: 'SK Admin' <admin@skauto.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: FINALIZATION OF 2 VEHICLE

Dear SK admin,

Any update on the finalization?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 17 July 2018 2:53 PM
To: SK Admin <admin@skauto.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FINALIZATION OF 2 VEHICLE

Hi,

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 09:41
Date Of Accident	18/12/2017 07:15
Exact Location Of Accident	CENTRAL EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN7510H
Insured/Policyholder	
Name Of Registered Owner	TSG LIMO SERVICES
Co Reg No	53326564M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91873347

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091016255
Cover Note Number	

Driver

Name of Driver	TAN SIAK GUAN
NRIC No	S7046177C
Date Of Birth	29/12/1970
Occupation	OUTDOOR
Date Of Driving Pass	17/11/1989
Driving Experience	28 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91873347
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 639 #03-145 HOUGANG AVENUE 8
Postcode	530639
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE-PROPIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20171218/2014. ATTENDED BY SITI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF9996L
Vehicle Make/Model/Colour	YAHAMA FZ16
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	

Email Address

DETAILS OF INJURED PERSON 1

Name	RIDER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBF9996L
Were seat belts worn?	NO
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/12/2017
9.43am

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Office: Policyholder's Signature
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vacb@singnet.com.sg

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 18/12/2017
9.43 AM

IDAC KAKI BUKIT(VAC)

23 KAKI BUKIT AVE 4

Singapore 415933

Reporting Centre Tel: 67492305

Name: Fax: 67492305

Email: idackb@singnet.com.sg

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20171218/2014

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 3

Report No: T/20171218/2014

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/12/2017 08:58	Vide Report No.: F/20171218/0078	Station Diary No.: 11
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TAN SIAK GUAN			Address: APT BLK 639 HOUGANG AVENUE 8 #03-145 SINGAPORE 530639	
ID Type / ID No.: NRIC NO / S7046177C			Contact No.: Home/Office:	Mobile: 91873347
Nationality SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 46	Date of Birth: 29/12/1970	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3,4	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/12/2017 07:15	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY Near Braddell Rd Exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF9996L	Motorcycle	YAMAHA	FZ 16	Red		0
SLN7510H	Car	TOYOTA	PRIUS HYBRID 1.8E AT ABS D/AIRBAG 2WD	Black	Seriously Damaged	0

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20171218/2014

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

2 of 3

Report No. T/20171218/2014

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	Unknown	ID No.	NIL
Related Vehicle	FBF9996L (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN SIAK GUAN	ID No.	S7046177C
Related Vehicle	SLN7510H (Car)	Contact No.	91873347
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 18/12/2017 at about 0713hrs, I was driving my black color Toyota (SLN7510H) and was travelling on the CTE heading towards the City. I was travelling on the extreme left lane and was preparing to exit via Braddell Road. I wish to state that there was a lorry on my right at the point of time. Just before exiting, there was a red color Yamaha (FBF9996L) suddenly came out from the front of the lorry and cut in front of my lane. I was unable to stop in time as it was too sudden and we collided.

Due to the impact, the rider fell off his motorcycle. My vehicle suffered a major dent on the right front portion of the vehicle, a punctured right tire, a damaged sports rim my driver side windscreen has a crack on it. An ambulance came together with the police and the rider was conveyed to Tan Tock Seng Hospital. I did not suffer any injuries. I was attended by the police and was instructed by IO Khairul to lodge a NP158 vide F/20171218/0078.

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T/20171218/2014

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

3 of 3

Report No. T/20171218/2014

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 EDMUND TOH JING WEN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/12/2017 08:58

Officer In Charge Of Case:

TP / GIT /


Sgt 3 LIM ENG KUAN, CLARENCE

Contact No.: 65476195

Classification Of Case:

Authentication Stamp

NP158





SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: MSIG	DATE	: 21-Dec-17
ATTENTION	: MOTOR CLAIMS DEPT		: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>			
NAME	:		
ADDRESS	:		
TEL. NO.	:		
OWNER'S INSURANCE	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

LKK Auto Consultants hence notify the Repairer of the following:

VEHICLE DETAILS

- * To display damaged part of car resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * Legal modification
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

VEHICLE NO : SLN7510H

MODEL : TOYOTA PRIUS

CHASSIS NO :

Acknowledged by Repairer

Signature:

Date:

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET X	1	\$ 1,359.00	\$ 1,359.00 X
2	BONNET SENSOR X	1	\$ 259.00	\$ 259.00 X
3	FRONT BUMPER OUTER GARNISH X	1	\$ 345.00	\$ 345.00 X
4	FRONT BUMPER LOGO / MCL	1	\$ 68.00	\$ 68.00 /
5	FRONT BUMPER / DIS	1	\$ 1,245.00	\$ 1,245.00 972.45
6	FRONT BUMPER FOGLAMP RH X NN	1	\$ 389.00	\$ 389.00 X
7	FRONT BUMPER FOGLAMP COVER RH / MCL	1	\$ 168.00	\$ 168.00 84
8	FRONT BUMPER LAMP RH X NN	1	\$ 225.00	\$ 225.00 X
9	FRONT BUMPER TOP GRILLE ? / MCL	1	\$ 145.00	\$ 145.00 /
10	FRONT BUMPER GRILLE BASE X NN	1	\$ 296.00	\$ 296.00 X
11	FRONT BUMPER TOP RUBBER / MCL	1	\$ 68.00	\$ 68.00 /
12	FRONT BUMPER TOP BEAM X NN	1	\$ 212.00	\$ 212.00 X
13	FRONT BUMPER LOWER GRILLE X / MCL	1	\$ 186.00	\$ 186.00 /
14	FRONT BUMPER UNDER GARNISH X / MCL	1	\$ 298.00	\$ 298.00 178.3
15	FRONT BUMPER SIDE RETAINER / MCL	1	\$ 68.00	\$ 136.00 76.9
16	FRONT BUMPER REINFORCEMENT X NN	1	\$ 498.00	\$ 498.00 X
17	FRONT BUMPER TOWING COVER / MCL	1	\$ 85.00	\$ 85.00 35
18	FRONT BUMPER SPONGE / MCL	1	\$ 120.00	\$ 120.00 /
19	FRONT BUMPER NUMBER PLATE GARNISH X NN	1	\$ 56.00	\$ 56.00 X

20	FRONT WINDSCREEN GLASS MOULDING / NBC	1	\$ 456.00	\$ 456.00	85
21	FRONT WINDSCREEN GLASS / CRA	1	\$ 1,895.00	\$ 1,895.00	-
22	FRONT WIPER GARNISH X NN	1	\$ 321.00	\$ 321.00	X
23	FRONT FENDER RH / mc	1	\$ 1,025.00	\$ 1,025.00	435
24	FRONT FENDER INNER PANEL RH X NN	1	\$ 698.00	\$ 698.00	X
25	FRONT FENDER INNER COWLING RH / cc	1	\$ 135.00	\$ 135.00	-
26	FRONT CHASSIS EXTENSION RH X NN	1	\$ 312.00	\$ 312.00	X
27	HEADLAMP RH / BR	1	\$ 3,120.00	\$ 3,120.00	785
28	HEADLAMP TOP PANEL RH / BT	1	\$ 216.00	\$ 216.00	165
29	FRONT SUPPORT TOP PANEL X { NN	1	\$ 468.00	\$ 468.00	X
30	FRONT SUPPORT LOWER PANEL X { NN	1	\$ 548.00	\$ 548.00	X
31	FRONT SUPPORT TOP GARNISH / cc	1	\$ 289.00	\$ 289.00	-
32	AIRCON CONDENSOR X / BT	1	\$ 1,445.00	\$ 1,445.00	-
33	AIR GUARD GARNISH RH X / ORA	1	\$ 78.00	\$ 78.00	-
34	RADIATOR X / CRA	1	\$ 1,758.00	\$ 1,758.00	-
35	RADIATOR SPARE TANK / cc	1	\$ 321.00	\$ 321.00	190
36	FUSE BOX / plaster. CRA	1	\$ 1,544.00	\$ 1,544.00	450-
37	FRONT KNUCKLE ARM RH X / BT	1	\$ 957.00	\$ 957.00	798.5
38	FRONT KNUCKLE BEARING RH X / mc	1	\$ 197.50	\$ 197.50	-
39	FRONT SHOCK ABSORBER RH X { NN	1	\$ 689.00	\$ 689.00	X
40	FRONT DRIVESHAFT RH X { NN	1	\$ 1,028.00	\$ 1,028.00	X
41	FRONT LOWER ARM RH X / BT	1	\$ 668.00	\$ 668.00	412.6
42	STABILIZER LINK RH X { NN	1	\$ 204.60	\$ 204.60	X
43	STEERING RACK AND PINION X { NN	1	\$ 2,985.00	\$ 2,985.00	X
44	STEERING TIE ROD END RH X { NN	1	\$ 211.40	\$ 211.40	X

TOTAL PRICE \$ 27,727.50
 LESS 25% \$ 6,931.88
 SUB TOTAL PRICE \$ 20,795.63

10652.25
 7989.18

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE X NN	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS / NBC	10	\$ 6.50	\$ 65.00
3	CENTRE GRILLE CLIPS X NN	3	\$ 8.50	\$ 25.50
4	FRONT WINDSCREEN GLASS SEALANT / mc	1	\$ 80.00	\$ 80.00
5	FRONT WINDSCREEN GLASS INNER SEAL / mc	1	\$ 80.00	\$ 80.00
6	FRONT TYRE RH / TN	1	\$ 380.00	\$ 380.00
7	FRONT SPORT RIM RH / cc CRA	1	\$ 1,200.00	\$ 1,200.00
8	IU BRACKET / NBC	1	\$ 50.00	\$ 50.00
9	FRONT FENDER COWLING CLIPS { mc	20	\$ 6.50	\$ 130.00
10	BRAKE FLUID / { mc	1	\$ 60.00	\$ 60.00
11	COOLANT / { mc	1	\$ 80.00	\$ 80.00

X
 30
 X
 20
 20
 150
 X(500)
 20
 20
 20
 30

TOTAL \$ 2,200.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	800
3	TUFF COAT	\$ 150.00	60
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	60
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	40
7	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	100
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 550.00	300
9	RESET ABS LIGHT	\$ 350.00	80.
10	CONDUCT WHEEL ALIGNMENT	\$ 120.00	60
11	FRONT CHASSIS ALIGNMENT	\$ 250.00	x ndv
TOTAL		\$ 4,020.00	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,996.13
 TOTAL LABOUR COST : \$ 4,020.00
 TOTAL REPAIR COST : \$ 27,016.13

APPROVED DETAILS

EXCESS
 NO. OF WORKING DAYS
 RE-SURVEY
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

8 Days.
 Lump sum Repairs.
 After repair photos.
 Gino Qiao - 82880282
 26/12/17

230
 11028.18
 230 = 8800

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024487/GTBN2

Date: 15/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-358698
Claimant Vehicle No :	SLN7510H	Insured Vehicle No :	FBF9996L
Date of Loss:	18/12/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-001973

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7510H	Engine No:	2ZR6848719
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	ZVW518019786
Reg. Date:	16/05/2017 (Man. Year: 2016)	Odometer:	51416 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55ZR16	Rear Tyre Size:	205/55ZR16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,996.12	8,799.19	14,196.93	61.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,230.00	1,790.00	44.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,016.12	11,029.19	15,986.93	59.18
Approved Total (Overridden) (\$\$)		8,800.00		
(\$\$)	27,016.12	8,800.00	18,216.12	67.43
+ GST 7.00/7.00% (\$\$)	1,891.13	616.00	1,275.13	67.43
Nett Amount (\$\$)	28,907.25	9,416.00	19,491.25	67.43

INSPECTION

Date of Assignment:	22/12/2017	
Date Inspected:	26/12/2017 Inspected At:	Sk Automobile Pte Ltd 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2018)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN7510H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,359.00 FL	*- FL
2	1		*BONNET SENSOR	Not Necessary	259.00 FL	*- FL
3	1		*FRONT BUMPER OUTER GARNISH	Not Necessary	345.00 FL	*- FL
4	1		*FRONT BUMPER LOGO	Necessary	68.00 FL	*68.00 FL
5	1		*FRONT BUMPER	Distorted	1,245.00 FL	*972.45 FL
6	1		*FRONT BUMPER FOGLAMP RH	Not Necessary	389.00 FL	*- FL
7	1		*FRONT BUMPER FOGLAMP COVER RH	Missing	168.00 FL	*84.00 FL
8	1		*FRONT BUMPER LAMP RH	Not Necessary	225.00 FL	*- FL
9	1		*FRONT BUMPER TOP GRILLE	Cracked	145.00 FL	*145.00 FL
10	1		*FRONT BUMPER GRILLE BASE	Not Necessary	296.00 FL	*- FL
11	1		*FRONT BUMPER TOP RUBBER	Necessary	68.00 FL	*68.00 FL
12	1		*FRONT BUMPER TOP BEAM	Not Necessary	212.00 FL	*- FL
13	1		*FRONT BUMPER LOWER GRILLE	Deformed	186.00 FL	*186.00 FL
14	1		*FRONT BUMPER UNDER GARNISH	Deformed	298.00 FL	*178.30 FL
15	1		*FRONT BUMPER SIDE RETAINER	Necessary	136.00 FL	*76.90 FL
16	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	498.00 FL	*- FL
17	1		*FRONT BUMPER TOWING COVER	Deformed	85.00 FL	*35.00 FL
18	1		*FRONT BUMPER SPONGE	Deformed	120.00 FL	*120.00 FL
19	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	56.00 FL	*- FL
20	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	456.00 FL	*85.00 FL
21	1		*FRONT WINDSCREEN GLASS	Cracked	1,895.00 FL	*1,895.00 FL
22	1		*FRONT WIPER GARNISH	Not Necessary	321.00 FL	*- FL
23	1		*FRONT FENDER RH	Buckled	1,025.00 FL	*435.00 FL
24	1		*FRONT FENDER INNER PANEL RH	Not Necessary	698.00 FL	*- FL
25	1		*FRONT FENDER INNER COWLING RH	Deformed	135.00 FL	*135.00 FL
26	1		*FRONT CHASSIS EXTENSION RH	Not Necessary	312.00 FL	*- FL
27	1		*HEADLAMP RH	Broken	3,120.00 FL	*785.00 FL
28	1		*HEADLAMP TOP PANEL RH	Bent	216.00 FL	*165.00 FL
29	1		*FRONT SUPPORT TOP PANEL	Not Necessary	468.00 FL	*- FL
30	1		*FRONT SUPPORT LOWER PANEL	Not Necessary	548.00 FL	*- FL
31	1		*FRONT SUPPORT TOP GARNISH	Cut	289.00 FL	*289.00 FL
32	1		*AIRCON CONDENSOR	Bent	1,445.00 FL	*1,445.00 FL
33	1		*AIR GUARD GARNISH RH	Cracked	78.00 FL	*78.00 FL
34	1		*RADIATOR	Cracked	1,758.00 FL	*1,758.00 FL
35	1		*RADIATOR SPARE TANK	Deformed	321.00 FL	*190.00 FL
36	1		*FUSE BOX	Cracked	1,544.00 FL	*450.00 FL
37	1		*FRONT KNUCKLE ARM RH	Bent	957.00 FL	*398.50 FL
38	1		*FRONT KNUCKLE BEARING RH	Necessary	197.50 FL	*197.50 FL
39	1		*FRONT SHOCK ABSORBER RH	Not Necessary	689.00 FL	*- FL
40	1		*FRONT DRIVESHAFT RH	Not Necessary	1,028.00 FL	*- FL
41	1		*FRONT LOWER ARM RH	Bent	668.00 FL	*412.60 FL
42	1		*STABILIZER LINK RH	Not Necessary	204.60 FL	*- FL
43	1		*STEERING RACK AND PINION	Not Necessary	2,985.00 FL	*- FL
44	1		*STEERING TIE ROD END RH	Not Necessary	211.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
46	10		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
47	3		*CENTRE GRILLE CLIPS	Not Necessary	25.50 FS	*- FS
48	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*20.00 FS
49	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	80.00 FS	*20.00 FS
50	1		*FRONT TYRE RH	Torn	380.00 FS	*150.00 FS
51	1		*FRONT SPORT RIM RH	Cracked	1,200.00 FS	*500.00 FS
52	1		*IU BRACKET	Necessary	50.00 FS	*20.00 FS
53	20		*FRONT FENDER COWLING CLIPS	Necessary	130.00 FS	*20.00 FS
54	1		*BRAKE FLUID	Necessary	60.00 FS	*20.00 FS
55	1		*COOLANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	29,928.00	11,462.25
- List Item Discount on L Items 25.00/25.00% (S\$)	6,931.88	2,663.06
Total Parts (S\$)	22,996.12	8,799.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,REMOVE AND REPLACE PARTS	New	1,200.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	800.00
3	TUFF COAT	New	150.00	60.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	New	120.00	60.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	40.00
7	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	100.00
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	550.00	300.00
9	RESET ABS LIGHT	New	350.00	80.00
10	CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
11	FRONT CHASSIS ALIGNMENT	New	250.00	-
Gross Labour Cost (S\$)			4,020.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >