



TK CAR REPAIRS PTE LTD

Business Reg. No. 201202611N

176, SIN MING DRIVE, #01-12 SIN MING AUTOCARE, SINGAPORE 575721 TEL: 6453 2598, 6453 9730
FAX: 6552 0866 Email: tklow50@hotmail.com

GREAT AUTO
BLK 69, CIRCUIT ROAD, #06-105
370069

Attention : THE OWNER

Contact : 90695399

Estimate : ES001448

Date : 22/12/2017
Vehicle Num. : SLT 8060 B
Make/Model : MIT LANCER
Chassis/Eng# :
Accident Date : 22/12/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT NUMBER PLATE GARNISH		34.00
2.	1	FRONT BUMPER		701.00
3.	10	FRONT BUMPER CLIP	3.00	30.00
4.	2	FRONT BUMPER SIDE BEAMS	45.00	90.00
5.	1SET	FRONT BUMPER SIDE BEAMS RIVETS		20.00
6.	1	FRONT BUMPER REINFORCEMENT		178.00
7.	2	FRONT BUMPER FOG GARNISH	35.00	70.00
8.	1	FRONT BUMPER LOWER GARNISH		49.00
9.	1	FRONT BUMPER INNER GARNISH		155.00
10.	1	FRONT BUMPER LOGO		45.00
11.	2	FRONT GRILL	82.00	164.00
12.	2	FRONT HEAD LAMP	528.00	1,056.00
13.	1	FRONT SUPPORT PANEL		569.00
14.	1	FRONT BONNET		689.00
15.	1	FRONT BONNET LOCK		55.00
16.	2	FRONT BONNET HINGE	47.00	94.00
17.	2	FRONT FENDER	456.00	912.00
18.	1	AIR CON CONDENSER		1,121.00
19.	1	AIR CON FAN COWLING		125.00
20.	1	AIR CON FAN MOTOR ASSY		291.00
21.	1	AIR CON FAN BLADE		45.00
22.	1	RADIATOR ASSY		792.00
23.	1	RADIATOR FAN COWLING		110.00
24.	1	RADIATOR FAN MOTOR ASSY		296.00
25.	1	RADIATOR FAN BLADE		45.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TK CAR REPAIRS PTE LTD

Business Reg. No. 201202611N

176, SIN MING DRIVE, #01-12 SIN MING AUTOCARE, SINGAPORE 575721 TEL: 6453 2598, 6453 9730
FAX: 6552 0866 Email: tklow50@hotmail.com

GREAT AUTO
BLK 69, CIRCUIT ROAD, #06-105
370069

Attention : THE OWNER
Contact : 90695399

Estimate : ES001448

Date : 22/12/2017
Vehicle Num. : SLT 8060 B
Make/Model : MIT LANCER
Chassis/Eng# :
Accident Date : 22/12/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
26.	1	AIR DUCT ASSY		96.00 ✓
27.	1	AIR CON SUCTION HOSE		228.00 ✓
28.	1	AIR CON DISCHARGE HOSE		208.00 ✓
29.	2	REAR NO PLATE LAMP	55.00	110.00 X
30.	1	REAR BUMPER		698.00 ✓
31.	1 SET	REAR BUMPER CLIP		30.00 ✓
32.	2	REAR BUMPER SIDE HOLDERS	41.00	82.00 ✓
33.	1 SET	REAR BUMPER SIDE HOLDER RIVETS		20.00 ✓
34.	2	REAR BUMPER BRACKET	161.00	322.00 ✓
35.	1	REAR END PANEL		406.00 ✓
36.	1	REAR END PANEL TOP GARNISH		145.00 ✓
37.	2	REAR TAIL LAMP	344.00	688.00 ✓
38.	2	REAR TAIL LAMP PANEL	61.00	122.00 ✓
39.	1	REAR BOOT LID		675.00 ✓
40.	1	REAR BOOT LIP LOCK		58.00 ✓
41.	1	REAR BOOT LID WEATHERSTRIPE		136.00 ✓
42.	2	REAR BOOT LID HINGE	70.00	140.00 X
43.	1	REAR BOOT LID OUTER GARNISH		195.00 ✓
44.	1 SET	REAR BOOT LID OUTER GARNISH CLIPS		15.00 ✓
45.	1	REAR LOGO		42.00 ✓
46.	2	REAR FENDER INNER TRIM	212.00	424.00 X
47.	1 SET	REAR FENDER INNER TRIM CLIP		60.00 ✓
48.	1	REAR SPARE TYRE PANEL		969.00 ✓
49.	1	REAR SPARE TYRE TOP COVER		142.00 ✓
50.	1	REAR SPARE TYRE LOCK SCREW		38.00 ✓
51.	1	REAR EXHAUST PIPE		587.00 ?
52.	2	REAR EXHAUST MOUNTING	35.00	70.00 ✓

CONTINUE / ...



TK CAR REPAIRS PTE LTD

Business Reg. No. 201202611N

176, SIN MING DRIVE, #01-12 SIN MING AUTOCARE, SINGAPORE 575721 TEL: 6453 2598, 6453 9730
FAX: 6552 0866 Email: tklow50@hotmail.com

GREAT AUTO
BLK 69, CIRCUIT ROAD, #06-105
370069

Attention : THE OWNER
Contact : 90695399

Estimate : ES001448

Date : 22/12/2017
Vehicle Num. : SLT 8060 B
Make/Model : MIT LANCER
Chassis/Eng# :
Accident Date : 22/12/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
53.	1 SET	REAR WINDSCREEN GLASS MOULDING		141.00 ✓
54.	2	REAR FENDER	850.00	1,700.00 X
List Total S\$:				16,283.00
10.00% Discount S\$:				1,628.30
				14,654.70
SPECIAL NETT ITEMS :				
1.	1	FRONT NUMBER PLATE		30.00 ✓
2.	1	FRONT NUMBER PLATE HOLDER		30.00 ✓
3.	1	REAR NUMBER PLATE		30.00 X
4.	1	REAR NUMBER PLATE HOLDER		30.00 X
5.	1	REAR REVERSE SENSOR		350.00 260.00
6.	1	REAR END PANEL SEALANT		60.00 30.00
7.	1	REAR SPARE TYRE INSULATOR PAD		280.00
8.	1	REAR WINDSCREEN SEALANT		55.00 40.00
Special Nett Total S\$:				865.00
LABOUR :				
TO CHECK LIGHTING & ELECTRICAL SYSTEM				150.00
TO REMOVE & REFIT REAR W/SCREEN GLASS				240.00
CUT OUT, REPLACE AND WELD REAR END PANEL, REAR TAIL LAMP				
PANEL, REAR SPARE TYRE PANEL AND FRONT SUPPORT PANEL,				
PANEL BEAT REAR FENDERS AND REAR DOORS. STRAIGHTEN				
FRONT AND REAR CHASSISES. REMOVE AND REPLACE ALL				

CONTINUE / ...



TK CAR REPAIRS PTE LTD

Business Reg. No. 201202611N

176, SIN MING DRIVE, #01-12 SIN MING AUTOCARE, SINGAPORE 575721 TEL: 6453 2598, 6453 9730
FAX: 6552 0866 Email: tklow50@hotmail.com

GREAT AUTO
BLK 69, CIRCUIT ROAD, #06-105
370069

Attention : THE OWNER
Contact : 90695399

Estimate : ES001448

Date : 22/12/2017
Vehicle Num. : SLT 8060 B
Make/Model : MIT LANCER
Chassis/Eng# :
Accident Date : 22/12/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		DAMAGED PARTS		2200 3,000.00
		REMOVE AND REINSTALL REAR UPHOLSTERY, CUSHION SEATS		120 380.00
		AND ROOF LINING TO ENABLE REPAIR		100.00 500
		TO RENEW REAR REVERSE SENSOR		150.00 1000
		TO REMOVE & REFIT AIR CON COND & TOP UP GAS		120.00 500
		TO REMOVE & REFIT RADIATOR & CONDUCT PRESSURE TEST		2200 2,600.00
		TO SPRAY PAINTS ON ACCIDENT PARTS		150.00 600
		TO REMOVE AND REINSTALL REAR EXHAUST SILENCER		150.00 500
		TRANSFER REAR BOOT LID FITTINGS		
		TO MOUNT VEHICLE ON MEASURING BENCH TO COLLECT		250 380.00
		CHASSIS ALIGNMENT		150.00 600
		TO REMOVE AND REINSTALL FUEL TANK		200 120.00
		TO CONDUCT WATERPROOF TEST AFTER REPAIR		1800 400.00
		TO RUST PROOFING TREATMENT ON AFFECTED AREA		
		Labour Total S\$:		8,090.00

E. & O.E.

Total S\$: 23,609.70


for TK CAR REPAIRS PTE LTD