

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: SOMPO	DATE	: 26-Dec-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLR6336E
ADDRESS	: <i>Xiao Chun</i>	MODEL	: LEXUS RX200
TEL. NO.	:	CHASSIS NO	: <i>JTJBMCAx02030383</i>
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Del d</i>	1	\$ 1,445.00	\$ 1,445.00
2	REAR BUMPER LOWER <i>Del d</i>	1	\$ 1,025.00	\$ 1,025.00
3	REAR BUMPER REFLECTOR <i>RH could</i>	2	\$ 287.10	\$ 574.20
4	REAR BUMPER REINFORCEMENT <i>Bert</i>	1	\$ 458.00	\$ 458.00
5	REAR BUMPER REINFORCEMENT SPONGE <i>could</i>	1	\$ 270.70	\$ 270.70
6	REAR BUMPER UPPER RETAINER <i>rer</i>	2	\$ 70.60	\$ 141.20
7	REAR BUMPER SIDE RETAINER <i>r</i>	2	\$ 68.50	\$ 137.00
8	REAR PARKING SENSOR <i>And</i>	2	\$ 348.00	\$ 696.00
9	TAILGATE <i>2</i>	1	\$ 1,879.00	\$ 1,879.00
10	TAILGATE WEATHERSTRIP <i>AP</i>	1	\$ 194.10	\$ 194.10
11	TAILGATE STOPPER <i>r</i>	2	\$ 32.00	\$ 64.00
12	TAILGATE EMBLEM	1	\$ 115.00	\$ 115.00
13	TAILGATE EMBLEM "LEXUS"	1	\$ 107.60	\$ 107.60
14	TAILGATE EMBLEM "RX200"	1	\$ 94.50	\$ 94.50

520
287.10
560.
X
X
+
+
+
X

15	TAILLAMP RH	1	\$ 689.00	\$ 689.00	+
16	REAR WINDSCREEN MOULDING	1	\$ 158.60	\$ 158.60	+
17	REAR END PANEL	1	\$ 715.30	\$ 715.30	+
18	REAR END PANEL TOP GARNISH	1	\$ 611.70	\$ 611.70	+
19	REAR FENDER SIDE INNER TRIM RH	1	\$ 969.10	\$ 969.10	+
20	REAR AMPLIFIER SPEAKER	1	\$ 1,060.80	\$ 1,060.80	+
21	EXHAUST PIPE CHROME	1	\$ 428.00	\$ 428.00	350
22	EXHAUST BRACKET	1	\$ 180.30	\$ 180.30	+
23	EXHAUST PIPE MOUNTING	2	\$ 45.00	\$ 90.00	+

4027.8
3625.02

TOTAL PRICE \$ 12,104.10
LESS 10% \$ 1,210.41
SUB TOTAL PRICE \$ 10,893.69

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR WINDSCREEN INNER SEAL	1	\$ 125.00	\$ 125.00	+
2	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	+
3	REAR BUMPER CLIP SET	1	\$ 70.00	\$ 70.00	30
4	TAILGATE INNER TRIM CLIP SET	1	\$ 70.00	\$ 70.00	+
5	END PANEL TOP GARNISH CLIP SET	1	\$ 55.00	\$ 55.00	+
6	END PANEL JOINT SEALANT	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER SIDE INNER TRIM CLIP SET	1	\$ 120.00	\$ 120.00	30

SUB TOTAL PRICE \$ 600.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,400.00	300	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,000.00	400	
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 150.00	x	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 200.00	60	
5	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	\$ 150.00	x	
6	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 80.00	30	

7	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	x	
8	DRILL HOLE TO ENABLE REFIX TAILGATE SPOILER.	\$ 120.00	x	
9	REMOVE AND INSTALL REAR WINDSCREEN GLASS.	\$ 150.00	x	
10	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING.	\$ 300.00	x	
11	APPLY TUFF COATING TREATMENT.	\$ 200.00	x	

SUB TOTAL

\$ 3,850.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,493.69
TOTAL LABOUR COST : \$ 3,850.00
TOTAL REPAIR COST : \$ 15,343.69

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

90707777

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Approved by Repairer

Adrian Lj
L/s 28/12/17
03 ap.

tel: 4445 02
Y/S: 3.5K ✓