

ASS. REC. BY:

REF:

CS/FCI7024496/71fbm

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): CWS May Chua

of FCL

Date/Time: 27/22017 11:33am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 9487G

Insured:

SHD 7200C

at Workshop m/s

Ethoz

Tel:

6654 7519

of

30 Bukit Batok Crescent

Policy No:

Claim No:

D17011635 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

27/22017 11:40am

Person Contacted:

Shah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 9487G - X

SHD 7200G - X

Confirm \$4879.96, 8 days (Ad: \$3572.72, 42%).

(08/11/17)

REF:

FCI

Surrey: Taufik

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Shah, I

Veh No: SLD 94876 Yr Regn: 2016 June

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c

1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

63209

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SM6BM42A860342803

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

25/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27/12/17 @ 1330

Survey held at

Etno, Hut Gth.

Des. of Damages

Frt.

Rear

O/S

N/S

U/C

Rooftop

or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 29 AUG 2018

Date/Time, File Pass to?

1)

typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

160

50

50

68

328

Report Format:

7P

Lump Sum / I.B.I. (\$ 4879.96)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024496/T1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7200C	Veh. Inspected	SLD 9487G
Policy No.		Coverage (\$)	0.00
Claim No.	D17011635MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/12/2017	Inspection Date	27/12/2017
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Janice Lee (LKKAUTO)

From: Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>
Sent: Friday, March 16, 2018 8:50 AM
To: Taufikh (LKKAUTO); SUR
Subject: FW: Finalization for SLD9487G - Reminder
Attachments: 2_20180122120359.pdf; b4 (1).JPG; b4 (2).JPG; b4 (3).JPG; b4 (4).JPG; b4 (5).JPG; b4 (6).JPG; b4 (7).JPG; b4 (8).JPG; rear reinforcement (1).JPG; rear reinforcement (2).JPG; rear reinforcement (3).JPG

Importance: High

Hi Taufik,

Appreciate if you could make confirmation soonest.

Please assist to confirm final amount at \$4,879.96 8 days

Warmest regards,

Selamatshahh Zainal

Senior Executive
Motor Claims Operations

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

HP: 9624 8656 | DID: 6654 7519 | Fax: 6654 7542

Website: www.ethozgroup.com



From: Selamatshahh Zainal
Sent: Monday, January 22, 2018 12:27 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalization for SLD9487G

Hi Taufik,

Please assist to confirm final amount at \$4,879.96 8 days

Warmest regards,

Selamatshahh Zainal

Senior Executive
Motor Claims Operations

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

HP: 9624 8656 | DID: 6654 7519 | Fax: 6654 7542

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-12-2017	Our Ref No. D17011635MFSH
Accident Date	15-12-2017	Claim Type. Third Party
Insured Vehicle	SHD7200C	Third Party Vehicle. SLD9487G
Survey Location	30 BUKIT BATOK CRESCENT	
Contact Person.	SELAMATSHAH ZAINAL	
Contact No.	66547519/ 96248656	Fax No. 65547542
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ETHOZ GROUP LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232072)



PRI Documents



Close



PRI Header Details

Claim No	D17011635MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & ETI
Workshop Name	ETHOZ GROUP LTD (Contact Person : SELAMATSHAH ZAINAL)	Survey Location & Contact Details	30 BUKIT BATOK CRESCENT Mobile: 96248656 , Phone: 66547519 , Fax: EmailId: SELAMATSHAH.ZAINAL@ETHOZGR		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD7200C	TP Vehicle No	SLD948
PRI Recieved Date	26-12-2017 08:30:35 PM	Surveyor Appointed Date	27-12-2017 11:32:39 AM	Surveyor Accept Date	27-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-12-2017	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name	Action
-----------	--------

Surveyor Job Remarks

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 26/12/2017
To : **FIRST CAPITAL INSURANCE LIMITED**

ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 15/12/2017
Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

- 1 REAR BUMPER
- 2 REAR BUMPER RETAINER
- 2 REAR BUMPER BRACKET
- 2 REAR BUMPER TOW COVER.
- 1 REAR BUMPER REINFORCEMENT
- 10 REAR BUMPER CLIPS
- 10 REAR BUMPER RIVETS
- 1 END PANEL
- 1 END PANEL TOP GARNISH

RESTORE

1,074.80 *del* / 1074.80
106.00 ?
111.20 ? } x um
82.20 *
537.30 ? 537.30 *ht*
50.00 *del* 50.00
90.00 *del* 90.00
185.10 x } x nm

Date : 26/12/2017

To : FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000064

Accident Date : 15/12/2017

Vehicle No : SLD-9487-G

Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	RESTORE		
1	BOOT LID	59.40	X R
1	EMBLEM - MAZDA 3	63.60	59.40
1	EMBLEM - SKYACTIV	925.10	63.60
1	FRONT BUMPER	108.20	925.10
2	FRONT BUMPER RETAINER	50.00	X n n
10	FRONT BUMPER CLIPS	444.50	50.00
1	FRONT BUMPER REINFORCEMENT	119.60	X n n
1	FRONT GRILLE ASSY	54.20	119.60
1	FRONT GRILLE LOGO	393.40	54.20
2	FRONT GRILLE CHROME MOULDING		X n n

Date : 26/12/2017
 To : FIRST CAPITAL INSURANCE LIMITED
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTRENT000064 Accident Date : 15/12/2017
 Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER TOP PANEL	194.70	de 194.70
1	BONNET	1,067.30	Rv
1	BONNET LOCK	197.10	Xun
1	FRONT FENDER LH	395.90	add damage.
1	SUPPORT PANEL		BT
	Sub Total	6309.60	
	Discount 20% On Parts	(1261.92)	
	Special Nett Item		
1	FRONT NUMBER PLATE	35.00	on 35.00
1	REVERSE SENSOR	220.00	200? Xun

RESTORE R

Date : 26/12/2017
To : FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 15/12/2017
Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

255.00

Labour & Misc

LABOUR TO FACILITATE REPAIR
TO RESPRAY AFFECTED AREAS
TO CHECK AND RECONNECT ALL NECESSARY WIRINGS
RUST PROOFING

1,500.00 / 200 1200.00

1,500.00 / 200 1000.00

50.00 30. 30.00

100.00 40. 40.00

Sub Total

3150.00

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Remarks:

Acknowledged by Repairer
Signature:
Date:

8,452.68

SUB TOTAL

GST 7.0 % 591.69

TOTAL 9,044.37

Yoko 205/60R16.

Surveyor's name: Tanpin 97425749

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 27/12/17 1330

WP' 27/12/17 Today
Resurvey before paint.
sur @ LKK auto.com



Date : 22/01/2018
To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 15/12/2017
Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	REAR BUMPER	1074.80	1074.80
2	REAR BUMPER RETAINER	106.00	0.00
2	REAR BUMPER BRACKET	111.20	0.00
2	REAR BUMPER TOW COVER.	82.20	0.00
1	REAR BUMPER REINFORCEMENT	537.30	537.30
10	REAR BUMPER CLIPS	50.00	50.00
10	REAR BUMPER RIVETS	90.00	90.00
1	END PANEL RESTORE	0.00	0.00
1	END PANEL TOP GARNISH	185.10	0.00
1	BOOT LID RESTORE	0.00	0.00
1	EMBLEM - MAZDA 3	59.40	59.40
1	EMBLEM - SKYACTIV	63.60	63.60
1	FRONT BUMPER	925.10	925.10
2	FRONT BUMPER RETAINER	108.20	0.00

PAGE : 1



Date : 22/01/2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000064 Accident Date : 15/12/2017

Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
10	FRONT BUMPER CLIPS	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	444.50	0.00
1	FRONT GRILLE ASSY	119.60	119.60
1	FRONT GRILLE LOGO	54.20	54.20
2	FRONT GRILLE CHROME MOULDING	393.40	0.00
1	FRONT BUMPER TOP PANEL	194.70	194.70
1	BONNET	1067.30	0.00
1	BONNET LOCK	197.10	0.00
1	FRONT FENDER LH	395.90	0.00
1	SUPPORT PANEL RESTORE	0.00	0.00
Sub Total		6309.60	3218.70
Discount 20% On Parts		(0.00)	(643.74)
Special Nett Item			
1	FRONT NUMBER PLATE	35.00	35.00

PAGE : 2



Date : 22/01/2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000064 Accident Date : 15/12/2017

Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REVERSE SENSOR	220.00	0.00
	Sub Total	255.00	35.00
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	1500.00	1200.00
	TO RESPRAY AFFECTED AREAS	1500.00	1000.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30.00
	RUST PROOFING	100.00	40.00
	Sub Total	3150.00	2270.00

PAGE : 3



Date : 22/01/2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000064 Accident Date : 15/12/2017

Vehicle No : SLD-9487-G Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	8,452.68	4,879.96
	GST 7.0 %	591.69	341.60
	Total	9,044.37	5,221.56

Surveyor Name : TAUFIK - LKK

Date & Time : 27/12/2017 1:30:00 PM

Selamatshahh

PAGE: 4

CLAIM DEPARTMENT

DID : 66547519

FAX :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17024496/T1rbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7200C	Veh. Inspected	SLD 9487G	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011635MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0342803	Colour	BLUE	
Odometer	63209	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2017	Inspection Date	27/12/2017	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 9487G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,074.80	1,074.80
2	REAR BUMPER RETAINER	NOT NECESSARY	106.00	-
2	REAR BUMPER BRACKET	NOT NECESSARY	111.20	-
2	REAR BUMPER TOW COVER	NOT NECESSARY	82.20	-
1	REAR BUMPER REINFORCEMENT	BENT	537.30	537.30
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
10	REAR BUMPER RIVETS	NECESSARY	90.00	90.00
1	END PANEL (NPA)	NOT NECESSARY	-	-
1	END PANEL TOP GARNISH	NOT NECESSARY	185.10	-
1	BOOT LID (NPA)	TO REPAIR SEE LABOUR	-	-
1	EMBLEM-MAZDA 3	NECESSARY	59.40	59.40
1	EMBLEM-SKYACTIV	NECESSARY	63.60	63.60
1	FRONT BUMPER	NECESSARY	925.10	925.10
2	FRONT BUMPER RETAINER	NOT NECESSARY	108.20	-
10	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	444.50	-
1	FRONT GRILLE ASSY	CRACKED	119.60	119.60
1	FRONT GRILLE LOGO	NECESSARY	54.20	54.20
2	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	393.40	-
1	FRONT BUMPER TOP PANEL	DEFORMED	194.70	194.70
1	BONNET	TO REPAIR SEE LABOUR	1,067.30	-
1	BONNET LOCK	NOT NECESSARY	197.10	-
1	FRONT FENDER LH (BENT)	OLD DAMAGED	395.90	-
1	SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,261.92	-643.74
			5,047.68	2,574.96
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	CRACKED	35.00	35.00

Report Ref No. CS/FCI17024496/T1rnb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			255.00	35.00
	LABOUR			
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF BOOT LID,BONNET AND SUPPORT PANEL.		1,500.00	1,200.00
	TO RESPRAY AFFECTED AREAS.		1,500.00	1,000.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		50.00	30.00
	RUST PROOFING.		100.00	40.00
			3,150.00	2,270.00
GRAND TOTAL			8,452.68	4,879.96
RECOMMENDED COST OF REPAIRS				4,879.96

Report Ref No. CS/FC117024496/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.