



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 1655D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	NECESSARY		
	SUNDRIES (SN)		50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	RESPRAY FRT BONNET,RH FRT AND REAR DOOR,ROOF TOP,REAR BOOT FRT AND REAR FENDER. R/I DOOR TIMMING AND PARTS TO FAC REPAIR.		4,048.00 1,848.00 5,896.00	3,036.00 1,232.00 4,268.00
GRAND TOTAL			5,946.00	4,318.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				4,318.00

Report Ref No. CS/GAI17024497/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.