

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Jan-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1045 Z

1 pc	Washer tank	✓ <i>CR</i>	\$	47.00
1 pc	Washer tank motor	✓ <i>CR</i>	\$	48.00
1 pc	Front n/s shock absorber	✓ <i>Best</i>	\$	330.00
1 pc	Front n/s lower arm	✓ <i>Best</i>	\$	439.00
1 pc	Front n/s knuckle bearing	✓ <i>Best</i>	\$	157.00
1 pc	Front n/s tie rod end	✓ <i>Best</i>	\$	61.00
1 pc	Engine cross member	✓ <i>Best</i>	\$	654.00
1 pc	Insulator Assy- Strut	✓ <i>Best</i>	\$	105.00
1 pc	Front o/s ABS sensor	✓ <i>slashed</i>	\$	232.00
1 pc	Engine under cover- Front	✓ <i>CR</i>	\$	44.00
1 pc	Engine under cover- n/s	✓ <i>CR</i>	\$	144.00
1 pc	Engine under cover- o/s	✓ <i>CR</i>	\$	173.00
1 pc	Intercooler	✓ <i>Best</i>	\$	800.00
1 pc	Valve Body cover	✓ <i>CR</i>	\$	132.00
			\$	3,366.00
			Less 10%	\$ 336.60
			\$	3,029.40

To lift engine to facilitate repair on chassis member	\$	450.00 <i>X</i>
<i>1st Estimate given</i>		
To dismantle and replace the front n/s undercarriage	\$	250.00 <i>100</i>
To dismantle and refir the engine cross member	\$	200.00 <i>100</i>
		3929.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

✓ *1st Estimate given* *(1/1/18)*