

123 CASE OWNER:

Bernard

CC 4/1817024503 / KX 3

123

123

Surveyor:

KENNETH

DOI:

27/12/17

Date / Time:

27/12/17

Registered in Meritron:

27/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLS 66912

Name of Insured:

NG HUAY ONG

Insured Tel No.:

HP: 84187621

Excess Sec II :SS

D.O.A: 24/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

06161625554

Policy No.:

1700058646

Make / Model:

MAZDA 3-1.5 SEDAN L SP. GRN

Place of Accident:

30 UPPER SERANGOON URBAN RI
VICTA CP

If NO, Driver Name / Age: NG WEE KIAT MATTHEW

Of GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: 84187621

(V/L YES / NO)

Insured Liability:

% Final? Yes / No

SFD 8276X



INSRS:

WSP: Accord Auto (Amk)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

02/01/18 (vic)

SFD 8276X - X ; SLS 66912 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of: 24/1/18 254

After call ltr to OI: 08/02/18 - No OI

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

24/1/18 12:12

Spoke to OI, LTA Package submitted to OI reporting
Centre in Trans 'Eurocar' per LTA - Sergei Pader.
Informed OI of TP claim and if there's no supporting
evidence will try to settle at best. Will sent out
Hitler.

05/01/18

Send letter to OI.
Email unknown unclear.
PINKHEAD.
ORIGINAL TP LOD IN.

12-02-14

TO VERIFY ACCIDENT CAUSE FROM CCTV BEFORE JUDGING
WHO IS LIABLE. BUT IT SEEMS NOT IN 3/2'S FAVOR.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 2,450.00

4 days

Reduction:

59

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NL

If NO or B 28, Ass. Lia:

(OLD REJECTED TO MARK)

Repair Cost:

SS 2,450.00

Loss of Rental (LOR):

SS 600.00

(5

days) x 120

Loss of Use (LOU):

SS -

(3

x days)

Loss of Income (LOI):

SS -

(3

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow / Independent)

Legal Cost

SS -

Total:

SS 2,050.00

Global Sum SS: 3,200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 3,200.00

Name 1:

Accord Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4300

6/1/18

ASS. REC. BY:

REF:

A-6-1

Kinnersh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 823k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFD 8376X Yr Regn: 10 108Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Accord c.c. 2354Colour: N. Grey A/C: Insured / Std / NI / NASp. Reading: 138871 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: MR17CP 26308 P020377Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal: 6 mmL/Bal: 6 mmD.O.A. 24/12/17

Survey held at

Rear

R/Bal: 2 mmL/Bal: 2 mmD.O.A. 27/12/17Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12 File sent to Customer

LIG \$2,460.00

CRSD: \$3,528.80 (59%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation:

S - RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

ESTIMATE

Date: 26/12/2017
Vehicle No: SFD8376X
Veh Make/Model: Honda Accord 2.4L
YOM: 2008
Chassis No: MRHCP26308P020377
Date of Accident: 24/12/2017

Not Notified
4 days
4 days

No	Qty	Description	Amount \$
List Items:-			
1	1	Front bumper	\$ 620.50
2	1	Front bumper side retainer - RH	\$ 18.00
3	10	Front bumper clips	\$ 30.00
4	1	Front bumper reinforcement	\$ 253.90
5	1	Front grille	\$ 114.40
6	1	Front grille chrome	\$ 132.60
7	6	Front grille clips	\$ 22.80
8	1	Support panel	\$ 600.60
9	1	RH headlamp	\$ 621.70
10	1	Front RH fender	\$ 607.70
11	1	Front RH fender splash shield	\$ 116.40
12	8	Front RH fender splash shield clips	\$ 30.40
Total - List Item			\$ 3,169.00
Less 20%			\$ 633.80
Total			\$ 2,535.20
Special Nett Items:-			
1	1	Front RH tyre	\$ 380.00
2	1	Front RH wheel rim	\$ 513.60
Total - SN Item			\$ 893.60
Labour Charges:-			
1		Spray painting on all affected area.	\$ 1,000.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,200.00
3		To apply anti rust treatment.	\$ 150.00
4		To check wiring system & light.	\$ 80.00
5		To check & adjust wheel alignment.	\$ 120.00
Total - L/C			\$ 2,550.00
Sub-Total			\$ 5,978.80
7% GST			\$ 418.52
Total			\$ 6,397.32

Accord Auto Consultants hence notify the Repairer of the following:
• To reserve damaged parts during repairs
• To display damaged part(s) during repairs
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date

Kh

619

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11, KSM Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Ashamed ESTIMATE

AIG Asean Insurance Pte Ltd

78 S

AIG 11-11-11-11

Singapore

Attn: Claims Department

Udy 8 245d
Running After pain
4 days

Date: 26/12/2017
Vehicle No: SFD8376X
Veh Make/Model: Honda Accord 2.4L
YOM: 2008
Chassis No: MRHCP26308P020377
Date of Accident: 24/12/2017

N	Description	Amount \$
1	Bumper	\$ 620.50
2	Bumper side retainer - RH	\$ 18.00
3	Bumper clips	\$ 30.00
4	Bumper reinforcement	\$ 253.90
5	Bumper reinforcement	\$ 114.40
6	chrome	\$ 132.60
7	clips	\$ 22.80
8	trim	\$ 600.60
9	trim	\$ 621.70
10	trim	\$ 607.70
11	Under splash shield	\$ 116.40
12	Under splash shield clips	\$ 30.40
Total - List Item		\$ 3,169.00
Less 20%		\$ 633.80
Total		\$ 2,535.20
Total - SN Item		\$ 893.60
Total - L/C		\$ 2,550.00
Sub-Total		\$ 5,978.80
7% GST		\$ 418.52
Total		\$ 6,397.32

• In stock damaged parts during repairs
• Parts prices are subject to availability
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplementary item(s) must be submitted and is subject to final approval from Insurance Company

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SFD8376X
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	ACCORD 2.4L
Chassis No. :	MRHCP26308P020377
Propellant :	Petrol
Engine No. :	K24Z21955615
Engine Capacity :	2354 cc
Maximum Power Output :	133.0 kW (178 bhp)
Maximum Laden Weight :	2000 kg
Unladen Weight :	1550 kg
Year Of Manufacture :	2008
Original Registration Date :	17 Oct 2008
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$14,400.00
COE Expiry Date :	16 Oct 2018
Road Tax Expiry Date :	16 Apr 2018
PARF Eligibility Expiry Date :	16 Oct 2018
Inspection Due Date :	16 Oct 2019

ACCORD AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A
#03-11 AMK AUTOPOINT
SINGAPORE 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516
Email: claims@mycarworkshop.com.sg

Date: 26/12/2017

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building #09-16
Singapore 079120
Att: Accident Claims Department

Fax: 6415 3727

Dear Sir/Mdm,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We have been appointed by Tsui Kok Leong Nico to repair his motor vehicle no. SFD8376X.

Please provide us the 10 surveyor name list.

Please be informed that the said vehicle can be inspected at:

Accord Auto Services Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint
Singapore 568047

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, we will commence repairs thereafter without further reference to you.

Yours faithfully,

ACCORD AUTO SERVICES PTE. LTD.
10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint
Singapore 568047

Jessy Soe

NB: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

- Pre repair inspection request - SFD8376X VS SLS6691Z (OI) DOA: 24/12/2017

From: Chan, Yoke Shi
To: assignments, Admin A
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang; Fan, Winnie-LW
Sent: Tuesday, 26 December, 2017 3:42:59 PM
Attachments:  SFD8376X.TIF

Hi,

Please refer to the enclosed request from **Accord Auto Services Pte Ltd**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (867191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com www.aig.com

10.25am @ 27/12/2017
vehicle In
person @ Jessy
sur @ Kenneth

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]

Sent: Tuesday, December 26, 2017 3:39 PM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang; Fan, Winnie-LW

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS6691Z AND SFD8376X ON 24/12/2017

Hi,

We would be appointing Kenneth Kong - LKK Auto Consultants Pte Ltd conduct PRS.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On 26 December 2017 at 15:27, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:
Without Prejudice

Your Reference : SFD8376X

Our Reference : SLS6691Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 195, Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017 Edit Reg		27 Dec 2017 00:00 Edit Adj Rpt	S\$2,450.00 Edit Estimates	S\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	NG HUAY ONG, ID: S1486504G		
Main Claimant:	TSUI KOK LEONG NICO, ID: S7414998G		
Vehicle Reg. No.:	SFD8376X	Date of Loss:	24/12/2017 16:00 - :59 [110 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0616162555SG	Policy/Cover Note No.:	1700058646
Vehicle Reg. No. (Insured):	SLS6691Z	Policy No. (Claimant):	5092811727
		Excess:	
Repairer:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQuan.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFD8376X (0616162555SG)
[SLS6691Z]
TP
TSUI KOK LEONG NICO
Dec 24 2017 4:00PM
[NG HUAY ONG]
Accord Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/09/19 08:50	Video - Accident From: SC - Reg. No: SLS6691Z, Claimant: NG HUAY ONG	Load MP4	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	

Assessment Reports

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/12/17 10:55	Accident Statement From: SC - Reg. No: SLS6691Z, Claimant: NG HUAY ONG	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 17:04	Odometer Reading	Load JPG	☒
2	09/05/18 17:04	Chassis Number	Load JPG	☒
3	09/05/18 17:04	General View	Load JPG	☒
4	09/05/18 17:04	General View	Load JPG	☒
5	09/05/18 17:04	General View	Load JPG	☒
6	09/05/18 17:04	General View	Load JPG	☒
7	09/05/18 17:04	General View	Load JPG	☒
8	09/05/18 17:04	General View	Load JPG	☒
9	09/05/18 17:04	General View	Load JPG	☒
10	09/05/18 17:04	General View	Load JPG	☒
11	09/05/18 17:04	General View	Load JPG	☒
12	09/05/18 17:04	General View	Load JPG	☒
13	09/05/18 17:04	General View	Load JPG	☒
14	09/05/18 17:04	General View	Load JPG	☒
15	09/05/18 17:06	General View	Load JPG	☒
16	09/05/18 17:07	Reinspection Photo	Load JPG	☒
17	09/05/18 17:07	Reinspection Photo	Load JPG	☒
18	09/05/18 17:07	Reinspection Photo	Load JPG	☒
19	09/05/18 17:07	Reinspection Photo	Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/17 17:43	EMAIL FROM AIG DD 26.12.2017	Load PDF	
2	27/12/17 17:43	ACKNOWLEDGEMENT EMAIL TO AIG DD 27.12.2017	Load PDF	
3	27/12/17 17:43	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	Load PDF	
4	02/01/18 11:35	TP ESTIMATE- MARKED	Load PDF	
5	26/01/18 11:01	LETTER TO GI	Load PDF	
6	09/12/19 08:17	WORKSHOP INVOICE	Load PDF	
7	09/12/19 08:17	AUTHORISATION TO ACT FORM	Load PDF	
8	09/12/19 08:17	Release Voucher	Load PDF	
9	09/12/19 08:17	RENTAL RECEIPT	Load PDF	
10	09/12/19 08:17	LOD	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLS6691Z (Insd veh)	Model:	HONDA ACCORD 2.4 (A)
	SFD8376X (TP veh)		
Date of Accident:	24/12/2017		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	6,397.32
Final Repair Cost	:	\$	3,200.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	5 days
LTA / GIA Search Fee	:	\$	_____
Others:	:	\$	_____
	:	\$	_____
Final Settlement Sum (Global Sum)	:	\$	3,200.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	Accord Auto Services Pte Ltd	:	\$	3,200.00
2)		:	\$	

JOANNE LEE KHANG MIN

09 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17024503/KEB3Q2

Date: 09/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700058646
Claimant
Vehicle No : SFD8376X **Insured Vehicle No :** SLS6691Z
Date of Loss: 24/12/2017 **Nature of Claim:** TP **Claim No:** 0616162555SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFD8376X**
 Make & Model: HONDA ACCORD, 2.4 (A) Engine No: K24Z21955615
 Reg. Date: 17/10/2008 (Man. Year: 2008) Chassis No: MRHCP26308P020377
 Colour: Metallic Grey Odometer: 138877 km
 Engine Capacity: 2354 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R17 Rear Tyre Size: 225/50Z R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 8 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,428.80	2,149.36	1,279.44	37.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	960.00	1,590.00	62.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,978.80	3,109.36	2,869.44	47.99
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	5,978.80	2,450.00	3,528.80	59.02
+ GST 7.00/7.00% (S\$)	418.52	171.50	247.02	59.02
Nett Amount (S\$)	6,397.32	2,621.50	3,775.82	59.02
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
Nett Liability (S\$)		3,221.50		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 27/12/2017
 Date Inspected: 27/12/2017 Inspected At: Accord Auto Services Pte Ltd (Bukit Merah)
 BLK 1009 BUKIT MERAH LANE 3,
 #01-80
 Singapore 159723

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	620.50 FL	*620.50 FL
2	1		*FRONT BUMPER SIDE RETAINER -RH	Distorted	18.00 FL	*18.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	253.90 FL	*- FL
5	1		*FRONT GRILLE	Serviceable	114.40 FL	*- FL
6	1		*FRONT GRILLE CHROME	Serviceable	132.60 FL	*- FL
7	6		*FRONT GRILLE CLIPS	Not Necessary	22.80 FL	*- FL
8	1		*SUPPORT PANEL	Repair	600.60 FL	*- FL
9	1		*RH HEADLAMP	Bent / Cracked	621.70 FL	*621.70 FL
10	1		*FRONT RH FENDER	Bent	607.70 FL	*607.70 FL
11	1		*FRONT RH FENDER SPLASH SHIELD	Distorted	116.40 FL	*116.40 FL
12	8		*FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	30.40 FL	*30.40 FL
13	1		*FRONT RH TYRE	Serviceable	380.00 FS	*- FS
14	1		*FRONT RH WHEEL RIM	Dented	513.60 FS	*513.60 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,062.60	2,558.30
- List Item Discount on L Items 20.00/20.00% (S\$)	633.80	408.94
Total Parts (S\$)	3,428.80	2,149.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTIG ON ALL AFFECTED AREA	New	1,000.00	450.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	400.00
3	TO APPLY ANTI RUST TREATMENT	New	150.00	30.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	80.00	20.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			2,550.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >