

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                 |   |                                     | Ref:           | NS/INC17024514/K1tbn2 |                    |  |
|--|---|-------------------------------------|----------------|-----------------------|--------------------|--|
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |   |                                     | Date:          | 15-01-2018<br>INC4    |                    |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |   |                                     |                |                       |                    |  |
|  | Insured Veh.  | SLM 8253Z                           | Veh. Inspected |                       | SHA 2671A          |  |
|  | Policy No.  | 5088313745-01                       | Coverage (\$)  |                       | 0.00               |  |
|  | Claim No.   | MT/0974848-002                      | Exces          | s (\$)                | 0.00               |  |
|  | Assign From   |                                     | Assign         | n Date                | 22/12/2017         |  |
| 2. Vehicle Particulars & Condition                                     |   |                                     |                |                       |                    |  |
|  | Make & Model  | HYUNDAI I40                         | c.c            |                       | 1685               |  |
|  | Engine No.  | HIDDEN                              | Year o         | f Reg.                | 2014               |  |
|  | Chassis No.   | KMHLB41UMEU052699                   | Colou          | r                     | BLUE               |  |
|  | Odometer  | 447089                              | Steering       |                       | IN ORDER           |  |
|  | Brakes  | IN ORDER                            | Modifi         | cation                | STANDARD ALLOY RIM |  |
|  | General   | FAIR                                |                |                       |                    |  |
| 3. Conditions of Tyres   |   |                                     |                |                       |                    |  |
|  |   | Size                                | Make           |                       | Balance            |  |
|  | R/H Front Tyre  | 205/60 R16                          | WEST           | LAKE                  | 7 mm               |  |
|  | L/H Front Tyre  | 205/60 R16                          | WEST           | LAKE                  | 7 mm               |  |
|  | R/H Rear Tyre   | 205/60 R16                          | WEST           |                       | 7 mm               |  |
|  | L/H Rear Tyre   | 205/60 R16                          | WEST           |                       | 7 mm               |  |
| 4.   |   |                                     |                |                       |                    |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.   |                                     |                |                       |                    |  |
|  | DAMAGES SEE DETAILS.  |                                     |                |                       |                    |  |
| 5.   | General Information   |                                     |                |                       |                    |  |
|  | Accident Date   | 21/12/2017                          | Inspec         | tion Date             | 22/12/2017         |  |
|  | Survey held at  | COMFORTDELGRO ENGINEERING PTE LTD   |                |                       |                    |  |
|  |   | 59 LOYANG DRIVE<br>SINGAPORE 508969 |                |                       |                    |  |
| 5a.  | a. Remarks  |                                     |                |                       |                    |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                     |                |                       |                    |  |
| 5b.  | 5b. Estimate Days of Repair   |                                     |                |                       |                    |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days  |                                     |                |                       |                    |  |