

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

26-Dec-17

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6940 L

1 pc	Bonnet grille		\$	386.00
1 pc	Front bumper	<i>X repair</i>	\$	531.00
			\$	917.00
		Less 10%	\$	91.70
			\$	825.30

### S/NETT

1 set	Front bumper clips	<i>X</i>	\$	48.00
1 pc	Front number plate with casing	<i>X</i>	\$	50.00

Sundry

\$	<del>50.00</del> <i>X</i>
----	---------------------------

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same

\$	<del>550.00</del> <i>200</i>
----	------------------------------

To putty and spray painting on front bumper, bonnet grille


\$	<del>400.00</del> <i>360</i>
----	------------------------------

To apply rustproofing on repaired and replaced panels

\$	<del>200.00</del> <i>X</i>
----	----------------------------

\$	2,123.30
----	----------

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.



*Keluz 1000*  
*26/12/17 0930h*  
*2 Pys.*  
*P/P*  
*Before P/L P/L*