

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Estimated Repair Cost

Page 1 of 3

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

S/N

1	Special Nett Items:	Qty	
	FRONT NUMBER PLATE C/W HOLDER X	1	\$ 60.00
Special Nett Total			\$ 60.00
Spare Part's Total Price			\$ 4790.40

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJQ 6945B

Vehicle Model : CHEVROLET AVEO 1.4MT 5DR T255

Chassis Number : KL1SF48719B683550

S/N	Labour Descriptions	Charges
1	Labour charges to remove & install rear end attachments & fittings to enable repairs; to cut & weld where necessary; to straighten & repairs tail-gate, rear luggage floor panel, both rear fenders and tail-gate panels; to replace damaged parts as listed above	\$ 1500.00 400
2	To spray painting on:- tail-gate, rear bumper & reinforcement, rear end panel, both rear fenders and rear luggage floor panel	\$ 1000.00 600
3	To remove & install rear compartment attachments, trimmings and fittings to enable repairs	\$ 100.00 50
4	To check rear electrical wirings & lights functions	\$ 50.00 30
5	To remove & replace rerar exhaust silencer	\$ 80.00 X
Labour Total		\$ 2730.00
Parts & Labour Total		\$ 7520.40

8 days.

Sebastian.
27/12/2017.

- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint.
90036121

sebastianyeang@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJQ 6945B

Vehicle Model : CHERVOLET AVEO 1.4MT 5DR T255

Chassis Number : KL1SF48719B683550

Estimated Repair Cost

S/N	Parts Description (Front)	Qty		
1	BONNET ✓ ST	1	\$	1687.00
2	BONNET LOCK X	1	\$	38.00
3	BONNET HINGE ✓ ST	2	\$	76.00
4	FRONT BUMPER ✓ CRK	1	\$	614.00
5	FRONT BUMPER CLIPS ✓ NEC	10	\$	50.00
6	FRONT BUMPER REINFORCEMENT ?	1	\$	219.00
7	FRONT BUMPER CENTRE FOAM ?	1	\$	106.00
8	FRONT BUMPER SIDE FOAM ?	2	\$	100.00
9	FRONT BUMPER BRACKET ✓ NEC ?	2	\$	40.00
10	FRONT BUMPER RHS RETAINER ✓ NEC	1	\$	25.00
11	FRONT RHS FENDER SPLASH SHIELD X	1	\$	36.00
12	FRONT RHS FENDER SPLASH SHIELD CLIPS X	10	\$	50.00
13	FRONT GRILLE ?	1	\$	280.00
14	FRONT GRILLE CHROME MOULDING ✓ SCR	1		
15	FRONT GRILLE CLIPS ?	10	\$	50.00
16	FRONT GRILLE TOP COVER ?	1	\$	15.00
17	FRONT BUMPER "+" EMBLEM ✓ NEC	1	\$	66.00
18	FRONT BUMPER LOWER CENTRE GRILLE ?	1	\$	160.00
19	FRONT BUMPER LOWER CENTRE GRILLE CLIPS ?	10	\$	50.00
20	FRONT FOG LAMP GARNISH ✓ SCR	1 pcs	\$	40.00
21	FRONT TOP PANEL R	1	\$	527.00
22	HEADLAMP (LHS & RHS) ?	2	\$	1156.00
23	A/C CONDENSER C/W RECEIVER DRYER ?	1	\$	650.00
24	RADIATOR ?	1	\$	543.00
25	RADIATOR TOP BRACKET ?	2	\$	20.00
26	RADIATOR TOP BRACKET MOUNTING ?	2		
27	BONNET LOWER LOCK X	1	\$	30.00
28	RADIATOR FAN COWLING ?	1	\$	615.00
29	RADIATOR ELECTRIC FAN ASSY ?	1		
30	ABS SENSOR SWITCH ?	1	\$	110.00
			\$	7353.00
	Discount Less 10%		\$	735.30
	List Prices Total		\$	6,617.70

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJQ 6945B

Vehicle Model : CHERVOLET AVEO 1.4MT 5DR T255

Chassis Number : KL1SF48719B683550

S/N	Labour Descriptions	Charges
1	Labour charges to remove & install front end attachments & fittings to enable repair; to cut & weld front panellings where necessary; to straighten, repairs both front fenders & inner panels and re-align same; to replace damaged parts as listed above	\$ 1200.00 400
2	To spray painting on: bonnet (inner & outer), front panellings, both front fenders , front bumper and reinforcement	\$ 1000.00 600
3	To remove & replace A/C condenser & reconnet A/C hoses; to vacuum & charge up gas	\$ 150.00
4	To remove & replace radiator, fan cowling & electric fan assembly; to reconnet hoses and pressurize cooling system	\$ 100.00
5	To remove & replace Air bag sensor; to check & reset E.C.U unit & remove fault codes	\$ 180.00 X
6	To remove & replace headlamps; check wirings & focus headlights	\$ 50.00 30
7	Towing charges	\$ 100.00
Labour Total		\$ 2780.00
Parts & Labour Total		\$ 9397.70