

INS. CASE OWNER:

CC 7/CTI1702

LKK:

IDAC

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTF



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

NAME: MOHAMED NAIMER AHMED MOHAMED

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 1156.11

Loss of Rental (LOR):

S\$ 625.00

(5 days) x 125

Loss of Use (LOU):

S\$ 250.00

(550 x 5 days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$ 2036.46

Global Sum S\$: 2030.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17024527/K1ub3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGQ 9740R	Veh. Inspected	SHC 8937J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/12/2017	Inspection Date	27/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Job: ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO: 205100837

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO: SHC8937J	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 23.12.2017 11:30
	YR OF MANU 14.04.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU087464	COMPLETION DATE/TIME

CHINA
AIG

Accident Date: 22.12.2017
Nature: 3P 23.12.2017

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION

Checked & Passed Out By: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHC8937J LKE/KALVIN

Vehicle No.: SHC8937J

Signature/Date Name of Service Advisor Date

Returned to Service Reception upon collection

To be kept by Security Guard



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI17024527/K1ub3

Date: 27.12.2017

The Motor Claims Department
M/s CHINA TAILING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC8937J

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.12.2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,411.58
Revised Estimate Amount	: S\$	1,080.48
"Check" Items Amount	: S\$	845.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Our Job Ref No : 305100837
Date : 31/12/17

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508669
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No : SHC8937J CTPL

Fax :


22.12.17


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA -- SGQ9740R
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$680.48
 - (b) Labour Charges \$400.00
 - Total for Part-By-Part Repair Cost \$1,080.48
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Kalvin
Date : 2/1/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 31.12.2017

REPAIR ESTIMATE

Time: 10:02:37

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305100837
REGN NO : SHC8937J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.04.2016
DATE/TIME IN : 23.12.2017 11:30
ACCIDENT DATE : 22.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	603.60	20.00	482.88
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	225.00	20.00	180.00

SUB-TOTAL : 680.48

JOB NATURE

0000 L	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	180.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 400.00

TOTAL : 1,080.48

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

DATE: 27/12/2017 10:03

$P \rightarrow P$

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper — <i>Refined</i>			\$ 603.60
	Rear Bumper Reinforcement <i>X_{sc}</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X_{sc}</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X_{sc}</i>			\$ 49.00
	Rear Bumper Clips — <i>sc</i>			\$ 22.00
	Rear Bumper Sponge <i>X_{sc}</i>			\$ 143.40
	Rear Bumper Under Cover — <i>sc</i>			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor <i>X_{sc}</i>			\$ 135.70
				\$ 135.70
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,411.58
	<i>Kelvin (LKK)</i>			
	<i>27/12/17 1045h</i>			
	<i>200</i>			
	<i>PIP</i>			
	<i>Before Paint photo</i>			

LKK Auto Repair Centre

We hereby notify the Repairer that we will:

- To repair the damaged parts
- To disassemble and reassemble the damaged parts
- Parts prices will be based on the latest market survey
- Third party claims will be handled on a non-profit basis
- No claim will be accepted if the repair is not completed within 30 days
- Supplier will be responsible for the quality of the parts

Accepted by Repairer: _____

Signature: _____

Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8937J

DATE 27/12/2017 10:03

MAKE :

MODEL : HYUNDAI i40

LKK/Kalvin

pby P

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper —			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips —			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover —			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70 Nett
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 380.00 200
	Spray Painting Charge			\$ 200.00 180
	Wiring Charge			\$ 50.00 X
	R/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,411.58
	Kellie (LKK) 27/12/17 1045h 2 Pcs PIP Before Paint photo			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No legal modification is allowed • Supplementing must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

COMFORTDELGRO ENGINEERING

Our Ref : T 1217 / SHC8937J /WT(st)
Your Ref : _____
Date : 05-Jan-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 19890048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 726791

Yishun
Yishun Industrial Park A
Singapore 768732

CHINA INSURANCE CO LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC8937J YOUR INSURED SGQ9740R
AND OTHER _____ ON 22.12.17

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHC8937J which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SGQ9740R we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

- 1 Cost of Repair
- 2 6 days Loss of Rental @ \$ 125.00 per day
- 3 Survey Report Fees (Surveyed by M/s LKK)
- 4 LTA Search Fees
- 5 GIA / Police Report Fees
- 6 Towing / Medical / Transporation Fees

\$	1,156.11
\$	750.00
\$	-
\$	7.49
\$	-
\$	-
Sub Total :	\$ 1,913.60

HIRER'S CLAIM

- 7 6 days Loss of Income @ \$ 80.00 per days

\$	480.00
Total Claims :	\$ 2,393.60

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photostat photographs :
 - b) LTA search slip/s of : SGQ9740R
 - c) GIA / Police report/s of : SHC8937J
 - d) Letter of authority from owner / hirer / operator
- () Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance
(X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
William Tan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Friday, 5 January 2018 5:24 PM
To: 'lwf@laiyewseng.com.sg'
Cc: 'mohideen@laiyewseng.com.sg'
Subject: ACCIDENT INVOLVING SGQ 9740R AND SHC 8937J ON 22/12/2017



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI17024527/K1ub3

08 JANUARY 2018

LAI WAN FONG

Dear Sir/Madam,

ACCIDENT INVOLVING SGQ 9740R AND SHC 8937J ON 22/12/2017

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
Fax: 6741 4108
Email: thinthin@lkkauto.com

c.c. China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGi 40 SHC8937J , SGQ9470R
S'GOON NORTH AVE 4 JUNCTION OF S'GOON NORTH AVE 5.

ON 22-Dec-17 20:30

I / We

ONG CHEE CHENG

(Hirer) NRIC No.: S1732799B

and/or

CHEW POH SOON

(Relief) NRIC No.: S1495042G

Taxi Number

SHC8937J

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

23-Dec-2017

Name of Hirer
Hirer NRICONG CHEE CHENG
S1732799B

Signature :

Address

299A COMPASSVALE STREET #14-134
541299

Contact No.

91095542

Name of Relief
Relief NRICCHEW POH SOON
S1495042G

Signature :

Address

837 HOUGANG CENTRAL #03-531
530837

Contact No.

98152527

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN3006651700 Claim No : SNM17D07284

Claimant : COMFORT TRANSPORTATION PTE LTD

Amount : S\$ 2,030.00
Singapore Dollars Two Thousand and Thirty Only

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHC 8937J

Insured Vehicle No. : SGQ 9740R

Date of Loss : 22/12/2017

Place of Accident : JUNCTION OF SERANGOON NORTH AVE 4 & 5

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : LAI WAN FONG

Driver Name : MOHAMED NAINAR AHAMAD MOHIDEEN

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Global Sum	:	<u>S\$ 2,030.00</u>
Total	:	<u>S\$ 2,030.00</u>

Claimant Name : COMFORT TRANSPORTATION PTE LTD NRIC No : _____

Signature : _____ Date : 22-1-18

cc signed

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
98 LOYANG DRIVE
SINGAPORE 508669

*The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document*

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 1

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLEAF TOWER3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO
SHC8937JMAKE
HYUNDAIMODEL
I-40DATE OF REG
14.04.2016CHASSIS CODE
KMHLB41UMGU087464INV. NO/DATE
91349392 30.12.2017JOB NO.
305100837

ODOMETER READING

DATE/TIME IN
23.12.2017 11:30

Description : 3P 22.12.2017

S/No Part No.

Qty Unit Price %Disc Net

PART REQUISITION

0001	04-01-0103-0579	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002	04-01-0101-0111	HYUNDAI BUMPER COVER CLIP	10	2.20	20.00	17.60
0003	04-01-0103-0738	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
SUB-TOTAL			:			680.48

JOB NATURE

0001	L	PANEL BEATING	200.00		200.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	180.00		180.00
0003	20-22	REMOVE/REFIX REVERSE SENSOR	20.00		20.00
SUB-TOTAL			:		400.00

ComfortDelGro Engineering Pte Ltd
Member of COMFORTDELGROOffice:
Braddell Road
Singapore 579701

Please note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91349392	1,156.11	

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 2

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO
SHC8937J

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
14.04.2016

CHASSIS CODE
KMHLB41UMGU087464

INV. NO/DATE
91349392 30.12.2017

JOB NO.
305100837

ODOMETER READING

DATE/TIME IN
23.12.2017 11:30

Items total	1,080.48
Add GST @ 7.000 %	75.63
Invoice amount	1,156.11

Issued by : CHEWBEELENG 02.01.2018 16:22:56
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd
member of COMFORTDELGRO

Head Office:
15 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91349392	1,156.11	

Our Ref: CT17120859

Date: 02 January 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	22/12/2017 @ 20:30 hrs
ALONG	S'GOON NORTH AVE 4 JUNCTION OF S'GOON NORTH AVE 5
INVOLVING	SGQ9740R

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC8937J** (the "Taxi"). The Taxi was hired to **ONG CHEE CHENG IC NO S1732799B** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO
764	04.30	1530
338	1600	0150
316	04.30	1530
285	1600	0230
313	04.30	1530
259	1600	0120
370	05.00	1610
330	1300	0400
392	0530	2050
369	04.30	1600
390	1600	0040

DATE	NAME OF DRIVER	MILEAGE READING			MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		3	1	2		FROM	TO
19/12/17	Ony	3	1	2	336	04.30	1450
19/12/17	Ony	3	1	2	364	1600	0230
20/12/17	Ony	3	1	3	289	04.30	1550
20/12/17	Ony	3	1	3	358	1600	
21/12/17	Ony	3	1	3	289	04.30	1530
21/12/17	Ony	3	1	3	266	1600	0130
21/12/17	Ony	3	1	4	309	04.30	1540
22/12/17	Ony	3	1	4	309	1600	0245
22-12-17	Ony	3	1	4	117	04.30	0700
23/12/17	Ony	3	1	4	117	1130	—
23/12/17	Accident				Layang	—	1100
28/12/17	Repair					—	—

Ony drive deng

Thank you



Goh Cheng Chuan Andrew Cornelius has successfully logged out.

Your last login date and time was 26 Dec 2017, 11:09:15.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SGQ9740R -		18.32 Insurance Enquiry (GIRO Payment)	7.49	26 Dec 2017 / 11:11:55

SHC8937J

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
-------------	--------------------	---------------	------------------------	------------------------

SGQ9740R	22 Dec 2017 / 20:30:00	Successful
----------	------------------------	------------

C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#) [OK](#)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17024527/K1ub3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 30-01-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGQ 9740R	Veh. Inspected	SHC 8937J
Policy No.	DMPCSN3006651700	Coverage (\$)	0.00
Claim No.	SNM17D07284	Excess (\$)	0.00
Assign From		Assign Date	27/12/2017
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU087464	Colour	BLUE
Odometer	314738	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/12/2017	Inspection Date	27/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8937J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	-
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	CRACKED	225.00	225.00
	LESS 20% DISCOUNT		-381.47	-170.12
			1,525.88	680.48
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			135.70	-
<u>LABOUR</u>				
	PANEL BEATING .		380.00	200.00
	SPRAY PAINTING CHARGE .		200.00	180.00
	WIRING CHARGE .	NOT NECESSARY	50.00	-
	R/REFIX REVERSE SENSOR .		120.00	20.00
			750.00	400.00
GRAND TOTAL			2,411.58	1,080.48
RECOMMENDED COST OF REPAIRS				1,080.48

Report Ref No. CC3/CT117024527/K1ub3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.