

DING AUTO PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	SJG397A
Model:	TOYOTA COROLLA ALTIS 1.6 (A)
Chassis:	MR053ZEE106111819

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR DOOR RH <i>Not work</i>	1	\$ 1,135.50	25%	\$ 1,021.95	✓
2	REAR FENDER RH	1	\$ 1,034.95	25%	\$ 776.46	X
3	REAR BUMPER ASSY	1	\$ 534.00	25%	\$ 400.50	X
4	REAR BUMPER SIDE RETAINER RH	1	\$ 72.60	25%	\$ 54.45	X
5	REAR DOOR MOULDING RH	1	\$ 101.90	25%	\$ 76.43	✓
6	REAR DOOR CHROME RH	1	\$ 32.40	25%	\$ 24.30	✓
TOTAL:					\$ 2,665.22	

	LABOUR	PRICE	SURVEYOR MARKING
7	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	\$ 600.00	500
8	R & R R/H/R DOOR COMPOENTS	\$ 120.00	60
9	R & R R/H/R QUARTER GLASS	\$ 100.00	X
10	CHECK & REPAIR WIRING SYSTEM	\$ 60.00	60
11	RESPRAY FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, ROCKER PANEL RH & REAR BUMPER	\$ 1,000.00	650
TOTAL:		\$ 1,000.00	

PARTS	\$ 2,665.22	
LABOUR	\$ 1,000.00	
SPECIAL NETT	#REF!	
TOTAL	#REF!	
GST 7%	#REF!	
FINAL TOTAL	#REF!	

*Not with work
L1 By @ 1650
Review After Paint
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before enter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: