

## **REPAIR ESTIMATE\***

DATE 27/12/2017 13:36

**MODEL : HYUNDAI i40**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Front fender (RH) x repair			
	SUB TOTAL			\$ 593.90
	LESS 20%			\$ 118.78
	DISCOUNTED TOTAL			\$ 475.12
	Frt Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 400.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 1,375.12
	Kalvin LKK/KC			
	27/12/17 1420h			
	2 Days.			
	P/P			
	Before Paint photo			
	LKK Auto Consultants hence notify the Repairer of the following:			
	To resurvey before/after spray painting			
	To display damaged part(s) during resurvey			
	Parts prices are subject to confirmation			
	Third party survey is on a "Without Prejudice" basis			
	No illegal modification(s) is allowed			
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			