

REPAIR ESTIMATE*

VEHICLE NO : SHC 1942P

DATE 27/12/2017 10:30

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) ✗			\$ 86.00
	Front Fender Retainer ?			\$ 9.20
	Front Wheel Hub Cap (RH) ✓			\$ 145.00
	SUB TOTAL			\$ 833.20
	LESS 20%			\$ 166.64
	DISCOUNTED TOTAL			\$ 666.56
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 200
	Spray Painting Charge			\$ 400.00 360
	Tuff Kote			\$ 50.00 20
	FRT Wheel Alignment			\$ 120.00 60
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 1,896.56
	1 Calm 166K 27/12/17 1520h 2 Days 4/5 After Repair p Loto			

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.