

INS. CASE OWNER:

Tune

CC 3 / CTI17024569 / K115302

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

27/12/17

Date / Time:

27/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGL 4447Y

Claim No.:

SNM 17D0729/C02/7

Name of Insured:

PANNEERSELVAM S/O RAMASAMY

Policy No.:

DUPCON3079351600

Insured Tel No.:

HP: 9145 8638

Make / Model:

TOYOTA VIOS - 1.5 (A)

Excess Sec II :\$

D.O.A: 23/12/17

Place of Accident:

WOODLANDS AVE 12 T

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 6716T



INSRS:

WSP: Premier Auto (Chang)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time		STAGE	DATE / PIC
12/01/18 (V.C)	SHC 6716T - CC3/CTI17000664/H109302 DOA: 02/01/18 SGL 4447Y - NA/INCO2023318/SI DOA: 21/05/18	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
12/1/18 (A 1532 pm)	Spoke to OI Mr PANNEERSELVAM 9145 8638 agreed to settled on TP claims - will sent out letter.	Call OI: 12/1/18 7:51m Hawn	
		After call ltr to OI: 12/1/18 - OK OK	
13/01/18	SEND LETTER TO OI. TYPE REPORT. PROVIDING TP LOD. TP LOD IN BY EMAIL. REPORT DONE. BROW BK REQUESTED 16 JAN 2018	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
28/02/18	SEND 1ST OFFER TO TP. TP ACCEPTED OFFER. ALL DOCS IN ORDER. TO CLOSE.	Car Rental Invoice:	
		Towing Invoice	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: 28/12/17

Sent By: Shirley Hiew

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: P/P SS 2,281.60: 3 days Reduction: 60 %			Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: 28/02/18 Confirm with: GARY			Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27			If NO or B 28, Ass. Lia: (OI RATE - ENDED TP)
Repair Cost: C/W/650 SS 2,441.31			
Loss of Rental (LOR): SS 269.70 (2.5 days) X \$107.88			
Loss of Use (LOU): SS 100.00 (\$ 40 x 2.5 days)			
Loss of Income (LOI): SS - (\$ x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/> [Tick only one]			
GIA/LTA Search SS 2.00			
Medical: SS -			
Disbursement: SS - (e.g. Tow/ Independent)			
Legal Cost SS -			
Total: SS 2,813.01 Global Sum SS: 2,810.00			
FINAL PAYMENT Date/Time: Confirm with:			Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1: SS 2,810.00 Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTD			
Payee 2: (Strike if N.A.) SS - Name 2: -			
Payee 3: (Strike if N.A.) SS - Name 3: -			

Summary

Kalvin

REF.

ASSIGNMENT

From _____ Date _____
Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHC 67167

Reg:

19 Mar 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Tr~~ / Prima Mover /

Truck / Trailer or

Make

KIA optima

cc 1600

Colour

silver

A/C Insured / Std / NI / NA

Sp Reading

306695

T-Radio Insured / Std / NI / NA

Eng No:

C/No

KN AHM 414MF 8593369

Gen. Cond: Good / ~~F~~ / Poor / Burnt

Steering: In ~~o~~ / Jammed / Leaked / Burnt or

Brake: In ~~o~~ / Jammed / Leaked / Burnt or

Mod: Nil / SiRim / STD ~~R~~ Rim or

Tyre Size

F: 205 / 65 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D/O.A.

23/12/12

D/O.A.

27/1/13

Survey held at

Premier

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/12/12 Control P/R \$2281.60/3hr.
CRO: \$3,481.70 (60%)

CTI
P/R

Date/Time File Pass to:

☐

: Preli. Report

1.

☐

: Final Report

Date/Time File Return to:

2.

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Weekend \$

Report Format:

Lump Sum / I.B.I. / S

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Inspector:

12-12-12

Printed:

Checked:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17024569/K1hs3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 28-12-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGL 4447Y	Veh. Inspected	SHC 6716T	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM17D07291C02/7	Excess (\$)	0.00	
Assign From		Assign Date	28/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/12/2017	Inspection Date	27/12/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI17024569/K1hs3

Date: 28.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 6716T


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.12.2017 at the premises of M/s Premier Automotive Services Pte Ltd (Changi South) and have the following to report:-

Workshop Estimate Amount	: S\$	5,763.30
Revised Estimate Amount	: S\$	2,281.60
"Check" Items Amount	: S\$	810.90
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	19 Mar 2015 / 10:19:23	Receipt No.:	AACCK001-AX239-150319-000023
Asset Type:	Vehicle	Transaction Amount:	\$65,578.00
Asset ID:	SHC6716T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150319101923951692		
Vehicle No.:	SHC6716T		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:-	19 Mar 2015		
Original Registration Date:	19 Mar 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis-No.:	KNAGM414MF5593369		
Engine No.:	D4FDEH313357		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,318.00		
Minimum PARF Benefit:	\$8,607.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	19 Mar 2015 10:19:23		
COE No.:	2015031901002283C		
COE Expiry Date:	18 Mar 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$51,092.00		
Lifespan Expiry Date:	18 Mar 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

26-Dec-17

Chin

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6716 T

1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	Rear muffler assy ✓	\$	1,009.00
1 pc	Rear exhaust pipe hanger ✓	\$	49.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✓	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>MSX o/s ✓</i>	\$	92.00
		\$	3,317.00
		Less 10%	\$ 331.70
		\$	2,985.30

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 <i>200</i>
1 pc	Rear bumper top protector ✓	\$	80.00 <i>50</i>

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6716 T

Sundry

\$ ~~50.00~~ ²⁰

To dismantle / replace exhaust pipe

\$ ~~120.00~~ X

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ ~~120.00~~ ²⁰

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ X

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the bootlid lower garnish, etc.

\$ ~~750.00~~ ⁴⁰⁰

To putty and spray painting on bootlid, bootlid lower garnish, end panel & rear bumper

\$ ~~900.00~~ ⁵⁴⁰

To apply rustproofing on the repaired and replaced panels.

\$ ~~150.00~~ X

\$ 5,763.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin Kelly

27/12/17 0954hrs.

3 Rys.

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Dec-17

Chris

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6716 T

1 pc	Bootlid emblem	✓ ne	\$	27.00 ✓
1 pc	Bootlid CRDi	✓ ne	\$	29.00 ✓
1 pc	End panel	X repair	\$	250.00
1 pc	Rear muffler assy	X su	\$	1,009.00
1 pc	Rear exhaust pipe hanger	X su	\$	49.00
1 pc	Rear bumper	✓ Rehl	\$	696.00 ✓
1 pc	Rear bumper lower cover	✓ cm	\$	206.00 ✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X su	\$	58.00
1 pc	Rear bumper inner sponge	X su	\$	114.00
1 pc	Rear bumper reinforcement	X su	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X su	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X su	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X su	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	MS X su o/s ✓ or	\$	92.00
			\$	3,317.00
			Less 10%	\$ 331.70
			\$	2,985.30

S/NETT

1 set	Rear bumper clips	✓ ne	\$	48.00
1 set	Bootlid stickers	✓ ne	\$	100.00
1 set	Reverse sensor	✓ shelt	\$	280.00 200
1 pc	Rear bumper top protector	✓ ne	\$	80.00 50

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6716 T

Sundry *NEL*

\$ ~~50.00~~ ²⁰

To dismantle / replace exhaust pipe

\$ ~~120.00~~ ^{X an}

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ ~~120.00~~ ²⁰

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ ^{X an}

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off ~~the~~ the end panel, including knock-out, straighten, repair, reshape and adjust of the bootlid lower garnish, etc.

\$ ~~750.00~~ ⁴⁰⁰

To putty and spray painting on bootlid, bootlid lower garnish, end panel & rear bumper

\$ ~~900.00~~ ⁵⁴⁰

To apply rustproofing on the repaired and replaced panels.

\$ ~~150.00~~ ^{X an}
\$ 5,763.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Koluk KKK

27/12/17 0954h

3Ry1.

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

29/12/17

coluk P/P \$2281.60 / 3Ry1

Shirley Hiew (LKK Auto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Thursday, 11 January 2018 10:12 AM
To: Shirley Hiew (LKK Auto); Asher Sng (LKKAuto); Admin A
Cc: Irene Tay; Alfred Toh; Chee So Chow; KKLau; Olivia Lau (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SGL4447Y (OI : SNM17D07291C02/7) AND SHC6716T (TP : LKK REF - CC3/CTI17024569/K1hs3) on 23/12/2017
Attachments: MSAT17168751-SGL4447Y.pdf

LKK REF - CC3/CTI17024569/K1hs3
CTI REF - SNM17D07291C02/7 (SGL4447Y)

Dear Shirley

We refer to your email of even date pertaining to the above matter.

Attach herewith Insured's SAS report for your attention and necessary action.

Irene, please follow up on the matter.

Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID : +65 6389 6183
FAX: +65 6224 7175/6224 7478
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, January 11, 2018 9:54 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SGL4447Y (OI : SNM17D07291C02/) AND SHC6716T (TP : LKK REF - CC3/CTI17024569/K1hs3) on 23/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Vic (LKKAUTO)

From: Gary Shi <gary.shi@premiertaxi.com>
Sent: Wednesday, 28 February, 2018 3:27 PM
To: Vic (LKKAUTO)
Cc: AccReport; Admin A; Asher Sng (LKKAUTO)
Subject: RE: LOD / Accident involving SHC6716T & SGL4447Y on 23.12.17 (China Taiping case) LKK REF CC3/CTI17024569/K1hs3
Attachments: SHC6716T - DV.pdf

WITHOUT PREJUDICE

Dear Vic,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6716T, our client agreed to direct settle the above claims at \$2810.00

We enclosed hereby Discharge voucher & ATA for your kind attention. Original copies will pass to Mr Kalvin

Kindly let us have your settlement sum of S\$2810.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Wednesday, 28 February, 2018 12:23 PM
To: Gary Shi
Cc: AccReport; Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)
Subject: RE: LOD / Accident involving SHC6716T & SGL4447Y on 23.12.17 (China Taiping case) LKK REF CC3/CTI17024569/K1hs3

Without Prejudice

Dear Gary,

We refer to further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we propose a global sum of **\$2,810.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the enclosed **DV and ATA** then forward back to us the original signed copy together with the LOD and supporting documents for payment processing.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Friday, 19 January, 2018 9:27 AM

To: Gary Shi

Cc: AccReport; Admin A; Vic (LKKAuto); Asher Sng (LKKAuto)

Subject: RE: LOD / Accident involving SHC6716T & SGL4447Y on 23.12.17 (China Taiping case) LKK REF CC3/CTI17024569/K1hs3

Without Prejudice

Dear Gary,

We refer to your below email and the contents were noted.

We will get back to you for an update/offer in due course.

Thank you.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Gary Shi [<mailto:gary.shi@premiertaxi.com>]

Sent: Thursday, 18 January, 2018 10:29 AM

To: Asher Sng (LKKAuto); Vic (LKKAuto)

Cc: AccReport; CS A Team

Subject: LOD / Accident involving SHC6716T & SGL4447Y on 23.12.17 (China Taiping case)

WITHOUT PREJUDICE

Dear Asher & Vic,

Your Ref: SGL4447Y

Our Ref: SHC6716T/GS

Date of accident: 23/12/2017

We refer to the above mentioned accident.

Hereby we would like to append our losses from China Taiping Insurance (S) Pte Ltd, as insurers of vehicle number SGL4447Y which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Regards

Gary Shi

Senior Executive, Claims

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443

Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17024569/K1hs3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-03-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGL 4447Y	Veh. Inspected	SHC 6716T	
Policy No.	DMPCSN3079351600	Coverage (\$)	0.00	
Claim No.	SNM17D07291C02/7	Excess (\$)	0.00	
Assign From		Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5593369	Colour	SILVER	
Odometer	306695	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/12/2017	Inspection Date	27/12/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6716T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	REAR MUFFLER ASSY	SERVICEABLE	1,009.00	-
1	REAR EXHAUST PIPE HANGER	SERVICEABLE	49.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	O/S CRACKED / N/S SERVICEABLE	92.00	46.00
	LESS 10% DISCOUNT		-331.70	-100.40
			2,985.30	903.60
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			558.00	418.00
LABOUR				
	TO DISMANTLE/REPLACE EXHAUST PIPE.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00

Report Ref No. CC3/CTI17024569/K1hs3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE BOOTLID LOWER GARNISH, ETC. INCLUSIVE OF THE REPAIR OF END PANEL.		750.00	400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, END PANEL & REAR BUMPER.		900.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			2,220.00	960.00
GRAND TOTAL			5,763.30	2,281.60
RECOMMENDED COST OF REPAIRS				2,281.60

Report Ref No. CC3/CTI17024569/K1hs3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.