

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Dec-17

Chin

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6716 T

1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	Rear muffler assy <i>X</i>	\$	1,009.00
1 pc	Rear exhaust pipe hanger <i>X</i>	\$	49.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>MSX o/s ✓</i>	\$	92.00
		\$	3,317.00
		Less 10%	\$ 331.70
			\$ 2,985.30

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 <i>200</i>
1 pc	Rear bumper top protector ✓	\$	80.00 <i>50</i>

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6716 T

Sundry	\$ 50.00 ²⁰
To dismantle / replace exhaust pipe	\$ 120.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 ²⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the bootlid lower garnish, etc.	\$ 750.00 ⁴⁰⁰
To putty and spray painting on bootlid, bootlid lower garnish, end panel & rear bumper	\$ 900.00 ⁵⁴⁰
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 X
	<u>\$ 5,763.30</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin (LKK)

27/12/17 0954hrs.

3R71.

P/P

Before Paint photo