

Xnd.

REF:

AKG

CC3/ALH17024570/Gabnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s **Premium Auto**

of _____

Insured: _____

Policy No: _____

Claims No: **757674127 SK**

Sum Insured: _____ Excess: **2800 07/1/18**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value: **\$233K.**

IDAC Accident Rpt.: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **8** days Res.: Yes or No

Lum Sum: _____ % 3-Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLP 9792L** Yr Regn: **23 Jun 2017**

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Audi A5 Sport 1984**

Colour: **white** A/C: Insured / Std / NI / NA

Sp. Reading: **3739** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WAU8ZZFY4H 2025432**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: **235/55 R19**

R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **continental**

Front

R/Bal. **9** mm

L/Bal. **9** mm

D.O.A. _____

Rear

R/Bal. **9** mm

L/Bal. **9** mm

D.O.I. **27-12-17**

Survey held at: **w/s**

5:30pm

Des. of Damages: ☒ Fr / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12/17 @ 3.45pm went to Victor via messenger.
07/1/18 @ 11.17am Victor informed O/A via messenger.
07/1/18 @ 11.34am informed Tony C/A 3 ex: \$2800 by email.
07/1/18 @ 5.42pm confirmed with Carvine final fig \$16815.52, 8 days by email.
Chad \$13836.48, 45%.

RECEIVED 13 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **8**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Photos

Others

TOTAL

Report Format: **net-00**

Lump Sum / I.B.I: (\$ **16815.52**)

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17024570/Gqb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 28-12-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLP 9792L
Policy No.	Coverage (\$)	0.00
Claim No. 999994947	Excess (\$)	0.00
Assign From	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 23/12/2017	Inspection Date 27/12/2017
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 28 Dec 2017

Preliminary Advice

Vehicle No	: SLP9792L	Accident Date	: 23/12/2017
Make	: AUDI Q5	Policy No.	: 999994947/100828728-00000
Assignment Date	: 28/12/2017	Excess	: S\$0.00
Date of Inspection	: 27/12/2017	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,652.00
Revised Amount	:S\$	19,249.00
Check Items (Estimated)	:S\$	7,580.00
Total	:S\$	26,829.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	233,000.00
COE / PARF Rebate	:S\$	90,277.00
Salvage Value	:S\$	
Margin for Repair	:S\$	142,723.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 7 November 2018 5:42 PM
To: PAL Claim; Guo Qiang (LKKAUTO); SUR
Cc: 'Nora Khai'; jiayee.yap@premiumauto.com.sg; 'Boo seng yak';
claims@premiumautocare.com.sg; carrine.leong@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLP9792L - OD AIG - SURVEYED 23 DEC 17

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$16,815.52 before excess \$2,800.00 & GST and 8 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 14 September 2018 4:16 PM
To: PAL Claim <claims@premiumauto.com.sg>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Nora Khai' <nora.khai@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; 'Boo seng yak' <boojohnny@gmail.com>; claims@premiumautocare.com.sg; carrine.leong@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLP9792L - OD AIG - SURVEYED 23 DEC 17

Dear Sir/Madam,

Kindly assist as below email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 16 August 2018 12:13 PM
To: PAL Claim <claims@premiumauto.com.sg>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Nora Khai' <nora.khai@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; 'Boo seng yak' <boojohnny@gmail.com>; claims@premiumautocare.com.sg; carrine.leong@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLP9792L - OD AIG - SURVEYED 23 DEC 17

Dear Jeffrey,

Kindly provide us the damaged photo of tyre – Continental SP.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 2 January, 2018 11:34 AM
To: 'Claims'; SUR
Subject: RE: SLP 9792 L Own Damage Claims (Vehicle IN)

Dear Tony,

As instructed by our client, please proceed to repair the insured vehicle **SLP 9792L (excess \$2,800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 29 December, 2017 8:43 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLP 9792 L Own Damage Claims (Vehicle IN)

Dear All,

Any update on approval?

Thank you and Wishing you a Happy New Year 2018!

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	27 Dec 2017 17:31	Clim Veh Model Changed	Reg No: SLP9792L. Policy No: 999994947/100828728-00000. Acct Date: 2017/12/23. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA117169998	[] Merimen Administrator
2	27 Dec 2017 17:31	Clim Created		[I] Merimen Administrator
3	28 Dec 2017 12:00	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	28 Dec 2017 12:00	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	28 Dec 2017 12:00	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	28 Dec 2017 12:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/09	[A] CATHERINE CHONG KAI LING
7	28 Dec 2017 12:00	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	28 Dec 2017 12:00	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	28 Dec 2017 12:00	Clim Veh Model Changed	(201613) AUDI Q5 2.0 TFSI Quattro (A).	[A] CATHERINE CHONG KAI LING
10	28 Dec 2017 12:00	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
11	28 Dec 2017 14:05	Adj Rpt Initiated		[A] SHIAU CHAN
12	28 Dec 2017 14:05	Clim Details Notified		[A] SHIAU CHAN
13	28 Dec 2017 15:45	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/09	[A] SHIAU CHAN
14	28 Dec 2017 15:45	Adj Mandate Request	Cur.Req:26829.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	28 Dec 2017 16:26	Clim Registration Modified	Init.Est.->7,000 - 8,000. Excess: -> 2800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mohd Zawaye, Norsazani
16	28 Dec 2017 16:26	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	02 Jan 2018 11:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/09. Mandate Remarks: Re-inspect and upload damage photos of Charged air cooler, Sub frame. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
18	02 Jan 2018 11:17	Adj Mandate Set	Approved:19249.00:Re-inspect and upload damage photos of Charged air cooler, Sub frame. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1680233	28/12/2017 14:05	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLP9792L		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2271W
Vehicle Details	
Vehicle No.:	SLP9792L
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC (PSR)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	DAX006007
Chassis No.:	WAUZZZFY4H2025432
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$46,423.00
Original Registration Date:	23 Jun 2017
First Registration Date:	23 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$56,993.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2027
PARF Rebate Amount:	\$42,744.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2027
COE Category:	E - Open - all except motorcycle

COE Period(Years):	10
QP Paid:	\$50,526.00
COE Rebate Amount:	\$47,533.00
Total Rebate Amount:	\$90,277.00

The information contained herein is correct as at 28 Dec 2017

OK

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA117169998 Vehicle Registration No : CLP 9792L

Name(as shown in NRIC): PREMIUM AUTOMOBILES

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

NRIC/Passport No : _____

Address : _____

Contact (Tel) : _____ (H/P) : _____

(Email) : _____

Date of Accident : 23/12/2017 Time of Accident : 1000

Place of Accident : PIE TOWARDS ALEXANDRA

Insurance Company : AIG AGA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:


Select Country / State of Loss SINGAPORE



Signature of Vehicle Owner / Driver

Date: 27/12/17

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm





HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

POLICY SCHEDULE

COMPREHENSIVE COMMERCIAL MOTOR

ATTACHMENT (II)

THIS SCHEDULE IS NOT MEANT FOR ROAD TAX RENEWAL PURPOSES
PLEASE PRODUCE YOUR ORIGINAL CERTIFICATE OF INSURANCE

PERIOD OF INSURANCE (both dates inclusive)	: From : 6 Jul 2017 To : 5 Jul 2018	POLICY NO.	999994947/100828728
INSURED	Premium Automobiles Pte Ltd	ENDORSEMENT NO.	00000
ADDRESS		PREMIUM CALCULATION :	S\$
BUSINESS/PROFESSION		After 10% Fleet Discount	
REGISTRATION NO.	SLP9792L	Premium	\$1,935.00
MAKE & TYPE OF BODY	Audi Q5 2.0 TFSI QU TIP	GST @ 7%	\$135.45
YEAR OF REGISTRATION	2017		
SEATING CAPACITY	4	Premium	\$2,070.45
CHASSIS NO.	WAUZZZF4H202		
ENGINE NO.	DAX006007		
SUM INSURED	S\$1.00		
INSURING WITH COE/PARF	YES		
EXCESS	S\$2,800.00		
NAMED DRIVERS :			
HIRE PURCHASE OWNERS/EMPLOYER'S LOAN :		SUBJECT TO ENDORSEMENT(S) :	
DBS BANK LTD		15, 18, 25, 57, 72b, 89 & 131. Drivers must be of age 23 to 65 with at least 2 years driving experience	
		Issued in SINGAPORE on	27 Sep 2017

Person(s) Entitled To Drive :

Any person who is driving on the Insured's order or with their permission.

An Elderly Young and Inexperienced Driver (EYIDR) Excess of S\$2,500 (unless otherwise stated) applies to any drivers (named and unnamed) whose above age 65, below age 26 or has less than 2 years driving experience. If the EYIDR is not named in the policy, an additional S\$500 unnamed driver excess will be imposed.

Please refer to policy terms and conditions

Limitation As To Use :

- 1) Use in connection with the Insured's business.
 - 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.
 - 3) Use for social, domestic or pleasure purposes.
- The Policy does not cover
- a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.
 - b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle

PREMIUM AUTOMOBILES-FLEET
55 UBI ROAD 1
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 408699

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Authorised Representative

ORIGINAL

SSPIUS

AIG

HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723**CERTIFICATE OF INSURANCE**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MZ300

COMPREHENSIVE COMMERCIAL MOTOR		OWN DAMAGE EXCESS	S\$2,800.00 (1)
CERTIFICATE NO. 999994947/100828728-00000		WINDSCREEN EXCESS	S\$100.00
		(for policies with effect from 1st November 2002)	
		SUM INSURED	S\$1.00
		INSURING WITH COE/PARF	YES
1) VEHICLE REGISTRATION NO.	SLP9792L		
2) NAME OF INSURED	Premium Automobiles Pte Ltd		
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	6 Jul 2017		
4) DATE OF EXPIRY OF INSURANCE	5 Jul 2018		
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *			

Any person who is driving on the Insured's order or with their permission.
An Elderly Young and Inexperienced Driver (EYIDR) Excess of S\$2,500 (unless otherwise stated) applies to any drivers (named and unnamed) who are above age 69, below age 26 or has less than 2 years driving experience. If the EYIDR is not named in the policy, an additional S\$500 unnamed driver excess will be imposed

DELETED

Please refer to policy terms and conditions

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

1) Use in connection with the Insured's business.
2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.
3) Use for social, domestic or pleasure purposes.
The Policy does not cover
a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.
b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

LOSS OF USE NOT INCLUDED

* NAMED DRIVER N/A

HIRE PURCHASE COMPANY DBS BANK LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 27 Sep 2017

AIG ASIA PACIFIC INSURANCE PTE. LTD.

504108 222
PREMIUM AUTOMOBILES PTE LTD
55 UBI ROAD 1
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 408699

Authorised Representative

ORIGINAL

SGPIUS

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1259/2017/JT
Date	:	27-Dec-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Automobiles Pte Ltd
Address	:	55 Ubi Road 1
		Singapore 408699
Telephone	:	HP +65 8777 9608
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SLP 9792 L
Model Code	:	Audi Q5 Sport 2.0 TFSI qu
Model / Year	:	Jun-17
Engine No	:	DAX 006007
Chassis No	:	WAUZZZF4H202532
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	
Place of Accident	:	PIE towards Alexandra

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 9792 L.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/
2	To remove and transfer aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N \$ 1,100.00	? / NN
3	To dismantle front bumper. Renew front lock carrier and align to position. Renew front bumper and re-align LHS front fender. Re-organize front crash management components. Reinstall all parts removed.	\$ 3,500.00	500 /
4	To respray front bumper and wheel arch trims.	\$ 1,600.00	# 850 /
5	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly, including rear suspension components.	S/N \$ 3,200.00	/
6	To remove and renew centre and rear exhaust silencer. Replace and renew centre silencer heat shield.	S/N \$ 800.00	/
TOTAL LABOUR CHARGES		: \$ 10,680.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 9792 L.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To carry out wheel alignment.	S/N \$ 240.00	/
8	To carry out diagnostic checks.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: <u>\$ 11,112.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 9792 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER / CMA	\$ 2,151.00	1720
2	FRONT BUMPER SECURING STRIP / MC	\$ 30.00	23.63
3	FRONT BUMPER CLOSING ELEMENT - LHS / M's	\$ 90.00	77.92
4	FRONT BUMPER CENTRE GRILLE / CMA	\$ 117.00	93.60
5	FRONT BUMPER LOWER SPOILER / MC CMA	\$ 612.00	489.70
6	LOWER UNDERRUN BAR / cut	\$ 386.00	308.80
7	FRONT BUMPER CLOSING ELEMENT / Dis	\$ 45.00	35.76
8	RADIATOR GRILLE X { NN	\$ 2,998.00	X
9	RADIATOR GRILLE HOLDER X { NN	\$ 206.00	X
10	FOG LIGHT COVER - LHS / M's	\$ 473.00	378.40
11	HEADLIGHT WASHER CAP - LHS X NN	\$ 73.00	X
12	FRONT BUMPER GUIDE - LHS X NN	\$ 31.00	X
13	FOAM FILLER PIECE / CMA	\$ 236.00	188.80
14	FRONT WHEEL ARCH TRIM - LHS/RHS / MC	\$ 1,062.00	848.80
15	FRONT WHEEL SPOILER - LHS /	\$ 131.00	104.40
16	FRONT WHEEL HOUSE LINER - LHS X	\$ 224.00	X
17	JOINT SHAFT COVER X	\$ 32.00	X
18	LOCK CARRIER CMA X { NN	\$ 1,121.00	X
19	LOCK CARRIER SUPPORT X	\$ 43.00	X
20	LOCK CARRIER BRACE X	\$ 48.00	X
SUB TOTAL SPARE PARTS CHARGES		\$ 10,109.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 9792 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	COOLANT CONCENTRATE / MC	\$ 132.00	105.28
22	CHARGED AIR COOLER X GAA {NN	\$ 665.00	X
23	FRONT NUMBER PLATE X S/N	\$ 25.00	X
24	NOISE INSULATION PAN - FRONT /	\$ 682.00	545.60
25	NOISE INSULATION PAN - REAR /	\$ 431.00	344.40
26	UNDERBODY TRIM - CENTRE / Cut	\$ 58.00	45.76
27	UNDERBODY TRIM - FRONT LHS /	\$ 341.00	272.40
28	UNDERBODY TRIM - CENTRE LHS /	\$ 113.00	90
29	UNDERBODY TRIM - REAR LHS /	\$ 149.00	119.20
30	SUB-FRAME / Cut	\$ 1,604.00	1283.20
31	FRONT WISHBONE LINK - LHS / Cut	\$ 462.00	369.60
32	FRONT WHEEL BEARING - LHS X MC {NN	\$ 267.00	X
33	BALL JOINT - LHS X	\$ 157.00	X
34	FRONT LOWER WISHBONE - LHS / Cut	\$ 736.00	588.40
35	STONE CHIP GUARD - LHS / Cut	\$ 36.00	28.16
36	CENTRE SILENCER HEAT SHIELD / Cut	\$ 601.00	480.80
37	CENTRE SILENCER / Cut	\$ 856.00	684.80
38	DUAL CLIP / MC.	\$ 42.00	33.20
39	REAR SILENCER X / BT	\$ 1,195.00	956 ✓
40	REAR EXHAUST TENSIONING STRAP / Cut	\$ 79.00	62.96
SUB TOTAL SPARE PARTS CHARGES :		\$ 8,631.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 9792 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	SUSPENSION BOLTS AND NUTS ✓ NBL	\$ 400.00	151.76
42	SUNDRIES ✓ NBL	\$ 400.00	176.64 ✓
TOTAL SPARE PARTS CHARGES :		\$ 19,540.00	
TOTAL LABOUR CHARGES		\$ 11,112.00	
GRAND TOTAL		\$ 30,652.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Eme Qian - 82880282

27/12/17

Not Authorised

before paint photos.

8 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LK & Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1259/2017/JT
Date	:	27-Dec-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Guo Qiang

You recommended 10 days

We took 21 days exclude 3 Sundays

jb - 18 Apr 18 ref : Jeffrey Tan

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Automobiles Pte Ltd
Address	:	55 Ubi Road 1

	:	Singapore 408699
Telephone	:	HP +65 8777 9608
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SLP 9792 L
Model Code	:	Audi Q5 Sport 2.0 TFSI qu
Model / Year	:	Jun-17
Engine No	:	DAX 006007
Chassis No	:	WAUZZZF4H202532
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	
Place of Accident	:	PIE towards Alexandra

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 9792 L.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To remove and transfer aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N \$	1,100.00	nn
3	To dismantle front bumper. Renew front lock carrier and align to position. Renew front bumper and re-align LHS front fender. Re-organize front crash management components. Reinstall all parts removed.	\$	3,500.00	\$ 500.00
4	To respray front bumper and wheel arch trims.	\$	1,600.00	\$ 850.00
5	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly, including rear suspension components.	S/N \$	3,200.00	\$ 3,200.00
6	To remove and renew centre and rear exhaust silencer. Replace and renew centre silencer heat shield.	S/N \$	800.00	\$ 800.00
TOTAL LABOUR CHARGES		:	<u>\$ 10,680.00</u>	<u>\$ 5,830.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 9792 L.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		c/f		\$ 5,830.00
7	To carry out wheel alignment.	S/N	\$ 240.00	\$ 240.00
8	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 11,112.00</u>	<u>\$ 6,262.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 9792 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,151.00	\$ 1,720.00
2	FRONT BUMPER SECURING STRIP	\$ 30.00	\$ 23.68
3	FRONT BUMPER CLOSING ELEMENT - LHS	\$ 90.00	\$ 71.92
4	FRONT BUMPER CENTRE GRILLE	\$ 117.00	\$ 93.60
5	FRONT BUMPER LOWER SPOILER	\$ 612.00	\$ 489.20
6	LOWER UNDERRUN BAR	\$ 386.00	\$ 308.80
7	FRONT BUMPER CLOSING ELEMENT	\$ 45.00	\$ 35.36
8	RADIATOR GRILLE	\$ 2,998.00	
9	RADIATOR GRILLE HOLDER	\$ 206.00	
10	FOG LIGHT COVER - LHS	\$ 473.00	\$ 378.40
11	HEADLIGHT WASHER CAP - LHS	\$ 73.00	
12	FRONT BUMPER GUIDE - LHS	\$ 31.00	
13	FOAM FILLER PIECE	\$ 236.00	\$ 188.80
14	FRONT WHEEL ARCH TRIM - LHS/RHS	\$ 1,062.00	\$ 848.80
15	FRONT WHEEL SPOILER - LHS	\$ 131.00	\$ 104.40
16	FRONT WHEEL HOUSE LINER - LHS	\$ 224.00	
17	JOINT SHAFT COVER	\$ 32.00	
18	LOCK CARRIER	\$ 1,121.00	
19	LOCK CARRIER SUPPORT	\$ 43.00	
20	LOCK CARRIER BRACE	\$ 48.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 10,109.00	\$ 4,262.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 9792 L.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
	c/f	\$	4,262.96
21	COOLANT CONCENTRATE	\$ 132.00	\$ 105.28
22	CHARGED AIR COOLER	\$ 665.00	
23	FRONT NUMBER PLATE	S/N \$ 25.00	
24	NOISE INSULATION PAN - FRONT	\$ 682.00	\$ 545.60
25	NOISE INSULATION PAN - REAR	\$ 431.00	\$ 344.40
26	UNDERBODY TRIM - CENTRE	\$ 58.00	\$ 45.76
27	UNDERBODY TRIM - FRONT LHS	\$ 341.00	\$ 272.40
28	UNDERBODY TRIM - CENTRE LHS	\$ 113.00	\$ 90.00
29	UNDERBODY TRIM - REAR LHS	\$ 149.00	\$ 119.20
30	SUB-FRAME	\$ 1,604.00	\$ 1,283.20
31	FRONT WISHBONE LINK - LHS	\$ 462.00	\$ 369.60
32	FRONT WHEEL BEARING - LHS	\$ 267.00	
33	BALL JOINT - LHS	\$ 157.00	
34	FRONT LOWER WISHBONE - LHS	\$ 736.00	\$ 588.40
35	STONE CHIP GUARD - LHS	\$ 36.00	\$ 28.56
36	CENTRE SILENCER HEAT SHIELD	\$ 601.00	\$ 480.80
37	CENTRE SILENCER	\$ 856.00	\$ 686.80
38	DUAL CLIP	\$ 42.00	\$ 33.20
39	REAR SILENCER	\$ 1,195.00	\$ 956.00
40	REAR EXHAUST TENSIONING STRAP	\$ 79.00	\$ 62.96
SUB TOTAL SPARE PARTS CHARGES		\$ 8,631.00	\$ 10,275.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 9792 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		c/f	\$ 10,275.12
41	SUSPENSION BOLTS AND NUTS	\$ 400.00	\$ 151.76
42	Added labour - see attached	s/n \$ 480.00	\$ 480.00
43	SUNDRIES	\$ 400.00	\$ 126.64
	TOTAL SPARE PARTS CHARGES	\$ 20,020.00	\$ 11,033.52
	TOTAL LABOUR CHARGES	\$ 11,112.00	\$ 6,262.00
	GRAND TOTAL	\$ 31,132.00	\$ 17,295.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

revised purpose.

X

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0390/2017/JN

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Tyre - Continental SP s/n	\$ 480.00	\$ 480.00
		<u>\$ 480.00</u>	
<u>LABORS</u>			
	TOTAL	\$ 480.00	\$480.00

(-10%) 432

45 ?
photos.

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLP 9792 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1259/2017/MAS

13 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLP 9792 L, Audi Q5 Sport 2.0 TFSI Qu S-Tro

With reference to the above-mentioned vehicle, no **SLP 9792 L**, claimant,
Premium Automobiles Pte Ltd, please find the related document per
attached.

1. A copy of the Original invoice no. 85013088 – S\$14,996.61
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the
payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at
6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLP 9792 L

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Dec 2017 14:05		28 Dec 2017 12:00 Edit Adj Rpt	S\$16,815.52 Edit Estimates	S\$16,815.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	PREMIUM AUTOMOBILES PTE LTD, Co. Reg. No.: 199902271W		
Vehicle Reg. No.:	SLP9792L	Date of Loss:	23/12/2017 10:00 - :59 [6 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 7576741127SG	Policy/Cover Note No.:	999994947/100828728-00000 (Comprehensive)
		Excess:	S\$2,800.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/01/2018]		
Driver/Custodian:	WONG LI LING, MELISSA (29 / Female), NRIC: S8831579J, Tel: +6587779608		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG (02/01/2018): Alert - Adj Mandate Approved (S\$19249.00) - SLP9792L - Claim Handler: Mohd Zaway...
- AIG_SG (28/12/2017): SLP9792L / OD / 23/12/2017 / Coverage & Excess update

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP9792L (7576741127SG)
OD
Dec 23 2017 10:00AM
[PREMIUM AUTOMOBILES PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer	
Assessment Reports							1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	28/12/17 15:45	Adjuster Immediate Advice		 Load HTM				
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	28/12/17 13:59	General View		 Load JPG	☒			
2	28/12/17 13:59	General View		 Load JPG	☒			
3	28/12/17 13:59	General View		 Load JPG	☒			
4	28/12/17 13:59	General View		 Load JPG	☒			
5	28/12/17 13:59	General View		 Load JPG	☒			
6	28/12/17 13:59	General View		 Load JPG	☒			
7	28/12/17 13:59	General View		 Load JPG	☒			
8	28/12/17 13:59	General View		 Load JPG	☒			
9	28/12/17 13:59	General View		 Load JPG	☒			
10	28/12/17 13:59	General View		 Load JPG	☒			
11	28/12/17 13:59	General View		 Load JPG	☒			
12	28/12/17 13:59	General View		 Load JPG	☒			
13	28/12/17 13:59	General View		 Load JPG	☒			
14	28/12/17 13:59	General View		 Load JPG	☒			
15	28/12/17 13:59	General View		 Load JPG	☒			
16	28/12/17 13:59	General View		 Load JPG	☒			
17	28/12/17 13:59	General View		 Load JPG	☒			
18	28/12/17 13:59	General View		 Load JPG	☒			
19	28/12/17 13:59	General View		 Load JPG	☒			
20	28/12/17 13:59	General View		 Load JPG	☒			
21	28/12/17 13:59	General View		 Load JPG	☒			
22	28/12/17 13:59	General View		 Load JPG	☒			
23	28/12/17 13:59	General View		 Load JPG	☒			
24	28/12/17 13:59	General View		 Load JPG	☒			
25	28/12/17 13:59	General View		 Load JPG	☒			
26	28/12/17 13:59	General View		 Load JPG	☒			
27	28/12/17 13:59	General View		 Load JPG	☒			
28	28/12/17 13:59	General View		 Load JPG	☒			
29	28/12/17 13:59	General View		 Load JPG	☒			
30	28/12/17 13:59	General View		 Load JPG	☒			
31	28/12/17 13:59	General View		 Load JPG	☒			
32	28/12/17 13:59	General View		 Load JPG	☒			
33	28/12/17 13:59	General View		 Load JPG	☒			
34	28/12/17 13:59	General View		 Load JPG	☒			
35	28/12/17 13:59	General View		 Load JPG	☒			
36	28/12/17 13:59	General View		 Load JPG	☒			
37	28/12/17 13:59	General View		 Load JPG	☒			
38	28/12/17 13:59	General View		 Load JPG	☒			
39	28/12/17 13:59	General View		 Load JPG	☒			
40	28/12/17 13:59	General View		Load JPG				

					☒
41	28/12/17 13:59	General View	1	Load JPG	☒
42	28/12/17 13:59	General View	1	Load JPG	☒
43	28/12/17 13:59	General View	1	Load JPG	☒
44	28/12/17 13:59	General View	1	Load JPG	☒
45	28/12/17 13:59	General View	1	Load JPG	☒
46	28/12/17 13:59	General View	1	Load JPG	☒
47	28/12/17 13:59	General View	1	Load JPG	☒
48	28/12/17 13:59	General View	1	Load JPG	☒
49	28/12/17 13:59	General View	1	Load JPG	☒
50	28/12/17 13:59	General View	1	Load JPG	☒
51	28/12/17 13:59	General View	1	Load JPG	☒
52	28/12/17 13:59	General View	1	Load JPG	☒
53	28/12/17 13:59	General View	1	Load JPG	☒
54	28/12/17 13:59	General View	1	Load JPG	☒
55	28/12/17 13:59	General View	1	Load JPG	☒
56	28/12/17 13:59	General View	1	Load JPG	☒
57	28/12/17 13:59	General View	1	Load JPG	☒
58	28/12/17 13:59	General View	1	Load JPG	☒
59	28/12/17 13:59	General View	1	Load JPG	☒
60	28/12/17 13:59	General View	1	Load JPG	☒
61	28/12/17 13:59	General View	1	Load JPG	☒
62	28/12/17 13:59	General View	1	Load JPG	☒
63	28/12/17 13:59	General View	1	Load JPG	☒
64	28/12/17 13:59	General View	1	Load JPG	☒
65	28/12/17 13:59	General View	1	Load JPG	☒
66	28/12/17 13:59	General View	1	Load JPG	☒
67	28/12/17 13:59	General View	1	Load JPG	☒
68	28/12/17 13:59	General View	1	Load JPG	☒
69	28/12/17 13:59	General View	1	Load JPG	☒
70	28/12/17 13:59	General View	1	Load JPG	☒
71	28/12/17 13:59	General View	1	Load JPG	☒
72	28/12/17 13:59	General View	1	Load JPG	☒
73	28/12/17 13:59	General View	1	Load JPG	☒
74	28/12/17 13:59	General View	1	Load JPG	☒
75	28/12/17 13:59	General View	1	Load JPG	☒
76	28/12/17 13:59	General View	1	Load JPG	☒
77	28/12/17 13:59	General View	1	Load JPG	☒
78	28/12/17 13:59	General View	1	Load JPG	☒
79	28/12/17 13:59	General View	1	Load JPG	☒
80	28/12/17 13:59	General View	1	Load JPG	☒
81	28/12/17 13:59	General View	1	Load JPG	☒
82	28/12/17 13:59	General View	1	Load JPG	☒
83	28/12/17 13:59	General View	1	Load JPG	☒
84	28/12/17 13:59	General View	1	Load JPG	☒
85	28/12/17 13:59	General View	1	Load JPG	☒
86	28/12/17 13:59	General View	1	Load JPG	☒
87	28/12/17 13:59	General View	1	Load JPG	☒
88	28/12/17 13:59	General View	1	Load JPG	☒
89	28/12/17 13:59	General View	1	Load JPG	☒
90	28/12/17 13:59	General View	1	Load JPG	☒
91	28/12/17 13:59	General View	1	Load JPG	☒
92	28/12/17 13:59	General View	1	Load JPG	☒
93	28/12/17 13:59	General View	1	Load JPG	☒

94	28/12/17 13:59	General View	1	Load JPG	☒
95	28/12/17 13:59	General View	1	Load JPG	☒
96	28/12/17 13:59	General View	1	Load JPG	☒
97	28/12/17 13:59	General View	1	Load JPG	☒
98	28/12/17 13:59	General View	1	Load JPG	☒
99	28/12/17 13:59	General View	1	Load JPG	☒
100	28/12/17 13:59	General View	1	Load JPG	☒
101	28/12/17 13:59	General View	1	Load JPG	☒
102	28/12/17 13:59	General View	1	Load JPG	☒
103	28/12/17 13:59	General View	1	Load JPG	☒
104	28/12/17 13:59	Odometer Reading	1	Load JPG	☒
105	28/12/17 13:59	Chassis Number	1	Load JPG	☒
106	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
107	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
108	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
109	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
110	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
111	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
112	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
113	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
114	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
115	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
116	07/11/18 17:39	Reinspection Photo	1	Load JPG	☒
Documentation			1 per page	☒	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	28/12/17 13:58	Singapore Accident Statement	1 Load PDF		
2	28/12/17 13:58	ADDENDUM GIA REPORT	1 Load PDF		
3	28/12/17 13:58	Certificate of Insurance	1 Load PDF		
4	28/12/17 13:58	Driver's Driving License	1 Load PDF		
5	28/12/17 13:58	WORKSHOP ESTIMATE	1 Load PDF		
6	19/11/18 15:54	WORKSHOP INVOICE	1 Load PDF		
7	19/11/18 15:54	DISCHARGE VOUCHER	1 Load PDF		

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page	☒	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	27/12/17 17:31	Accident Statement	1 Load HTM		
2	27/12/17 17:36	Addendum Sheet	1 Load JPG	☒	
3	27/12/17 17:36	Accident Statement Addm. #1	1 Load HTM		
Photos/Images			3 per page	☒	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
2	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
3	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
4	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
5	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
6	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
7	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
8	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
9	27/12/17 17:29	Accident Photo	1 Load JPG	☒	
Documentation			1 per page	☒	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	27/12/17 16:15	Sketch Plan	1 Load JPG	☒	
2	27/12/17 16:15	Sketch Plan #2	1 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17024570/GQBN2

Date: 19/11/2018

REFERENCE

Insured/Claimant:	PREMIUM AUTOMOBILES PTE LTD	Policy No:	999994947/100828728-00000	Claim No:	7576741127SG
Date of Loss:	23/12/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP9792L	Engine No:	DAX006007
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZF4H2025432
Reg. Date:	23/06/2017 (Man. Year: 2017)	Odometer:	3739 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$233,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,540.00	10,553.52	8,986.48	45.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,112.00	6,262.00	4,850.00	43.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,652.00	16,815.52	13,836.48	45.14
- Excess (S\$)	2,800.00	2,800.00	0.00	0.00
(S\$)	27,852.00	14,015.52	13,836.48	49.68
+ GST 7.00/7.00% (S\$)	1,949.64	981.09	968.55	49.68
Nett Amount (S\$)	29,801.64	14,996.61	14,805.03	49.68

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 27/12/2017 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	2,151.00 FS	*1,720.00 FS
2	1		*FRONT BUMPER SECURING STRIP	Necessary	30.00 FS	*23.68 FS
3	1		*FRONT BUMPER CLOSING ELEMENT-LHS	Missing	90.00 FS	*71.92 FS
4	1		*FRONT BUMPER CENTRE GRILLE	Cracked	117.00 FS	*93.60 FS
5	1		*FRONT BUMPER LOWER SPOILER	Cracked	612.00 FS	*489.20 FS
6	1		*LOWER UNDERRUN BAR	Cut	386.00 FS	*308.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Distorted	45.00 FS	*35.36 FS
8	1		*RADIATOR GRILLE	Not Necessary	2,998.00 FS	*- FS
9	1		*RADIATOR GRILLE HOLDER	Not Necessary	206.00 FS	*- FS
10	1		*FOG LIGHT COVER-LHS	Missing	473.00 FS	*378.40 FS
11	1		*HEADLIGHT WASHER CAP-LHS	Not Necessary	73.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE-LHS	Not Necessary	31.00 FS	*- FS
13	1		*FOAM FILLER PIECE	Cracked	236.00 FS	*188.80 FS
14	2		*FRONT WHEEL ARCH TRIM-LHS/RHS	Necessary	1,062.00 FS	*848.80 FS
15	1		*FRONT WHEEL SPOILER-LHS	Necessary	131.00 FS	*104.40 FS
16	1		*FRONT WHEEL HOUSE LINER-LHS	Not Necessary	224.00 FS	*- FS
17	1		*JOINT SHAFT COVER	Not Necessary	32.00 FS	*- FS
18	1		*LOCK CARRIER	Not Necessary	1,121.00 FS	*- FS
19	1		*LOCK CARRIER SUPPORT	Not Necessary	43.00 FS	*- FS
20	1		*LOCK CARRIER BRACE	Not Necessary	48.00 FS	*- FS
21	1		*COOLANT CONCENTRATE	Necessary	132.00 FS	*105.28 FS
22	1		*CHARGED AIR COOLER	Not Necessary	665.00 FS	*- FS
23	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
24	1		*NOISE INSULATION PAN-FRONT	Cut	682.00 FS	*545.60 FS
25	1		*NOISE INSULATION PAN-REAR	Cut	431.00 FS	*344.40 FS
26	1		*UNDERBODY TRIM-CENTRE	Cut	58.00 FS	*45.76 FS
27	1		*UNDERBODY TRIM-FRONT LHS	Cut	341.00 FS	*272.40 FS
28	1		*UNDERBODY TRIM-CENTRE LHS	Cut	113.00 FS	*90.00 FS
29	1		*UNDERBODY TRIM-REAR LHS	Cut	149.00 FS	*119.20 FS
30	1		*SUB-FRAME	Cut	1,604.00 FS	*1,283.20 FS
31	1		*FRONT WISHBONE LINK-LHS	Cut	462.00 FS	*369.60 FS
32	1		*FRONT WHEEL BEARING-LHS	Not Necessary	267.00 FS	*- FS
33	1		*BALL JOINT-LHS	Not Necessary	157.00 FS	*- FS
34	1		*REAR LOWER WISHBONE-LHS	Cut	736.00 FS	*588.40 FS
35	1		*STONE CHIP GUARD-LHS	Cut	36.00 FS	*28.56 FS
36	1		*CENTRE SILENCER HEAT SHIELD	Cut	601.00 FS	*480.80 FS
37	1		*CENTRE SILENCER	Cut	856.00 FS	*686.80 FS
38	1		*DUAL CLIP	Necessary	42.00 FS	*33.20 FS
39	1		*REAR SILENCER	Bent	1,195.00 FS	*956.00 FS
40	1		*REAR EXHAUST TENSIONING STRAP	Cut	79.00 FS	*62.96 FS
41	1		*SUSPENSION BOLTS AND NUTS	Necessary	400.00 FS	*151.76 FS
42	1		*SUNDRIES	Necessary	400.00 FS	*126.64 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	19,540.00	10,553.52
--------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCOND CONDENSER,RADIATOR,CHARGED AIR COOLER,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURIZE COOLING SYSTEM	New	1,100.00	-
3	TO DISMANTLE FRONT BUMPER.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RENEW FRONT BUMPER AND RE-ALIGN LHS FRONT FENDER.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,500.00	500.00
4	TO RESPRAY FRONT BUMPER AND WHEEL ARCH TRIMS	New	1,600.00	850.00
5	TO SUSPEND ENGINE,DISMANTLE FRONT SUSPENSION ASSY.INSPECT FOR DAMAGES AND RENEW ACCORDINGLY,INCLUDING REAR SUSPENSION COMPONENTS	New	3,200.00	3,200.00
6	TO REMOVE AND RENEW CENTRE AND REAR EXHAUST SILENCER.REPLACE AND RENEW CENTRE SILSNCER HEAT SHIELD	New	800.00	800.00
7	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
8	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			11,112.00	6,262.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >