

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9987C - TOKIO**AAD1712-257***Not Authorized*
61 Imp & 3700

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9987C - JHOW**VF1ABL15AUC278136****RENAULT****LATITUDE****23.12.2017****TOKIO****PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>N</i>	1,108.46	} X
2	1	BUMPER LOWER REAR	\$	<i>SL</i>	768.84	
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i>	113.47	
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i>	135.97	
5	1	BUMEP R RETAINER RH REAR	\$	<i>SL</i>	44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i>	43.61	
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i>	135.97	
8	1	BUMEP R RETAINER LH REAR	\$	<i>SL</i>	44.99	
9	1	ROCKER PANEL OUTER RH	\$	<i>N</i>	987.49	
10	1	FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13	} X
11	1	WHEELARCH REAR RH	\$	<i>SL</i>	543.47	
12	1	TAILLAMP RH	\$	<i>SL</i>	552.55	
13	1	TAILLAMP PANEL RH	\$	<i>N</i>	986.70	
14	1	DOOR PANEL REAR RH	\$	<i>N</i>	2,844.66	
15	1	DOOR GUIDE REAR RH	\$	<i>SL</i>	176.82	
16	1	DOOR HINGE UPPER RH	\$	<i>N</i>	274.50	
17	1	DOOR HINGE LOWER RH	\$	<i>N</i>	300.55	
18	1	DOOR GRAB HANDLE REAR RH	\$	<i>SL</i>	210.96	
19	1	DOOR HANDLE OUTER REAR RH	\$	<i>SL</i>	126.49	
20	1	DOOR HANDLE CAP REAR RH	\$	<i>SL</i>	35.52	
21	1	DOOR HANDLE SEAL REAR RH	\$	<i>SL</i>	7.89	
22	1	DOOR HANDLE COVER REAR RH	\$	<i>SL</i>	13.22	
23	1	DOOR HANDLE MODULE REAR RH	\$	<i>SL</i>	133.60	
24	1	DOOR FINISHER REAR RH	\$	<i>SL</i>	423.10	
25	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>SL</i>	410.66	
26	1	DOOR SEAL REAR RH	\$	<i>N</i>	162.02	
27	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>SL</i>	334.69	
28	1	DOOR MOULDING REAR RH	\$	<i>SL</i>	176.82	

TOTAL	\$	14,397.14
10%	\$	1,439.71
	\$	12,957.43

Specical Nett

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-257**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9987C - TOKIO

1	1SET	PARKING AID	\$	Sn	700.00	
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	nn	10.00	
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
8	1	TAILLAMP CLIP RH	\$	nn	5.00	
9	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00	
10	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
11	1	WINDSCREEN MOULDING	\$	nn	100.00	
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
13	1	CAP HUB RH RR	\$	nn	35.00	
14	1	RIM RH RR	\$	Sn	385.00	X
15	1	TYRE RH RR	\$	Sn	330.00	X
16	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
17	1	DOOR STICKER "Classic"	\$	nn	30.00	X
18	1	DOOR STICKER "6555-3333"	\$	nn	80.00	6555

TOTAL	\$	2,208.00
TOTAL PARTS	\$	15,165.43

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	6601
To reinstall rear bumper parking sensor.	\$	nn	170.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	6001
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
Towing Fees	\$	nn	120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	1001

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-257**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9987C - TOKIO

To transfer of rear windscreen fittings and
conduct water seepage test.

\$ 170.00 *120*

To check steering geometry and computer
wheel alignment

\$ 220.00 *60*

To transfer of door fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

TOTAL \$ 7,710.00

Over All Total \$ 22,875.43

(PARTS BY PARTS)**Repair Days***10 Days**4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: