

Not Authorized
L1 Buy @ 3550

Vehicle No.: SHB7666C - CANDY
 Chassis No.: KL1LA69RJB122650
 Vehicle Make: CHEVROLET
 Vehicle Model: EPICA 2.0
 Date of Accident : 23.12.2017
 Third Party Insurer : AIG

PART		LIST
1	1 Rear Bumper	\$ Bu 1,202.00 ✓
2	1 Rear Bumper Beam	\$ Bz 239.94 ✓
3	1 Rear Bumper Centre Absorber	\$ CMA 260.00 ✓
4	1 Rear Bumper Side Retainer RH	\$ CM 68.76 ✓
5	1 Rear Bumper Side Retainer LH	\$ Sm 68.76 X
6	1 Rear Bumper Reflectors RH	\$ Br 119.74 ✓
7	1 Rear Bumper Reflectors LH	\$ Sm 119.74 X
8	1 Rear Bumper Tow Hook Cover	\$ Sm 93.00 X
9	1 Rear Luggage Floor Panel	\$ R 973.00 ✓
10	1 Rear Luggage Floor Panel Insulator	\$ Sm 63.50 X
11	1 Rear Luggage Floor Panel Trim Board	\$ Sm 378.00 X
12	1 Rear End Panel Outer	\$ Bz 623.76 ✓
13	1 Rear End Panel Inner Trim	\$ Dig 263.84 ✓
14	1 Bootlid	\$ R 973.00 ✓
15	1 Bootlid inner trim board	\$ Sm 400.00 X
16	1 Bootlid Weatherstrip	\$ 172.14 Sm Di 1 Pd 344.28 508 Sm
17	1 Bootlid Lock - Top	\$ R 466.56 ✓
18	1 Bootlid 'CHEVROLET' Badge	\$ R 120.62 ✓
19	1 Bootlid Logo	\$ R 138.84 ✓
20	1 Bootlid 'EPICA LT' Badge	\$ R 119.84 ✓
21	1 Bootlid Reflector Centre	\$ Sm 217.97 X
22	1 Bootlid Reflector RH	\$ CMA 128.40 ✓
23	1 Bootlid Reflector LH	\$ Sm 128.40 X
24	1 Bootlid Hinge RH	\$ R 120.00 X
25	1 Bootlid Hinge LH	\$ R 120.00 X
26	1 Rear Tail Lamp RH	\$ R/CMA 479.30 ✓
27	1 Rear Tail Lamp Panel RH	\$ R 359.00 X
28	1 Rear Tail Lamp LH	\$ Sm 479.30 X
29	1 Rear Tail Lamp Panel LH	\$ R 359.00 X
30	1 Rear Exhaust Box (Muffler A-EXH,RR)	\$ R 1,110.00 X

31	1	Rear Fender RH	\$	R	1,145.00	}
32	1	Rear Fender Inner Trim RH	\$	Sn	418.44	
33	1	Rear Fender Inner Cowling RH	\$	Sn	76.60	
34	1	Rear Fender LH	\$	R	1,145.00	
35	1	Rear Fender Inner Trim LH	\$	Sn	418.44	
36	1	Rear Fender Inner Cowling LH	\$	Sn	76.60	

TOTAL	\$	13,818.63
10%	\$	1,381.86
	\$	12,436.77

Special Nett

1	1Set	Licence Plate With Holder	\$	Sn	60.00	X
2	1Set	Bootlid inner trim board Clip	\$	nn	40.00	X
3	1Set	Rear Bumper Parking Sensor	\$	nd/shwt	300.00	✓
4	1Set	Rear Bumper Fastener Clip	\$	nn	44.00	✓
5	1Set	Rear Fender Inner Trim Clip LH	\$	nn	30.00	X
6	1Set	Rear Fender Inner Trim Clip RH	\$	nn	30.00	X
7	1Set	Rear Bumper End Dust Cover Clip	\$	nn	30.00	X
8	1	Rear Boot Sticker 'Trans-cab'	\$	nn	30.00	✓
9	1	Rear Boot Sticker '6555-3333'	\$	nn	30.00	✓
10	1	Rear Exhaust Mounting	\$	nn	10.00	X
11	2	Rear Windscreen Sealant	\$	nn	80.00	X
12	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	X
13	1	Spare Tyre	\$	Sn	180.00	X
14	1	Spare Wheel Rim	\$	Sn	126.74	X

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,527.51

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 5,400.00 *700*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *600*

Putty And Spray Painting Of The Affected Portion.	\$	5,350.00	<i>800</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	<i>600</i>
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of boot fittings and conduct water seepage test.	\$	170.00	<i>600</i>
Towing fees	\$	<i>nn</i> 120.00	<i>X</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
	\$	12,830.00	
TOTAL	\$	26,357.51	

Repair Days

20 Days

5 days

<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____</p>
