



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2010 HYUNDAI I30 1.6 (SJY5585X)

Date of Loss

22 December 2017

Time of Loss

23.45

Loss Description

SJY5585X (INSD) > SJU7990S (TP) > SKV6742G

Comment

Workshop Details

Total Rebate Amount

17339

Nett Loss Amount

\$12,661.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

14/05/2018



Days of work completion *

53



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJY5585X

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

14/09/2010



Mileage

114861

Age of Vehicle

7

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2010

ASSESSMENT INFO...

2010

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POH ENG OON

POST SURVEY INF...

CATEGORY	Make
POLICY INFORMAT...	HYUNDAI
ASSESSMENT INFO...	HYUNDAI

CATEGORY	Model
POLICY INFORMAT...	I30 1.6
ASSESSMENT INFO...	FD I30 CW 1.6 A

CATEGORY	Type
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Type of Paint
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Chassis No
POLICY INFORMAT...	KMHDC81DMAU073475

CATEGORY	
----------	----------------------

CATEGORY	Date of Birth
FNOL INFORMATI...	19 August 1957
POST SURVEY INF...	dd/mm/yyyy 

CATEGORY	Age
FNOL INFORMATI...	60
POST SURVEY INF...	

CATEGORY	Occupation
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Education Qualification
FNOL INFORMATI...	Other
POST SURVEY INF...	

CATEGORY	Driving Experience
----------	--------------------

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... G4FCAU829123

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 40

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 123E RIVERVALE DRIVE, 545123,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1238228F

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

28/12/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/60R15

Condition of Vehicle at time of survey

General condition

Good ▼

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good ▼

Tyre Condition

Spare wheel

Rear Tyre Size

195/60R15

Front left side

HANKOOK8mm

Front right side

HANKOOK8mm

Rear left side

HANKOOK8mm

Rear right side

HANKOOK8mm

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes☐ No

Save

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts				
Add Approve Deny														
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
		1	1			FRONT BONNET			Bent	385				385
		2	2			FRONT BONNET HINGE LH & RH			Damaged	22				44
		3	1			FRONT BONNET INSULATOR			Damaged	120				120
		4	12			FRONT BONNET INSULATOR CLIPS			Necessary	1.5				18
		5	1			FRONT BONNET LOCK			Damaged	30				30
		6	1			FRONT BONNET LOCK CABLE			Serviceable	0	0	0	0	0
		7	1			FRONT BONNET INNER CTR RUBBER			Cut	15				15
		8	1			FRONT GRILLE OUTER CHROME MOULDING			Cracked	65				65
		9	1			FRONT GRILLE EMBLEM			Necessary	15				15
		10	8			FRONT GRILLE CLIPS			Necessary	1				8
		11	2			HEADLAMP LH & RH (NOT HID)			Cracked	187.5				375
		12	1			HEADLAMP LOWER BEAM RH			Bent	15				15
		13	2			HEADLAMP CLIPS (4PCS)			Necessary	1				2

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
		14	1			FRONT BUMPER			Cracked	135				135
		15	1			FRONT BUMPER SIDE RETAINER RH			Damaged	12				12
		16	12			FRONT BUMPER CLIPS			Necessary	1				12
		17	1			FRONT BUMPER LOWER GRILLE CTR			Cracked	44				44
		18	1			FRONT BUMPER REINFORCEMENT			Bent	85				85
		19	1			FRONT BUMPER REINFORCEMENT BRACKET			Repair	0	0	0	0	0
		20	1			FRONT BUMPER SPONGE			Cracked	35				35
		21	1			FRONT BUMPER LOWER COVER CTR			Serviceable	0	0	0	0	0
		22	1			FOGLAMP ASSY RH			Serviceable	0	0	0	0	0
		23	1			FRONT FENDER RH			Buckled	150				150
		24	1			FRONT FENDER COWLING RH			Serviceable	0	0	0	0	0
		25	20			FRONT FENDER COWLING CLIPS			Serviceable	0	0	0	0	0
		26	1			RADIATOR SUPPORT PANEL			Cracked	235				235
		27	2			RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE LH & RH			Damaged	4				8
		28	1			RADIATOR SUPPORT PANEL TOP GARNISH			Cracked	5				5

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
		29	10			RADIATOR SUPPORT PANEL TOP GARNISH CLIPS			Necessary	1				10
		30	2			HORN			Serviceable	0	0	0	0	0
		31	1			AIR DUCT TOP ASSY			Serviceable	0	0	0	0	0
		32	1			AIR CON CONDENSER ASY			Damaged	150				150
		33	1			AIR CON CONDENSER PIPE (COND-VALVE) (NPA)			Serviceable	0	0	0	0	0
		34	1			AIR CON CONDENSER PIPE (COND-COMP) (NPA)			Serviceable	0	0	0	0	0
		35	1			AIR CON CONDENSER PIPE (COMP-VALVE) (NPA)			Serviceable	0	0	0	0	0
		36	1			RADIATOR ASSY			Damaged	185				185
		37	1			RADIATOR FAN BLADE/COWLING/MOTOR ASSY			Cracked	135				135
		38	1			RADIATOR SPARE TANK			Damaged	35				35
		39	1			RADIATOR SPARE TANK HOSE			Serviceable	0	0	0	0	0
		40	1			RADIATOR SPARE TANK CTR PIPE			Damaged	32				32
		41	1			RADIATOR TOP HOSE			Damaged	18				18
		42	1			WIPER WASHER TANK RH			Serviceable	0	0	0	0	0

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
		43	1			ENGINE OVERHAUL (NPA)			Serviceable	0	0	0	0	0
		44	1			FRONT GRILLE			Cracked	38				38
		45	1			HEADLAMP LOWER BEAM LH			Serviceable	0	0	0	0	0
		46	1			FRONT BUMPER SIDE RETAINER LH			Serviceable	0	0	0	0	0
		47	1			FRONT FENDER LH			Repair	0	0	0	0	0
		48	1			RADIATOR BOTTOM HOSE			Serviceable	0	0	0	0	0

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
		1		TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	20	0	0	Reviewing	
		2		TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS	100	0	0	Reviewing	
		3		TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR (NPA)	0	0	0	Deny	
		4		TO REMOVE & REINSTALL/REPLACE ENGINE OVERHAUL (NPA)	0	0	0	Deny	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	5		TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT & BRACKET. TO KNOCK & REPAIR FRONT WHEELHOUSE LH & RH, FRONT DOOR RH, FRT CHASSIS FRAME RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	600	0	0	Reviewing	
	6		TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT & BRACKET RH, RADIATOR SUPPORT PANEL, FRONT FENDER LH & RH, FRONT DOOR RH, FRONT CHASSIS FRAME RH, FRONT WHEELHOUSE LH & RH	600	0	0	Reviewing	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	BUMPER TOP BRACKET RH	Reviewing	15	(DISTORTED) SUPP 1 - 09/01/18	
		2	BONNET IN GARNISH	Reviewing	15	(CRACKED) SUPP 1 - 09/01/18	
		3	CHASSIS FRAME BRACKET RH	Reviewing	85	(BENT) SUPP 1 - 09/01/2018	
		4	DAYS OF REPAIR : 5 DAYS	Reviewing			
		5	RADIATOR COOLANT	Reviewing	20	NECESSARY	
		6	NUMBER PLATE	Reviewing	35	DENTED	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$3,906.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,320.00	\$1,320.00
Spare Parts	\$2,416.00	\$2,416.00
Miscellaneous	\$170.00	\$170.00

Submit for Review